

# RT500 ROM A0 Patch 0.1

Friday, April 26, 2019 1:26 PM

## ROM patch list for the A0 chip.

Patch index	JIRA Ticket	Criticality	Patch details	Patch type	Patch data in ROM patch fuses
0	<a href="#">KBL-4308</a>		<i>It is likely that the ROM cannot boot from Octal FLASH devices (for example, MX25UM51345G, ATXP032 or MT35X) on some boards, see the details from the TKT description</i>	Code patch	0x55020106 0x1301cb73 0x51faf44f 0x1e414608 0xd1fb2800 0x506cf641 0x0001f2c1 0x47709000
1	<a href="#">KBL-4566</a>		<i>Flash config block will be programmed to offset 0x0 without patch</i>	Code patch	0x55020103 0x130171d9 0x4400F240 0x0400F6C0 0x47709400 0x55020103 0x1301720b 0x4400F240 0x0400F6C0 0x47709400
2	<a href="#">KBL-4586</a>		<i>Writing data at alias address will fail without patch, caused by the MPU protection</i>	Code patch	0x55020106 0x13011815 0xF64F9901 0xF6CE72FF 0xEA0172FF 0xF04F0102 0x91010204 0x47709202
3	<a href="#">KBL-4189</a>		<i>SPI clock is 99Mhz in High power boot without patch, should patch to 50Mhz</i>	Code patch	0x55020102 0x13002941 0x90002007 0x47704770
4	<a href="#">KBL-4662</a>		<i>This issue found in the eMMC device Sandisk SDINBDG4-8G Here are the test steps to reproduce the issue. 1. Power up the board.</i>	Code patch	0x55020104 0x13018637 0xF2426820 0x4A017110

			<p>2. Do a power cycle for the eMMC: power down the eMMC and wait about 20ms. And then power up the eMMC and wait about 5ms.</p> <p>3. (optional) wait 100ms to make sure the eMMC power is table.</p> <p>4. Send CMD0. (No response is needed)</p> <p>5. Send CMD1, and get no response.{code}</p> <p>The root cause seems that the eMMC devices need more clock cycles to do the clock sync, which cannot be completed during CMD</p>		0x47704710 0x130196E3
5	<a href="#">KBL-4661</a>		<p>This issue found in two eMMC devices</p> <p>Micron MTFC8GAKAJCN-1M WT</p> <p>Sandisk SDINBDG4-8G</p>	Code patch	0x55020107 0x1301796B 0xBF1C2E00 0x47709600 0x0040980D 0x6D21BF42 0x7180F441 0x96006521 0x47704770
6	<a href="#">KBL-4718</a>		<p>There is an un-initialized variable in the code.</p> <p>So it depends on the run-time context to have an real impact.</p>	Data patch	0x55010001 0x13018a69 0xe01670f5

- Merge all the R500 A0 0.1 patches together, program them from Fuse word **0xA1**

```

@000000A1 0x55020106 // KBL-4308
@000000A2 0x1301cb73
@000000A3 0x51faf44f
@000000A4 0x1e414608
@000000A5 0xd1fb2800
@000000A6 0x506cf641
@000000A7 0x0001f2c1
@000000A8 0x47709000

@000000A9 0x55020103 // KBL-4566
@000000AA 0x130171d9
@000000AB 0x4400F240
@000000AC 0x0400F6C0
@000000AD 0x47709400
@000000AE 0x55020103
@000000AF 0x1301720b
@000000B0 0x4400F240
@000000B1 0x0400F6C0

```

@000000B2 0x47709400

@000000B3 0x55020106 // KBL-4586  
@000000B4 0x13011815  
@000000B5 0xF64F9901  
@000000B6 0xF6CE72FF  
@000000B7 0xEA0172FF  
@000000B8 0xF04F0102  
@000000B9 0x91010204  
@000000BA 0x47709202

@000000BB 0x55020102 // KBL-4189  
@000000BC 0x13002941  
@000000BD 0x90002007  
@000000BE 0x47704770

@000000BF 0x55020104 // KBL-4662  
@000000C0 0x13018637  
@000000C1 0xF2426820  
@000000C2 0x4A017110  
@000000C3 0x47704710  
@000000C4 0x130196E3

@000000C5 0x55020107 // KBL-4661  
@000000C6 0x1301796B  
@000000C7 0xBF1C2E00  
@000000C8 0x47709600  
@000000C9 0x0040980D  
@000000CA 0x6D21BF42  
@000000CB 0x7180F441  
@000000CC 0x96006521  
@000000CD 0x47704770

@000000CE 0x55010001 // KBL-4718  
@000000CF 0x13018a69  
@000000D0 0xe01670f5