

LAB 1 Report

3190104611 Xuzheng Chen


Lab Target

This Lab need to write a program in LC-3 machine language to detect whether or not a 16-bit value has at least three consecutive '1's.

Algorithm

The algorithm is :

- Get number from x3100 in binary and storage it in register, init the register which needed.
- Do a loop to find 1
 - if now number is negative, it means the sign bit is 1, so we add 1 to counter
 - else if number is zero or positive, it means the sign bit is 0, so we clean the counter
- if the counter is 3, then we break out.
- then we left shifted the now number and subtraction 1 to number counter.
- finally we check the number counter
 - 0 means it don't break out , we put 0 to register 010
 - else means it break out, we put 1 to register 010.



Code

```

0011 0000 0000 0000 ; (start address at 0x3000)

; This program use 5 register
; 001: the number of x3100    010: the left shifted of num
; 011: the last number to shift  100: the number of '1'
; 101: the 100reg -3
0010 001 011111111; load 0x3100 number to reg001
0001 010 001 1 00000; 010 reg store the now number we check
0101 011 011 1 00000; clean 011 register
0101 100 100 1 00000; clean 100 register
0001 011 011 1 01111; add 011reg 15
0001 011 011 1 00001; add 011reg 1

0000 010 000001010;
    0001 010 010 1 00000; reput condition code
    0000 011 000000010;
        0001 100 100 1 00001; add 100reg 1
        0000 111 000000001;

        0101 100 100 1 00000; clear reg100
        0001 101 100 1 11101;
        0000 011 000000011;
        0001 010 010 0 00010; left shifted 010reg
        0001 011 011 1 11111; add 011reg -1;

0000 111 111110101;

0101 010 010 1 00000; clean reg010
0001 011 011 1 00000;
0000 001 000000010;    postive or zero
    0001 010 010 1 00000;
    0000 111 000000001;
0001 010 010 1 00001;

1111 0000 0010 0101 ; halt

```

Test Results

Memory

Q

x3100

Manage Labels

0x	Label	Hex	Instruction
▼	x3100	xFFFF	FILL xFFFF
▼	x3101	x0000	NOP
▼	x3102	x0000	NOP
▼	x3103	x0000	NOP
▼	x3104	x0000	NOP
▼	x3105	x0000	NOP
▼	x3106	x0000	NOP
▼	x3107	x0000	NOP
▼	x3108	x0000	NOP
▼	x3109	x0000	NOP
▼	x310A	x0000	NOP
▼	x310B	x0000	NOP
▼	x310C	x0000	NOP
▼	x310D	x0000	NOP
▼	x310E	x0000	NOP
▼	x310F	x0000	NOP

▲▼

Jump to PC

⏻

AssembleRaw

Status

Registers

R0: x7FFF
R4: x0003
PC: xFD79

R1: xFFFF
R5: x0000
IR: xB02C

R2: x0001
R6: x0000
PSR: x8001

R3: x000E
R7: xFD75
CC: P

Clear R0-R7

Reset all registers

StepNextFinishRunPauseContinueUnhalt

☒ Follow PC

Console

----- Halting the processor -----

Clear Input Buffer (0 characters)

Clear Output

☒ Newline as 0x0A

☐ Newline as 0x0D

☐ Binary (leave newlines unchanged)