

TOP SECRET//COMINT//REL TO USA, FVEY

(Report generated on: 4/11/2013 3:31:05PM)

NewCrossProgram		Active ECP Count:	1
CrossProgram-1-13	New	ECP Lead:	NAME REDACTED
Title of Change:	Update Software on all Cisco ONS Nodes		
Submitter:	NAME REDACTED	Approval Priority:	C-Routine
Site(s):	APPLE1 : CLEVERDEVICE : HOMEMAKER : DOGHUT : QUARTERPOUNDER : QUEENSLAND : SCALLION : SPORTCOAT : SUBSTRATUM : TITAN POINTE : SUBSTRATUM : BIRCHWOOD : MAYTAG : EAGLE : EDEN :	Project(s):	No Project(s) Entered
System(s):	Comms/Network : Comms/Network : Comms/Network : Comms/Network :	SubSystem(s):	No Subsystem(s) Entered
Description of Change:	Update software on all Cisco Optical Network Switches.		

Reason for Change:

All of our Cisco ONS SONET multiplexers are experiencing a software bug that causes them to intermittently drop out.

Mission Impact:

The mission impact is unknown. While the existing bug doesn't appear to affect traffic, applying the new software update could. Unfortunately, there is now way to be sure. We can't simulate the bug in our lab and so it's impossible to predict exactly what will happen when we apply the software update. We propose to update one of the nodes in NBP-320 first to determine if the update goes smoothly.

Recently we tried to reset the standby manager card in the HOMEMAKER node. When that failed, we attempted to physically reseal it. Since it was the standby card, we did not expect that would cause any problems. However, upon resealing the card, the entire ONS crashed and we lost all traffic through the box. It took more than an hour to recover from this failure.

The worst case scenario is that we have to blow away the entire configuration and start from scratch. Prior to starting our upgrade, we will save the configuration so that if we have to configure the box from scratch, we can simply upload the saved configuration. We estimate that we will be down for no more than an hour for each node in the system.

Additional Info:

3/26/2013 8:16:13 AM

NAME REDACTED

We have tested the upgrade in our lab and it works well. However, we can't repeat the bug in our lab, so we don't know if we will encounter problems when we attempt to upgrade a node that is affected by the bug.

Last CCB Entry:

04/10/13 16:08:11 NAME REDACTED

09 Apr Blarney CCB - Blarney ECP board approved

ECP lead: NAME REDACTED

Programs Affected:

Blarney Fairview Oakstar Stormbrew

No Related Work Tasks