

高通Lab Test技术期刊 – 201511



Qualcomm Technologies, Inc.

Confidential and Proprietary – Qualcomm Technologies, Inc.

机密和专有信息——高通技术股份有限公司



Confidential and Proprietary – Qualcomm Technologies, Inc.

Confidential and Proprietary – Qualcomm Technologies, Inc.

NO PUBLIC DISCLOSURE PERMITTED: Please report postings of this document on public servers or web sites to: DocCtrlAgent@qualcomm.com. **禁止公开：**如在公共服务器或网站上发现本文档，请报告至：DocCtrlAgent@qualcomm.com.

Restricted Distribution: Not to be distributed to anyone who is not an employee of either Qualcomm or its affiliated without the express approval of Qualcomm's Configuration Management. **限制分发：**未经高通配置管理部门的明示批准，不得发布给任何非高通或高通附属及关联公司员工的人。 Not to be used, copied, reproduced, or modified in whole or in part, nor its contents revealed in any manner to others without the express written permission of Qualcomm Technologies, Inc. 未经高通技术股份有限公司明示的书面允许，不得使用、复印、复制、或修改全部或部分文档，不得以任何形式向他人透露其内容。

The user of this documentation acknowledges and agrees that any Chinese text and/or translation herein shall be for reference purposes only and that in the event of any conflict between the English text and/or version and the Chinese text and/or version, the English text and/or version shall be controlling. 本文档的用户知悉并同意中文文本和/或翻译仅供参考之目的，如英文文本和/或版本和中文文本和/或版本之间存在冲突，以英文文本和/或版本为准。

This document contains confidential and proprietary information and must be shredded when discarded. 未经高通明示的书面允许，不得使用、复印、复制全部或部分文档，不得以任何形式向他人透露其内容。本文档含有高通机密和专有信息，丢弃时必须粉碎销毁。

Qualcomm reserves the right to make changes to the product(s) or information contained herein without notice. No liability is assumed for any damages arising directly or indirectly by their use or application. The information provided in this document is provided on an "as is" basis. 高通保留未经通知即修改本文档中提及的产品或信息的权利。本公司对使用或应用本文档所产生的直接或间接损失概不负责。本文档中的信息为基于现状所提供，使用风险由用户自行承担。

Qualcomm is a trademark of QUALCOMM Incorporated, registered in the United States and other countries. All QUALCOMM Incorporated trademarks are used with permission. Other product and brand names may be trademarks or registered trademarks of their respective owners. Qualcomm是高通公司在美国及其它国家注册的商标。所有高通公司的商标皆获得使用许可。其它产品和品牌名称可能为其各自所有者的商标或注册商标。

This technical data may be subject to U.S. and international export, re-export, or transfer ("export") laws. Diversion contrary to U.S. and international law is strictly prohibited. 本文档及所含技术资料可能受美国和国际出口、再出口或转移出口法律的限制。严禁违反或偏离美国和国际的相关法律。

Qualcomm Technologies, Inc. 5775 Morehouse Drive San Diego, CA 92121 U.S.A.
高通技术股份有限公司，美国加利福尼亚州圣地亚哥市莫豪斯路 5775 号，邮编 92121

Revision History

Revision	Date	Description
A	Oct 2015	Initial release

Note: There is no Rev. I, O, Q, S, X, or Z per Mil. standards.

Contents

- About CT B41 LTE Protocol Test
- Disable LTE Fast Dormancy for Lab Test
- LTE Protocol Failures in CT Lab Testing
- Configuration Summary for GCF/PTCRB MFBI Cases
- CTA测试中CDMA注网问题排查方法
- CMCC APSS测试中的常见问题
- 关于CMCC VOLTE样机送测

About CT B41 LTE Protocol Test

- Issue
 - For CT PA test, if UE only supports 2555~2655MHz (EARFCN 40240~41240) for China market, below LTE protocol cases will be failed due to unsupported B41 FREQ in test scenario.
- Solution:
 - Remove the SW limitation (by deleting EFS /nv/item_files/modem/lte/ML1/update_band_range) on UE side to support full B41 bandwidth as 194M if there is no limitation on OEM HW for B41;
 - Or, get waiver from CT for below cases as UE can't support the test FREQs of B41.
- Affected case list (39 TCs in CT spec)

China Telecom Case No.	36.523-1 Case No.	B41 EARFCN
6.2.1 Operations in idle mode		
TC-TD LTE-PCT-01001 [Mandatory]RPLMN, HPLMN/EHPLMN, UPLMN and OPLMN / PLMN selection under auto-mode	6.1.1.1	41490/40620/39750/40970
TC-TD LTE-PCT-01002 [Mandatory]Auto-mode PLMN selection/ combinations of other PLMN and access technologies	6.1.1.2	41490/40620/39750/40970
TC-TD LTE-PCT-01003 [Mandatory]Cell reselection of ePLMN in manual mode	6.1.1.3	40620/41490/39750
TC-TD LTE-PCT-01004 [Mandatory]PLMN selection of RPLMN, HPLMN/EHPLMN, UPLMN and OPLMN / Automatic mode / User reselection	6.1.1.6	41490/40620/39750/40970
TC-TD LTE-PCT-01011 [Mandatory]Cell reselection / Equivalent PLMN	6.1.2.7	40620/41490/39750
TC-TD LTE-PCT-01012 [Mandatory]Cell reselection using cell mode and cell reservations / Access control class 0 to 9	6.1.2.8	40620/41490/39750

About CT B41 LTE Protocol Test

TC-TD LTE-PCT-01013 [Mandatory]Cell reselection using cell mode and cell reservations / Access control class 11 to 15	6.1.2.9	40620/41490/39750
TC-TD LTE-PCT-01014 [Mandatory]Inter-frequency cell reselection	6.1.2.11	40620/40620/41490
TC-TD LTE-PCT-01016 [Mandatory]Cell reselection, Sintrasearch, Snonintrasearch	6.1.2.13	40620/41490
TC-TD LTE-PCT-01018 [Mandatory]Inter-frequency cell reselection according to cell reselection priority provided by SIBs	6.1.2.15	40620/41490/39750
TC-TD LTE-PCT-01019 [Mandatory]Cell reselection for Squal to check against SintraSearchQ and SnonIntraSearchQ	6.1.2.17	40620/40620/41490
TC-TD LTE-PCT-01020 [Mandatory]Inter-frequency cell reselection based on common priority information with parameters ThreshX, HighQ, ThreshX, LowQ and ThreshServing, LowQ	6.1.2.18	40620/41490
TC-TD LTE-PCT-01021 [Required] PLMN selection / Automatic mode/between FDD and TDD	6.1.1.1a	1575/41490
TC-TD LTE-PCT-01022 [Required] Cell reselection of ePLMN in manual mode/between FDD and TDD	6.1.1.3a	1575/41490
TC-TD LTE-PCT-01024 [Required] Inter-band cell reselection/between FDD and TDD	6.1.2.16	1575/41490/40620
6.2.3 RRC		
TC-TD LTE-PCT-03031 [Mandatory]RRC connection reconfiguration / Handover / Success / Inter-frequency	8.2.4.6	40620/41490
TC-TD LTE-PCT-03037 [Mandatory]Measurement configuration control and reporting / Intra E-UTRAN measurements / Two simultaneous events A3 (intra and inter-frequency measurements)	8.3.1.3	40620/41490
TC-TD LTE-PCT-03038 [Mandatory]Measurement configuration control and reporting / Intra E-UTRAN measurements / Two simultaneous events A3 (intra and inter-frequency measurements) / RSRQ based measurement	8.3.1.3a	40620/41490
TC-TD LTE-PCT-03039 [Mandatory]Measurement configuration control and reporting / Intra E-UTRAN measurements / Periodic reporting (intra and inter-frequency measurements)	8.3.1.4	40620/41490/39750
TC-TD LTE-PCT-03041 [Mandatory]Measurement configuration control and reporting / Intra E-UTRAN measurements / Two simultaneous events A2 and A3 (inter-frequency measurements)	8.3.1.6	40620/41490
TC-TD LTE-PCT-03045 [Mandatory]Measurement configuration control and reporting / Intra E-UTRAN measurements / Inter-frequency handover / IE measurement configuration not present	8.3.1.10	40620/41490
TC-TD LTE-PCT-03046 [Mandatory]Measurement configuration control and reporting / Intra E-UTRAN measurements / Continuation of the measurements after RRC connection re-establishment	8.3.1.11	40620/41490
TC-TD LTE-PCT-03064 [Required] RRC connection reconfiguration / Handover / Success (with measurement) / Inter-band / Between FDD and TDD	8.2.4.13a	1575/41490
TC-TD LTE-PCT-03065 [Required] RRC connection reconfiguration / Handover / Failure / Re-establishment successful / Inter-band / Between FDD and TDD	8.2.4.14a	1575/41490
TC-TD LTE-PCT-03067 [Required] Measurement configuration control and reporting / Intra E-UTRAN measurements / Two simultaneous events A3 (inter-band measurements) / Between FDD and TDD	8.3.1.12a	1575/41490

About CT B41 LTE Protocol Test

TC-TD LTE-PCT-03069 [Required] Measurement configuration control and reporting / Intra E-UTRAN measurements / Two simultaneous events A2 and A3 (inter-band measurements) / Between FDD and TDD	8.3.1.14a	1575/ 41490
6.2.4 EPS mobility management		
TC-TD LTE-PCT-04013 [Optional] Attach Procedure / Success / Last visited TAI, TAI list and equivalent PLMN list handling	9.2.1.1a	40620/ 39750 / 41490
TC-TD LTE-PCT-04015 [Mandatory] Attach Procedure / Success / List of equivalent PLMNs in the ATTACH ACCEPT message	9.2.1.1.7	40620/ 41490
TC-TD LTE-PCT-04016 [Mandatory] Attach / Rejected / IMSI invalid	9.2.1.1.9	40620/ 41490
TC-TD LTE-PCT-04018 [Mandatory] Attach / Rejected / EPS services and non-EPS services not allowed	9.2.1.1.11	40620/ 41490
TC-TD LTE-PCT-04019 [Mandatory] Attach / Rejected / EPS services not allowed	9.2.1.1.12	40620/ 41490
TC-TD LTE-PCT-04020 [Mandatory] Attach / Rejected / PLMN not allowed	9.2.1.1.13	41490 /40620
TC-TD LTE-PCT-04022 [Mandatory] Attach / Rejected / Roaming not allowed in this tracking area	9.2.1.1.15	39750 / 41490 /40620
TC-TD LTE-PCT-04023 [Mandatory] Attach / Rejected / EPS services not allowed in this PLMN	9.2.1.1.16	41490 /40620
TC-TD LTE-PCT-04024 [Mandatory] Attach / Rejected / No suitable cells in tracking area	9.2.1.1.17	40620/ 41490
TC-TD LTE-PCT-04035 [Mandatory] Combined attach / Rejected / Tracking area not allowed	9.2.1.2.10	40620/40620/ 41490
TC-TD LTE-PCT-04036 [Optional] Combined attach / Rejected / EPS services not allowed in this PLMN	9.2.1.2.12	41490 / 41490 /40620
TC-TD LTE-PCT-04064 [Optional] Combined tracking area update / Rejected / Tracking area not allowed	9.2.3.2.12	40620/ 41490
TC-TD LTE-PCT-04065 [Optional] Combined tracking area update / Rejected / No suitable cells in tracking area	9.2.3.2.15	40620/ 41490

Disable LTE Fast Dormancy for Lab Test

■ Background

- In some commercial LTE network, eNodeB does not release LTE RRC connection within a reasonable amount of time, causing large UE power consumption.
- QC has implement LTE fast dormancy feature to optimize such network issue. But such optimization is not complaint with 3GPP TS36.331.
- As a result, some LTE protocol/RRM/CT SRLTE Throughput test cases failed owing to LTE Fast Dormancy feature is enabled.

■ Log Snippet:

//The fast dormancy timer is started after data transfer

```
08:47:06.286      1967      EVENT_LTE_EMM_OTA_OUTGOING_MSG      Message ID =
ATTACH COMPLETE
08:47:06.290      1610      EVENT_LTE_RRC_UL_MSG      UL Channel Type = UL DCCH,
Message Type = UL Information Transfer
08:47:06.292      lte_mac_qos.c      3125      H      UL activity detected, fast dormancy
timer=29
08:47:06.302      lte_mac_qos.c      3085      H      DL activity detected, fast dormancy
timer=9
```

//Fast dormancy timer expired

```
08:47:16.302      lte_mac_qos.c      3115      E      fast dormancy traffic in activity
timer = 10000 expired
```


Disable LTE Fast Dormancy for Lab Test

//UE release RRC connection locally

08:47:16.303	lte_rrc_ueinfo.c	2328	H	UEINFO : Received UEINFO
trigger with cause 0x40f0402 ctrl st 4				
08:47:16.303	lte_rrc_ueinfo.c	2371	H	UEINFO Trigger received for Fast Dormancy, Ignored
08:47:16.304	lte_rrc_cre.c2177	H		Received
LTE_MAC_RANDOM_ACCESS_PROBLEM_IND (due to FAST_DORMANCY) releasing Conn				
08:47:16.304	lte_rrc_cre.c649	L		CRE: Initiated Connection Release
08:47:16.304	lte_rrc_cre.c2413	H		Fast Dormancy - release connection WO TAU
08:47:16.304	lte_rrc_crp.c2946	H		CRP: Processing Initiate Conn Rel indication

//RLF triggered

08:47:16.304	lte_rrc_crp.c629	L		CRP: Sent Connection Release Started Ind
08:47:16.304	EVENT_LTE_RRC_RADIO_LINK_FAILURE			Counter = 1
08:47:16.304	EVENT_LTE_RRC_RADIO_LINK_FAILURE_STAT			RLF Count since RRC
Connected = 1, RLF Count since LTE Active = 1, RLF Cause = OTHER FAILURE				

- So we need to disable LTE fast dormancy feature during lab test to avoid unexpected radio link failure
- This feature can be disabled by deleting EFS:
/nv/item_files/modem/lte/L2/mac/lte_mac_fast_local_release_timer

LTE Protocol Failures in CT Lab Testing

- Issue Description

- During CT lab testing, FULL RAT mode is enabled before OOS timer expires due to oos_scan_cnt getting incremented. Entering into FULL RAT quickly causes certain tests to fail because they expect a long OOS time.
- Below is the related rule defined in carrier_policy.xml on Bolt 2.6

```
3  <!-- Carrier Policy file for SRLTE+G with GWL+G DSDS roaming for 7+5 mode
4  $Header: //commercial/MPSS.B0.2.6.c1.2/Main/modem_proc/mmcp/policyman/configurations/Carrier/OpenMarket/
5  -->
6  <policy name      = "generic"
7      changelist   = "$Change: 8934492 $"
8      enabled      = "true"
9      schema_ver   = "1"
10     policy_ver    = "74.3.12"
11 >
12
13 Rules to handle OOS situations and timers.
14 =====
15 -->
16 <!-- RULE #2 -->
17 <rule precondition="none">
18   <conditions>
19     <true/>
20   </conditions>
21   <actions>
22     <boolean_set name="full_rat_eval">
23       <any_of>
24         <timer_expired name="noservice" />
25         <all_of>
26           <oos_scan_cnt test=">" value="1" />
27           <not> <have_service /> </not>
28         </all_of>
29       </any_of>
30     </boolean_set>
31     <if>
32       <cond> <timer_expired name="noservice" /> </cond>
33       <then> <expired_timer_handled name="noservice" /> </then>
34     </if>
35     <continue />
36   </actions>
37 </rule>
```

LTE Protocol Failures in CT Lab Testing

- **Affected Cases:**TC-LTE_FDD-PCT-04047(36.523-1 TC9.2.3.1.4), TC-LTE_FDD-PCT-04048(36.523-1 TC9.2.3.1.5)

- **Log Analysis:**

//TS36.523-1 TC9.2.3.1.5 step 16~19:

//serving cell is set to "non-suitable cell" for 8 minutes and back to service, expecting UE send TAU request on cell 1

//The original rat_capability is CHL

21:31:52.757 policyman_rat_capability.c 725 H action <rat_capability> set
Base to 0x0214 for subs 0

21:37:57.676 EVENT_LTE_RRC_DL_MSG DL Channel Type = DL DCCH, Message Type =
RRC Connection Release

21:37:57.766 EVENT_LTE_RRC_NEW_CELL_IND Cause = Selection, Frequency = 1575, Cell ID = 1

//cell 1 becomes non suitable, no service reported by RRC, OOS timer start

21:38:09.969 emm_rrc_handler.c 2839 H DS: SUB 1 =EMM=

RRC_SERVICE_IND - MCC: D1 0, D2 0, D3 0

21:38:09.969 emm_rrc_handler.c 2844 H DS: SUB 1 =EMM=

RRC_SERVICE_IND - MNC: D1 0, D2 0, D3 0

21:38:09.969 emm_rrc_handler.c 2849 H DS: SUB 1 =EMM=

RRC_SERVICE_IND - TAC 0, Cell ID 0, IMS EMC spt 0

21:38:09.969 emm_rrc_handler.c 2853 H DS: SUB 1 =EMM=

RRC_SERVICE_IND - Div Duplex 0, Detach Reqd 0

21:38:09.969 emm_rrc_handler.c 2858 H DS: SUB 1 =EMM=

RRC_SERVICE_IND - CSG Id = 0, Hybrid cell = 0

21:38:09.969 emm_rrc_handler.c 2862 H DS: SUB 1 =EMM=

RRC_SERVICE_IND - ACQ Status = 0

LTE Protocol Failures in CT Lab Testing

21:38:25.188	policyman_serving_system.c	3258	H	condition <have_service>
returns 0				
21:38:25.188	policyman_timer.c	1244	H	executing <timer_start> on timer 1
21:38:25.188	policyman_timer.c	237	H	Starting timer 1 for subs 0 with
duration 1200 secs				

//condition oos_scan_cnt is met, set rat_capability to CHGWTl to get FULL RAT

21:38:27.324	policyman_serving_system.c	2935	H	condition
<oos_scan_cnt> test 3 returns 1				
21:38:27.325	policyman_rat_capability.c	725	H	action <rat_capability>
set Base to 0x0a3c for subs 0				
21:38:27.325	policyman_rf.c	455	H	action <rf_bands> set for subs 0:
21:38:27.325	policyman_rf.c	735	H	GW-32-MSB 0x00020000, GW-32-LSB
0x04e80387				
21:38:27.325	policyman_rf.c	736	H	LTE-32-MSB 0x000001e0, LTE-32-LSB
0x00000045				
21:38:27.325	policyman_rf.c	737	H	TDS-32-MSB 0x00000000, TDS-32-
LSB 0x00000000				

//rat_capability change to CHL

21:45:37.525	policyman_serving_system.c	3258	H	condition <have_service>
returns 1				
21:45:37.525	policyman_timer.c	1292	H	executing <timer_stop> on timer 1
21:45:37.525	policyman_timer.c	254	H	Stopping timer 1 for subs 0
21:45:37.525	policyman_rat_capability.c	725	H	action <rat_capability>
set Base to 0x0214 for subs 0				

LTE Protocol Failures in CT Lab Testing

//local detach triggered

```
21:45:37.529      policyman_rat_capability.c      446      H      get_rat_capability returned
0x0214
21:45:37.531      cmph.c      17667      H      =CM= PS detach: Mode pref change detected. SIM
state: 1
21:45:37.531      cmph.c      17695      H      =CM= Marking PS detach required as TRUE
```

//As a result, UE triggers Attach request, other than TAU request on cell 1

```
21:45:37.830      EVENT_LTE_RRC_NEW_CELL_IND Cause = Selection, Frequency = 1575, Cell ID = 1
21:45:37.904      EVENT_LTE_EMM_OTA_OUTGOING_MSG      Message ID = ATTACH REQUEST
```

■ Solution:

- Workaround: Remove oos_scan_cnt from XML or replace with a very large number , i.e., 10,000 when requiring a long OOS time.
- Official fix: CR917412 for this issue.
- Additional: Please make sure the OOS timer is long enough to pass those GCF cases, as defined below in carrier_policy.xml:

```
<!-- Define the OOS timer with a 20 minute interval -->
```

```
<define_timer name = "noservice" interval = "20" units = "min" id = "1" />
```

Configuration Summary for MFBI cases

- Multiple Frequency Band Indicator (MFBI) related cases:
 - 3GPP 36.523-1 6.1.2.19 (intra-frequency case)
 - 6.1.2.20 (inter-frequency case)
 - 6.1.2.21 (inter-band case)
 - TS36.523-1 6.2.3.34/6.2.3.35 (inter-RAT cases, not required currently)
- Related PICS/PIXIT:
 - px_MFBI_FrequencyBand: An Overlapping EUTRAN Band under test
 - px_OverlappingNotSupportedFrequencyBand_MFBI: An overlapping not supported frequency band MFBI under test
 - px_MFBI_BandChannelBandwidth: bandwidth
 - pc_eBandx_Supp, the EUTRAN band supported by UE, “x” refers to any band number
- Related UE setting:
 - FGI31: should be enabled for MFBI test cases
 - NV6828: should inline with the overlap band under test

Configuration Summary for GCF/PTCRB MFBI cases

- EUTRAN overlap band table:

px_OverlappingNotSupportedFrequencyBand_MFBI	px_MFBI_FrequencyBand
2	25
3	9
4	10
5	18, 19, 26
9	3
10	4
12	17
17	12
18	5, 26, 27
19	5, 26
25	2
26	5, 18, 19, 27
27	18, 26
33	39
38	41
39	33
41	38

- Configuration example:


- If test TC6.1.2.20(Eband4), should set:
 - px_MFBI_FrequencyBand=4; px_OverlappingNotSupportedFrequencyBand_MFBI=10; pc_eband4_supp=TRUE; pc_eband10_sup=FLASE(refer to the above table);
 - In UE side, should disable EUTRAN band10 via NV6828.
- If test TC6.1.2.21(Eband12-Eband17), should set:
 - px_MFBI_FrequencyBand=12; px_OverlappingNotSupportedFrequencyBand_MFBI=17; pc_eband12_supp=TRUE; pc_eband17_sup=FLASE;
 - In UE side, should disable EUTRAN band17 via NV6828.

CTA Lab测试中CDMA 注网问题排查方法

- 若CDMA/EVDO送测手机不能正常注网，请关注以下几点：
 - 选择正确的网络模式：修改NV10为19 (CDMA And HDR only)。写入后重启手机，开机后读取NV10的值，检查是否修改生效。也可以通过手机UI里面的设置->移动网络->网络模式来设置。还有一种方式 通过Android手机工程指令 `*##4636##`，在网络模式里选择CDMA/HDR 模式。
 - 在UI 上关闭移动数据和数据漫游，避免手机重复发送origination Message 干扰手机驻网信息发送。
 - 若DO session 不能建立，确认NV562为1（允许混合模式）。设置ehrpdp 类型 NV4964=4。
 - 若DO session 不能建立，UATI 没有分配，可以设置HDR SCP session为 Inactive（NV475=0）。
 - 确认手机的SID、NID 接入频点，band 设置与实验室测试系统一致；若不一致，会导致驻网不成功。
 - 测试应在屏蔽环境下进行，以避免实际网络的干扰。如果没有屏蔽环境，可以通过修改NV255，把外网SID、NID 写入，屏蔽实网干扰。

CTA测试中CDMA 注网问题排查方法

- 如果用NV only模式实现手机注网，则方法如下：
 - 在QXDM的command窗口输入spc，并修改NV855为1。
 - 在QPST configuration中选则Service Programming，选择Roam→Browse... 导入prl 文件，点击Write to Phone写入需要加载的prl。



CTA测试中CDMA 注网问题排查方法

- 在导入prl 文件的同时，请确认SID、NID、Band、channel与测试仪表设置保持一致。

QPST Roaming List Editor - [chuizi]

File View Window Help

Properties

Roaming List Type: IS-683C Default Roaming Indicator: 0

Preferred Only: ☒ Preferred Roaming List ID: 61010

Index	Acquisition Type	Band 1	Channel 1	Band 2	Channel 2	Band 3	Channel 3	Band 4	Channel 4	Band 5	Channel 5	Band 6
0	CDMA Generic	:800-MHz-Cellular	384	:800-MHz-Cellular	777	1:1900-MHz-PCS	500	1:1900-MHz-PCS	125			
1	HDR Generic	:800-MHz-Cellular	125	:800-MHz-Cellular	260							

System Records

Index	System Type	Neg/Pref	Geography	Priority	Acq Index	Roam Indicator	Assn Incl	Assn Tag	PN Assn	Data Assn	SID	NID		
0	95(A,B)/1x	Pref	New	Same	0	0	Yes	0	No	No	331	1		
1	95(A,B)/1x	Pref	New	Same	0	0	Yes	0	No	Yes	2	2		
2	IS-956	Pref	Same	Same	1	0	Yes	0	No	No	/0			

CMCC APSS测试中的常见问题

- USB debug和连接问题：中国移动要求，第一次开机没有SIM卡插入时，USB的debug功能不能开启，不能与PC端传输文件；非第一次开机无SIM卡，要有提示给用户。
- 手机外壳4G标识问题，很多客户手机在外壳没有4G标识。
- 各卡槽标识问题，很多客户手机各个卡槽没有明确的标识。
- 版本问题，注意手机实际版本要与移动存档的版本一致。
- 预装APK问题，注意要预装移动要求的APK，版本要与移动要求一致。
- 状态栏中网络模式的显示问题，包括刚开机注册时，通话时的模式切换显示等。
- 计算器，浏览器输入长度限制问题，应该有最大输入限制并在达到限制是给提示。
- 锁屏界面在各种情况下紧急呼叫的显示问题，什么时候应该显示，什么时候不应该显示需要正确。
- 备份与恢复的问题，名称是否与移动一致，是否放置在桌面上，备份时有没有各种提示等，比如SD卡提示，换机提示。
- 数据在卡1，卡2中切换功能问题。

CMCC APSS测试中的常见问题

- 手机IMEI号显示问题，双卡手机要么显示一个IMEI号，要么显示两个相同的IMEI号，请注意不要显示两个不同的IMEI号。
- 数据网络和WLAN在各种情况下的切换提示问题，很多产品没有提示。
- 桌面时钟与屏幕右上角时钟显示不一致问题，能不能自动更新时间等。
- 终端字体设置为超大时的显示问题，桌面图标是否显示正常，各个APP是否能正常打开。
- 省电模式问题，手机要支持省电模式。

关于CMCC VoLTE样机送测

- 若仅做变更测试（仅升级VoLTE功能）：
 - 对于lab 测试仅仅需要提交三台样机：一台标注为VoLTE MOS音频；两台标注为开口类型4（1台用于VoLTE 协议测试，另一台用于测试VoLTE NS-IOT）。
 - 目前中移动允许切换MBN，但建议对于开口类型4的样机在射频口附近进行标识：加载MBN Lab_Conf_Volte的样机标注为VoLTE PCT；加载MBN Lab_Nsiot_Volte的样机标注为VoLTE NS-IOT。
- VoLTE A库测试样机送测：
 - 正常天线开口类型样机13台，编号为62~74，具体如下：
 - 天线开口类型1：5台，激活MBN Comb_Attach_TGL；
 - 天线开口类型2：2台，激活Commercial MBN；
 - 天线开口类型3：1台，激活MBN EPS_ONLY；
 - 天线开口类型4：3台，激活MBN Comb_Attach_TGL；
 - 天线开口类型5：2台，激活MBN Comb_Attach_TGL。
 - VoLTE样机：3台（两台开口类型4和一台VoLTE MOS音频）：
 - 样机编号#93：天线开口类型4，激活MBN Lab_Conf_Volte；
 - 样机编号#94：天线开口类型4，激活MBN Lab_Nsiot_Volte；
 - 样机编号#99：天线开口类型1，VoLTE MOS音频，激活MBN Commercial_Volte。

References

Documents	
Qualcomm Technologies, Inc.	
<i>Title</i>	DCN
<i>Local Release of LTE RRC Connection Application Note</i>	80-NU143-1
<i>CMCC Device Configuration and Testing Information</i>	80-NP425-3

Questions?

<https://support.cdmatech.com>

