

高通RF技术期刊2016-03-31



Qualcomm Technologies, Inc.

Confidential and Proprietary – Qualcomm Technologies, Inc.

机密和专有信息——高通技术股份有限公司



Confidential and Proprietary – Qualcomm Technologies, Inc.

Confidential and Proprietary – Qualcomm Technologies, Inc.

NO PUBLIC DISCLOSURE PERMITTED: Please report postings of this document on public servers or web sites to: DocCtrlAgent@qualcomm.com. **禁止公开：**如在公共服务器或网站上发现本文档，请报告至：DocCtrlAgent@qualcomm.com.

Restricted Distribution: Not to be distributed to anyone who is not an employee of either Qualcomm or its affiliated without the express approval of Qualcomm's Configuration Management. **限制分发：**未经高通配置管理部门的明示批准，不得发布给任何非高通或高通附属及关联公司员工的人。 Not to be used, copied, reproduced, or modified in whole or in part, nor its contents revealed in any manner to others without the express written permission of Qualcomm Technologies, Inc. 未经高通技术股份有限公司明示的书面允许，不得使用、复印、复制、或修改全部或部分文档，不得以任何形式向他人透露其内容。

The user of this documentation acknowledges and agrees that any Chinese text and/or translation herein shall be for reference purposes only and that in the event of any conflict between the English text and/or version and the Chinese text and/or version, the English text and/or version shall be controlling. 本文档的用户知悉并同意中文文本和/或翻译仅供参考之目的，如英文文本和/或版本和中文文本和/或版本之间存在冲突，以英文文本和/或版本为准。

This document contains confidential and proprietary information and must be shredded when discarded. 未经高通明示的书面允许，不得使用、复印、复制全部或部分文档，不得以任何形式向他人透露其内容。本文档含有高通机密和专有信息，丢弃时必须粉碎销毁。

Qualcomm reserves the right to make changes to the product(s) or information contained herein without notice. No liability is assumed for any damages arising directly or indirectly by their use or application. The information provided in this document is provided on an "as is" basis. 高通保留未经通知即修改本档中提及的产品或信息的权利。本公司对使用或应用本文档所产生的直接或间接损失概不负责。本文档中的信息为基于现状所提供，使用风险由用户自行承担。

Qualcomm is a trademark of QUALCOMM Incorporated, registered in the United States and other countries. All QUALCOMM Incorporated trademarks are used with permission. Other product and brand names may be trademarks or registered trademarks of their respective owners. Qualcomm是高通公司在美国及其它国家注册的商标。所有高通公司的商标皆获得使用许可。其它产品和品牌名称可能为其各自所有者的商标或注册商标。

This technical data may be subject to U.S. and international export, re-export, or transfer ("export") laws. Diversion contrary to U.S. and international law is strictly prohibited. 本文档及所含技术资料可能受美国和国际出口、再出口或转移出口法律的 限制。严禁违反或偏离美国和国际的相关法律。

Qualcomm Technologies, Inc. 5775 Morehouse Drive San Diego, CA 92121 U.S.A.
高通技术股份有限公司，美国加利福尼亚州圣地亚哥市莫豪斯路 5775 号，邮编 92121

Revision History

| Revision | Date | Description |
|----------|----------|-----------------|
| A | Mar 2016 | Initial release |


Note: There is no Rev. I, O, Q, S, X, or Z per Mil. standards.

Contents

- RF HW
- RF SW

1. TDD LTE Power Control -- Relative Power Tolerance Issue
2. How to power VBATT of PA with QFE3100
3. RF5425 Current Leakage issue
4. QPA miscellaneous calibration failure issue

RF HW



RF HW case filing

- There will be some change on RF HW problem area on early April time frame. Below is new table:
- 射频HW case的Problem Area在2016年4月份会有所改变，如下表所示：


| PA1 | PA2 | PA3 |
|-------------|-------------|-----------------------------|
| RF Hardware | Transceiver | GSM |
| | | CDMA |
| | | WCDMA |
| | | TDS |
| | | LTE |
| | | Coexistence |
| | | Cal/NV |
| | | other |
| | RFFE | QPA/Switch/PAMID |
| | | Antenna Tuner |
| | | QLN/DRX modules |
| | | ET/APT |
| | | Char/Cal/NV |
| | | Other |
| | Antenna/EMC | EMC/Radiated <u>Desense</u> |
| | | SAR |
| | | TIS/TRP |
| | | other |

TDD LTE Power Control -- Relative Power Tolerance Issue

- **Platform:** All with MIPI RFFE
- **适用平台：** All with MIPI RFFE
- **Symptom:** UE failed to pass TDD LTE B38/40/41 power control relative power tolerance (3GPP 36.521-1, 6.3.5.2) test case. UE TX power didn't increase monotonously with 1dB step during ramp up test.
- **问题描述：** 手机在TDD LTE B38/40/41 功率控制-相对功率控制容限(TS 36.521, 6.3.5.2)测试失败。在Ramp Up测试中，手机发射功率并不是步进1dB单调上升。
- **Analysis:** By using the spectrum analyzer, we can see the TX power in sub-frame 2 and 7 is much larger than sub-frame 3 and 8 (see result in next slide). But according to 3GPP, the TX power in sub-frame 3 and 8 should be 1dB larger than sub-frame 2 and 7.
- **问题分析：** 通过频谱仪可以看出，手机在第2和第7子帧的功率远大于第3和第8子帧（测试结果详见下一页）。但是根据3GPP规范，手机在第3和第8子帧里的功率应该是比第2和第7子帧分别增加1dB。


TDD LTE Power Control -- Relative Power Tolerance Issue

- We use B41 as an example. B41 failure spectrum.
- 我们用B41做为例子。下图是B41测试失败时截取的频谱。



TDD LTE Power Control -- Relative Power Tolerance Issue

- B39 pass spectrum.
- B39测试通过时的频谱。



TDD LTE Power Control -- Relative Power Tolerance Issue

- TQF6297H MIPI register setting.
- TQF6297H MIPI寄存器设置。

Recommended MIPI Register Settings

| Mode of Operation | Pin Routing | Register 0 | Register 1 |
|------------------------|-------------|------------|----------------|
| Sleep | N/A | 0x00 | X = Don't care |
| Band 41N TX HPM | 9 | 0x1C | 0xBF |
| Band 41N TX LPM | 9 | 0x1E | 0X9D |
| Band 41N TX LPM (0dBm) | 9 | 0x1E | 0x53 |
| Band 38 RX | 10 to 6 | 0x30 | X = Don't care |
| Band 40 RX | 12 to 7 | 0x28 | X = Don't care |
| Band 41N RX | 9 to 6 | 0x38 | X = Don't care |

- In B41 Tx RF driver code, ASM TQF6297H is configured with port 4. Port 4 will set Register 0 to 0x1C which is high gain of LTE B41:
- 在B41的Tx RF驱动代码部分,配置了TQF6297H开关并使用了port4. 在TQF6297H开关的驱动代码中,port4会将Register0配置为0x1C,这对应于B41的高增益状态。

```
{
  RFDEVICE_ASM,
  GEN_ASM /* ASM_SP6T */, /* NAME TQF6297H */
  2, /* DEVICE_MODULE_TYPE_INSTANCE */
  0 /*Warning: Not specified*/, /* PHY_PATH_NUM */
  {
    0 /* Orig setting: */, /* INTF_REV */
    (0x0286 << 22)/*mfg_id*/ | (0x1C << 14)/*prd_id*/ | (4)/*port_num*/, /* PORT_NUM */
    0, /* Array Filler */
    0, /* Array Filler */
    0, /* Array Filler */
    0, /* Array Filler */
  },
},
```

TDD LTE Power Control -- Relative Power Tolerance Issue

- Port 4 in ASM TQF6297H driver code:
- Port 4 在TQF6297H开关驱动中的设置：

```
static uint8 rfdevice_asm_tqf6297_asm_on_regs[RFDEVICE_ASM_TQF6297_ASM_ON_NUM_REGS] = {0x00, };
static int16 rfdevice_asm_tqf6297_asm_on_data[RFDEVICE_ASM_TQF6297_NUM_PORTS][RFDEVICE_ASM_TQF6297_ASM_ON_NUM_REGS] =
{
    { /* PORT NUM: 0 */ /* B41 Rx*/
        0x38,
    },
    { /* PORT NUM: 1 */ /* B40 Rx*/
        0x28,
    },
    { /* PORT NUM: 2 */ /* B38 Rx*/
        0x30,
    },
    { /* PORT NUM: 3 */ /* B7 Tx*/
        0x24,
    },
    { /* PORT NUM: 4 */ /* B41 Tx*/
        0x1C,
    },
}
```

- So For each Tx slot, if ASM code set register 0 to 0x1C later than PA code setting of register0, then the PA will switch to high gain mode and lead to this issue.
- 因此，在每个Tx时隙，如果ASM配置代码将Reg0设置为0x1C的动作发生在PA设置Reg0的动作后面，那么PA将切换到高增益状态并产生这种问题。



TDD LTE Power Control -- Relative Power Tolerance Issue

- **Root Cause:** TQF6297H is used in customer design. This HCPA integrate HB PA and switch and B40 filter and B41 narrow band filter inside. From it's datasheet, Tx band is using Register 0 to control and Rx band is using Register 0 to control as well. Customer configure TQF6297 PA and TQF6297 ASM in Tx RF driver which lead to ASM setting of Register 0 will overwrite PA setting of Register 0 and cause PA range jumping. The result is wrong PA range during sub-frame 2 and 7 For TDD band. There is no need to configure TQF6297 ASM in Tx RF driver part.
-
- **问题原因:** 客户使用了TQF6297H这颗PA. 这颗PA内部集成了高频PA,开关以及B40和B41窄带的滤波器。从它的datasheet看, Tx和Rx都使用到了Reg0来控制。客户驱动中在TDD频段的Tx驱动代码里面对PA和ASM模组都进行了配置。而ASM和PA共用了Reg0。对ASM进行配置会把PA range的配置信息覆盖而进入高增益状态, 从而导致了手机在第2和第7子帧的发射功率大于第3和第8子帧。实际上B38/40/41的Tx驱动部分并不需要配置ASM。
-
- **Solution:** Remove the ASM part configure for TDD band's Tx driver code in RFC.
-
- **解决办法:** 删除TDD频段Tx驱动部分关于ASM的配置代码。

How to power VBATT of PA with QFE3100

- **Platform:** All+QFE3100
- **适用平台：** All+QFE3100
- **Description:** Normally, VBATT pin is used to power APT/ET PA bias, when QFE1100/1101 powers ET PA, VBATT is also powered from QFE1100 PA_VBAT. For some TDD HB PA Modules, for example, sky77807, internal switch is also powered by VBATT. If using PA_VBAT of QFE1100 to power VBATT of PA, PA_VBAT will be pulled down at standby/sleep mode, that cause TDD RX path to be switched off. So such PA is not recommended to be powered from PA_VBAT of QFE1100. But for QFE3100, how to power VBATT pin of PA?
- **问题描述：** APT和ET PA的偏置电路供电一般是VBATT pin，在用QFE1100/1101给PA供电时，VBATT pin用QFE1100/1101的PA_VBAT输出来供。但对于有些TDD HB PA Module，比如SKY77807，内部TX/RX Switch也是用该pin脚供电。那么如果用QFE1100的PA_VBAT供电，且手机处于standby/sleep模式的时候，QFE1100的PA_VBAT电压是被拉低的，就会导致TDD的RX通路断开而工作不正常，因而对于这种PA不建议用QFE1100/1101的PA_VBAT供电。那用QFE3100如何给PA的VBATT供电呢？

How to power VBATT of PA with QFE3100



How to power VBATT of PA with QFE3100

- **Reply:** (1)For QFE3100, PA_VBATT can be always on even in standby/sleep mode. It's different to QFE1100. (2)For APT only PA, VBATT pin can be powered with both VPH_PWR and PA_VBAT of QFE3100. (3)For ET PA , if phone works within 3.0V-4.5V and will shutdown below 3.0V, VBATT pin of PA can be powered from VPH_PWR; if phone still can work below 3.0V, VBATT pin of PA is required to be powered from PA_VBAT of QFE3100 , not VPH_PWR, because QFE3100 can make sure VBATT to stay within 3.0V-4.5V and work normally.
- **问题回复：**（ 1 ）QFE3100不同于QFE1100/1101，它的PA_VBATT输出可以一直是高电压，甚至在standby/sleep 模式也可以是常高。（ 2 ）对于APT only的PA，VBATT pin既可以用VPH_PWR供电，也可以用QFE3100的PA_VBAT供电。（ 3 ）对于ET PA，如果手机电池电压工作在3.0V-4.5V，3.0V以下手机会自动关机，那么VBATT除了可以用QFE3100的PA_VBAT供电，也可以接VPH_PWR供电。如果3.0V以下手机仍然可以工作，给ET PA仍然需要用QFE3100的PA_VBAT供电，不建议用VPH_PWR供电，因为QFE3100可以确保VBATT上的电压处于3.0v-4.5v，以保证ET在低电池电压下仍可以正常工作。

RF5425 Current Leakage issue

- **Platform:** All
- **适用平台：** All
- **Description:** Under sleep mode, RF5425 has 0.3mA current leakage with VBAT and VIO supplied.
- **问题描述：** 在睡眠模式下，如果VBAT和VDD_IO都存在，则RF5425会有0.3mA的漏电流。
- **Analysis:** We identify the current leakage issue to the Low Band section of the 5425, and then further lock the issue down to the Register 0 BS bit in the Low Band RFFE. If the bit is set to 1 (default) with VIO applied, Ibat current is ~380uA (@Vbat=3.7V). If the bit is set to 0 with VIO applied, Ibat current is ~4.3uA. The BS bit is only used in the 5427 part, and is used to switch between LB and VLB. The default at power up for BS is 1, so it would have to be explicitly set to 0 to eliminate the current leakage issue.
- **问题分析:** 我们发现漏电流的问题来自5425的低频部分，进一步定位到RFFE寄存器0的BS比特位。当VDD_IO有1.8V供电且该比特位被设置为1（5425PA的缺省值），则Ibat上的电流为380微安。如果该比特位被设置为0且VDD_IO有1.8V供电，则Ibat上的电流为4.3微安。该比特位仅在5427上用来切换低频和更低频波段。在开机上电后该比特位为1，因此需要将它再初始化一次设置为0来消除漏电问题。

RF5425 Current Leakage issue

- **Solution:** Apply for CR986194 & CR987444.
- **解决办法：**申请CR986194和CR987444。

| | | |
|------------------------|-------------|---|
| 986194 | RFA_DEVICES | Current Consumption in RF5425 is higher than expected, need init PA to OFF after UE bootup |
| 987444 | RFA_DEVICES | [3rd party PA init addition for RF5425][rfdevice_pa][JO]3rd party PA init addition for RF5425 |

QPA miscellaneous calibration failure issue

- 1 - Tx XPT Swp2 - M Line RGI Compression fail**
- 2 - Tx XPT Swp3 – XPT Swp3 power fail**
- 3- Tx XPT Swp3 – Delta measure power fail**
- 4 - DPD Valid FFlag for Requested Power 1700 is FALSE**
- 5 - Max power cal fail**
- 6 - RGI out of range**

1 - Tx XPT Swp2 - M Line RGI Compression fail

Description : This issue is found in lab . Cannot get compression point, the fail rate is about 20%

描述 : 这个问题在实验室发现。获取压缩点失败，不良率大约20%

MEASUREMENTS: Tx XPT Swp2 - M Line RGI Compression

| Channel | XPT Mode | TxAGC | Vcc (mV) | Compression (dB) | Compression Min | Time (s) |
|---------|----------|-------|----------|------------------|-----------------|----------|
| 24374 | 1 | 66 | 1500 | 4.2934 | 2.5 | |
| 24374 | 1 | 67 | 2200 | 4.43697 | 2.5 | |
| 24374 | 1 | 69 | 3000 | -8.1308 | 2.5 | |
| 24374 | 1 | 71 | 3500 | 3.8764 | 2.5 | |

Root cause : Swp1 IQ capture segment length is too short

原因 : 第一个sweep的IQ capture时间太短

1 - Tx XPT Swp2 - M Line RGI Compression fail

Solution : Increase the sweep1 Cap segment length

解决方案 : 增大第一个sweep的IQ capture时间 :

<XPT_Swp1_Cap_Segment_Length>4000</XPT_Swp1_Cap_Segment_Length>
to :

<XPT_Swp1_Cap_Segment_Length>8000</XPT_Swp1_Cap_Segment_Length>

```
<XPT_Swp1_IQ_Gain>420</XPT_Swp1_IQ_Gain>  
<XPT_Swp1_Env_Scale>820</XPT_Swp1_Env_Scale>  
<XPT_Swp1_Num_IQ_Samples>9216</XPT_Swp1_Num_IQ_Samples>  
<XPT_Swp1_Cap_Segment_Length>4000</XPT_Swp1_Cap_Segment_Length>  
<XPT_Swp1_RGI_Delta_RGI_List>60,61,62,63,64,65,66,67,68,69,70,71,72,73</XPT_Swp1_RGI_Delta_RGI_List>  
<XPT_Swp1_RGI_Delta_Bias>3500</XPT_Swp1_RGI_Delta_Bias>  
<XPT_Swp1_Minimum_RGI_Delta_Power_dBm100>-100</XPT_Swp1_Minimum_RGI_Delta_Power_dBm100>
```

2 - Tx XPT Swp3 – XPT Swp3 power fail

Description : This issue is found in lab .Cannot get XPT swp3 power, the fail rate is about 20%

描述 : 这个问题在实验室发现。XPT Sweep3 功率测试失败，不良率大约20%

MEASUREMENTS: Tx XPT Swp3 - Linearizer

| Channel | XPT Mode | PA State | TxAGC | Vcc | Exp Power | XPT Swp3 Power | XPT Swp3 Power Min | XPT Swp3 Power Max | Delta Expected Power | Delta Measure Power |
|---------|----------|----------|-------|------|-----------|----------------|--------------------|--------------------|----------------------|---------------------|
| 24374 | 1 | 3 | 64 | 1666 | 17 | 17.3 | 9 | 25 | 0 | 0 |
| 24374 | 1 | 3 | 67 | 2364 | 20 | -21.9 | 12 | 28 | 3 | -39.2 |
| 24374 | 1 | 3 | 68 | 2714 | 22 | 22.9 | 14 | 30 | 2 | 44.8 |
| 24374 | 1 | 3 | 69 | 3070 | 24 | 24 | 16 | 32 | 2 | 1.1 |

Root cause : Swp2 IQ capture segment length is too short

原因 : 第二个sweep的IQ capture时间太短

2 - Tx XPT Swp3 – XPT Swp3 power fail

Solution : Increase the sweep2 Cap segment length:

解决方案 : 增大第二个sweep的IQ capture时间 :

<XPT_Swp2_Cap_Segment_Length>4000</XPT_Swp2_Cap_Segment_Length>
to :

<XPT_Swp2_Cap_Segment_Length>8000</XPT_Swp2_Cap_Segment_Length>

```
<XPT_Swp2_Channel_List>24374</XPT_Swp2_Channel_List>  
<XPT_Swp2_EPT_PA_State>3</XPT_Swp2_EPT_PA_State>  
<EPT_Swp2_Meas_Pwr_List>17,20,22,24</EPT_Swp2_Meas_Pwr_List>  
<XPT_Swp2_Num_IQ_Samples>9216</XPT_Swp2_Num_IQ_Samples>  
<XPT_Swp2_Cap_Segment_Length>4000</XPT_Swp2_Cap_Segment_Length>  
<XPT_Swp2_MLine_Calc_Segment_Length>30000</XPT_Swp2_MLine_Calc_Segment_Length>  
<XPT_Swp2_IQ_Processing_Segment_Length>30000</XPT_Swp2_IQ_Processing_Segment_Length>
```


3 - Tx XPT Swp3 – Delta measure power fail

Description : EPT swp3 delta measure power fail

描述 : EPT sweep3 delta功率测试失败

MEASUREMENTS: Tx XPT Swp3 - Linearizer

| Channel | XPT Mode | PA State | TxAGC | Vcc | Exp Power | XPT Swp3 Power | XPT Swp3 Power Min | XPT Swp3 Power Max | Delta Expected Power | Delta Measure Power |
|---------|----------|----------|-------|------|-----------|----------------|--------------------|--------------------|----------------------|---------------------|
| 9848 | 1 | 3 | 69 | 2155 | 17 | 18.1 | 12 | 22 | 0 | 0 |
| 9848 | 1 | 3 | 70 | 2617 | 19 | 20.4 | 14 | 24 | 2 | 2.3 |
| 9848 | 1 | 3 | 70 | 2617 | 20 | 20.3 | 15 | 25 | 1 | -0.1 |
| 9848 | 1 | 3 | 72 | 3500 | 23 | 23.8 | 18 | 28 | 3 | 3.5 |

Root cause : The EPT power list setting wrong, the 4 power list gap is too narrow.

原因: EPT power list 设置不对导致 , 4个功率值的间隔太小

3 - Tx XPT Swp3 – Delta measure power fail

Solution : Keep the power at least 2db gap for EPT_Swp_Meas_Pwr_List.

解决方案： EPT power list里面的4个功率点间隔至少2db，增大功率点间隔

Modify the power list from

```
<EPT_Swp2/3_Meas_Pwr_List>17,19,20,23</EPT_Swp2/3_Meas_Pwr_List>  
<EPT_Fcomp_Meas_Pwr_List>17,19,20,23</EPT_Fcomp_Meas_Pwr_List> To  
<EPT_Swp2/3_Meas_Pwr_List>15,18,20,23</EPT_Swp2/3_Meas_Pwr_List>  
<EPT_Fcomp_Meas_Pwr_List>15,18,20,23</EPT_Fcomp_Meas_Pwr_List>
```

Pass log – after modify the power list

MEASUREMENTS: Tx XPT Swp3 - Linearizer

| Channel | XPT Mode | PA State | TxAGC | Vcc | Exp Power | XPT Swp3 Power | XPT Swp3 Power Min | XPT Swp3 Power Max | Delta Expected Power | Delta Measure Power |
|---------|----------|----------|-------|------|-----------|----------------|--------------------|--------------------|----------------------|---------------------|
| 9848 | 1 | 3 | 68 | 1820 | 15 | 16.1 | 10 | 20 | 0 | 0 |
| 9848 | 1 | 3 | 69 | 2163 | 18 | 18.2 | 13 | 23 | 3 | 2.1 |
| 9848 | 1 | 3 | 70 | 2678 | 20 | 20.6 | 15 | 25 | 2 | 2.4 |
| 9848 | 1 | 3 | 72 | 3500 | 23 | 23.8 | 18 | 28 | 3 | 3.2 |

4 - DPD Valid FFlag for Requested Power 1700 is FALSE -page1

Description: DPD Construction fail, compare good board with failure board, get different calibration log. Normally the Swp2 M Line table Tx AGC is same as delta RGI sweep list.

描述：DPD创建失败，对比好的板子和fail的板子log，正常的板子Sweep2的M Line table中的Tx AGC 和Delta RGI sweep中的一致：

Fail log:

Pass log

MEASUREMENTS: Tx XPT Swp2 - M Line table

| Channel | XPT Mode | TxAGC | Vcc (mV) | Pout (dBm) | Time (s) |
|---------|----------|-------|----------|------------|----------|
| 24374 | 1 | 51 | 1061 | 5.66 | |
| 24374 | 1 | 52 | 1180 | 8.48 | |
| 24374 | 1 | 53 | 1383 | 11.84 | |
| 24374 | 1 | 54 | 1515 | 13.49 | |
| 24374 | 1 | 55 | 1823 | 16.43 | |
| 24374 | 1 | 56 | 2045 | 18.06 | |
| 24374 | 1 | 57 | 2156 | 18.78 | |
| 24374 | 1 | 58 | 2449 | 20.42 | |
| 24374 | 1 | 59 | 3172 | 23.5 | |
| 24374 | 1 | 60 | 3862 | 25.68 | |
| 24374 | 1 | 61 | 4312 | 26.85 | |
| 24374 | 1 | 62 | 5148 | 28.68 | |
| 24374 | 1 | 63 | 5323 | 29.02 | |
| 24374 | 1 | 64 | 7039 | 31.79 | |
| 24374 | 1 | 65 | 7039 | 31.79 | |
| 24374 | 1 | 66 | 7039 | 31.79 | |
| 24374 | 1 | 67 | 6960 | 31.68 | |
| 24374 | 1 | 68 | 6960 | 31.68 | |
| 24374 | 1 | 69 | 6960 | 31.68 | |
| 24374 | 1 | 70 | 6883 | 31.57 | |
| 24374 | 1 | 71 | 6883 | 31.57 | |

MEASUREMENTS: Tx XPT Swp2 - M Line table

| Channel | XPT Mode | TxAGC | Vcc (mV) | Pout (dBm) | Time (s) |
|---------|----------|-------|----------|------------|----------|
| 24374 | 1 | 60 | 1243 | 12.71 | |
| 24374 | 1 | 61 | 1319 | 13.67 | |
| 24374 | 1 | 62 | 1443 | 15.05 | |
| 24374 | 1 | 63 | 1552 | 16.1 | |
| 24374 | 1 | 64 | 1687 | 17.25 | |
| 24374 | 1 | 65 | 1826 | 18.29 | |
| 24374 | 1 | 66 | 2066 | 19.84 | |
| 24374 | 1 | 67 | 2352 | 21.38 | |
| 24374 | 1 | 68 | 2692 | 22.91 | |
| 24374 | 1 | 69 | 3066 | 24.34 | |
| 24374 | 1 | 70 | 3540 | 25.87 | |
| 24374 | 1 | 71 | 4064 | 27.28 | |
| 24374 | 1 | 72 | 4538 | 28.4 | |
| 24374 | 1 | 73 | 5290 | 29.91 | |

4 - DPD Valid FFlag for Requested Power 1700 is FALSE -page2

Root cause: The swp2 Mline calc segment length and IQ capture segment length are too short .

原因： swp2 Mline 计算时间IQ capture的时间太短导致

Solution :check the swp2 segment length setting: Normal segment length is about 30000.

解决方案：检查swp2的时间设置，正常值设置在30000：

<XPT_Swp2_MLine_Calc_Segment_Length>60000</XPT_Swp2_MLine_Calc_Segment_Length>

<XPT_Swp2_IQ_Processing_Segment_Length>20000</XPT_Swp2_IQ_Processing_Segment_Length>

<Waveform>

```
<XPT_Swp2_Channel_List>24374</XPT_Swp2_Channel_List>
<XPT_Swp2_EPT_PA_State>3</XPT_Swp2_EPT_PA_State>
<EPT_Swp2_Meas_Pwr_List>17,20,22,24</EPT_Swp2_Meas_Pwr_List>
<XPT_Swp2_Num_IQ_Samples>9216</XPT_Swp2_Num_IQ_Samples>
<XPT_Swp2_Cap_Segment_Length>8000</XPT_Swp2_Cap_Segment_Length>
<XPT_Swp2_MLine_Calc_Segment_Length>60000</XPT_Swp2_MLine_Calc_Segment_Length>
<XPT_Swp2_IQ_Processing_Segment_Length>20000</XPT_Swp2_IQ_Processing_Segment_Length>
<XPT_Swp2_MLine_Bias_Option>0</XPT_Swp2_MLine_Bias_Option>
<XPT_Swp2_Enable_Mline_Debug_Info>TRUE</XPT_Swp2_Enable_Mline_Debug_Info>
<Post_Sweep_Computation>1</Post_Sweep_Computation>
<Compute_For_Sweep>2</Compute_For_Sweep>
```

5 - Max power cal fail

Description : EPT/ET max power calibration fail

描述 : EPT/ET 最大功率校准失败

Fail log: M Line Bias for expected power > Vmax and interpolated Bias is also > Vmax

MEASUREMENTS: Tx XPT Swp2 - Max M Line Power

| Channel | XPT Mode | Vcc (mV) | XPT Swp2 Max MLine Power | Time (s) |
|---------|----------|----------|--------------------------|----------|
| 21102 | 1 | 3300 | 24.0412 | |

Root cause/原因:

1. The max target power setting is too higher than measurement power:

1. 最大期望功率设置过高，大于实际测试功率：

<EPT_Swp2/3_Meas_Pwr_List>18,20,22,25</EPT_Swp2_Meas_Pwr_List>

<EPT_Fcomp_Meas_Pwr_List>18,20,22,25</EPT_Fcomp_Meas_Pwr_List>

2. Poor matching : If the measure power is too lower (for example 21dbm) , it maybe the front end loss is too higher or PA output load shift too much.

2. 匹配比较差：如果实测功率过低（比如21dbm），这个种情况可能是前端插损过大或者PA输出load有问题。

5 - Max power cal fail

Solution /解决方法:

1. If the target power setting is too higher and test power is normal, need decrease the target power to cover most boards in input file.
1. 如果期望功率设置过高同时实测功率正常，这种情况需要在input file 中降低一下期望功率来覆盖大部分板子。
2. If it caused by abnormal IL or load shift, need check PA output S parameter from hardware side.
2. 如果是插损或者PA 输出load导致，需要从检查PA输出S参数。

6 - RGI out of range

Description: RGI setting is too higher in RGI sweep list

描述： RGI sweep list中 RGI 设置过高

The Max RGI is 75 on most platform, so the calibration RGI must be lower than 75 (need check with different WTR) .

Higher RGI will cause PA damaged issue and shorten the PA lifetime .

大部分平台最大RGI是75，所以校准的RGI必须小于75（不同的WTR不一样，需要根据平台来设置）

过高的RGI会导致PA损坏或缩短PA工作寿命。

Wrong RGI setting/错误的RGI设置：

6 - RGI out of range


```
<PA_State_List>2,1,0,0</PA_State_List>
<RGI_List>SSS(80,35,-2);SSS(80,35,-2);SSS(63,44,-2);SSS(43,10,-2)</RGI_List>
<Bias_List>3300,3300,1500,1500</Bias_List>
<PA_Quiescent_Current>127,127,127,127</PA_Quiescent_Current>
<IQ_Gain>622,622,622,622</IQ_Gain>
<Env_Scale>1258,1258,1258,1258</Env_Scale>
<HDET_Avgs>1,0,0,0</HDET_Avgs>
<LPM_HDET_Avgs>0,0,0,0</LPM_HDET_Avgs>
<Segment_Length>4000;4000;4000;4000</Segment_Length>
<Config_Segment_Length>60000</Config_Segment_Length>
<Tuning_Segment_Length>20000</Tuning_Segment_Length>
<Enable_Tx_Lin_Limits>TRUE</Enable_Tx_Lin_Limits>
<Min_Start_Pwr>17,7,-5,-30</Min_Start_Pwr>
<Max_Expected_Pwr>33,20,10,-10</Max_Expected_Pwr>
<Lowest_End_Pwr>12,-3,-12,-50</Lowest_End_Pwr>
<Purpose_List>3,3,3,3</Purpose_List>
<Minimum_Delta_Power_dBm100>-100</Minimum_Delta_Power_dBm100>
<XPT_Swp1_Channel_List>23821</XPT_Swp1_Channel_List>
<XPT_Swp1_PA_State>3</XPT_Swp1_PA_State>
<XPT_Swp1_RGI_List>75,76,77,78</XPT_Swp1_RGI_List>
<XPT_Swp1_Bias_List>1500,2300,2800,3500</XPT_Swp1_Bias_List>
```

Solution : set the right RGI refers to different WTR (lower than max RGI) , run the RGI sweep char to choose the right RGI for XPT_Swp1_RGI_List

解决方案 : 根据平台在RGI list设置RGI (低于最大RGI) , Swp1的RGI需要做RGI char 来设置。

1. HDR Open Loop Output Power failure issue
2. LTE B1 Tx Restricted Region Back-off
3. MSM8996 FBRx Char Failure Root Cause Analysis
4. Calibration issue of crash in rfgsm_core_tx.c
5. TDSCDMA NS Tx Max Power Issue

RF SW



HDR Open Loop Output Power failure issue



- **Platform:** MSM8996/MDM9x40
- **适用平台：** MSM8996/MDM9x40
- **Symptom:** HDR test case 4.3.1 Open Loop Output Power fails Test1 (@-25dBm). The measured Tx power is below the lower limit.
- **问题描述：** HDR 测试项4.3.1 开环发射功率 Test1 (@-25dBm)失败。测试仪器测量到的功率低于测试门限下限。

04_03_01

| Ev_A_04_03_01 Range of Open Loop Output | Status: FAIL | | | Channel: 37 | | Duration: 0 sec | |
|---|--------------|-------------|-------------|-------------|-----------|-----------------|--|
| Test Description | Meas. Value | Lower Limit | Upper Limit | Units | Pass/Fail | | |
| Open_Loop RT9.6k Acc Chan Test1 | -63.34 | -57.20 | -38.20 | dBm/B W | FAIL | | |
| Open_Loop RT9.6k Acc Chan Test2 | -5.12 | -17.20 | 1.80 | dBm/B W | PASS | | |
| Open_Loop RT9.6k Acc Chan Test3 | 20.24 | 10.80 | 29.80 | dBm/B W | PASS | | |
| Open_Loop RET1 28-bit Acc Chan Test1 | -63.35 | -57.20 | -38.20 | dBm/B W | FAIL | | |
| Open_Loop RET1 28-bit Acc Chan Test2 | -5.10 | -17.20 | 1.80 | dBm/B W | PASS | | |
| Open_Loop RET1 28-bit Acc Chan Test3 | 20.53 | 10.80 | 29.80 | dBm/B W | PASS | | |

HDR Open Loop Output Power failure issue

- **Analysis:** Use spectrum analyzer to capture probe power, could find spurs before access probe. The first spur is about -62dBm which matches the TE report value. For Test1, the TE lor is -25dBm, the TE trigger level is quite low and thus the false alarm caused by the spur leads to the failure.
- **问题分析：** 通过用频谱分析仪抓取时域上的发射功率信号，可以看到在access probe之前出现较多的毛刺。其中第一个毛刺的功率大约在-62dBm，符合测试仪器的测量值。Test1中，测试仪器的lor设置为-25dBm，因而发射功率的trigger level相对较低，由于毛刺引起虚警从而导致测试失败。



HDR Open Loop Output Power failure issue

- **Analysis:** Meanwhile by comparison that different designs which adopt different PAs have different behavior. Those PAs which have larger gain (e.g. 20dB) at low gain state will fail the case, while those with less gain could pass. The reason is the larger gain PAs will amplify the spurs to a significant level which will trigger the TE as detection of access probe and report the measurement and then lead to failure.
- **问题分析：** 同时通过比较发现采用不同PA的设计方案表现不一。那些在低增益状态下能够提供较大增益（例如 20dB）的PA方案会导致测试失败，而增益较小的PA方案则可以通过测试。原因在于较大增益的PA能够将毛刺放大到足够大，触发测试仪器认为access probe已经开始，从而进行测量和报告，导致测试失败。
- **Solution:** Submit case to RFSW team with test report, spectrum analyzer plot and test log as well as PA spec to confirm the issue and apply CR#982324.
- **解决方案：** 提case到RFSW team，提供测试报告，频谱分析仪截图，测试log和PA器件手册已确认问题，再申请CR#982324。

LTE B1 Tx Restricted Region Back-off

- **Platform:** All
- **适用平台：**所有
- **Problem:** LTE Band 1 can't pass TELEC PHS emissions requirements.
- **问题描述：** LTE Band 1无法通过日本PHS emission测试指标。
- **Standard requirement:** JAPAN requirement conflicts with 3GPP SPEC, where max 1dBm back-off is required for normal NS_05 (RFNV_LTE_B1_AMPR_NS_05_I (NV20138)). While it can't meet JAPAN requirement, a larger back-off value need to be applied for PHS emission. For non-JAPAN market, there is no such need.
- **标准要求：** 日本规范与3GPP规范有冲突，正常的3GPP NS_05 back-off NV (RFNV_LTE_B1_AMPR_NS_05_I (NV20138)) 无法满足日本规范需求，需要一个更大的back-off值来通过JAPAN PHS emission测试。对于非日本市场的UE，则没有这样的需求。

LTE B1 Tx Restricted Region Back-off

Table 6.6.3.3.1-1: Additional requirements (PHS)

| Frequency band (MHz) | Channel bandwidth / Spectrum emission limit (dBm) | | | | Measurement bandwidth |
|---|--|-----------|-----------|-----------|--------------------------|
| | 5 MHz | 10 MHz | 15 MHz | 20 MHz | |
| $1884.5 \leq f \leq 1915.7^{*1}$ | -41 | -41 | -41 | -41 | 300 KHz |
| Note 1: Applicable when the lower edge of the assigned E-UTRA UL channel bandwidth frequency is larger than or equal to the upper edge of PHS band (1915.7 MHz) + 4 MHz + the Channel BW assigned, where Channel BW is as defined in sub-clause 5.4.2. Additional restrictions apply for operations below this point. | | | | | |

- **Solution:** RFNV_LTE_B1_NS_05_RESTRICTED_REGION_BACKOFF (NV26708) is created to enable customers to pass TELEC PHS emissions requirements. This feature allows the UE to take power back-off for UL configurations which are explicitly prohibited by 3GPP. So that UE could take a generous back-off in such cases. The default value is 130, which stands for 13dB. It could be a smaller value (<13dB) if test could still pass.
- **解决方案:** 为了使客户能够通过日本PHS emissions测试，RFNV_LTE_B1_NS_05_RESTRICTED_REGION_BACKOFF (NV26708) 能允许UE将功率回退应用于3GPP规范明确禁止的配置。默认情况下，该NV设置数值是130代表了回退13dB。只要测试能够通过，也可以选择一个稍小的值。

LTE B1 Tx Restricted Region Back-off

- Test verification: For lab test verification with this NV, please follow below RB allocation rule.
- 测试验证: 如果想在实验室里做验证, 请根据下面的RB分配去做。

| BW (MHz) | RB start / Tx freq (Hz) | RB number | Apply backoff |
|----------|--|---------------------------------|---------------|
| 5 | Tx freq < 1927200 | Any | Yes |
| 10 | Tx freq < 1934700 | Any | Yes |
| 15 | Tx freq == 1932500 && rb_start <= 7 | Any | Yes |
| | Tx freq == 1932500 && 8 <= rb_start <= 66 | rb number > MIN(30,67-rb_start) | |
| | Tx freq == 1932500 && 67 <= rb_start <= 74 | Any | |
| | Tx freq < 1942200 | Any | |
| 20 | Tx freq == 1930000 && rb_start <= 23 | Any | Yes |
| | Tx freq == 1930000 && 24 <= rb_start <= 75 | rb number > MIN(24,76-rb_start) | |
| | Tx freq == 1930000 && 76 <= rb_start <= 99 | Any | |
| | Tx freq < 1949700 | Any | |

MSM8996 FBRx Char Failure Root Cause Analysis

- **Platform:** MSM8996/MDM9x45 platform
- **适用平台:** MSM8996/MDM9x45 平台
- **Symptom:**
FBRx char failure of all LTE bands and partial WCDMA bands
- **问题描述 :**
LTE所有band以及WCDMA部分band的FBRx char failure

MSM8996 FBRx Char Failure Root Cause Analysis

- Symptom details
- Issue 1: FB gain too low with LSE over range (FB gain值过低，且LSE 超标)

| FBGain FreqComp | FBGain FreqComp Min | FBGain FreqComp Max | LSE FreqComp | LSE FreqComp Max |
|--------------------|------------------------|------------------------|-----------------|------------------------|
| 4769 | 1000 | 20000 | 174 | 1000 |
| 3372 | 1000 | 20000 | 231 | 1000 |
| 4195 | 1000 | 20000 | 1435 | 1000 |
| 5221 | 1000 | 20000 | 192 | 1000 |
| 3732 | 1000 | 20000 | 188 | 1000 |
| 4656 | 1000 | 20000 | 1128 | 1000 |
| 5832 | 1000 | 20000 | 78 | 1000 |
| 4184 | 1000 | 20000 | 224 | 1000 |
| 5174 | 1000 | 20000 | 966 | 1000 |
| 6573 | 1000 | 20000 | 61 | 1000 |
| 4721 | 1000 | 20000 | 119 | 1000 |

| FBGain FreqComp | FBGain FreqComp Min | FBGain FreqComp Max | LSE FreqComp |
|--------------------|------------------------|------------------------|-----------------|
| 2548 | 1000 | 20000 | 399 |
| 1100 | 1000 | 20000 | 0 |
| 256 | 1000 | 20000 | 16240 |
| 2585 | 1000 | 20000 | 391 |
| 1115 | 1000 | 20000 | 1015 |
| 256 | 1000 | 20000 | 16240 |
| 2585 | 1000 | 20000 | 198 |
| 1055 | 1000 | 20000 | 1130 |
| 256 | 1000 | 20000 | 0 |

- Issue 2: FB gain normal while LSE over range (FB gain值正常，但LSE 超标)

| FBGain FreqComp | FBGain FreqComp Min | FBGain FreqComp Max | LSE FreqComp | LSE FreqComp Max |
|--------------------|------------------------|------------------------|-----------------|------------------------|
| 9568 | 1000 | 20000 | 46 | 1000 |
| 6635 | 1000 | 20000 | 64 | 1000 |
| 8231 | 1000 | 20000 | 105 | 1000 |
| 10742 | 1000 | 20000 | 100 | 1000 |
| 7530 | 1000 | 20000 | 125 | 1000 |
| 9367 | 1000 | 20000 | 163 | 1000 |
| 11095 | 1000 | 20000 | 23 | 1000 |
| 7831 | 1000 | 20000 | 70 | 1000 |
| 9879 | 1000 | 20000 | 58 | 1000 |
| 10463 | 1000 | 20000 | 52 | 1000 |
| 7237 | 1000 | 20000 | 55 | 1000 |
| 9151 | 1000 | 20000 | 85 | 1000 |
| 9869 | 1000 | 20000 | 59 | 1000 |
| 6761 | 1000 | 20000 | 62 | 1000 |
| 8469 | 1000 | 20000 | 158 | 1000 |
| 9239 | 1000 | 20000 | 67 | 1000 |
| 6323 | 1000 | 20000 | 19156 | 1000 |
| 7715 | 1000 | 20000 | 26905 | 1000 |
| 9117 | 1000 | 20000 | 101 | 1000 |
| 6305 | 1000 | 20000 | 21281 | 1000 |
| 7442 | 1000 | 20000 | 27131 | 1000 |

MSM8996 FBRx Char Failure Root Cause Analysis


- **Root cause** (software side):
 1. Miss configuration of 3rd party coupler in RFC.
 2. FB path switch control logic error.
 3. DPD CONFIG NV configuration error (should be QC issue).

- **问题原因** (软件方面):
 1. RFC中没有对第三方coupler进行配置。
 2. FB path中增加了两个开关用于tuner，但是开关逻辑配置错误。
 3. DPD CONFIG NV 配置错误 (高通默认版本中的NV配置的就有问题)

MSM8996 FBRx Char Failure Root Cause Analysis

- **Root cause** (hardware side):

1. Improper coupler selection, which will pull FB 50 ohm to 8 ohm.




- **问题原因** (硬件方面)

1. Coupler选型错误，导致coupler不在50 ohm。

MSM8996 FBRx Char Failure Root Cause Analysis

- **Root cause** (hardware side):

2. RF open-circuit stub on the reverse path termination resistor when forward coupling path is selected (red oval). It could affect fwd coupling factor at higher frequencies.




- **问题原因** (硬件方面)

2. FB path正向工作的时候，红色标记的线路会辐射蓝色部分，影响正向高频信号耦合因子。

MSM8996 FBRx Char Failure Root Cause Analysis

- **Root cause** (hardware side):

3. Potential via-to-via coupling between FBRx path and GRFC control line (yellow arrow). May couple digital noise into FBRX path (fwd and rvs directions).



- **问题原因** (硬件方面)

3. GRFC控制信号的过孔可能会影响FBRx信号。

Calibration issue of crash in rfgsm_core_tx.c


- **Platform:** MSM8996
- **适用平台：** MSM8996
- **Symptom:** crash happens as below during UE calibration.
- **问题描述：** UE在做校准时出现如下死机现象。
 - Coredump
 - =====
 - rfgsm_core_tx.c:666 rfgsm_core_tx_sleep: TX Device 6 Pwr Down (ON->LPM) failed for band 1
 - -000|qurt_exception_raise_nonfatal()
 - -001|err_Fatal_internal3()
 - -002|err_Fatal_internal2()
 - -003|rfgsm_core_tx_sleep()
 - -004|rfgsm_mc_tx_sleep()
 - -005|rfgsm_dispatch_tx_sleep_req()
 - -006|rfgsm_req_dispatch()
 - -007|rfgsm_req_dispatcher()
 - -008|rf_cmd_process()
 - -009|rf_task_1()
 - -010|TASK_ENTRY()
 - -011|rex_os_thread_entry_func()
 - -012|_pthread_stub()
 - -013|qurt_trampoline()
 - ----|end of frame

Calibration issue of crash in rfgsm_core_tx.c

- **Analysis:** From below F3 log, GSM (tech=2) is configuring WTR3925 into power OFF state (VoteOn=0), but WTR3925 has been already in power off state (pwr vote:st=0), this is unexpected.
- **问题分析：**从下面的F3消息可以看出，GSM正在配置WTR3925进入power OFF状态，但是此时WTR3925已经在power off状态了，这是不合预期的状态迁移。
- //F3 message
- 17:28:58.125: wtr3925_common.cpp:8155 pwr SM got enabled: st = 1, last=0 ← wtr3925 enter LPM
- 17:28:58.126: wtr3925_common.cpp:8184 pwr SM got disabled: st = 0, last=1 ← wtr3925 enter pwr OFF
- 17:29:00.275: wtr3925_common.cpp:7262 pwr vote:st=0,VoteOn=0,tech=2,comp=4 ← GSM cfg wtr3925 into pwr off, but it's already in pwr OFF state, unexpected behavior.
- 17:29:00.275: wtr3925_common.cpp:7298 pwr vote: wrong st=0,last_st=1,vote_on=0,tech=2,comp=4
- 17:29:00.275: wtr3925_common.cpp:7322 wtr3925 pwr vote(after): st=0, last=1, return=0

Calibration issue of crash in rfgsm_core_tx.c

- **Solution:** Add RFCal_ReLoadRFNVItems node after PS Off On in Xtt tree
- **解决方案：**在校准tree中PS Off On节点之后添加 RFCal_ReLoadRFNVItems节点



TDSCDMA NS Tx Max Power Issue

- **Platform:** all platform
- **适用平台：**所有平台
- **Symptom:** TDSCDMA max power is not flat and lower than target power for H/M/L channel on some boards when non-signaling test with CMW500
- **问题描述：**有些板子在CMW500上做TDSCDMA非信令测试的时候，高中低信道的最大功率不平坦，并且最大功率偏低。
- **Analysis:** From failure log, we can see that the error b/w HDET and TxAGC are applied to MTPL, but not applied to TxAGC. Thus TxAGC does not increase as MTPL accordingly, which result in Tx max power is not accurate.
- **问题分析：**从异常的log来看，TXAGC和HDET之间的误差被补偿到MTPL上，但是MTPL的变化并没有体现在TxAGC上，导致最大发射功率不准确。
- 00:04:08.261 rf_tdscdma_core_txplim.c 00887 RFTXPLIM-ACQ:00002,TxAGC:940,HDET:930,FreqComp:-3,UTRAN:940,NV:940,Desired:937,Target:947,DEM:000
- 00:04:08.261 rf_tdscdma_core_txplim.c 00895 RFTXPLIM-ACQ:00002,Gain:04,LimitErr:05.50,Filtered:01.37,MTPL:942.87
- 00:04:08.271 rf_tdscdma_core_txplim.c 00887 RFTXPLIM-ACQ:00003,TxAGC:940,HDET:930,FreqComp:-3,UTRAN:940,NV:940,Desired:937,Target:947,DEM:000
- 00:04:08.271 rf_tdscdma_core_txplim.c 00895 RFTXPLIM-ACQ:00003,Gain:04,LimitErr:04.12,Filtered:01.03,MTPL:943.90
- 00:04:08.281 rf_tdscdma_core_txplim.c 00887 RFTXPLIM-ACQ:00004,TxAGC:940,HDET:930,FreqComp:-3,UTRAN:940,NV:940,Desired:937,Target:947,DEM:000
- 00:04:08.281 rf_tdscdma_core_txplim.c 00895 RFTXPLIM-ACQ:00004,Gain:04,LimitErr:03.09,Filtered:00.75,MTPL:944.65

TDSCDMA NS Tx Max Power Issue

- From pass log, TxAGC behavior is same as MTPL.
- 从正常的log可以看出，TXAGC的变化跟MTPL的行为保持一致。
- 00:12:40.340 rf_tdscdma_core_txplim.c 00887 RFTXPLIM-ACQ:00003,TxAGC:940,HDET:931,FreqComp:-3,UTRAN:1030,NV:940,Desired:937,Target:946,DEM:000
- 00:12:40.340 rf_tdscdma_core_txplim.c 00895 RFTXPLIM-ACQ:00003,Gain:04,LimitErr:04.62,Filtered:01.15,MTPL:942.53
- 00:12:40.350 rf_tdscdma_core_txplim.c 00887 RFTXPLIM-ACQ:00004,TxAGC:941,HDET:932,FreqComp:-3,UTRAN:1030,NV:940,Desired:937,Target:946,DEM:000
- 00:12:40.350 rf_tdscdma_core_txplim.c 00895 RFTXPLIM-ACQ:00004,Gain:04,LimitErr:03.46,Filtered:00.84,MTPL:943.37
- 00:12:40.360 rf_tdscdma_core_txplim.c 00887 RFTXPLIM-ACQ:00005,TxAGC:942,HDET:933,FreqComp:-3,UTRAN:1030,NV:940,Desired:937,Target:946,DEM:000
- 00:12:40.360 rf_tdscdma_core_txplim.c 00895 RFTXPLIM-ACQ:00005,Gain:04,LimitErr:02.62,Filtered:00.65,MTPL:944.03
- From FW log, TxAGC override flag is enabled in the failure log, which result in max power is always limited to 24dbm
- 从FW log 看，在异常的log中，TXAGC override功能被使能，导致最大功率限制在24以内

```
1980 Jan 6 00:13:07.179 [58] 0xD11B TDSCDMA FW UPLINK Report
Version = 43
TimeStamp {
  subFrame = 4727
  slot = TS1
}
numChans = 1
servCellID = 100
minPwrLimited = FALSE
maxPwrLimited = TRUE
tpcPatternOverrideFlag = FALSE
txPwrOverrideFlag = FALSE
pathlossForSich = 0.00 dBm
frequency = 1919200000 Hz
txOutputPower = 24.38 dBm
```

pass

```
1980 Jan 6 00:04:19.526 [E5] 0xD11B TDSCDMA FW UPLINK Report
Version = 43
TimeStamp {
  subFrame = 3992
  slot = TS2
}
numChans = 1
servCellID = 0
minPwrLimited = FALSE
maxPwrLimited = FALSE
tpcPatternOverrideFlag = FALSE
txPwrOverrideFlag = TRUE
txPwrOverrideValue = 384
pathlossForSich = 0.00 dBm
frequency = 1919200000 Hz
txOutputPower = 24.00 dBm
```


failure

TDSCDMA NS Tx Max Power Issue

- From QSPR log, TxAGC override is indeed enabled when NS test on CMW500. While it's not enabled in other scenarios (no issue on 8820, or online test on CMW500)
- 从QSPR log看，在CMW500上做NS测试的时候，TxAGC override 被使能了。这个问题在其他时候不会遇到。（8820上或是CMW500信令测试都不会有此问题）

```
31:26:804    QMSL_L...  QLIB_IsPhoneConnected
31:26:855    QMSL_L...  QLIB_IsPhoneConnected
31:26:906    QMSL_L...  QLIB_FTM_TDSCDMA_BER_SET_UL_POWERbOverride=1, UL_Pwr_dBm10=0)
```

- **Solution:** Set UL max power to a higher value than target power (like 26 dBm) in NS XTT to avoid this issue
- **解决方案：**在NS测试的时候可以把最大功率设的大一点(例如26 dBm)



Questions?

<https://support.cdmatech.com>

