
高通多媒体技术期刊 20160406



Qualcomm Technologies, Inc.

Confidential and Proprietary – Qualcomm Technologies, Inc.

机密和专有信息——高通技术股份有限公司



Confidential and Proprietary – Qualcomm Technologies, Inc.

Confidential and Proprietary – Qualcomm Technologies, Inc.

NO PUBLIC DISCLOSURE PERMITTED: Please report postings of this document on public servers or web sites to: DocCtrlAgent@qualcomm.com. **禁止公开：**如在公共服务器或网站上发现本文档，请报告至：DocCtrlAgent@qualcomm.com.

Restricted Distribution: Not to be distributed to anyone who is not an employee of either Qualcomm or its affiliated without the express approval of Qualcomm's Configuration Management. **限制分发：**未经高通配置管理部门的明示批准，不得发布给任何非高通或高通附属及关联公司员工的人。 Not to be used, copied, reproduced, or modified in whole or in part, nor its contents revealed in any manner to others without the express written permission of Qualcomm Technologies, Inc. 未经高通技术股份有限公司明示的书面允许，不得使用、复印、复制、或修改全部或部分文档，不得以任何形式向他人透露其内容。

The user of this documentation acknowledges and agrees that any Chinese text and/or translation herein shall be for reference purposes only and that in the event of any conflict between the English text and/or version and the Chinese text and/or version, the English text and/or version shall be controlling. 本文档的用户知悉并同意中文文本和/或翻译仅供参考之目的，如英文文本和/或版本和中文文本和/或版本之间存在冲突，以英文文本和/或版本为准。

This document contains confidential and proprietary information and must be shredded when discarded. 未经高通明示的书面允许，不得使用、复印、复制全部或部分文档，不得以任何形式向他人透露其内容。本文档含有高通机密和专有信息，丢弃时必须粉碎销毁。

Qualcomm reserves the right to make changes to the product(s) or information contained herein without notice. No liability is assumed for any damages arising directly or indirectly by their use or application. The information provided in this document is provided on an "as is" basis. 高通保留未经通知即修改本档中提及的产品或信息的权利。本公司对使用或应用本文档所产生的直接或间接损失概不负责。本文档中的信息为基于现状所提供，使用风险由用户自行承担。

Qualcomm is a trademark of QUALCOMM Incorporated, registered in the United States and other countries. All QUALCOMM Incorporated trademarks are used with permission. Other product and brand names may be trademarks or registered trademarks of their respective owners. Qualcomm是高通公司在美国及其它国家注册的商标。所有高通公司的商标皆获得使用许可。其它产品和品牌名称可能为其各自所有者的商标或注册商标。

This technical data may be subject to U.S. and international export, re-export, or transfer ("export") laws. Diversion contrary to U.S. and international law is strictly prohibited. 本文档及所含技术资料可能受美国和国际出口、再出口或转移出口法律的 限制。严禁违反或偏离美国和国际的相关法律。

Qualcomm Technologies, Inc. 5775 Morehouse Drive San Diego, CA 92121 U.S.A.

高通技术股份有限公司，美国加利福尼亚州圣地亚哥市莫豪斯路 5775 号，邮编 92121

Revision History

Revision	Date	Description
A	Apr. 2016	Initial release

Note: There is no Rev. I, O, Q, S, X, or Z per Mil. standards.

内容

- Audio
 - Important docs update
 - Audio common issues
- Video
 - 如何Enable Wi-Fi Display的HDCP功能
 - 整合Wi-Fi Display的HDCP功能以及理解HDCP连接原理
 - 通过Log Debug HDCP 功能



Audio

Important docs update

- Docs
- Solutions
 - [00031389](#) - How to enable Dolby DS1 feature on MSM8996 M release
 - [00031403](#) - Example code to enable External echo reference on Quinary MI2S interface
 - [00031406](#) - Reference DTSL changes to enable only Quinary MI2S Tx/Rx on MSM8937
 - [00031407](#) - Reference DTSL changes to enable only Quaternary MI2S Tx/Rx on MSM8937
 - [00031408](#) - Reference DTSL changes to enable only Quinary and Quaternary MI2S Tx/Rx on MSM8937
 - [00031422](#) - MSM8953 Linux Audio Documents
 - [00031423](#) - MSM8953.LA.1.0 - Release schedule
 - [00031424](#) - MSM8953 LA.1.0 Audio POR specification - Audio features

Audio common issues (1)

- 描述：standby current is more higher after using QUAT_MI2S
- 复现步骤和现象：
 - 1, tinymix打开QUAT_MI2S
 - 2, tinypay播放一个wav文件
 - 3, tinypay关闭QUAT_MI2S
 - 4, 深入睡眠，测量待机电流
 - 结果：待机电流比平常高出30mA左右
- 基线：MSM8952、MSM8956
- CR：992618
- 代码修改：
 - 有正式的patch，目前在codeaurora上还看不到，QUAT_MI2S的修改如下页，其它路I2S的修改类似。

Audio common issues (1)

```

- @@ -1542,6 +1542,7 @@ static int quat_mi2s_clk_ctl(struct snd_pcm_substream *substream, bool enable)
-
-     if (enable) {
-         if (substream->stream == SNDRV_PCM_STREAM_PLAYBACK) {
-             + mi2s_rx_clk.clk_val2 = Q6AFE_LPASS_OSR_CLK_12_P288_MHZ;
-             if (mi2s_rx_bit_format == SNDRV_PCM_FORMAT_S24_LE)
-                 mi2s_rx_clk.clk_val1 =
-                     Q6AFE_LPASS_IBIT_CLK_3_P072_MHZ;
- @@ -1553,6 +1554,7 @@ static int quat_mi2s_clk_ctl(struct snd_pcm_substream *substream, bool enable)
-                                     &mi2s_rx_clk);
-         } else if (substream->stream == SNDRV_PCM_STREAM_CAPTURE) {
-             mi2s_tx_clk.clk_val1 = Q6AFE_LPASS_IBIT_CLK_1_P536_MHZ;
-             + mi2s_tx_clk.clk_val2 = Q6AFE_LPASS_OSR_CLK_12_P288_MHZ;
-             ret = afe_set_lpass_clock(
-                                     AFE_PORT_ID_QUATERNARY_MI2S_TX,
-                                     &mi2s_tx_clk);
- @@ -1566,11 +1568,13 @@ static int quat_mi2s_clk_ctl(struct snd_pcm_substream *substream, bool enable)
-         } else {
-             if (substream->stream == SNDRV_PCM_STREAM_PLAYBACK) {
-                 mi2s_rx_clk.clk_val1 = Q6AFE_LPASS_IBIT_CLK_DISABLE;
-                 + mi2s_rx_clk.clk_val2 = Q6AFE_LPASS_OSR_CLK_DISABLE;
-                 ret = afe_set_lpass_clock(
-                     AFE_PORT_ID_QUATERNARY_MI2S_RX,
-                     &mi2s_rx_clk);
-             } else if (substream->stream == SNDRV_PCM_STREAM_CAPTURE) {
-                 mi2s_tx_clk.clk_val1 = Q6AFE_LPASS_IBIT_CLK_DISABLE;
-                 + mi2s_tx_clk.clk_val2 = Q6AFE_LPASS_OSR_CLK_DISABLE;
-                 ret = afe_set_lpass_clock(
-                     AFE_PORT_ID_QUATERNARY_MI2S_TX,
-                     &mi2s_tx_clk);
-             }
-         }
-     }
- }
```


Audio common issues (2)

- 描述 : Media volume sound was cutting off
- 复现步骤和现象 :
 - Settings->Sound¬ification->Media volume
 - Change the Media volume with seek bar, there is no sound.
- 基线 : M release
- CR : 982822
- 代码修改 :
 - <https://us.codeaurora.org/cgit/quic/la/platform/frameworks/av/commit/?id=2bdf8e4f609606fcc6c9d110131484a817f107a6>

Audio common issues (3)

- 描述 : wechat TX no sound after voice call
- 复现步骤和现象 :
 - 1. Connect WIFI, install Wechat
 - 2. DUT make a Wechat voice call. Run Wechat voice call in background.
 - 3. DUT make a 10086 call during Wechat call.
 - 4. After some second 10086 call, hang up the 10086 call
 - 5. Check the Wechat call, DUT could hear far side, but far side can't hear DUT
- 基线 : MSM8952/76
- CR : 984904
- 代码修改 :
 - https://www.codeaurora.org/cgit/quic/la/platform/vendor/qcom/tellurium_64/commit/?id=e4264830eb5a2d8537970c294b75f461b6a80808

Audio common issues (4)

- 描述：TX mute when make a voice call during wechat call
- 复现步骤和现象：
 - 1. Connect WIFI, install Wechat
 - 2. DUT make a Wechat voice call. Run Wechat voice call in background.
 - 3. DUT make a voice call during Wechat call.
 - Result: Both voice call TX and Wechat call TX is muted, DUT RX is fine
- 基线：M release
- CR：988594
- 代码修改：
 - `diff --git a/hal/audio_hw.c b/hal/audio_hw.c`
 - `@@ -733,7 +733,7 @@ static void check_and_route_capture_usecases(struct audio_device *adev,`
 - `usecase->in_snd_device != snd_device &&`
 - `((uc_info->devices & AUDIO_DEVICE_OUT_ALL_CODEC_BACKEND) &&`
 - `((!(usecase->devices & ~AUDIO_DEVICE_BIT_IN) & AUDIO_DEVICE_IN_ALL_CODEC_BACKEND) ||`
 - `-(usecase->type == VOICE_CALL))) &&`
 - `+ (usecase->type == VOICE_CALL) || (usecase->type == VOIP_CALL))) &&`
 - `(usecase->id != USECASE_AUDIO_SPKR_CALIB_TX)) {`
 - `ALOGV("%s: Usecase (%s) is active on (%s) - disabling ..",`
 - `__func__, use_case_table[usecase->id],`

Audio common issues (5)

- 描述：FM no sound when disable touch tone
- 复现步骤和现象：
 - 1 Disable all touch tone
 - 2 Insert Headphone
 - 3 open QCOM FM APK and play FM
 - FM no sound; if enable touch tone, FM play back is OK.
- 基线：M release
- CR：957807
- 代码修改：
 - <https://us.codeaurora.org/cgit/quic/la/platform/hardware/qcom/audio/commit/?id=7fcac44dc7593c674a9820914c79f729c388b3aa>



Video

如何Enable Wi-Fi Display的HDCP功能

如果WFD Source需要传输DRM content protection到WFD Sink端，Source和Sink端必须同时支持HDCP 2.x。

- 如何在WFD Source端打开HDCP功能

把/system/etc/ 下面的wfdconfig.xml 用adb pull出来。

并做如下修改：

```
<ContentProtection>
  <Valid>1</Valid>
  <Version>WFD_HDCP_2_1</Version>
</ContentProtection>
```

最后把wfdconfig.xml push回到/system/etc目录下

- 上面只是默认打开Video的加密功能，对于Audio要在wfdconfig.xml里面打开下面的config。

```
<ContentProtection>
  <Valid>1</Valid>
  <Version>WFD_HDCP_2_1</Version>
  <EncryptAudio>1</EncryptAudio> <!-- Valid values 0 / 1 to indicate Audio
encryption or not -->
</ContentProtection>
```

关于HDCP的Enable也可以参考solution 28468

整合Wi-Fi Display的HDCP功能以及理解HDCP连接原理

■ 整合HDCP功能

除了在wfdconfig.xml 里enable HDCP, 还需要一个HDCP的Library,通常是由第三方 Santa Security

(<https://www.sansasecurity.com>) 或者ARM提供, 这两家也是QTI 建议的第三方。

所以, 联系第三方拿到Library, 包括License等事宜, 其他与HDCP集成相关的代码, 高通release版本默认都已经包含。

■ HDCP连接原理

如果Source和Sink都支持HDCP2.x, HDCP Session将会在RTSP session之前建立连接, 如果HDCP Session建立失败, 默认仍然可以建立RTSP Session, 也就是HDCP没有建立成功的情况下, WFD功能仍然可以使用, 这种情况下Source端将只能传输非DRM content protection到Sink端。

另外, 在HDCP Session失败的情况下, 也可以强制终止RTSP Session, 从而WFD功能不可用, 此禁止可以在wfdconfig.xml里添加如下config.

```
<EnforceLinkHDCP>1</EnforceLinkHDCP>
```

默认这个config在wfdconfig.xml里没有, 需要手动添加。

通过Log Debug HDCP 功能

- 如下log说明要启动HDCP的Session

01-18 17:42:12.717 2064 2743 D RTSPSession_CPP: RTSP
setupCallback: negotiated capability: HDCP port 9876, version 2

- 如下log说明HDCP Session connection 成功

01-18 17:42:12.937 2064 2745 E MM_OSAL: WFD_HdcpSessionConnect ():
SUCCESS!!

- 如下log说明数据被加密成功

01-18 17:42:13.828 2064 2757 E MM_OSAL: WFD_HdcpDataEncrypt-
params = 0, 22210

01-18 17:42:13.828 2064 2757 E MM_OSAL: WFD_HdcpDataEncrypt ():
ErrorStatus (0)

- 如下log可以确认HDCP的版本

MMCapability_CPP(2593): wfd_content_protection: HDCP2.2 port=6789

Questions?

<https://support.cdmatech.com>

