
高通8996功耗温升优化技术期刊- 20151225



Qualcomm Technologies, Inc.

Confidential and Proprietary – Qualcomm Technologies, Inc.

机密和专有信息——高通技术股份有限公司



Checklist

- Power Consumption Data Document/Link
- Power Measurement Checklist
- Power Debug Guide
- CR/Patches Checklist
- Tips

Checklist --- Power Consumption Data

- External Document
 - MSM8996_LA_Current_Consumption_Data
 - Document #: 80-NT204-7
 - You can find detailed power break down data in this document
 - Power Data for MSM8996.LA.1.0 Release 01600
 - Document #: 80-NT204-7
 - You can find power data for this release

Checklist --- Power Measurement

- Use perf_defconfig instead defconfig
 - Remove “Debug” features
 - Double check if “CORESIGHT” config is removed
 - Double check if “CONFIG_MSM_DEBUG_LAR_UNLOCK” config is removed
- Disable UART console
 - Especially for smart panel
- Remove unnecessary debug log with high frequency
- Remove on-device logging tools

Checklist --- Power Debug

- Power Debug Guide with Simplified Chinese
 - Document #: 80-P0955-1SC
 - There is detail guide on how to debug almost all cases like RBSC, MP3, MP4, camera etc. Just need to follow step by step
- Power Debug Guide with English
 - Document #: 80-P0955-1
- Camera Power Debug Guide
 - Document #: 80-NP961-1
- PerfLock API Overview
 - Document #: 80-NT384-1
- Multimedia Power Debugging Case
 - Document #: 80-NT616-1
- QUALCOMM ONDEVICE POWER DASHBOARD TEST GUIDE
 - Document #: 80-P1818-1EC
- LA Power Optimization
 - Document #: 80-NA157-246
- Android Power Overview
 - Document #: 80-NA157-246

Checklist --- CR/Patches

N -- No Impact

- means Side Effect

+ means Good Impact

CR	Fix	Patches	Perf	Power	Stability	Comment
CR1462552	Fix "CPU DCVS governor wrongly changed into performance mode	https://review-android.quicinc.com/#/c/1462552/2	N	+	N	
CR869281	On Isatri we are observing that DIAG_WS wakelock in not being released when we remove USB.		N	+	N	
CR1483407	15ms peaks on static display	https://review-android.quicinc.com/#/c/1483407/	N	+	N	
CR1356625	Cpu floor frequency settings	https://review-android.quicinc.com/#/c/1356625/9	N	N	N	
	> video dec regression fix	https://review-android.quicinc.com/#/c/1483407/ -	N	+	N	
	logd verbose removal for ViLTE	https://review-android.quicinc.com/#/c/1476833/ https://review-android.quicinc.com/#/c/1476832/ https://review-android.quicinc.com/#/c/1484835/	N	+	N	



CR	Fix	Patches	Perf	Power	Stability	Comment
	<u>thermal kernel code fix</u> (right now it is merged in <u>LA.HB.1.1.1 only</u>)	https://review-android.quicinc.com/#/c/1478225/	N	+	N	
	<u>Camera capture XO shutdown block</u>	https://review-android.quicinc.com/#/c/1453869/	N	+	N	

Checklist --- Tips

RBSC-1/2

- Use IR camera to scan board's hot spot if RBSC current is high ;
- Power breakdown board is strongly recommended to OEMs;
- If no power breakdown board and even IR scan can't find abnormal leakage , HW guys should be involved , they are helpful on removing some HW modules to figure out where does the leakage comes from;
- UART is very helpful as the debug information channel when do RBSC tuning, due to system can't enter VDDmin with USB connected, you can get the kernel logs from UART terminators in time;
- Use cmd line to enable dump enabled clocks before vddmin instead;
echo 1 > /sys/kernel/debug/clock/debug_suspend and then get kernel log after disconnect USB cable

Checklist --- Tips

RBSC-2/2

- Use full dump script for PMIC and GPIO dump
- Remove the corresponding drivers directly if need to see if RBSC can be improved or not ;
- When CX voltage is probed not match the voltage table in rpm code, for VDDmin case, please check if system went to VDDmin or not, there is a case that system can't go to VDDmin but can go to VDDlow due to finger print driver request CXO, but at that time RBSC just 2-3mA higher than VDDmin`s

Checklist --- Tips

MP3

- Identify the decoder used by OEM is software or hardware;
- If there are 3rd party sound effect lib in OEM`s build for headset case, try to disable it when comparing with reference;
- Check is there any Hi-Fi function, try to get breakdown data when Hi-Fi enabled, especially for Hi-Fi PA;

Checklist --- Tips

Static Display

- OEM UI may keep refreshing the home screen, peaks can be observed periodically on current waveforms;
- Touch panel may generate too much interrupts and leads a bigger power number;
- Get ftrace for further checking when other abnormal wakeups observed on current waveforms;
- Check with OEMs on if there is any display effective enhance technology they are using, which may adjust the display solution, not only the backlight, according the ambient light, please disable it when you get power number for this case
- 15ms periodical peaks observed, and can be reproduced on all display relate cases, there is a video regression fix for 1700, root cause is auto-refresh for cmd panel feature broken and fixed by the following CR
FYI : <https://review-android.quicinc.com/#/c/1483407/>

Checklist --- Tips

Camera

- Lower down the fps to 25fps for preview case if OEMs agree;
- Set a smaller output size of camera sensor;
- Face detection and auto focus cost more power;

Checklist --- Tips

Other CPU Intensive Use Case

- Ptable should be match to the power/DMIPs curve of specific chipset version(like MSM8996 chipset V3.1.3) ;
- Ptable can be get or replaced by : Steps to push energy-awareness:

```
adb shell
```

```
mv /system/bin/energy-awareness /system/bin/energy-awareness-original
```

```
adb push <energy-awareness> /system/bin/energy-awareness
```

```
adb shell chmod 777 /system/bin/energy-awareness
```

```
adb shell sync
```

reboot the device and check for new ptable values. One should see following output for LVT in bold.

```
adb shell
```

```
cat /d/msm_core/ptable
```

- Confirmed there was a bug related with BCL/Governor setting in 8996 init.qcom.post_boot.sh.

Will result in big cluster keep running at “performance” instead of “interactive” mode, and 100~200mA increasing for some cases

FYI CR [1478225](#)

Checklist --- Tips

DoU

- Brightness should be adjust to a reasonable value when do apple to apple comparing with the target HW;
- Camera case should have a much better power number for MSM8996 comparing with MSM8992/8994/8974, due to MSM8996 has a strong GPU;
- Thermal facts should be taken into account when do DoU test, different thermal configuration may leads a difference DoU result;

Checklist --- Tips

Thermal

- Thermal-engine thread sometime rise up to the top on cpu occupying list.

Root cause is “VIRTUAL-CPUS” sensor is higher than 60°C and works in polling mode for temperature read. A fix has been mainlined by rise up threshold from 60C to 75C to minimize power impact;

- Currently when using cpu_voltage rule there is an implied floor at 1GHz for gold cluster and 729MHz for silver cluster by default (despite not having device_max_limit set);

FYI

<https://review-android.quicinc.com/#/c/1356625/9>