




| | | | | | |
|---|--|--|-----------------------------------|---|---|
| DEFECT NUMBER | OC47.15 | EQUIPMENT | KPCV10 - MP Reject Conveyor 10M | FACILITY | Oaky Creek Open Cut |
| DEFECT CATEGORY | Structural | COMPONENT | Steel Plate | INSPECTED BY | Eduard Hernandez |
| DEFECT TYPE | Steel Corrosion | LOCATION | Discharge from Reject Screen No.4 | DATE | 08-11-2025 |
| Description of Structural Integrity Issue | Advanced corrosion is present on the surfaces of the discharge chute from Reject Screen No.4. The degradation is widespread, with material loss evident along the chute walls and at key structural transition points. | | | | |
| Structural Risk Assessment: | Potential Incident: | Structural Failure Mechanism: | | Consequence: | Likelihood |
| | If not fixed, the chute may failure, causing material spillage and operational downtime. This could also lead to injuries to personnel working nearby. | The chute is at risk of buckling and shear failure due to advanced corrosion weakening its structural integrity. | Risk Assessment: | 2-Minor. This rating is based on Financial impact: \$1M to \$5M operating profit \$300k to \$1M property damage \$1M to \$5M asset devaluation | C - Possible - Could occur more than once during a lifetime or life of plant. |
| | | | Required Action: | Preventive Action | |
| Previous Audit Result for Defect: | No previous report available. | | | | Severity Level: |
| | | | | | Moderate |
| Corrective Action: | 1. Remove all debris and loose material from the chute. 2. Sandblast all corroded areas to bare metal. 3. Weld reinforcement plates to areas of significant corrosion. 4. Replace any severely damaged sections of the chute. 5. Apply a protective coating to all repaired surfaces. | | | | Estimated Corrective Action Cost: |
| | | | | | 5,000 - 10,000 AUD |
| Photos: | <div><div><div>DIRECTION 190 deg(T)</div><div>23.06993°S 148.48742°E</div><div>ACCURACY 7 m DATUM WGS84</div><div>MP Reject Conv. 10M Reject Screen No.4</div><div>Steel Corrosion</div><div>2025-11-08 07:15:07+10:00</div></div><div><div>DIRECTION 238 deg(T)</div><div>23.06992°S 148.48742°E</div><div>ACCURACY 5 m DATUM WGS84</div><div>MP Reject Conv. 10M Reject Screen No.4</div><div>Steel Corrosion</div><div>2025-11-08 07:15:22+10:00</div></div><div><div>DIRECTION 314 deg(T)</div><div>23.06993°S 148.48743°E</div><div>ACCURACY 5 m DATUM WGS84</div><div>MP Reject Conv. 10M Reject Screen No.4</div><div>Steel Corrosion</div><div>2025-11-08 07:15:32+10:00</div></div></div> | | | | |