




DEFECT NUMBER		OC37.07		EQUIPMENT		KPBN01 - MP Reject Bin		FACILITY		Oak Creek Open Cut	
DEFECT CATEGORY		Structural		COMPONENT		Steel Beam		INSPECTED BY		Eduard Hernandez	
DEFECT TYPE		Steel Damage		LOCATION		Beam South Side Structure Bin		DATE		08-11-2025	
Description of Structural Integrity Issue		Permanent deformation was observed in the south beam of the MP Reject Bin structure, with the affected member displaying a noticeable lateral bend without signs of impact or collision. There is no visible tearing or section loss; however, the deflection may affect the structural alignment and induce secondary stresses in adjacent connections or support frames.									
Structural Risk Assessment:	Potential Incident:		Structural Failure Mechanism:			Consequence:		Likelihood		Risk Rating	
	If not fixed, the bent beam may lead to structural misalignment, risking failure of the bin. This could cause operational downtime and potential injuries to workers.		The beam is experiencing bending due to excessive load or residual stress, which may lead to buckling if not addressed.		Risk Assessment:	3-Moderate. This rating is based on Financial impact: \$5M to \$50M operating profit \$1M to \$5M property damage \$5M to \$25M asset devaluation		D - Unlikely - Could occur about once during a lifetime or life of plant.		Medium [9]	
						Required Action:					
Previous Audit Result for Defect:		No previous report available.							Severity Level:		Moderate
Corrective Action:		1. Install temporary supports for the affected beam and any connected elements. 2. Remove the deformed beam and replace it in accordance with the design characteristics. 3. Re-install all previously connected elements.							Estimated Corrective Action Cost:		10,000 - 20,000 AUD
Photos:		<div><div><div><div>DIRECTION 87 deg(T)</div><div>23.07109°S 148.48751°E</div><div>ACCURACY 3 m DATUM WGS84</div></div><div>MP Reject Bin South BeamSteel Deformation2025-11-08 08:19:51+10:00</div></div><div><div><div>DIRECTION 39 deg(T)</div><div>23.07110°S 148.48753°E</div><div>ACCURACY 5 m DATUM WGS84</div></div><div>MP Reject Bin South BeamSteel Deformation2025-11-08 08:20:02+10:00</div></div><div><div><div>DIRECTION 39 deg(T)</div><div>23.07110°S 148.48753°E</div><div>ACCURACY 5 m DATUM WGS84</div></div><div>MP Reject Bin South BeamSteel Deformation2025-11-08 08:20:12+10:00</div></div></div>									