

### STM32L15xxD, STM32L15xxC and STM32L15xxC-A ultra-low-power device limitations

## Silicon identification

This errata sheet applies to revisions A, Z, Y and X of the STMicroelectronics STM32L15xxD, STM32L15xxC and STM32L15xxC-A ultra-low-power products. This family features an ARM® 32-bit Cortex®-M3 core, for which an errata notice is also available (see [Section 1](#) for details). A full list of root part numbers is shown in [Table 1](#).

The products can be identified (see [Table 2](#)) by:

- The revision code marked below the sales type on the device package
- The last three digits of the internal sales type printed on the box label

**Table 1. Device summary**

Reference	Part number
STM32L151QD	STM32L151QDH6
STM32L151QC	STM32L151QCH6
STM32L151RC-A	STM32L151RCT6A, STM32L151RCY6, STM32L151RCY6DTR
STM32L151RD	STM32L151RDT6, STM32L151RDY6
STM32L151VC-A	STM32L151VCT6A
STM32L151VD	STM32L151VDT6
STM32L151ZC	STM32L151ZCT6
STM32L151ZD	STM32L151ZDT6
STM32L152QD	STM32L152QDH6
STM32L152QC	STM32L152QCH6
STM32L152RC-A	STM32L152RCT6A
STM32L152RD	STM32L152RDT6
STM32L152VC-A	STM32L152VCT6A
STM32L152VD	STM32L152VDT6
STM32L152ZC	STM32L152ZCT6
STM32L152ZD	STM32L152ZDT6

**Table 2. Device identification<sup>(1)</sup>**

Sales type	Revision code <sup>(2)</sup> marked on device
STM32L15xxD, STM32L15xxC, STM32L15xxZC, STM32L15xxRC-A <sup>(3)</sup> , STM32L15xxVC-A <sup>(3)</sup>	"A", "Z", "Y" or "X"

1. The REV\_ID bits in the DBGMCU\_IDCODE register show the revision code of the device (see the *STM32L151xx, STM32L152xx and STM32L162xx advanced ARM®-based 32-bit MCUs reference manual* (RM0038) for details on how to find the revision code).
2. Refer to the device datasheets for details on how to identify the revision code on the different packages.
3. The silicon limitation for STM32L15xxRC/VC products without 'A' letter as the last character of the sales types are described in STM32L15xxC errata sheet.

# Contents

<b>1</b>	<b>ARM® 32-bit Cortex®-M3 limitations</b>	<b>6</b>
1.1	Cortex®-M3 limitation description for the STM32L1xxxx ultra-low-power devices	6
1.1.1	Cortex®-M3 LDRD with base in list may result in incorrect base register when interrupted or faulted	6
1.1.2	Cortex®-M3 event register is not set by interrupts and debug	7
1.1.3	Cortex®-M3 interrupted loads to the stack-pointer can cause erroneous behavior	7
1.1.4	SVC and BusFault/MemManage may occur out of order	8
<b>2</b>	<b>STM32L15xxD/C/C-A silicon limitations</b>	<b>9</b>
2.1	System limitations	12
2.1.1	AOP_RANGE bit is mapped on register COMP_CSR(28) instead of register AOP_CSR(28)	12
2.1.2	Missing analog switch on PC10 GPIO	12
2.1.3	PG0 to PG15 and PF0 to PF5 port sink current when $V_{IN} > V_{DD}$	12
2.1.4	If debugger is connected in JTAG mode and JNTRST (PB4) pin configuration is changed, the connection is lost	12
2.1.5	Read protection: a mass erase occurs if the RDP register is written with level 0 when level 0 is already set	13
2.1.6	In Stop mode, RAMs are not in power down if DMA is enabled	13
2.1.7	Invalid read from data EEPROM after write in program Flash	14
2.1.8	Debugging Stop mode with WFE entry	14
2.1.9	Boot from bank2 limitation	14
2.1.10	Pull-up on PB7 when configured in analog mode	15
2.1.11	Range 1 of dynamic voltage scaling has a lower limit of 2.0 V	15
2.1.12	Wakeup sequence from Standby mode when using more than one wakeup source	16
2.1.13	Flash memory wakeup issue when waking up from Stop or Sleep with Flash memory in power-down mode	16
2.1.14	Unexpected system reset when waking up from Stop mode with regulator in low-power mode	17
2.2	LCD peripheral limitations	17
2.2.1	High drive resistive network total value too low	17
2.2.2	Injection from LCD_SEG2, LCD_SEG5, LCD_SEG21 pins	17
2.3	IWDG peripheral limitation	18

2.3.1	RVU and PVU flags are not reset in Stop mode	18
2.4	I <sup>2</sup> C peripheral limitations	18
2.4.1	SMBus standard not fully supported	18
2.4.2	Wrong behavior of I <sup>2</sup> C peripheral in Master mode after misplaced STOP	18
2.4.3	Violation of I <sup>2</sup> C “setup time for repeated START condition” parameter	19
2.4.4	In I <sup>2</sup> C slave “NOSTRETCH” mode, underrun errors may not be detected and may generate bus errors	19
2.4.5	10-bit Master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave	20
2.5	SPI/I2S peripheral limitations	21
2.5.1	In I2S slave mode, WS level must to be set by the external master when enabling the I2S	21
2.5.2	Wrong CRC calculation when the polynomial is even	21
2.5.3	BSY bit may stay high at the end of a data transfer in Slave mode	22
2.5.4	Wrong CRC transmitted in Master mode with delayed SCK feedback	23
2.5.5	SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI finishes its DMA transaction	23
2.5.6	Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback	24
2.6	USART peripheral limitations	25
2.6.1	Idle frame is not detected if receiver clock speed is deviated	25
2.6.2	In full duplex mode, the Parity Error (PE) flag can be cleared by writing the data register	25
2.6.3	Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection	25
2.6.4	Break frame is transmitted regardless of nCTS input line status	25
2.6.5	nRTS signal abnormally driven low after a protocol violation	26
2.6.6	Start bit detected too soon when sampling for NACK signal from the smartcard	26
2.6.7	Break request can prevent the Transmission Complete flag (TC) from being set	27
2.6.8	Guard time is not respected when data are sent on TXE events	27
2.6.9	nRTS is active while RE or UE = 0	27
2.7	SDIO peripheral limitations	28
2.7.1	SDIO hardware flow control	28
2.7.2	Wrong CCRCFAIL status after a response without CRC	28
2.7.3	No underrun detected and wrong data transmission	28
2.7.4	CE-ATA multiple write command and card busy signal management	29

2.8	FSMC peripheral limitation . . . . .	29
2.8.1	FSMC NOR Flash/PSRAM controller asynchronous access on bank2..4 when bank1 is in synchronous mode (CBURSTRW bit is set)	29
2.8.2	FSMC synchronous mode and disabled NWAIT signal . . . . .	30
2.8.3	Dummy read cycles inserted when reading synchronous memories . . .	30
2.9	DAC peripheral limitations . . . . .	30
2.9.1	Spurious activation of DAC output buffer (PA4 and PA5) . . . . .	30
2.10	RCC peripheral limitation . . . . .	31
2.10.1	Delay after an RCC peripheral clock enabling . . . . .	31
2.11	RTC limitation . . . . .	31
2.11.1	Spurious tamper detection when disabling the tamper channel . . . . .	31
2.11.2	RTC calendar registers are not locked properly . . . . .	31
<b>3</b>	<b>Revision history . . . . .</b>	<b>32</b>

List of tables

Table 1. Device summary . . . . . 1

Table 2. Device identification . . . . . 1

Table 3. Cortex®-M3 core limitations and impact on microcontroller behavior . . . . . 6

Table 4. Summary of silicon limitations . . . . . 9

Table 5. Maximum allowable APB frequency at 30 pF load . . . . . 24

Table 6. Document revision history . . . . . 32

# 1 ARM® 32-bit Cortex®-M3 limitations

An ARM errata notice of the STM32L1xxxx core is available searching for “Cortex®-M3 errata at the following web address: [www.arm.com](http://www.arm.com).

All the described limitations are minor and relate to revision r2p0-00rel0 of the Cortex®-M3 core. [Table 3](#) summarizes these limitations and their implications on the behavior of the STM32L1xxxx ultra-low-power devices.

**Table 3. Cortex®-M3 core limitations and impact on microcontroller behavior**

ARM ID	ARM category	ARM summary of errata	Impact on STM32L1xxxx ultra-low-power devices
602117	Cat 2	LDRD with base in list may result in incorrect base register when interrupted or faulted	Minor
563915	Cat 2	Event register is not set by interrupts and debug	Minor
752419	Cat 2	Interrupted loads to SP can cause erroneous behavior	Minor
740455	Cat 2	SVC and BusFault/MemManage may occur out of order	Minor

## 1.1 Cortex®-M3 limitation description for the STM32L1xxxx ultra-low-power devices

Only the limitations described below have an impact, even though minor, on the implementation of STM32L1xxxx ultra-low-power devices.

All other limitations described in the ARM errata notice (and summarized in [Table 3](#) above) have no impact and are not related to the implementation of the STM32L1xxxx ultra-low-power devices (Cortex-M3 r2p0-00rel0).

### 1.1.1 Cortex®-M3 LDRD with base in list may result in incorrect base register when interrupted or faulted

#### Description

The Cortex®-M3 Core has a limitation when executing an LDRD instruction from the system-bus area, with the base register in a list of the form LDRD Ra, Rb, [Ra, #imm]. The execution may not complete after loading the first destination register due to an interrupt before the second loading completes or due to the second loading getting a bus fault.

#### Workaround

1. This limitation does not impact the STM32L1xxxx code execution when executing from the embedded Flash memory, which is the standard use of the microcontroller.
2. Use the latest compiler releases. As of today, the compilers no longer generate this particular sequence. Moreover, a scanning tool is provided to detect this sequence on previous releases (refer to your preferred compiler provider).

### 1.1.2 Cortex®-M3 event register is not set by interrupts and debug

#### Description

When interrupts related to a wake from event (WFE) occur before the WFE is executed, the event register used for WFE wakeup events is not set and the event is missed. Therefore, when the WFE is executed, the core does not wake up from a WFE if no other event or interrupt occurs.

#### Workaround

1. For the following interrupt sources:
  - All external interrupts/events lines (EXTI)
  - PVD output on EXTI line 16 (if VREFINT is enabled only)
  - RTC alarm on EXTI line 17
  - USB wakeup on EXTI line 18
  - RTC tamper and timestamp on EXTI line 19
  - RTC wakeup on EXTI line 20
  - Comparator 1 wake-up on EXTI line 21 (if VREFINT is enabled only)
  - Comparator 2 wake-up on EXTI line 22 (if VREFINT is enabled only)
  - Channel acquisition on EXTI line 23

Use STM32L1xxxx external events instead of interrupts to wake up the core from a WFE by configuring an external or internal EXTI line in event mode.

2. For all other interrupt sources, a timer must be programmed to provide a timeout event and wake-up the core if the event is likely to arrive before the WFE instruction is executed.

### 1.1.3 Cortex®-M3 interrupted loads to the stack-pointer can cause erroneous behavior

#### Description

If an interrupt occurs during the data-phase of a single word load to the stack-pointer (SP/R13), an erroneous behavior can occur. In all cases, returning from the interrupt will result in the load instruction being executed in an additional time. For all instructions performing an update to the base register, the base register will be erroneously updated on each execution, resulting in the stack-pointer being loaded from an incorrect memory location.

The instructions affected by this limitation are the following:

- LDR SP, [Rn],#imm
- LDR SP, [Rn,#imm]!
- LDR SP, [Rn,#imm]
- LDR SP, [Rn]
- LDR SP, [Rn,Rm]

#### Workaround

As of today, no compiler generates these particular instructions. This limitation can only occur with hand-written assembly code.

Both issues can be solved by replacing the direct load to the stack pointer by an intermediate load to a general-purpose register followed by a move to the stack pointer.

Example:

Replace LDR SP, [R0] by

LDR R2,[R0]

MOV SP,R2

#### 1.1.4 SVC and BusFault/MemManage may occur out of order

##### Description

If an SVC exception is generated by executing the SVC instruction while the following instruction fetch is faulted, then the MemManage or BusFault handler may be entered even though the faulted instruction which followed the SVC should not have been executed.

##### Workaround

A workaround is only required if the SVC handler will not return to the return address that has been stacked for the SVC exception and the instruction access after the SVC will fault. If this is the case then padding can be inserted between the SVC and the faulting area of code, for example, by inserting NOP instructions.



## 2 STM32L15xxD/C/C-A silicon limitations

[Table 4](#) summarizes the fix status for products listed in [Table 2: Device identification](#).

The legend for [Table 4](#) is as follows:

- A = workaround available,
- N = no workaround available,
- P = partial workaround available,
- '-' and grayed = fixed.

**Table 4. Summary of silicon limitations**

Links to silicon limitations		Rev A	Rev Z	Rev Y	Rev X
Section 2.1: System limitations	<a href="#">Section 2.1.1: AOP_RANGE bit is mapped on register COMP_CSR(28) instead of register AOP_CSR(28)</a>	A	-	-	-
	<a href="#">Section 2.1.2: Missing analog switch on PC10 GPIO</a>	N	N	N	N
	<a href="#">Section 2.1.3: PG0 to PG15 and PF0 to PF5 port sink current when VIN&gt;VDD</a>	A	-	-	-
	<a href="#">Section 2.1.4: If debugger is connected in JTAG mode and JNTRST (PB4) pin configuration is changed, the connection is lost</a>	A	A	A	A
	<a href="#">Section 2.1.5: Read protection: a mass erase occurs if the RDP register is written with level 0 when level 0 is already set</a>	A	A	A	A
	<a href="#">Section 2.1.6: In Stop mode, RAMs are not in power down if DMA is enabled</a>	A	-	-	-
	<a href="#">Section 2.1.7: Invalid read from data EEPROM after write in program Flash</a>	A	-	-	-
	<a href="#">Section 2.1.8: Debugging Stop mode with WFE entry</a>	A	A	A	A
	<a href="#">Section 2.1.9: Boot from bank2 limitation</a>	A	A	-	-
	<a href="#">Section 2.1.10: Pull-up on PB7 when configured in analog mode</a>	A	A	A	A
	<a href="#">Section 2.1.11: Range 1 of dynamic voltage scaling has a lower limit of 2.0 V</a>	A	A	N	N
	<a href="#">Section 2.1.12: Wakeup sequence from Standby mode when using more than one wakeup source</a>	A	A	A	A
	<a href="#">Section 2.1.13: Flash memory wakeup issue when waking up from Stop or Sleep with Flash memory in power-down mode</a>	A	A	A	-
	<a href="#">Section 2.1.14: Unexpected system reset when waking up from Stop mode with regulator in low-power mode</a>	A	A	A	-
Section 2.2: LCD peripheral limitations	<a href="#">Section 2.2.1: High drive resistive network total value too low</a>	N	-	-	-
	<a href="#">Section 2.2.2: Injection from LCD_SEG2, LCD_SEG5, LCD_SEG21 pins</a>	A	A	A	A

Table 4. Summary of silicon limitations (continued)

Links to silicon limitations		Rev A	Rev Z	Rev Y	Rev X
Section 2.3: IWDG peripheral limitation	Section 2.3.1: RVU and PVU flags are not reset in Stop mode	A	A	A	A
Section 2.4: I2C peripheral limitations	Section 2.4.1: SMBus standard not fully supported	A	A	A	A
	Section 2.4.2: Wrong behavior of I2C peripheral in Master mode after misplaced STOP	A	A	A	A
	Section 2.4.3: Violation of I2C "setup time for repeated START condition" parameter	A	A	A	A
	Section 2.4.4: In I2C slave "NOSTRETCH" mode, underrun errors may not be detected and may generate bus errors	A	A	A	A
	Section 2.4.5: 10-bit Master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave	A	A	A	A
Section 2.5: SPI/I2S peripheral limitations	Section 2.5.1: In I2S slave mode, WS level must to be set by the external master when enabling the I2S	A	A	A	A
	Section 2.5.2: Wrong CRC calculation when the polynomial is even	A	A	A	A
	Section 2.5.3: BSY bit may stay high at the end of a data transfer in Slave mode	A	A	A	A
	Section 2.5.4: Wrong CRC transmitted in Master mode with delayed SCK feedback	A	A	A	A
	Section 2.5.5: SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI finishes its DMA transaction	N	N	N	N
	Section 2.5.6: Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback	A	A	A	A

Table 4. Summary of silicon limitations (continued)

Links to silicon limitations		Rev A	Rev Z	Rev Y	Rev X
Section 2.6: USART peripheral limitations	Section 2.6.1: Idle frame is not detected if receiver clock speed is deviated	N	N	N	N
	Section 2.6.2: In full duplex mode, the Parity Error (PE) flag can be cleared by writing the data register	A	A	A	A
	Section 2.6.3: Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection	N	N	N	N
	Section 2.6.4: Break frame is transmitted regardless of nCTS input line status	N	N	N	N
	Section 2.6.5: nRTS signal abnormally driven low after a protocol violation	A	A	A	A
	Section 2.6.6: Start bit detected too soon when sampling for NACK signal from the smartcard	N	N	N	N
	Section 2.6.7: Break request can prevent the Transmission Complete flag (TC) from being set	A	A	A	A
	Section 2.6.8: Guard time is not respected when data are sent on TXE events	A	A	A	A
	Section 2.6.9: nRTS is active while RE or UE = 0	A	A	A	A
Section 2.7: SDIO peripheral limitations	Section 2.7.1: SDIO hardware flow control	A	A	A	A
	Section 2.7.2: Wrong CCRCFAIL status after a response without CRC	A	A	A	A
	Section 2.7.3: No underrun detected and wrong data transmission	A	A	A	A
	Section 2.7.4: CE-ATA multiple write command and card busy signal management	A	A	A	A
Section 2.8: FSMC peripheral limitation	Section 2.8.1: FSMC NOR Flash/PSRAM controller asynchronous access on bank2..4 when bank1 is in synchronous mode (CBURSTRW bit is set)	A	A	A	A
	Section 2.8.2: FSMC synchronous mode and disabled NWAIT signal	A	A	A	A
	Section 2.8.3: Dummy read cycles inserted when reading synchronous memories	N	N	N	N
Section 2.9: DAC peripheral limitations	Section 2.9.1: Spurious activation of DAC output buffer (PA4 and PA5)	A	A	A	A
Section 2.10: RCC peripheral limitation	Section 2.10.1: Delay after an RCC peripheral clock enabling	A	A	A	A
Section 2.11: RTC limitation	Section 2.11.1: Spurious tamper detection when disabling the tamper channel	N	N	N	N
	Section 2.11.2: RTC calendar registers are not locked properly	A	A	A	A

## 2.1 System limitations

### 2.1.1 AOP\_RANGE bit is mapped on register COMP\_CSR(28) instead of register AOP\_CSR(28)

#### Description

The operational amplifier voltage range is controlled by COMP\_CSR(28) instead of AOP\_CSR(28). The COMP\_CSR(28) bit keeps its original function which selects GPIO PC3 as the ADC input channel CH13 together with the control of operational amplifier voltage range.

#### Workaround

When the operational amplifiers are enabled, the ADC channel CH13 must not be used. This limitation is planned to be fixed in the next revision.

### 2.1.2 Missing analog switch on PC10 GPIO

#### Description

An analog switch is not present on the PC10 port. As a consequence the RI\_ASMR3(10) bit has no effect, so the PC10 port cannot be used for the touch sensing feature.

#### Workaround

None.

### 2.1.3 PG0 to PG15 and PF0 to PF5 port sink current when $V_{IN} > V_{DD}$

#### Description

The PG0 to PG15 ports and PF0 to PF5 ports exhibit a leakage current when a voltage above  $V_{DD}$  is applied on them.

#### Workaround

When the current consumption is important, do not apply a voltage above  $V_{DD}$  on the port PG0 to PG15 and port PF0 to PF5.

This limitation is planned to be fixed in the next revision.

### 2.1.4 If debugger is connected in JTAG mode and JNTRST (PB4) pin configuration is changed, the connection is lost

#### Description

PB4 is configured by default in alternate function mode after reset.

When the configuration bit changes from an alternate function to an input, analog or GPIO, the reset signal connected to the CPU is tied to '0', and forces a reset on the CPU TAP that stops the debugger connection, even if the pin itself is pulled up.

Only JTAG mode with 4 wires is impacted. The Serial Wire Debug (SWD) mode is not impacted.

#### Workaround

During the debug phase, when the debugger is connected in JTAG mode is used, I/O port PB4 should not be used by the application. If the application needs to use PB4 even during debug phase, the debugger should use Serial Wire Debug (SWD) mode to connect.

### 2.1.5 Read protection: a mass erase occurs if the RDP register is written with level 0 when level 0 is already set

#### Description

The read protection ranges from the lowest level 0 (no read protection) to level 2 (disable debug/chip read protection). It is always possible to increase the read protection level without any side effects. It is not possible to decrease the protection level from level 2 to a lower level. It is possible to decrease the protection level from level 1 to level 0, but to avoid allowing an access to data that were previously protected, a mass erase of the data EEPROM, the program Flash and the backup registers is performed.

The limitation appears when level 0 is requested (writing 0xAA in the option byte RDP) while the protection level is already at 0. In this case an unwanted mass erase is performed.

#### Workaround

Before setting level 0 in the RDP register, check that the current level is not equal to level 0.

- If the current level is not equal to level 0, level 0 can be activated.
- If the current level is level 0 then the RDP register must not be written again with level 0.

### 2.1.6 In Stop mode, RAMs are not in power down if DMA is enabled

#### Description

In Stop mode, the RAM memories (Main and USB) are not in power-down when DMA1 and/or DMA2 are enabled in the RCC registers. If DMA1 and/or DMA2 are disabled, the RAMs are switched off. This induces an overconsumption of about 200 nA in Stop mode.

#### Workaround

Before entering Stop mode, if the DMA1EN and DMA2EN bits in the RCC\_AHBENR register are enabled then they have to be reset. When the MCU wakes up from Stop mode, the DMA1EN and DMA2EN bits in the RCC\_AHBENR register have to be enabled again (this can be done by the interrupt subroutine).

### 2.1.7 Invalid read from data EEPROM after write in program Flash

#### Description

When a read from data EEPROM in one bank is performed after a write in the program code, the value of the read might be wrong.

This problem can occur even if the write and the read access are separated by a delay of several CPU clock periods.

#### Workaround

In this case, perform two read operations from the same address location in data EEPROM, the first one should be discarded, the second one is correct and the value can be used.

### 2.1.8 Debugging Stop mode with WFE entry

#### Description

When the Stop debug mode is enabled (DBG\_STOP bit set in the DBGMCU\_CR register) this allows the software debugging during Stop mode. However, if the application software uses the WFE instruction to enter Stop mode, after wakeup some instructions could be missed if the WFE is followed by sequential instructions. This affects only Stop debug mode with WFE entry.

#### Workaround

To debug Stop mode with WFE entry, the WFE instruction must be inside a dedicated function with 1 instruction (NOP) between the execution of the WFE and the Bx LR.

Example: `__asm void _WFE(void) {`

`WFE`

`NOP`

`BX LR }`

### 2.1.9 Boot from bank2 limitation

#### Description

The condition is either “Read protection level 2 is set and the Boot pins are configured to boot from the system memory” or “BFB2 option bit is reset (boot from system memory) and the Boot pins are configured to boot from the Internal Main Flash memory”.

In both cases, the Bootloader is executed and checks if there is a valid code in Bank2, then it jumps to it, else if there is a valid code in Bank1 it jumps to it, otherwise it goes to an infinite loop. In case there is a valid code in Bank2 or Bank1, the Bootloader initializes the user code's top-of-stack address, then jumps to execute this code.

Two issues might occur:

1. The first issue is that the top-of-stack address that is initialized by the Bootloader is not the value stored by the linker in the first entry of the vector table, but this value incremented by 8. As a consequence, when the user code starts execution, the stack pointer is corrupted. Two behaviors can then occur depending on how the compiler/linker manages the stack memory:

- The compiler/linker (case of ARM/IAR) places the top of the stack in the first region of the SRAM memory. In this case, the stack corruption overflows the user data located in the adjacent 8-byte memory location.
  - The compiler/linker (case of GNU) places the top of the stack at the top of the SRAM memory. In this case, due to the MSP corruption, the top of the stack is moved beyond the SRAM address boundaries, and when the first stack push occurs a hard fault is generated.
2. The second issue occurs when the top of the stack is set at the top of the SRAM memory (i.e. the first word of the code area points outside the physical SRAM area). In that case, after reset, neither the code in bank1 nor the code in bank2 is executed.

### Workaround

Make sure the compiler/linker used does not place the top of the stack at the top of the SRAM memory.

In the startup file, the user code should force the top-of-stack address before jumping to the main program. This can be done in the “Reset\_Handler” routine using the following instructions:

```
LDR R1,=0x08000000 LDR R0, [R1] msr msp, r0
```

## 2.1.10 Pull-up on PB7 when configured in analog mode

### Description

PB7 can be used as a Power Voltage Detection Input. To select this, the IO is configured in analog mode through GPIOB\_MODER and selected as an external input analog voltage for the PVD level selection through the PLS[2:0] bits in the PWR\_CR register.

When PB7 is configured in analog mode but not selected for the PVD level selection, then an internal pull-up is visible through PB7.

### Workaround

Configuring PB7 to limit power consumption whatever the external connection can be done differently:

1. Keep PB7 in Input mode (default of GPIOB\_MODER)
2. Disconnect the schmidt trigger on PB7 by programming the RI\_HYSCR1

## 2.1.11 Range 1 of dynamic voltage scaling has a lower limit of 2.0 V

### Description

In newest revisions of documents, the range 1 of dynamic voltage scaling is available from VDD = 1.71 V and above. This does not apply to all revisions.

### Workaround

The revisions impacted by this limitation can use range 1 when VDD is equal to or above 2.0 V.

### 2.1.12 Wakeup sequence from Standby mode when using more than one wakeup source

#### Description

The various wakeup sources are logically OR-ed in front of the rising-edge detector which generates the wakeup flag (WUF). The WUF flag needs to be cleared prior to the Standby mode entry, otherwise the MCU wakes up immediately.

If one of the configured wakeup sources is kept high during the WUF flag clearing (by setting the CWUF bit), it may mask further wakeup events on the input of the edge detector. As a consequence, the MCU could not wake up from the Standby mode.

#### Workaround

To avoid this problem, the following sequence should be applied before entering the Standby mode:

1. Disable all used wakeup sources,
2. Clear all related wakeup flags,
3. Re-enable all used wakeup sources,
4. Enter the Standby mode.

*Note:* When applying this workaround, if one of the wakeup sources is still kept high, be aware that the MCU will enter the Standby mode but then wakes up immediately, generating the power reset.

### 2.1.13 Flash memory wakeup issue when waking up from Stop or Sleep with Flash memory in power-down mode

#### Description

When an external wakeup event (EXTI) occurs in a narrow time window around low-power mode entry (Stop or Sleep mode with Flash memory in power-down state), the Flash wakeup time may be increased. As a result, the first data read or the instruction fetch from the Flash memory may be incorrect.

**The probability that this issue occurs is very low since it may happen only during a very narrow time window.**

#### Workarounds

Two workarounds are available:

- Do not put the Flash memory module in power-down mode when entering Sleep or Low-power sleep modes.
- Before entering Stop mode by executing a WFI instruction from the RAM, set the RUN\_PD bit in the FLASH\_ACR register. After exiting from Stop mode, the Flash memory is automatically powered ON and the user can resume program execution from the Flash memory. After wakeup, clear the RUN\_PD bit.



### 2.1.14 Unexpected system reset when waking up from Stop mode with regulator in low-power mode

#### Description

If the device returns to Run mode after waking up from Stop mode while the internal voltage regulator is configured to switch to low-power mode in Stop mode (LPSSDR=1 in PWR\_CR register), an unexpected system reset may occur if the following conditions are met:

- The internal regulator is set to Range 2 or Range 3 before entering Stop mode.
- $V_{DD}$  power supply is below 2.7 V.

**The probability that this issue occurs is very low since it may happen only for very narrow supply voltage windows which vary from one device to another.**

This reset is internal only and does not affect the NRST pin state and the flags in the control/status register (RCC\_CSR).

#### Workarounds

Two workarounds are possible:

- Enter Stop mode with the internal voltage regulator set to main mode (LPSSDR=0 in PWR\_CR).
- Set the internal voltage regulator to Range1 before entering Stop mode.

## 2.2 LCD peripheral limitations

### 2.2.1 High drive resistive network total value too low

#### Description

The value of the high drive resistive network is 60 k $\Omega$  instead of 240 k $\Omega$ , which leads to a higher current consumption when used.

#### Workaround

None.

### 2.2.2 Injection from LCD\_SEG2, LCD\_SEG5, LCD\_SEG21 pins

#### Description

When VLCD is higher than VDDA+0.3V and LCD alternate function is enabled on PA3 or PB0 or PC3 pins (LCD\_SEG2, LCD\_SEG5, LCD\_SEG21) then a current injection internally occurs from those LCD pins into VDDA through the internal protection diodes on those pins (diode connected on shared OPAMP1\_VOUT, OPAMP2\_VOUT, OPAMP3\_VOUT analog pins). The consumption from VLCD supply (internal or external) then increases (~1.5mA).

#### Workaround

If PA3, PB0, PC3 are configured as LCD alternate function (AFIO11: SEG2, SEG5, SEG21) there must be VLCD < VDDA+0.3V.

If VLCD > VDDA+0.3V then do not configure PA3, PB0, PC3 pins for LCD alternate function.

## 2.3 IWDG peripheral limitation

### 2.3.1 RVU and PVU flags are not reset in Stop mode

#### Description

The RVU and PVU flags of the IWDG\_SR register are set by hardware after a write access to the IWDG\_RLR and the IWDG\_PR registers, respectively. If the Stop mode is entered immediately after the write access, the RVU and PVU flags are not reset by hardware.

Before performing a second write operation to the IWDG\_RLR or the IWDG\_PR register, the application software must wait for the RVU or PVU flag to be reset. However, since the RVU/PVU bit is not reset after exiting Stop mode, the software goes into an infinite loop and the independent watchdog (IWDG) generates a reset after the programmed timeout period.

#### Workaround

Wait until the RVU or PVU flag of the IWDG\_SR register are reset before entering Stop mode.

## 2.4 I<sup>2</sup>C peripheral limitations

### 2.4.1 SMBus standard not fully supported

#### Description

The I<sup>2</sup>C peripheral is not fully compliant with the SMBus v2.0 standard since it does not support the capability to NACK an invalid byte/command.

#### Workaround

The following higher-level mechanisms should be used to verify that a write operation is being performed correctly at the target device:

1. The SMBA pin if supported by the host
2. The alert response address (ARA) protocol
3. The host notify protocol

### 2.4.2 Wrong behavior of I<sup>2</sup>C peripheral in Master mode after misplaced STOP

#### Description

The I<sup>2</sup>C peripheral does not enter Master mode properly if a misplaced STOP is generated on the bus and the Start bit is already set in the I2C\_CR2 register. In this case the START condition is not correctly generated on the bus and can create bus errors.

#### Workaround

In the I<sup>2</sup>C standard, it is not allowed to send a STOP before the full byte is transmitted (8 bits + acknowledge). Other derived protocols like CBUS allow it, but they are not supported by the I<sup>2</sup>C peripheral.

In case of noisy environment in which unwanted bus errors can occur, it is recommended to reset the I2C peripheral by setting the SWRST bit in the I2C\_CR2 control register if a BERR is detected while the Start bit is set in the I2C\_CR2 register.

No fix is planned for this limitation.

### 2.4.3 Violation of I<sup>2</sup>C “setup time for repeated START condition” parameter

#### Description

In case of a repeated Start, the “setup time for repeated START condition” parameter (named  $t_{SU(STA)}$  in the datasheet and  $T_{su:sta}$  in the I<sup>2</sup>C specifications) may be slightly violated when the I<sup>2</sup>C operates in Master Standard mode at a frequency ranging from 88 to 100 kHz.  $t_{SU(STA)}$  minimum value may be 4  $\mu$ s instead of 4.7  $\mu$ s.

The issue occurs under the following conditions:

1. The I<sup>2</sup>C peripheral operates in Master Standard mode at a frequency ranging from 88 to 100 kHz (no issue in Fast mode)
2. And the SCL rise time meets one of the following conditions:
  - The slave does not stretch the clock and the SCL rise time is more than 300 ns (the issue cannot occur when the SCL rise time is less than 300 ns).
  - Or the slave stretches the clock.

#### Workaround

Reduce the frequency down to 88 kHz or use the I<sup>2</sup>C Fast mode if it is supported by the slave.

### 2.4.4 In I<sup>2</sup>C slave “NOSTRETCH” mode, underrun errors may not be detected and may generate bus errors

#### Description

The data valid time ( $t_{VD;DAT}$ ,  $t_{VD;ACK}$ ) described by the I<sup>2</sup>C specifications may be violated as well as the maximum current data hold time ( $t_{HD;DAT}$ ) under the conditions described below. In addition, if the data register is written too late and close to the SCL rising edge, an error may be generated on the bus: SDA toggles while SCL is high. These violations cannot be detected because the OVR flag is not set (no transmit buffer underrun is detected).

This issue occurs under the following conditions:

1. The I<sup>2</sup>C peripheral operates In Slave transmit mode with clock stretching disabled (NOSTRETCH=1)
2. and the application is late to write the DR data register, but not late enough to set the OVR flag (the data register is written before the SCL rising edge).

#### Workaround

If the master device supports it, use the clock stretching mechanism by programming the bit NOSTRETCH=0 in the I2C\_CR1 register.

If the master device does not support it, ensure that the write operation to the data register is performed just after TXE or ADDR events. The user can use an interrupt on the TXE or ADDR flag and boost its priority to the higher level or use DMA.

Using the “NOSTRETCH” mode with a slow I<sup>2</sup>C bus speed can prevent the application from being late to write the DR register (second condition).

*Note: The first data to be transmitted must be written into the data register after the ADDR flag is cleared, and before the next SCL rising edge, so that the time window to write the first data into the data register is less than  $t_{LOW}$ .*

*If this is not possible, a possible workaround can be the following:*

1. Clear the ADDR flag
2. Wait for the OVR flag to be set
3. Clear OVR and write the first data.

*The time window for writing the next data is then the time to transfer one byte. In that case, the master must discard the first received data.*

## 2.4.5 10-bit Master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave

### Description

In Master mode, the master automatically sends a STOP bit when the slave has not acknowledged a byte during the address transmission.

In the 10-bit addressing mode, if the first part of the 10-bit address (corresponding to 10-bit header + 2 MSB) has not been acknowledged by the slave, the STOP bit is sent but the Start bit is not cleared and the master cannot launch a new transfer.

### Workaround

When the I2C is configured in 10-bit addressing Master mode and the NACKF status flag is set in the I2C\_ISR register while the Start bit is still set in the I2C\_CR2 register, then proceed as follows:

1. Wait for the STOP condition detection (STOPF = 1 in I2C\_ISR register).
2. Disable the I2C peripheral.
3. Wait for a minimum of 3 APB cycles.
4. Enable the I2C peripheral again.

## 2.5 SPI/I2S peripheral limitations

### 2.5.1 In I2S slave mode, WS level must to be set by the external master when enabling the I2S

#### Description

In slave mode the WS signal level is used only to start the communication. If the I2S (in slave mode) is enabled while the master is already sending the clock and the WS signal level is low (for I2S protocol) or is high (for the LSB or MSB-justified mode), the slave starts communicating data immediately. In this case the master and the slave will be desynchronized throughout the whole communication.

#### Workaround

The I2S peripheral must be enabled when the external master sets the WS line at:

- High level when the I2S protocol is selected.
- Low level when the LSB or MSB-justified mode is selected.

### 2.5.2 Wrong CRC calculation when the polynomial is even

#### Description

When the CRC is enabled, the CRC calculation will be wrong if the polynomial is even.

#### Workaround

Use odd polynomial.

### 2.5.3 BSY bit may stay high at the end of a data transfer in Slave mode

#### Description

The BSY flag may sporadically remain high at the end of a data transfer in Slave mode. The issue appears when an accidental synchronization happens between the internal CPU clock and the external SCK clock provided by the master.

This is related to the end of data transfer detection while the SPI is enabled in Slave mode.

As a consequence, the end of data transaction may be not recognized when the software needs to monitor it (e.g. at the end of session before entering the low-power mode or before direction of data line has to be changed at half duplex bidirectional mode). The BSY flag is unreliable to detect the end of any data sequence transaction.

#### Workaround

When the NSS hardware management is applied and the NSS signal is provided by the master, the end of a transaction can be detected by the NSS polling by the slave.

- If the SPI receiving mode is enabled, the end of a transaction with master can be detected by the corresponding RXNE event signaling the last data transfer completion.
- In SPI transmit mode, the user can check the BSY under timeout corresponding to the time necessary to complete the last data frame transaction. The timeout should be measured from TXE event signaling the last data frame transaction start (it is raised once the second bit transaction is ongoing). Either BSY becomes low normally or the timeout expires when the synchronization issue happens.

When upper workarounds are not applicable, the following sequence can be used to prevent the synchronization issue at SPI transmit mode.

1. Write last data to data register
2. Poll TXE until it becomes high to ensure the data transfer has started
3. Disable SPI by clearing SPE while the last data transfer is still ongoing
4. Poll the BSY bit until it becomes low
5. The BSY flag works correctly and can be used to recognize the end of the transaction.

*Note: This workaround can be used only when CPU has enough performance to disable SPI after the TXE event is detected while the data frame transfer is still ongoing. It is impossible to achieve it when the ratio between CPU and SPI clock is low and the data frame is short especially. In this specific case the timeout can be measured from TXE, while calculating a fixed number of CPU clock periods corresponding to the time necessary to complete the data frame transaction.*

## 2.5.4 Wrong CRC transmitted in Master mode with delayed SCK feedback

### Description

In transmit transaction of the SPI interface in Master mode with the CRC enabled, the CRC data transmission may be corrupted if the delay of an internal feedback signal derived from the SCK output (further feedback clock) is greater than two APB clock periods. While the data and the CRC bit shifting and the transfer is based on an internal clock, the CRC progressive calculation uses the feedback clock. If the delay of the feedback clock is greater than two APB periods, the transmitted CRC value may get wrong.

The main factors contributing to the delay increase are low  $V_{DD}$  level, high temperature, high SCK pin capacitive load and low SCK I/O output speed. The SPI communication speed has no impact.

### Workaround

The following workaround can be adopted, jointly or individually:

- Decrease the APB clock speed.
- Configure the IO pad of the SCK pin to be faster.

[Table 5](#) gives the maximum allowable APB frequency versus the GPIOx\_OSPEEDR output speed control field setting for the SCK pin, at 30 pF of capacitive load.

## 2.5.5 SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI finishes its DMA transaction

### Description

When the SPI is running with the CRC feature enabled at all the modes, the CRC calculation may be frozen and checked corrupted before the CRCNEXT bit is written. It can happen if a peripheral, mapped on the same DMA channel than the SPI, is doing a DMA transfer whereas the SPI is configured to manage data transfers by software (IT or polling). As a consequence the CRC error flag is unduly raised.

### Workaround

There is no known workaround of this conflict. If possible use the DMA for SPI transfers to avoid this conflict.

## 2.5.6 Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback

### Description

In receive transaction, in both I<sup>2</sup>S and SPI Master modes, the last bit of the transacted frame is not captured when the signal provided by internal feedback loop from the SCK pin exceeds a critical delay. The lastly transacted bit of the stored data then keeps the value from the pattern received previously. As a consequence, the last receive data bit may be wrong and/or the CRCERR flag can be unduly asserted in the SPI mode if any data under check sum and/or just the CRC pattern is wrongly captured.

In SPI mode, data are synchronous with the APB clock. A delay of up to two APB clock periods can thus be tolerated for the internal feedback delay. The I<sup>2</sup>S mode is more sensitive than the SPI mode since the SCK clock is not synchronized with the APB clock. In this case, the margin of the internal feedback delay is lower than one APB clock period.

The main factors contributing to the delay increase are low V<sub>DD</sub> level, high temperature, high SCK pin capacitive load and low SCK I/O output speed. The SPI communication speed has no impact.

### Workaround

The following workaround can be adopted, jointly or individually:

- Decrease the APB clock speed.
- Configure the IO pad of the SCK pin to be faster.

[Table 5](#) gives the maximum APB frequency versus the GPIOx\_OSPEEDR output speed control field setting for the SCK pin, at 30 pF of capacitive load.

**Table 5. Maximum allowable APB frequency at 30 pF load**

Setting of OSPEEDR bits [1:0] for the SCK pin	Maximum APB frequency for SPI [MHz]	Maximum APB frequency for I2S [MHz]
Very high (11)	32	32
High (10)	28 (30 if VDD > 1.8 V)	28 (30 if VDD > 1.8 V)
Medium (01)	11 (13 if VDD > 1.8 V)	8 (9 if VDD > 1.8 V)
Low (00)	2	1.5



## 2.6 USART peripheral limitations

### 2.6.1 Idle frame is not detected if receiver clock speed is deviated

#### Description

If the USART receives an idle frame followed by a character, and the clock of the transmitter device is faster than the USART receiver clock, the USART receive signal falls too early when receiving the character start bit, with the result that the idle frame is not detected (IDLE flag is not set).

#### Workaround

None.

### 2.6.2 In full duplex mode, the Parity Error (PE) flag can be cleared by writing the data register

#### Description

In full duplex mode, when the Parity Error flag is set by the receiver at the end of a reception, it may be cleared while transmitting by reading the USART\_SR register to check the TXE or TC flags and writing data in the data register.

Consequently, the software receiver can read the PE flag as '0' even if a parity error occurred.

#### Workaround

The Parity Error flag should be checked after the end of reception and before transmission.

### 2.6.3 Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection

#### Description

The USART receiver is in Mute mode and is configured to exit the Mute mode using the address mark detection. When the USART receiver recognizes a valid address with a parity error, it exits the Mute mode without setting the Parity Error flag.

#### Workaround

None.

### 2.6.4 Break frame is transmitted regardless of nCTS input line status

#### Description

When the CTS hardware flow control is enabled (CTSE = 1) and the Send Break bit (SBK) is set, the transmitter sends a break frame at the end of current transmission regardless of nCTS input line status.

Consequently, if an external receiver device is not ready to accept a frame, the transmitted break frame is lost.

**Workaround**

None.

**2.6.5 nRTS signal abnormally driven low after a protocol violation****Description**

When the RTS hardware flow control is enabled, the nRTS signal goes high when a data is received. If this data was not read and a new data is sent to the USART (protocol violation), the nRTS signal goes back to low level at the end of this new data.

Consequently, the sender gets the wrong information that the USART is ready to receive further data.

On the USART side, an overrun is detected which indicates that some data has been lost.

**Workarounds**

Workarounds are required only if the other USART device violates the communication protocol which is not the case in most applications.

Two workarounds can be used:

- After data reception and before reading in the data in the data register, the software takes over the control of the nRTS signal as a GPIO and holds it high as long as needed. If the USART device is not ready, the software holds the nRTS pin high, and releases it when the device is ready to receive new data.
- The time required by the software to read the received data must always be lower than the duration of the second data reception. For example, this can be ensured by treating all the receptions by DMA mode.

**2.6.6 Start bit detected too soon when sampling for NACK signal from the smartcard****Description**

In the ISO7816, when a character parity error is incorrect, the smartcard receiver shall transmit a NACK error signal at  $(10.5 \pm 0.2)$  etu after the character Start bit falling edge. In this case, the USART transmitter should be able to detect correctly the NACK signal by sampling at  $(11.0 \pm 0.2)$  etu after the character Start bit falling edge.

The USART peripheral used in smartcard mode doesn't respect the  $(11 \pm 0.2)$  etu timing, and when the NACK falling edge arrives at 10.68 etu or later, the USART might misinterpret this transition as a Start bit even if the NACK is correctly detected.

**Workaround**

None.

## 2.6.7 Break request can prevent the Transmission Complete flag (TC) from being set

### Description

After the end of transmission of a data (D1), the Transmission Complete (TC) flag will not be set in the following conditions:

- CTS hardware flow control is enabled.
- D1 is being transmitted.
- A break transfer is requested before the end of D1 transfer.
- nCTS is de-asserted before the end of transfer of D1.

### Workaround

If the application needs to detect the end of transfer of the data, the break request should be done after making sure that the TC flag is set.

## 2.6.8 Guard time is not respected when data are sent on TXE events

### Description

In smartcard mode, when sending a data on TXE event, the programmed guard time is not respected. The data written in the data register are transferred on the bus without waiting for the completion of the guardtime duration corresponding to the previous transmitted data.

### Workaround

Write the data after TC is set because in smartcard mode, the TC flag is set at the end of the guard time duration.

## 2.6.9 nRTS is active while RE or UE = 0

### Description

The nRTS line is driven low as soon as the RTSE bit is set even if the USART is disabled (UE = 0) or the receiver is disabled (RE = 0) i.e. not ready to receive data.

### Workaround

Configure the I/O used for nRTS as alternate function after setting the UE and RE bits.

## 2.7 SDIO peripheral limitations

### 2.7.1 SDIO hardware flow control

#### Description

When enabling the hardware flow control by setting the bit 14 of the SDIO\_CLKCR register to '1', glitches can occur on the SDIOCLK output clock resulting in wrong data being written to the SD/MMC card or to the SDIO device. As a consequence, a CRC error is returned to the SD/SDIO MMC host interface (DCRCFAIL bit set to '1' in the SDIO\_STA register).

#### Workaround

There is no workaround. Do not use the hardware flow control. Overrun errors (Rx mode) and FIFO underrun (Tx mode) should be managed by the application software.

### 2.7.2 Wrong CCRCFAIL status after a response without CRC

#### Description

When a command is followed by a response which does not contain a CRC field, the CRC is calculated anyway. Consequently, after the SDIO command IO\_SEND\_OP\_COND (CMD5), the CCRCFAIL bit of the SDIO\_STA register is set.

#### Workaround

In this case the CCRCFAIL bit in the SDIO\_STA register must be ignored by software. CCRCFAIL must be cleared by setting the CCRCFAILC bit in the SDIO\_ICR register after reception of the response to the CMD5 command.

### 2.7.3 No underrun detected and wrong data transmission

#### Description

When a data transfer from SDIO host to card is on going and the HW Flow Control is disabled (bit 14 of the SDIO\_CLKCR is not set) and an underrun condition occurs, the controller may transmit a wrong data without detecting that an underrun condition occurs if the following clock frequencies relationship is verified:  
$$[3 \times \text{period}(\text{APBClock}) + 3 \times \text{period}(\text{SDIOCLK})] \geq (32 / (\text{BusWidth})) \times \text{period}(\text{SDIO\_CK})$$

#### Workaround

Ensure that the following clock frequencies relationship is verified:  
$$[3 \times \text{period}(\text{APBClock}) + 3 \times \text{period}(\text{SDIOCLK})] < (32 / (\text{BusWidth})) \times \text{period}(\text{SDIO\_CK})$$

by:

- Incrementing the APB frequency,
- or decreasing the transfer bandwidth,
- or reducing the SDIO\_CK frequency.

## 2.7.4 CE-ATA multiple write command and card busy signal management

### Description

The CE-ATA card may inform the host that it is busy by driving low the SDIO\_D0 line, two cycles after the transfer of a write command (RW\_MULTIPLE\_REGISTER or RW\_MULTIPLE\_BLOCK). When the card is in busy state, the host must not send any data until the BUSY signal is de-asserted (SDIO\_D0 released by the card).

This condition is not respected if the data state machine leaves the IDLE state (Write operation programmed and started DTEN = 1, DTDIR = 0 in SDIO\_DCTRL register and TXFIFOE = 0 in SDIO\_STA register).

As consequence, the write transfer fails and the data lines are corrupted.

### Workaround

After having sent the write command (RW\_MULTIPLE\_REGISTER or RW\_MULTIPLE\_BLOCK), the software must check that the card is not busy by polling the BSY bit of the ATA status register using FAST\_IO (CMD39) command before enabling the data state machine.

## 2.8 FSMC peripheral limitation

### 2.8.1 FSMC NOR Flash/PSRAM controller asynchronous access on bank2..4 when bank1 is in synchronous mode (CBURSTRW bit is set)

#### Description

If the bank1 of NOR/PSRAM controller is enabled in synchronous write mode (CBURSTRW bit is set), while any other NOR/PSRAM bank 2..4 is enabled in asynchronous mode, there are two issues:

- For the first write access to the asynchronous memory, the NBL[1:0] byte lane is not active (kept high).
- A write access to an asynchronous memory with extended feature enabled, the system hangs without any fault generation. The two issues occur only when the NOR/PSRAM bank1 is configured in synchronous write mode (CBURSTRW bit is set).

#### Workaround

If multiple banks are enabled with a mixed asynchronous and synchronous write access, use any NOR/PSRAM bank for a synchronous write access except bank1.

## 2.8.2 FSMC synchronous mode and disabled NWAIT signal

### Description

In case of FSMC synchronous mode with the NWAIT signal disabled, if the polarity (WAITPOL in the FSMC\_BCRx register) of the NWAIT signal is same as the NWAIT input signal level, the system hangs and no fault generated. Only a system reset will recover.

### Workaround

PD6 (NWAIT signal) must not be connected to AF12 and configure the NWAIT polarity to active high (set WAITPOL bit to 1 in FSMC\_BCRx register).

## 2.8.3 Dummy read cycles inserted when reading synchronous memories

### Description

When performing a burst read access to a synchronous memory, two dummy read accesses are performed at the end of the burst cycle whatever the type of AHB burst access. However, the extra data values which are read are not used by the FSMC and there is no functional failure.

### Workaround

none.

## 2.9 DAC peripheral limitations

### 2.9.1 Spurious activation of DAC output buffer (PA4 and PA5)

#### Description

The high speed signal with a falling edge and a slope higher than 7V/us can cause a spurious activation of the DAC buffer if applied on the pins PA4 and PA5. Such spurious activation can happen regardless of the GPIO configuration and it may pull a current from the signal source up to 1 mA in the typical conditions. As a result of this unintended DAC buffer pulling, a shape of the falling edge may change and cause a shifted timing of the digital signal applied on the pin.

#### Workarounds

- Use another IO with an equivalent function.
- Reduce the slope of the signal applied on the affected pins.

## 2.10 RCC peripheral limitation

### 2.10.1 Delay after an RCC peripheral clock enabling

#### Description

A delay between an RCC peripheral clock enable and the effective peripheral enabling should be taken into account in order to manage the peripheral read/write to registers.

This delay depends on the peripheral's mapping:

- If the peripheral is mapped on AHB: the delay should be equal to 2 AHB cycles.
- If the peripheral is mapped on APB: the delay should be equal to 1 + (AHB/APB prescaler) cycles.

#### Workarounds

1. Use the DSB instruction to stall the Cortex-M CPU pipeline until the instruction is completed.
2. Insert "n" NOPs between the RCC enable bit write and the peripheral register writes (n = 2 for AHB peripherals, n = 1 + AHB/APB prescaler in case of APB peripherals).

## 2.11 RTC limitation

### 2.11.1 Spurious tamper detection when disabling the tamper channel

#### Description

If the tamper detection is configured for detection on the falling edge event (TAMPFLT=00 and TAMPxTRG=1) and if the tamper event detection is disabled when the tamper pin is at high level, a false tamper event is detected.

#### Workaround

None.

### 2.11.2 RTC calendar registers are not locked properly

#### Description

When reading the calendar registers with BYPSHAD=0, the RTC\_TR and RTC\_DR registers may not be locked after reading the RTC\_SSR register. This happens if the read operation is initiated one APB clock period before the shadow registers are updated. This can result in a non-consistency of the three registers. Similarly, the RTC\_DR register can be updated after reading the RTC\_TR register instead of being locked.

#### Workaround

1. Use BYPSHAD = 1 mode (Bypass shadow registers), or
2. If BYPSHAD = 0, read SSR again after reading SSR/TR/DR to confirm that SSR is still the same, otherwise read the values again.

### 3 Revision history

Table 6. Document revision history

Date	Revision	Changes
14-Feb-2015	1	Initial release.
22-Jun-2015	2	<p>Removed appendix A section: all package markings put in the corresponding datasheets.</p> <p>Added USART limitations:</p> <ul style="list-style-type: none"> <li>- <i>Section 2.6.6: Start bit detected too soon when sampling for NACK signal from the smartcard.</i></li> <li>- <i>Section 2.6.7: Break request can prevent the Transmission Complete flag (TC) from being set.</i></li> <li>- <i>Section 2.6.8: Guard time is not respected when data are sent on TXE events.</i></li> <li>- <i>Section 2.6.9: nRTS is active while RE or UE = 0.</i></li> </ul> <p>Added SPI limitation:</p> <ul style="list-style-type: none"> <li>- <i>Section 2.5.2: Wrong CRC calculation when the polynomial is even.</i></li> </ul> <p>Added RTC limitation:</p> <ul style="list-style-type: none"> <li>- <i>Section 2.11.1: Spurious tamper detection when disabling the tamper channel.</i></li> </ul>
16-Nov-2015	3	<p>Updated cover adding revision X.</p> <p>Updated <i>Table 4: Summary of silicon limitations</i> adding revision X with same limitations as revision Y.</p> <p>Added 2 system limitations fixed by revision X:</p> <ul style="list-style-type: none"> <li>- <i>Section 2.1.13: Flash memory wakeup issue when waking up from Stop or Sleep with Flash memory in power-down mode.</i></li> <li>- <i>Section 2.1.14: Unexpected system reset when waking up from Stop mode with regulator in low-power mode.</i></li> </ul>
21-Nov-2016	4	<p>Added I<sup>2</sup>C limitation:</p> <ul style="list-style-type: none"> <li>- <i>Section 2.4.5: 10-bit Master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave.</i></li> </ul> <p>Added RTC limitation:</p> <ul style="list-style-type: none"> <li>- <i>Section 2.11.2: RTC calendar registers are not locked properly.</i></li> </ul> <p>Added DAC limitation:</p> <ul style="list-style-type: none"> <li>- <i>Section 2.9.1: Spurious activation of DAC output buffer (PA4 and PA5).</i></li> </ul> <p>Added SPI limitations:</p> <ul style="list-style-type: none"> <li>- <i>Section 2.5.3: BSY bit may stay high at the end of a data transfer in Slave mode.</i></li> <li>- <i>Section 2.5.4: Wrong CRC transmitted in Master mode with delayed SCK feedback.</i></li> <li>- <i>Section 2.5.5: SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI finishes its DMA transaction.</i></li> <li>- <i>Section 2.5.6: Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback.</i></li> </ul>



**IMPORTANT NOTICE – PLEASE READ CAREFULLY**

STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST's terms and conditions of sale in place at the time of order acknowledgement.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of Purchasers' products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2016 STMicroelectronics – All rights reserved