

Case: 03908134

Case Number	03908134 [View Hierarchy]	Account Name	Wingtech Mobile Communications Co., Ltd.
Parent Case		Contact Name	zk zk
Customer Tracking Number		Contact Email	zk_sw@wingtech.com
Status	Customer Updated Case	Contact Phone	
Priority	1 - Critical	Date/Time Opened	3/5/2019 12:45 AM
Important to me	<input type="checkbox"/>	Date/Time Closed	
Customer Project	T89239-AndroidO-Upgrade		
Expected Resolution Date			
Any CR Related To This Case	No		
Related CRs			
Feature Request	<input type="checkbox"/>		

Customer Project or Hardware Configuration

Customer Project	T89239-AndroidO-Upgrade		
Chipset	MSM8917		
PM	<div>None</div> <div>Other</div> <div>PMI8937</div> <div>PMI8952</div> <div>PM8937</div>		
Other PM IC			
Transceiver	<div>None</div> <div>Other</div>	WTR2965	Power Amplifier/Module
			<div>Third Party</div> <div>QFE2340</div> <div>QFE4320</div> <div>QPA4340</div> <div>QPA4360</div> <div>None</div>
Antenna Tuner	<div>Third Party</div> <div>QAT2514</div> <div>QAT3514</div> <div>QAT3514 (x2)</div> <div>QAT3514 (x3)</div> <div>None</div>		PA Power Management IC
			<div>Third Party</div> <div>QFE2101</div> <div>None</div>
Antenna Switch/Module	<div>QSW6310</div> <div>QSW8573</div> <div>QSW8574</div> <div>None</div>		LNA/Module
			<div>Other</div> <div>None</div>
			DRX Module
			<div>Other</div> <div>None</div>
			Antenna Switch Diversity
			<div>Other</div> <div>None</div> <div>QAT2522</div>
			60Ghz (WiGig) IC/Module
Other RF IC			Bluetooth IC/Module
WLAN IC/Module	WCN3615		WCN3615
Summit DC/DC Converter			NFC IC/Module
			No NFC
AMSS/DMSS Software			
AMSS/DMSS Software	AMSS8917		
AMSS/DMSS Build ID	MSM8917.LA.3.1.2-00340-STD.PROD-1		
OS Version			
Official SBA Delivered	<input type="checkbox"/>	Official SBA Delivery Date	
Brew Software			
Brew Version			
BREW PEK Version			

TAM Comments

External TAM Comments

Problem Description Information

Subject [P] 【VTS】 VtsHalSensorsV1_0Target模块测试fail

Description 【Issue Description】 : 1. 测试VTS的VtsHalSensorsV1_0Target模块出现fail
【Failure Rate in %】 : 100%
【Reproduce Step】 : 进行VTS测试

【Initial Analysis】: 通过log没有看出什么异常，请帮忙看看
【Contact Name/Email/Phone】: 18251987979

Operating System

Type of Lab Used

Lab Region

Lab

Case Type

Problem Area 1

Problem Area 2

Problem Area 3

Is this a Security Vulnerability?

Interoperability device

Software Tool Problem?

China

Shanghai Tejet Communications

Bug/Issue

BSP/HLOS

Drivers - Peripheral

Sensors - AP

☐

☐

Air-Interface Technology

Feature Request

Feature Name

Feature Description

Justification

OEM/Target Equipment

SmartPhone

Desired Delivery Date

Future Product

CR Info

Resolution Information

Customer Closing Comments

Case Team List

Case Team

Add Team Member

Add PreDefined Case Team

No records to display

Service Task

Service Tasks

No record(s) to display

Contact Information

Name	zk zk	Customer Number	163692
Account Name	Wingtech Mobile Communications Co., Ltd.	Contact Number	3507942
Company Name	Wingtech Mobile Communications Co., Ltd.	Email	zk_sw@wingtech.com
Division Name		Created By	tibco provision, 2/8/2018 7:19 PM
Contact Office Country	China	Start Date	2/9/2018 3:16 AM
		End Date	
		Contact Export Flag	

System Information

Contact Owner

tibco provision

Last Modified By

tibco provision, 1/4/2019 12:42 AM

NEW Case Attachments

diag_log_20190319_1403101552975390308.isf

Description

Isf

Uploaded By

Customer

Owner Alias

zk_sw

Import Date

3/19/2019 1:23 AM

File Size

7.673 MB

Created Date

3/19/2019

Visible to Customer

☒

new_sensor_log-0319.tar.gz

Description

new log

Uploaded By

Customer

Owner Alias

zk_sw

Import Date

3/18/2019 11:21 PM

File Size

1.772 MB

Created Date

3/18/2019

Visible to Customer

☒

diag_log_20190226_0617091551161829130.isf

Description

isf

Uploaded By

Customer

Owner Alias

zk_sw

Import Date

3/14/2019 11:14 PM

File Size

8.631 MB

Created Date

3/14/2019

Visible to Customer

☒

vt-sensor-0314.tar.gz

Description **vt test qxdm & ap log**
 Uploaded By **Customer**
 Owner Alias **zk_sw**
 Import Date **3/14/2019 2:05 AM**
 File Size **3.494 MB**
 Created Date **3/14/2019**
 Visible to Customer ☒

lsm6ds3.tar.gz

Description **driver&config**
 Uploaded By **Customer**
 Owner Alias **zk_sw**
 Import Date **3/12/2019 8:01 PM**
 File Size **87.860 KB**
 Created Date **3/12/2019**
 Visible to Customer ☒

8917-sns.tar.gz

Description **lsm6ds3**
 Uploaded By **Customer**
 Owner Alias **zk_sw**
 Import Date **3/12/2019 1:48 AM**
 File Size **5.380 KB**
 Created Date **3/12/2019**
 Visible to Customer ☒

sns-reg.about-html.tar.gz

Description **about & sns reg**
 Uploaded By **Customer**
 Owner Alias **zk_sw**
 Import Date **3/12/2019 12:44 AM**
 File Size **3.035 KB**
 Created Date **3/12/2019**
 Visible to Customer ☒

20190311.rar

Description **20190311.rar**
 Uploaded By **Customer**
 Owner Alias **zk_sw**
 Import Date **3/10/2019 7:44 PM**
 File Size **813.508 KB**
 Created Date **3/10/2019**
 Visible to Customer ☒

sns_log-0307.isf

Description **sns_log-0307.isf**
 Uploaded By **Customer**
 Owner Alias **zk_sw**
 Import Date **3/7/2019 1:48 AM**
 File Size **11.554 MB**
 Created Date **3/7/2019**
 Visible to Customer ☒

dumpsys_sensorservice.txt

Description **dumpsys_sensorservice.txt**
 Uploaded By **Customer**
 Owner Alias **zk_sw**
 Import Date **3/6/2019 6:09 PM**
 File Size **19.550 KB**
 Created Date **3/6/2019**
 Visible to Customer ☒

2019.03.05_16.27.08.rar

Description **log**
 Uploaded By **Customer**
 Owner Alias **zk_sw**
 Import Date **3/5/2019 12:46 AM**
 File Size **232.436 KB**
 Created Date **3/5/2019**
 Visible to Customer ☒

2019.03.05_16.27.08.zip

Description **result**
 Uploaded By **Customer**
 Owner Alias **zk_sw**
 Import Date **3/5/2019 12:46 AM**
 File Size **13.635 KB**
 Created Date **3/5/2019**
 Visible to Customer ☒

Case Comments**3/20/2019 2:08 AM**User **zk zk****3/20/2019 1:29 AM**User **Jianyun Kang**

Comment	非常感谢！ BRs	Comment	Dear Customer , 需求是1hz , 实际平均上报速率1.15hz , 这其实也是满足功能. 要求 , vts要求的实际测试速率范围为0.9hz~1.1hz , 所以失败 一般的驱动是不支持1hz的 , 是smgr通过最小的odr去过滤 , 对于该case来说 , 选择26hz , 实际测试速率可以控制在0.9hz 如果是在测试maxRate时失败 , 也可以采取去掉208以上的odr Thanks !
3/20/2019 12:59 AM		3/19/2019 11:14 PM	
User	zk zk	User	Jianyun Kang
Comment	Dears: 移除ODR 13之后复测可以pass , 请帮忙解释下原因 ? 是从qxdm log里定位出问题吗 ? BRs	Comment	Dear Customer , stm_lsm6dsm_gyr_odr_lsm6dsm_gyr_odr_reg_values[S166 // STM_LSM6DSM_GYR_ODR13, 67 STM_LSM6DSM_GYR_ODR26, 68 STM_LSM6DSM_GYR_ODR52, 69 STM_LSM6DSM_GYR_ODR104, 70 STM_LSM6DSM_GYR_ODR208, 71 STM_LSM6DSM_GYR_ODR416, 72 STM_LSM6DSM_GYR_ODR833, 73 STM_LSM6DSM_GYR_ODR1660, 74 } ; 75 Thanks!
3/19/2019 11:06 PM		3/19/2019 10:37 PM	
User	zk zk	User	Jianyun Kang
Comment	dears 目前看lsm6ds3的代码最小odr=13 , 你所说的移除odr=13具体是指将odr最小修改到多少 ?	Comment	Dear Customer , please try to remove the ODR 13 in gyro sensor and test Thanks !
3/19/2019 1:24 AM		3/19/2019 12:20 AM	
User	zk zk	User	Jianyun Kang
Comment	sorry,忘记转换了 , 已经上传 BRs	Comment	Dear Customer , 我这边正在下载安装qcat工具 , 但是由于网络原因 , 可能会稍将qxdm log转化为isf格式或者txt格式上传 ? 下次应该就不需 非常感谢您的协助。
3/18/2019 11:22 PM		3/18/2019 8:18 PM	
User	zk zk	User	zk zk
Comment	Dears: 新的log已上传 , 请帮忙再对应check下 !	Comment	ok , 了解 , 我稍后重新抓取一份时间戳同步的log
3/18/2019 7:01 PM		3/18/2019 6:40 PM	
User	Jianyun Kang	User	zk zk
Comment	Dear Customer , 1.陀螺仪本身不依赖加速度 , 但是如果您有这个校准的想法 , 您可以给这些sensor校准以后进行复测。 2.现在分析问题 , 不能精准的定位到smgr的行为 , 行为上层device_logcat_test_346270835439244207 , host_log_3205686682519380374的时间戳一个是2月的 , 一个是3月的 , 是否可以将设备的时间戳调整到与ap的时间戳一致 ? 这样我可以看到GyroscopeSamplingPeriodHotSwitchOperation测试的时候 , adsp端的rate是多少 , 理论上是1 , 但是现在提供的qxdm log看不出来。 3.现在的问题就是测试频率为1.16hz左右 , 与申请频率有一点偏差 , 所以失败。 Thanks !	Comment	Dears: 因为我们目前BP没有升级 , 所以checked O版本下的如下参数 #define SNS_SMGR_ENFORCED_MAX_FREQ_GYRO 250 另外 , 为了保证机器状态 , 我重新刷了O版本之后再升级到PA hardware/interfaces/sensors/1.0/vts/functional/VtsHalSerExpected: (std::abs(maxDelayAverageInterval - maxSamplingPeriodInNs / 10) , actual: 182700702 vs 1001 另外想确认下 , 陀螺仪这块是否也需要依赖于gsensor数据 , BRs
3/17/2019 8:47 PM		3/15/2019 3:45 AM	
User	Jianyun Kang	User	Jianyun Kang
Comment	Dear Customer , 请尝试以下修改再进行测试。 Sns_smgr_init.c (sensorslsmgrlsrc) -#define SNS_SMGR_ENFORCED_MAX_FREQ_GYRO 200 +#define SNS_SMGR_ENFORCED_MAX_FREQ_GYRO 250 Thanks !	Comment	Dear Customer , 现在遇到的问题是device_logcat_test_34627083543924420 host_log_3205686682519380374时间不一样 , 而hal层中的时候开始测试的 , adsp的时间戳就找不到 , 我这边再看看 , 因为的。 Thanks !
3/15/2019 12:18 AM		3/14/2019 10:34 PM	
User	zk zk	User	Jianyun Kang
Comment	Dear sir: isf文件已上传 , 从log里看有下不同的odr ; 请协助check下 BRs	Comment	Dear Customer , 1.抱歉 , 我这边不能转 , 请转换并上传。 2.lsm6ds3最小odr = 13hz , 代码里最小的odr确实是13 , 但 Thanks !
3/14/2019 8:25 PM		3/14/2019 6:52 PM	
User	zk zk	User	Jianyun Kang
Comment	.qmdl格式的 , 可以使用QXDM工具转换到isf~ BRs	Comment	Dear Customer , 哪个是您的qxdm log ? 是否可以转成isf格式或者txt格式上传 Thanks !
3/14/2019 2:30 AM		3/13/2019 11:29 PM	
User	zk zk	User	Jianyun Kang
Comment	Dear sir : ap setprop开启 sensor hal log ,并抓取了对应测试的adsp log , 请再帮忙确认下 ; 另外我看到代码里面 , lsm6ds3最小odr = 13hz 如有发现 , 请帮忙更新或电话 13002572935 dihongwei	Comment	SensorsContext.cpp
3/12/2019 10:52 PM			
User	Jianyun Kang		
Comment	Dear Customer , 请联系vendor获取最新驱动。为什么申请的ODR是13 , 返回的是26 ? [0053/0001] MSG 07:16:19.729 SNS/Medium [sns_smgr_util.c 307] get_adj_odrs - lower=13 given=0xF0000/15 higher=26 Thanks !		
3/12/2019 6:52 PM			
User	Jianyun Kang		
Comment	Dear Customer , 抱歉 , 给您修改是bmi160的 , 请上传您的陀螺仪驱动代码。 上传sensor_def_qcondev.conf		

	Thanks !		<div>void SensorsContext::enableLogging() { int debug_prop_len; char debug_prop[PROPERTY_VALUE_MAX]; ... } + g_hal_log_level = HAL_LOG_LEVEL_ALL; }</div>
<div>3/12/2019 1:42 AM</div>			
User	Jianyun Kang		
	Dear Customer , 1.设备上陀螺仪功能可以用吗？看着识别出来的参数都是0啊 item-registry-ID: name: value... 1918-1919: UUID: NULL 00000000-0000-0000-0000-000000000000 1920: off_to_idle: 0 1921: idle_to_ready: 0 1922: i2c_bus: 0x00 1923: reg_group_id: 0 1924: cal_grp_id: 0 1925: gpio1: 0x0000 1926: gpio2: 0x0000 1927: sensor_id: 0 1928: i2c_address: 0x00 1929: data_type1: 0 1930: data_type2: 0 1931: rel_sns_idx: 0 1932: sens_default: 0 1933: flags: 0x00 1983: device_select: 0 1983: vdd_rail: 0 1983: vddio_rail: 0 drv_cfg[2] 2.请上传sensor_def_qcondev.conf文件。 3.请修改adsp_proc/Sensors/dd/qcom/src/sns_dd_bmi160.h 进行测试。 -#define BMI160_CONFIG_GYR_LOWEST_ODR 25 +#define BMI160_CONFIG_GYR_LOWEST_ODR 13		
Comment	Thanks !		
<div>3/12/2019 1:07 AM</div>			
User	Jianyun Kang		
	Dear Customer , 1.设备上陀螺仪功能可以用吗？看着识别出来的参数都是0啊 item-registry-ID: name: value... 1918-1919: UUID: NULL 00000000-0000-0000-0000-000000000000 1920: off_to_idle: 0 1921: idle_to_ready: 0 1922: i2c_bus: 0x00 1923: reg_group_id: 0 1924: cal_grp_id: 0 1925: gpio1: 0x0000 1926: gpio2: 0x0000 1927: sensor_id: 0 1928: i2c_address: 0x00 1929: data_type1: 0 1930: data_type2: 0 1931: rel_sns_idx: 0 1932: sens_default: 0 1933: flags: 0x00 1983: device_select: 0 1983: vdd_rail: 0 1983: vddio_rail: 0 drv_cfg[2] 2.请上传sensor_def_qcondev.conf文件。 3.请修改adsp_proc/Sensors/dd/qcom/src/sns_dd_bmi160.h 进行测试。 -#define BMI160_CONFIG_GYR_LOWEST_ODR 25 +#define BMI160_CONFIG_GYR_LOWEST_ODR 25		
Comment	Thanks !		
<div>3/11/2019 7:34 PM</div>			
User	Jianyun Kang		
Comment	Dear customer, 请运行adb shell sns_regedit_ssi -r命令并反馈运行结果。 Thanks !		
<div>3/11/2019 2:13 AM</div>			
User	zk zk		
Comment	1. 这个我测试报错还是gyro的，而且基本log开关也都开了 2. SMGR_BUFFER_SIZE在adsp代码没找到		
<div>3/10/2019 7:45 PM</div>			
User	zk zk		
Comment	重新抓取了AP log：20190311.rar，请查收		
<div>3/7/2019 5:44 PM</div>			
User	zk zk		
Comment	03-08 09:40:37 I/ConsoleReporter: [14/36 arm64-v8a VtsHalSensorsV1_0Target J3AXGYN0171832C] VtsHalSensorsV1_0Target#SensorsHidTest.GyroscopeSamplingPeriodHotSwitchOperation(default)_64bit fail: hardware/interfaces/sensors/1.0/vts/functional/VtsHalSensorsV1_0TargetTest.cpp:1183 Expected: (std::abs(maxDelayAverageInterval - maxSamplingPeriodInNs) < (maxSamplingPeriodInNs / 10), actual: 144913164 vs 100000000		
<div>3/6/2019 11:46 PM</div>			
User	Jianyun Kang		
Comment	Dear customer, 现在gyro是工作在什么模式？polling，DRI 还是fifo？可以修改为fifo模式进行测试。 Thanks !		
<div>3/6/2019 6:23 PM</div>			
User	zk zk		
Comment	LSM6DS3		
<div>3/6/2019 5:37 PM</div>			
User	Jianyun Kang		
Comment	Dear customer, 最好还是运行一下adb shell dumpsys sensorservice，这样可以看一下驱动现在支持的最小频率是多少。 不修改驱动，这项测试应该过不了。 Thanks !		
<div>3/6/2019 12:47 AM</div>			
User	zk zk		
Comment	03-06 16:14:47 I/ConsoleReporter: [14/36 arm64-v8a VtsHalSensorsV1_0Target J3AXGYN0171832C] VtsHalSensorsV1_0Target#SensorsHidTest.GyroscopeSamplingPeriodHotSwitchOperation(default)_64bit		
			<div>void SensorsContext::enableLogging() { int debug_prop_len; char debug_prop[PROPERTY_VALUE_MAX]; ... } + g_hal_log_level = HAL_LOG_LEVEL_ALL; }</div>
<div>3/12/2019 8:09 PM</div>			
User	zk zk		
Comment	config & driver已上传		
<div>3/12/2019 1:49 AM</div>			
User	zk zk		
Comment	新的注册表信息已上传， 并且gyro功能正常，sns_cm_test -s 10 -d 10 -r 10 测试正常 BRs		
<div>3/12/2019 1:40 AM</div>			
User	zk zk		
Comment	sorry sir : 这次抓取的这个机器不支持gyro，稍后重新抓取提供下~ 另外，需要将odr蚕食从25修改到多少？ BRs		
<div>3/12/2019 12:45 AM</div>			
User	zk zk		
Comment	Dears: about html和sns_reg注册表信息已上传，请知悉		
<div>3/11/2019 6:54 PM</div>			
User	Jianyun Kang		
Comment	Dear customer, 是否可以上传about.html文件，我这边确认一下您的版本。 Thanks !		
<div>3/11/2019 2:09 AM</div>			
User	Jianyun Kang		
Comment	Dear customer, 现在的问题就是实际测试速率偏大。 1.上传的logcat没有gyro的log信息。 2.请确认您的adsp代码是否有SMGR_BUFFER_SIZE 的定义。 Thanks !		
<div>3/8/2019 1:29 AM</div>			
User	Jianyun Kang		
Comment	Dear customer, logcat中，看着没有打开sensor ap debug log，请参考KBA AP sensor log 再次抓取测试log。 Thanks !		
<div>3/7/2019 1:16 AM</div>			
User	zk zk		
Comment	#gyro1 LSM6DS3 2103 0x0b25b8431bfd46bc 0x00010001 #UUID 2102 0xc14075963795c661 0x00010001 #UUID 2104 200000 0x00010001 #off_to_idle 2105 250000 0x00010001 #idle_to_ready 2106 41 0x00010001 #gpio1 2107 1010 0x00010001 #reg_group_id 2108 10 0x00010001 #cal_grp_id 2109 4 0x00010001 #i2c_bus 2110 0X6A 0x00010001 #i2c_address 2111 3 0x00010001 #sens_default 2112 0xD0 0x00010001 #flag 2168 0x8E 0x00010001 #vdd 2169 0x8E 0x00010001 #vddio		
<div>3/6/2019 11:38 PM</div>			
User	Jianyun Kang		
Comment	Dear customer, hardware/interfaces/sensors/1.0/vts/functional/VtsHalSer Expected: (std::abs(maxDelayAverageInterval - maxSampl (maxSamplingPeriodInNs / 10), actual: 144850797 vs 1000000000 maxSamplingPeriodInNs = 1000000000 *10 = 1000000000 r 1hz (申请测试速率) maxDelayAverageInterval = 1000000000 - 144850797 = 85 >test minrate ~1.16hz (实际测试速率) 看dumpsys sensorservice的结果看，minRate为1hz，理论 qxdm log，查看实际速率是多少。 Thanks !		

fail: hardware/interfaces/sensors/1.0/vts/functional/VtsHalSensorsV1_0TargetTest.cpp:1183
Expected: (std::abs(maxDelayAverageInterval - maxSamplingPeriodInNs)) < (maxSamplingPeriodInNs / 10), actual: 144850797 vs 100000000

03-06 16:20:42 I/ConsoleReporter: [14/36 armeabi-v7a VtsHalSensorsV1_0Target J3AXGYN0171832C]
VtsHalSensorsV1_0Target#SensorsHidlTest.GyroscopeSamplingPeriodHotSwitchOperation(default)_32bit
fail: hardware/interfaces/sensors/1.0/vts/functional/VtsHalSensorsV1_0TargetTest.cpp:1183
Expected: (std::abs(maxDelayAverageInterval - maxSamplingPeriodInNs)) < (maxSamplingPeriodInNs / 10), actual: 144856890 vs 100000000

3/6/2019 12:21 AM

Userzk zk

Dear qcom ,

Comment1. 使用提供的修改解决了SensorListValid(default)_32bit,SensorListValid(default)_64bit问题
2. generic_arm64_ab:/ # dumpsys sensorservice
Can't find service: sensorservice
请帮忙看下

3/5/2019 5:39 PM

UserJianyun Kang

Dear customer
I'll look at it and give you feedback soon.

CommentThanks!
Tel:151 0150 5427

3/6/2019 6:12 PM

Userzk zk

Dear qcom ,

Comment烧写dailybuild抓取了dumpsys_sensorservice.txt , 昨天烧帮忙看看有什么建议

3/6/2019 1:01 AM

Userzk zk

1. 使用的GYRO为icm206xx , 使用的是O版本配置, BP侧未

Comment2. 根据说明现在最大速率为1HZ , 而测试实际速率为1.17HZ是
3. 因为升级只做了AP , 能否不动BP侧让此测试通过呢 ?
Tks

3/6/2019 12:25 AM

UserJianyun Kang

Dear customer,
如果gyro是bmi160 , 尝试以下修改 :

gyro maxRate为250.00Hz.

但是实际测试速率为400hz

hardware/interfaces/sensors/1.0/vts/functional/VtsHalSer
Expected: (std::abs(minDelayAverageInterval - minSamp
(minSamplingPeriodInNs / 10), actual: 1532273 vs 400000

CommentminSamplingPeriodInNs = 400000*10 = 4000000ns = 4 ms
请测试速率)
minDelayAverageInterval = 4000000 - 1532273 = 2467727
rate ~400hz (实际测试速率)

请参考以下修改adsp_proc/Sensors/dd/qcom/src/sns_dd_
#define BMI160_CONFIG_ACC_FASTEST_ODR 1600
#define BMI160_CONFIG_ACC_FASTEST_ODR 200

#define BMI160_CONFIG_GYR_FASTEST_ODR 1600
#define BMI160_CONFIG_GYR_FASTEST_ODR 200

Thanks!

3/5/2019 6:00 PM

UserJianyun Kang

Dear customer
1.SensorListValid(default)_32bit,SensorListValid(default).
请尝试以下修改 :

diff --git a/dsps/libhalsensors/src/SensorsContext.cpp
b/dsps/libhalsensors/src/SensorsContext.cpp
index f9d890e..0377038 100644
--- a/dsps/libhalsensors/src/SensorsContext.cpp
+++ b/dsps/libhalsensors/src/SensorsContext.cpp
@@ -1639,6 +1639,11 @@ void
SensorsContext::processSingleSensorInfoResp(Sensor*
mSensors[handle]->setResBufferedSamples(0);
}

+ /* This is to avoid setting undefined value to non BMA s
+ if (strcmp(ACCEL_SENSOR_NAME,
+ mSensors[handle]->getName()) != 0) {
+ mSensors[handle]->setMaxFreqBkp(mSensors[handle]
+ }
(static_cast<SMGRSensor*>(mSensors[handle]))->setSei

CommentHAL_LOG_INFO("%s: sensor1: name: %s, vendor: %s, m
@@ -1721,6 +1726,8 @@ void
SensorsContext::processSingleSensorInfoResp(Sensor*
mSensors[handle_wakeup]->setMaxBufferedSamples(srr
>num_buffered_reports[i]);
}

+ /* This is to avoid setting undefined value */
+ mSensors[handle_wakeup]->setMaxFreqBkp(mSensor:
>getMaxFreq());
(static_cast<SMGRSensor*>(mSensors[handle_wakeup])
>setSensorInfo(sensor_datatype);

HAL_LOG_INFO("%s: sensor1: name: %s, vendor: %s, m

2.GyroscopeSamplingPeriodHotSwitchOperation错误 , 您
sensorservice结果。

Thanks !