

Thales e-Security

# **payShield 9000 Release Note Base Software Versions 3.0b**

PPRN0523-050

5 December 2015



# Contents

<b>COPYRIGHT NOTICE .....</b>	<b>4</b>
<b>INTRODUCTION.....</b>	<b>5</b>
LATEST SOFTWARE NUMBERS.....	5
IMPORTANT NOTES.....	5
PCI HSM COMPLIANCE.....	6
UPGRADING SOFTWARE ON EXISTING PAYSHIELD 9000 UNITS .....	6
<b>ENHANCEMENTS AND BUG FIXES .....</b>	<b>7</b>
VERSION 3.0 DEVELOPMENT STREAM .....	7
<i>Relationship to v2.4</i> .....	7
1407-0901 (v3.0b) .....	7
VERSION 2.4 DEVELOPMENT STREAM .....	8
<i>Relationship to v2.3</i> .....	8
1346-0918 (v2.4a) .....	8
VERSION 2.3 DEVELOPMENT STREAM .....	10
<i>Relationship to v2.2</i> .....	10
1346-0917 (v2.3f) .....	10
1346-0916 (v2.3e) .....	10
1346-0915 (v2.3d) .....	11
1346-0914 / 1346-1914 (v2.3c) .....	11
1346-0913 (v2.3b) .....	12
1346-0912 (v2.3a) .....	17
VERSION 2.2 DEVELOPMENT STREAM .....	18
<i>Relationship to v2.0</i> .....	18
1346-0911 (v2.2b) .....	18
1346-0910 (v2.2a) .....	19
VERSION 2.1 DEVELOPMENT STREAM .....	23
1346-0908 (v2.1e) .....	23
1346-0907 (v2.1d) .....	23
1346-0905 / 1346-1905 (v2.1c) .....	25
VERSION 2.0 DEVELOPMENT STREAM .....	26
<i>Relationship to v1.4</i> .....	26
1346-0904 (v2.0c).....	26
1346-0902 (v2.0b) .....	27
1346-0900 (v2.0a) .....	30
VERSION 1.4 DEVELOPMENT STREAM .....	32
<i>Relationship to v1.3</i> .....	32
1317-0922 (v1.4g) .....	32
1317-0920 (v1.4e) .....	33
1317-0919 (v1.4d) .....	33
1317-0917 (v1.4b) .....	34
1317-0916 (v1.4a) .....	35
VERSION 1.3 DEVELOPMENT STREAM .....	38
<i>Relationship to v1.2</i> .....	38
1317-0915 (v1.3e) .....	38
1317-0914 (v1.3d) .....	39
1317-0912 (v1.3b) .....	40
1317-0911 (v1.3a) .....	41
VERSION 1.2 DEVELOPMENT STREAM .....	43
1317-0900 / 1317-1900 (v1.2a).....	43
VERSION 1.1 DEVELOPMENT STREAM .....	45
1110-0921 (v1.1b) .....	45

## ***payShield 9000 Software Release Notes***

1110-0920 (v1.1a) .....	47
VERSION 1.0 DEVELOPMENT STREAM .....	51
1110-0914 (v1.0f) .....	51
1110-0913 (v1.0e) .....	52
1110-0912 (v1.0d) .....	52
1110-0911 (v1.0c).....	53
1110-0904 (v1.0b) .....	55
1110-0902 (v1.0b) .....	56
1110-0901 (v1.0a) .....	56
<b>KNOWN SIGNIFICANT BASE SOFTWARE ISSUES .....</b>	<b>58</b>
<b>OTHER USEFUL INFORMATION .....</b>	<b>59</b>
PCI HSM CERTIFIED VERSIONS OF PAYSHIELD 9000 BASE SOFTWARE .....	59
PAYSHIELD 9000 VS. HSM 8000.....	61
LOCAL & REMOTE HSM MANAGER COMPATIBILITY INFORMATION.....	63
TECHNICAL SUPPORT CONTACTS .....	65

# Copyright Notice

**Copyright 2015 Thales UK Limited. All rights reserved.**

Copyright in this document is the property of Thales UK Limited. It is not to be reproduced, modified, adapted, published, translated in any material form (including storage in any medium by electronic means whether or not transiently or incidentally) in whole or in part nor disclosed to any third party without the prior written permission of Thales UK Limited neither shall it be used otherwise than for the purpose for which it is supplied.

payShield is a registered trademark of Thales UK Limited.

All other trademarks are the property of the respective trademark holders.

Information in this document is subject to change without notice.

Thales UK Limited makes no warranty of any kind with regard to this information, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Thales UK Limited shall not be liable for errors contained herein or for incidental or consequential damages concerned with the furnishing, performance or use of this material.

These release notes do not cover all situations and are intended as a supplement to the documentation provided with Thales products. Disclaimer: Thales UK Limited disclaims all liabilities regarding third-party products and only provides warranties and liabilities with its own products as addressed in the Terms and Conditions for Sale.

# Introduction

This payShield 9000 release note contains details of the following subjects:

- Enhancements and bug fixes
- Known significant issues in base software
- Compatibility information
- Manuals version to be used.
- Other useful information

## Latest Software Numbers

<b>Version 3.0 Development Stream</b>	<b>1407-0901 (v3.0b)</b>
<b>Version 2.4 Development Stream</b>	<b>1346-0918 (v2.4a)</b>
<b>Version 2.3 Development Stream</b>	<b>1346-0917 (v2.3f)</b>
<b>Version 2.2 Development Stream</b>	<b>1346-0911 (v2.2b)</b>
<b>Version 2.1 Development Stream:</b>	<b>1346-0907 (v2.1d)/ 1346-1907 (v2.1d)</b>
<b>Version 2.0 Development Stream:</b>	<b>1346-0904 (v2.0c)</b>
<b>Version 1.4 Development Stream:</b>	<b>1317-0922 (v1.4g)</b>
<b>Version 1.3 Development Stream:</b>	<b>1317-0915 (v1.3e)</b>
<b>Version 1.2 Development Stream:</b>	<b>1317-0900 (v1.2a) / 1317-1900 (v1.2a)</b>
<b>Version 1.1 Development Stream:</b>	<b>1110-0921 (v1.1b)</b>
<b>Version 1.0 Development Stream:</b>	<b>1110-0914 (v1.0f)</b>

## Important Notes

1. See the table in the section "Local & Remote HSM Manager Compatibility Information" later in this document for an overview of compatibility between HSM Manager software and HSM 8000/payShield 9000 software.
2. Because different software versions (e.g. v1.0 and v1.1) may be in development at the same time, it may be that some fixes and enhancements in the lower-numbered version may not be included in the higher-numbered version. The entries below now provide information for this situation to be understood.
3. Within a software version (e.g. v1.1) there may be some instances where changes in one release are not included in a later release. This is explained in the entries for the relevant releases.
4. The term "Limited release only" below means that the software release was a maintenance release which was not generally distributed but was available to customers who experienced any issues that the release addressed and required an urgent resolution. Such releases may have had limited system testing.
5. The term "Special request only" below identifies versions which relate to Security Advisories TESA-2014-001 or TESA-2015-004. These versions are available if a

request is made to users' Thales account managers or resellers, or (in the case of a software download) to Thales Support.

## **PCI HSM Compliance**

**Selected versions of payShield 9000 from v1.2a will be certified to the PCI HSM requirements. Please note the following:**

1. The information below for each release indicates which versions of payShield 9000 software are certified to PCI HSM. For handy reference, a table of the compliances is included in the sub-section "PCI HSM Certified versions of payShield 9000 base software" towards the end of this document.
2. In order to allow backwards compatibility, some settings are not compliant with PCI HSM. The certified software becomes PCI HSM compliant only when these settings are given compliant values.
3. PCI HSM compliance requires that the HSM is delivered in a compliant method. Any order for a payShield 9000 that is required to be PCI HSM compliant must specify that PCI HSM compliance is required.
4. As an indicator that the software is certified and all the settings are compliant, the software revision number (accessible using, for example, the VR Console command) changes from format nnnn-09nn to format nnnn-19nn. If VR shows a software revision in the format nnnn-09nn then that version of payShield 9000 software is not PCI HSM certified and/or some settings are not compliant.
5. Information about PCI HSM is included with the manuals for payShield 9000 v1.2a onwards – for example, see Chapter 10 of the *payShield 9000 General Information Manual*. You can also find information in the Thales Application Note "*payShield 9000 Overview of PCI HSM Certification Requirements*".
6. Where Local or HSM Manager is to be used with a payShield 9000 that is required to be PCI HSM compliant then the appropriate version of HSM Manager (as defined in the section on *Local & Remote HSM Manager Compatibility Information*) must be used.

## **Upgrading software on existing payShield 9000 units**

Where it is required to update the software on a payShield 9000 which is already in use, users with appropriate support contracts with Thales may be able to acquire the new software at no cost.

Different classes of Thales support contracts are available. All entitle the user to both minor release updates (e.g. from v1.0a to 1.0b or from v1.0a to v1.3f), and major release updates (e.g. from v1.3f to v2.0a).

Users who do not have an appropriate support contract can purchase a license for the updated software by ordering:

- HSM9-LIC001 where the new software is in the v1 range, or
- HSM9-LIC001Vx (x = 2 or more) where the new software is in the vx range.

The normal delivery method is by download from the Thales Support site. If required, software can be delivered on a CD at additional cost.

# Enhancements and Bug Fixes

## Version 3.0 Development Stream

*Note: When Thales ships a payShield 9000 HSM pre-loaded with v3.0 software, a certificate will be installed inside the HSM (known as a 'warrant') to enable remote commissioning of the HSM using payShield Manager. However, remote commissioning is not permitted when an LMK is already installed in the HSM. Therefore, prior to shipping, Thales will not pre-install the Test LMK into any HSM which is loaded with v3.0 software.*

## Relationship to v2.4

All fixes and enhancements in the v2.4 stream up to and including 1346-0918 (v2.4a) are included in v3.0b. Changes in later versions in the v2.4 stream are not included in the v3.0 stream unless these Release Notes explicitly say that they have been included.

## 1407-0901 (v3.0b)

### PCI HSM Compliant?

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

### HSM Manager Compatibility

This version of HSM software is not compatible HSM Manager, but introduces support for payShield Manager, which is accessed using a regular web browser.

### Manuals

- Issue 30 of the payShield 9000 manuals should be used with this release.

### New functions

Ref.	Description of Enhancement
	Introduce support for payShield Manager.



## **Version 2.4 Development Stream**

### **Relationship to v2.3**

All fixes and enhancements in the v2.3 stream up to and including 1346-0917 (v2.3f) are included in v2.4a. Changes in later versions in the v2.3 stream are not included in the v2.4 stream unless these Release Notes explicitly say that they have been included.

### **1346-0918 (v2.4a)**

#### **(Not yet released)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 5.1.7

#### **Manuals**

- Issue 19 of the payShield 9000 manuals should be used with this release.

#### **New functions**

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 13361	Add functionality introduced via early-release software 1401-09xx: <ul style="list-style-type: none"><li>• Host Card Emulation support in host commands KW, KI, PM, IO, IQ, IU, IW, IY, GI.</li><li>• PAN Tokenization support in host commands CC, EC, CI, G0, CM, GQ, CU, DC, DG.</li><li>• X9 TR-31:2010 support in host commands A0, A6, A8.</li><li>• New/modified settings in console commands CS, QS, RS, SS.</li></ul>
CR 13361	HSM now issues gratuitous ARP at start up.
CR 13261	Allow export of ZKA Master Key type (requires Authorized state).
CR 12726	Add functionality to support triple-length Variant LMKs.



## ***payShield 9000 Software Release Notes***

### **Bugs and Errors Corrected**

Ref.	Description of Error
CR 13419	GETCMDS console command has memory allocation problem.
CR 13406	M0 host command incorrectly returning error 06.
CR 13371	HSM Manager connection failing intermittently.
CR 13359	HSM Manager connection failing after reading full audit log.
CR 13330	HSM failing to release TCP sessions on host i/f.
CR 13307	JG host command – incorrectly returning error code 14 instead of 15.
CR 13282	NO & commands supporting Weak PIN functionality were occasionally performing slowly, as data was written to Flash memory.
CR 13239	Host Ethernet interface not properly handling 10/100MBps connections to managed switches
CR 13215	XC console command doesn't appear in commands auth category until after the HSM is restarted.
CR 13211	ROUTE console command may cause lockup.
CR 13163	KI host command fails when using method C and derivation data contains 0x19.
CR 13158	A4 host command isn't permitted although authorized.
CR 13120	Loading LMK into HSM now enforces unique components.
CR 12953	IE host command incorrectly outputs DGI value and length fields when using non-STORE DATA APDUs.

## **Version 2.3 Development Stream**

### **Relationship to v2.2**

All fixes and enhancements in the v2.2 stream up to and including 1346-0910 (v2.2b) are included in v2.3a. Changes in later versions in the v2.2 stream are not included in the v2.3 stream unless these Release Notes explicitly say that they have been included.

### **1346-0917 (v2.3f)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 5.1.7

#### **Manuals**

- Issue 18 of the payShield 9000 manuals should be used with this release.

#### **Security Enhancements and Fixes**

Ref.	Description of Error
CR 13277	Addresses vulnerability outlined in Security Advisory TESA-2015-004.

#### **Bugs and Errors Corrected**

Ref.	Description of Error
CR 13284	Improved TCP & UDP performance.
CR 13271	Modified SG console command in its use of the hardware RNG.

### **1346-0916 (v2.3e)**

#### **(Special request only)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

➤ 5.1.7

**Manuals**

- Issue 18 of the payShield 9000 manuals should be used with this release.

**Bugs and Errors Corrected**

Ref.	Description of Error
CR 13240	Upgrading from pre-v2.2a to any version from 2.2a-2.3d can result in the loss of the private key for remote access.
CR 13118	NO host command can cause timeout errors
CR 13113	HSM may fail to resend a command when requested
C R 12872	Command processing latency is sometimes higher than expected

**1346-0915 (v2.3d)**

**(Special request only)**

**PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

**HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 5.1.7

**Manuals**

- Issue 17 of the payShield 9000 manuals should be used with this release.

**Bugs and Errors Corrected**

Ref.	Description of Error
CR 12872	Performance of command processing improved to minimize latency.
CR 13113	Fix to ensure lost response messages are always resent.

**1346-0914 / 1346-1914 (v2.3c)**

**(Special request only)**

**Special Notes**

- ***It is recommended that existing users of v2.3a and v2.3b upgrade to v2.3c.***
- Remote HSM Manager does not currently support the use of AES LMKs. Local HSM Manager or the Console should be used where AES LMKs are to be deployed.
- An intermittent error has been reported where the console may become unresponsive if connected to the left-hand USB port on the front panel of the payShield 9000. This

## **payShield 9000 Software Release Notes**

has been observed to happen after events such as a software load or a restart. If this error is encountered, it can be circumvented by connecting the console to a different USB port or re-starting the payShield 9000.

### **PCI HSM Compliant?**

- ***This software has been certified for PCI HSM compliance.*** PCI HSM compliance of the payShield 9000 is subject to appropriate user settings having compliant values – see manuals.
- Software number 1346-0914 applies if some security settings are not PCI HSM compliant. Software number 1346-1914 applies if all security settings are PCI HSM compliant: only this software number appears on the PCI certificate. (See manuals)

### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 5.1.7

### **Manuals**

- Issue 17 of the payShield 9000 manuals should be used with this release.

### **Security Enhancements and Fixes**

Ref.	Description
CR 13099	Addresses POODLE vulnerability in OpenSSL libraries by implementing OpenSSL v1.0.1j
CR 13098	Addresses vulnerability outlined in Security Advisory TESA-2014-001.

### **Bugs and Errors Corrected**

Ref.	Description of Error
CR 13037	A0 Host Command returns response code when generating and exporting an IKEY/IPEK after 100+ iterations when using Keyblock LMKs
CR 13000	JK Host Command (Get Instantaneous Health Check Status) returns incorrect value for "Ethernet Host link 1 state" in certain cases.

## **1346-0913 (v2.3b)**

### **(Special request only)**

#### **Special Notes**

- ***It is recommended that existing users of v2.3a upgrade to v2.3b.***
- Remote HSM Manager does not currently support the use of AES LMKs. Local HSM Manager or the Console should be used where AES LMKs are to be deployed.
- An intermittent error has been reported where the console may become unresponsive if connected to the left-hand USB port on the front panel of the payShield 9000. This

## **payShield 9000 Software Release Notes**

has been observed to happen after events such as a software load or a restart. If this error is encountered, it can be circumvented by connecting the console to a different USB port or re-starting the payShield 9000.

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 5.1.7

### **Manuals**

- Issue 16 of the payShield 9000 manuals should be used with this release.

### **New functions**

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 11558	Secure Host Communications using TLS or SSL v3 is now available on general release. This feature requires the use of Optional License HSM9-LIC036. ( <i>Note: USB memory sticks are used to transfer material such as certificates in and out of the payShield 9000. The Operating System used in the payShield 9000 supports most types of USB memory stick, but may not have the drivers for some of the newer types. If difficulties are experienced when trying to read from or write to a USB device, an alternative memory stick should be used.</i> )
CR 12686	QY Host Command to generate a dCVV
CR 12476	payShield 9000 IP address can now be obtained from a DHCP server or via a DNS name server.
CR 12194	Access Control Lists can now be applied to Ethernet host ports.
CR 11471	N0 Host Command introduced to generate and return a Random Number.
CR 10261	Support for native USB printers.

### **Enhancements to Existing Functions**

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 12890	OpenSSL upgraded to version 1.0.1h.
CR 12800 CR 12738	Upgrade OpenSSL Toolkit used for Secure Host Communications to v1.0.1g: this prevents the Heartbleed vulnerability.
CR 12719	Card Issuing Enhancements – support for Global Platform SCP02 (i=055 mode)
CR 12703	G0 Host Command extended to support any valid PIN Block format.
CR 12690	A0 Host Command extended to allow export of an IPEK under a TMK.

## **payShield 9000 Software Release Notes**

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 12662	BU Host Command extended to generate a Key Check Value on an HMAC key.
CR 12627	Users can now specify which Ethernet port is to be used for SNMP
CR 12622	GETCMDS, CONFIGCMDS, and AUDITOPTIONS Console commands can now handle more than 120 commands.
CR 12596	When using the SI Console command, user is informed if no certificates are found on the USB memory device.
CR 12575	Users can now select whether to limit the authorization period for console commands. This limitation must be selected where PCI HSM compliance is required.
CR 12548	Users can now audit whenever an attempt to establish a Secure Host Sessions fails because the certificate has expired. The audit log entry identifies the certificate.
CR 12543	A0 Host command extended to provide GBIC/ZKA key derivation.
CR 12508	Internet network numbers are now displayed in standard CIDR format.
CR 12504	Major upgrade to user Storage capability. New "Variable" length setting allows longer data items including RSA keys and Keyblock LMK-encrypted keys to be held in the user Storage area inside the payShield 9000.
CR 12475	Software no longer reports whether it is PCI HSM certified or not. Instead it refers users to online certificate at PCI web site, in line with PCI wishes. Software just reports on status of security settings that affect PCI HSM compliance.
CR 12429	BU host command does not generate KCVs for AES keyblocks.
CR 12346	GQ, GS and GU Host commands enhanced so that they support Mode=2 (Verify PIN only using a unidirectional PIN key)
CR 12306	The use of multiple components can be enforced when forming keys or loading LMKs. This setting must be used for PCI HSM compliance.
CR 12235	A0 Host command now allows a TMK to be exported under a TMK.
CR 12217	Card Issuer Password can now be restored to its original value.
CR 12210 CR 12145	Management and Default LMKs can now be reassigned without having to delete LMKs.
CR 12144	When deleting the LMK that is the Management or Default LMK (when there is another LMK present), the user is prompted to re-assign Management and/or Default LMK first.
CR 12001	Auditing of Error responses now ignores response 43
CR 11953	Settings can now be saved in Online and Offline states
CR 11862	PIN translation <b>to</b> a BDK.
CR 10606	Improvements of display of utilisation data when using the UTILSTATS Console command.

## **Security Enhancements and Fixes**

<b>Ref.</b>	<b>Description</b>
CR 12992	Enhancement to certain console commands following updated best practise review.
CR 12884	-P option removed from NETSTAT console command to (a) ensure compliance with security advisory related to the NetBSD implementation, and (b) to remove option deemed unnecessary for HSM operations. <i>[NOTE: the -p (lower case) option is still available.]</i>

## **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description of Error</b>
CR 13002	Error code 28 returned when importing a PVK (key type 002) when security settings are PCI HSM-compliant.
CR 12926	Restore Settings, (RS console command) appears to restore PIN Block Formats correctly but after power cycle the settings are back to what they were before RS was run.
CR 12922	GK Console command prompt for TDES Keyblock LMKs corrected: "Enter value C:" changed to "Enter secret value C:"
CR 12917	After using facility to Return To Factory Settings, a manual restart may be required in addition to the automatic restart.
CR 12905	When authorizing activities using the A console command, if authorizations are made using both the menu and command line methods, the output from the A command may show multiple entries for time remaining for authorization with conflicting values.
CR 12866	Error code 17 incorrectly returned when host command A0 used to generate a TPK and export under a TMK when using a keyblock LMK.
CR 12816	Self test run time value not retrieved correctly from saved settings via RS command.
CR 12801	Changes made in CH and CM console commands now take effect on completion of the command.
CR 12755	Sometimes unable to load software using FTP
CR 12752	G0 host command may fail with error response A3 instead of 23.
CR 12727	When importing a GISKE key using A8 host command, encrypted key is all zeroes.
CR 12691	If Security Setting "Enable weak PIN checking" is set to NO, weak PIN checking is not performed if a local Weak PIN table is included in a command.
CR 12671	ROUTE command not setting up persistent routes correctly



## ***payShield 9000 Software Release Notes***

Ref.	Description of Error
CR 12611 CR 12557 CR 12099 CR 11647 CR 11527	Corrections to display of installed optional licenses.
CR 12603	Message Trailers not being returned for J6 and JI Host commands
CR 12594	A0 Host command is not correctly exporting, for example, a ZPK under a ZMK with the AS2805 H key scheme applied.
CR 12565	BA Host command now checks that cleartext PINs are padded with F to the encrypted PIN length.
CR 12559	RG Console command (Generate RMK) command on an incorrectly formatted smartcard causes error then the smartcard cannot be formatted.
CR 12558	Under some circumstances there may be an inability to print and system logs may outgrow the file system.
CR 12514	Cannot read an AES decimalization table from user storage.
CR 12506	Console can crash if user input is too long to A6 and MI Console commands.
CR 12482	PE host command may fail and cause the HSM to become unresponsive if binary data is sent to the printer.
CR 12246	Invalid MAC calculated with intermediate to final block when verified with C4 command.
CR 12190	Remote HSM Manager lost connection to HSM and was not able to connect again until the HSM was rebooted.
CR 11183	I8 Host Command / Sub Command Code 04 (Load Cipher Data) fixed for Cipher Data Type 2 (Triple DES key encrypted under KEK)
CR 11510	BW host command returns error 33 when there is no old LMK loaded.
CR 10914	When auditing forming of keys from components while using HSM Manager, multiple audit log entries are made.
CR 10727	A8 Host command does not import a GISKE key correctly: it populates the encrypted key field with all 0's
CR 10607	Utilisation Stats are not being reset when new firmware loaded using USB stick.
CR 10398	Process for switching between Console management and HSM Manager management enhanced to prevent attempted Denial of Service attacks.
CR 10311	Audit Log may be corrupted if user changes time or audit counter.
CR 10232	Save settings may not save host comms interface type correctly
CR 10027	If a port number is used in a test to specify an incorrect LMK, sometimes error code A1 returned instead of error code 13.
CR 9171	Single-character wildcards (e.g. "+CR?") not working for enabling commands in CONFIGMDS Console command.

**1346-0912 (v2.3a)**

**(Withdrawn)**

***This software has been withdrawn and should not be used. It has been replaced by v2.3c.***

Enhancements and error corrections that were made in v2.3a have been included in the lists provided above for v2.3b.

## **Version 2.2 Development Stream**

### **Relationship to v2.0**

All fixes and enhancements in the v2.0 stream up to and including 1346-0904 (v2.0c) are included in the v2.2 stream. Changes in later versions in the v2.0 stream are not included in the v2.2 stream unless these Release Notes explicitly say that they have been included.

### **1346-0911 (v2.2b)**

#### **(Special request only)**

##### **Special Notes**

- ***This release replaces v2.2a and is in response to the Heartbleed bug.***
- ***V2.2a contains software to provide a Secure Host Communications feature, which was to be enabled in the future using a new license. This feature makes use of OpenSSL.***
- ***Although v2.2a is not susceptible to the Heartbleed vulnerability because the license that activates Secure Host Communications was never made available, Thales recommends that users of v2.2a upgrade to v2.3c. This allows a clear statement to be made that the product does not contain the vulnerable version of OpenSSL. The only changes in this release compared with v2.2a are:***
  - ***the dormant OpenSSL component has been upgraded to a version not vulnerable to the Heartbleed bug, and***
  - ***the ability to activate the Secure Host Communications license has been removed.***

***payShield 9000 versions prior to v2.2a did not include OpenSSL, and therefore users of these versions do not need to take any action.***

***Users who want to move from v2.1 or earlier to v2.2 software should move to v2.2b or later.***

- See Special Notes for v2.2a.

##### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)

##### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 5.1.4 (for v2.2a of the payShield 9000)

##### **Manuals**

- Issue 14.6 of the payShield 9000 manuals should be used with this release.

## **Enhancements to Existing Functions**

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 12806	OpenSSL 1.0.1f upgraded to OpenSSL 1.0.1g. Optional License to activate Secure Host Communications is not operational in this release.

## **1346-0910 (v2.2a)**

### **(Withdrawn)**

## **Special Notes**

- Remote HSM Manager does not currently support the use of AES LMKs. Local HSM Manager or the Console should be used where AES LMKs are to be deployed.
- An intermittent error has been reported where the console may become unresponsive if connected to the left-hand USB port on the front panel of the payShield 9000. This has been observed to happen after events such as a software load or a restart. If this error is encountered, it can be circumvented by connecting the console to a different USB port or re-starting the payShield 9000.

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

## **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 5.0.19

## **Manuals**

- Issue 14 of the payShield 9000 manuals should be used with this release.

## **New functions**

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 11861	RSA Booster license (HSM9-LIC033) to increase performance of main RSA functions.
CR 11781	New host command (QK) introduced to enable the account number to be changed (without changing the PIN) in an LMK-encrypted PIN. This allows card issuers to issue replacement cards while retaining the old PIN.
CR 11558	Introduction of Secure Host Communications, using TLS or SSL. <i>Notes:</i> <ol style="list-style-type: none"><li>1. <i>This capability is undergoing customer trials, and the enabling licence will be made available when these trials have been completed.</i></li><li>2. <i>The default set of ciphers on the IBM z/OS platform do not support connections to the payShield 9000. Users affected by this should contact their IBM representative to obtain an updated set of ciphers.</i></li></ol>

## ***payShield 9000 Software Release Notes***

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 11415	MACing of Issuer Discretionary Data.
CR 11285	Support for Discover ZIP contactless transactions.

### **Enhancements to Existing Functions**

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 12195	Reporting of Authorisation State identifies whether commands are Host, Console, or All
CR 12064	A5 console command now allows current fraud detection settings to be viewed while the payShield 9000 is in Online and unauthorized state.
CR 12063	HEALTHSTATS console command now allows health statistics settings to be viewed while the payShield 9000 is in Online and unauthorized state.
CR 11994	Temperature sensor/alarm is now permanently active.
CR 11968	Users no longer need to specify an SNMP community write string.
CR 11935	HSM Manager user interface improved when asking whether configuration changes should be applied at next restart.
CR 11916	PSU failure (on dual-PSU models) now reported immediately instead of at next restart,
CR 11858	Improvements to way that battery life is reported.
CR 11857	Enhancements to card personalization and MULTOS capabilities.
CR 11741	VC console command now identifies the component type (i.e. Variant, 3DES-Keyblock or AES-Keyblock) on the card.
CR 11676	Audit log is now displayed with most recent entries first. On the console, audit log display can be terminated by using Ctrl-C. This supports the recent increase in Audit Log size to 50,000 records, which will take a long time to display on a serial console.
CR 11365	Console commands show the maximum permissible value of LMK ID.
CR 10937 CR 10793 CR 10758	Error messages enhanced.
CR 10907	Enforced audit log entries for key entry ("KE") actions now identified as user actions to distinguish them for KE console command entries.
CR 10051	Support for 20 LMK option for Multiple LMK licenses - HSM9-LIC022.
CR 9112	When loading an LMK using the LK console command, if no management or default LMK already exists the user is asked whether they want to allocate the new LMK as management/default LMK.

## ***payShield 9000 Software Release Notes***

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 8817	Authorising activities by command line now notifies which activities will be authorized before requesting cards and PINs.

### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description of Error</b>
CR 12435	Incorrect reporting of voltages being out of range.
CR 12431 CR 12430 CR 11774 CR 11135 CR 11103	Corrections made to SNMP MIB.
CR 12404 CR 12403	Some optional licenses not being reported correctly with VR console command.
CR 12399	Use of Reset to Factory settings feature sets Ethernet port speeds to an invalid value.
CR 12385	HSM Manager Health Check data for fans and PSU status inconsistent with Console DT command.
CR 12254	Cannot authorise all required key types for BU host command and CK console command.
CR 12246	Invalid MAC calculated with intermediate to final block when verified with C4 command.
CR 12236	Error Message on VR Console command and no serial number shown after Return to factory Settings
CR 12183	After applying new Ethernet host settings to the payShield, the TCP and/or UDP server stop working.
CR 12166	Presence of LIC030 not being reported in HSM Manager
CR 12165	Console command "SNMP" to view the SNMP settings returns error "No such file or directory", and not able to add an SNMP community.
CR 12109	HSM Manager Health Check data showing incorrect vales for numbers of tampers and reboots.
CR 12085	GW host command may incorrectly return error code 15.
CR 12040	C4 host command may incorrectly return error code 01.
CR 12032	Problems when configuring printer using HSM Manager
CR 12025	Generate Components function returning "Incompatible Key length" error.
CR 12012	SNMPADD console commands allows entry of zero-length community/user names, which prevents the SNMP agent from running after a reboot.
CR 11985	QH console command may show errors when displaying interface settings.
CR 11980	HC host command returns a corrupted header when the PCI HSM key separation setting is on.
CR 11960	VR command not reporting presence of LIC030

## ***payShield 9000 Software Release Notes***

<b>Ref.</b>	<b>Description of Error</b>
CR 11959	KK host command incorrectly returns error code 07.
CR 11956	Some saved audit settings are not restored when using HSM Manager.
CR 11952	KK host command returns error code 15
CR 11548	Software update may result in error message 'Failed reading single item setting'
CR 11487	RI host command has the wrong Mode of Use used in the keyblock response of TPK.
CR 11309	Parity should not be set or checked in IKEY (a.k.a. IPEK) keys.
CR 11112	Async option may not appear when using CH console command.
CR 11013	Error in Fraud Detection Total PIN Attacks counter.
CR 10968	Certain RSA Key pairs sizes can be created using EI host command that fail to work in EW host command.
CR 10829	Activity terminated on incorrect PIN entry instead of allowing a retry.
CR 10807	Cannot establish SNMP v3 connection.
CR 10558	Changing SNMP configuration starts the SNMP service even if it is disabled (and can cause an error to be logged)
CR 10534	SNMPADD console command allows spaces to be included in usernames, but SNMP cannot connect when spaces are used.
CR 10302	If no Old Key is loaded in Key Storage, BS returns error code 13 instead of 00.
CR 10137	If you try to delete a route that isn't there the HSM still asks you if you want to delete the persistent route
CR 9895	FK console command should display KCV of component as entered by custodian and be given the opportunity to re-enter component.
CR 9881	EW host command fails with AF (invalid end date) instead of AE (Invalid start date)
CR 9434	Retrieve Setting command incorrectly deletes the LMKs - LMKs should only be deleted for Alarm and Security settings.
CR 7147	In the NY host cmd, it should be an error if the 5N ATC field is > 65535 or if the Unpredictable Number field is 10N and > 4294967295.



## **Version 2.1 Development Stream**

### **Relationship to v2.0**

All fixes and enhancements in the v2.0 stream up to and including 1346-0904 (v2.0c) are included in v2.1c. Changes in later versions in the v2.0 stream are not included in the v2.1 stream unless these Release Notes explicitly say that they have been included.

### **1346-0908 (v2.1e)**

#### **(Special request only)**

#### **Special Notes**

- Remote HSM Manager does not currently support the use of AES LMKs. Local HSM Manager or the Console should be used where AES LMKs are to be deployed.
- An intermittent error has been reported where the console may become unresponsive if connected to the left-hand USB port on the front panel of the payShield 9000. This has been observed to happen after events such as a software load or a restart. If this error is encountered, it can be circumvented by connecting the console to a different USB port or re-starting the payShield 9000.

#### **PCI HSM Compliant?**

- This software is not certified to the PCI HSM standard. (Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)
- Software number 1346-0908 applies if some security settings are not PCI HSM compliant. Software number 1346-1908 applies if all security settings are PCI HSM compliant. (See manuals)

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 4.1.7

#### **Manuals**

- Issue 13.5 of the payShield 9000 manuals should be used with this release.

#### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description of Error</b>
CR 13275 CR 12872	Command processing latency is sometimes higher than expected

### **1346-0907 (v2.1d)**

#### **Special Notes**

- Remote HSM Manager does not currently support the use of AES LMKs. Local HSM Manager or the Console should be used where AES LMKs are to be deployed.

## ***payShield 9000 Software Release Notes***

- An intermittent error has been reported where the console may become unresponsive if connected to the left-hand USB port on the front panel of the payShield 9000. This has been observed to happen after events such as a software load or a restart. If this error is encountered, it can be circumvented by connecting the console to a different USB port or re-starting the payShield 9000.

### **PCI HSM Compliant?**

- This software is not certified to the PCI HSM standard, but it will be submitted for certification. (Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)
- Software number 1346-0907 applies if some security settings are not PCI HSM compliant. Software number 1346-1907 applies if all security settings are PCI HSM compliant: only this software number will appear on the PCI certificate if the software is successfully certified. (See manuals)

### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 4.1.7

### **Manuals**

- Issue 13.5 of the payShield 9000 manuals should be used with this release.

### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description of Error</b>
CR 13037	A0 host command fails to export an IPEK after a large number of iterations
CR 13032	Remote Manager disconnects when the Audit log becomes full (50,000 entries).
CR 12691	If Security Setting "Enable weak PIN checking" is set to NO, weak PIN checking is not performed if a local Weak PIN table is included in a command.
CR 12603	Message Trailers not being returned for J6 and JI Host commands
CR 12475	Software no longer reports whether it is PCI HSM certified or not. Instead it refers users to online certificate at PCI web site, in line with PCI wishes. Software just reports on status of security settings that affect PCI HSM compliance.
CR 12420	A0 host command returns Error Code A6 generating KB types K0 and 52
CR 12190	Remote HSM Manager lost connection to HSM and was not able to connect again until the HSM was rebooted.
CR 12085	GW host command returns Error Code 15
CR 12040	C4 host command returning C501 with Good Data
CR 11991	NG host command processing not checking for authorized state and clear PIN security setting. (Note: this affects only v2.0a software.)

## **Security Enhancements and Fixes**

<b>Ref.</b>	<b>Description</b>
CR 13098	Addresses vulnerability outlined in Security Advisory TESA-2014-001.
CR 12992	Enhancement to certain console commands following updated best practise review.
CR 12884	-P option removed from NETSTAT console command to (a) ensure compliance with security advisory related to the NetBSD implementation, and (b) to remove option deemed unnecessary for HSM operations. <i>[NOTE: the -p (lower case) option is still available.]</i>
CR 11994	Temperature sensor/alarm is now permanently active.

## **1346-0905 / 1346-1905 (v2.1c)**

### **(Special request only)**

#### **Special Notes**

- Remote HSM Manager does not currently support the use of AES LMKs. Local HSM Manager or the Console should be used where AES LMKs are to be deployed.
- An intermittent error has been reported where the console may become unresponsive if connected to the left-hand USB port on the front panel of the payShield 9000. This has been observed to happen after events such as a software load or a restart. If this error is encountered, it can be circumvented by connecting the console to a different USB port or re-starting the payShield 9000.

#### **PCI HSM Compliant?**

- ***This software has been certified for PCI HSM compliance.*** PCI HSM compliance of the payShield 9000 is subject to appropriate user settings having compliant values – see manuals.
- Software number 1346-0905 applies if some security settings are not PCI HSM compliant. Software number 1346-1905 applies if all security settings are PCI HSM compliant: only this software number appears on the PCI certificate. (See manuals)

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 4.1.0 & 4.1.4

#### **Manuals**

- Issue 13 of the payShield 9000 manuals should be used with this release.

## **Version 2.0 Development Stream**

### **Relationship to v1.4**

All fixes and enhancements in the v1.4 stream up to and including 1317-0917 (v1.4b) are included in v2.0a. Changes in later versions in the v1.4 stream are not included in the v2.0 stream unless these Release Notes explicitly say that they have been included.

### **1346-0904 (v2.0c)**

#### **(Special request only)**

#### **Special Notes**

- Remote HSM Manager does not currently support the use of AES LMKs. Local HSM Manager or the Console should be used where AES LMKs are to be deployed.
- An intermittent error has been reported where the console may become unresponsive if connected to the left-hand USB port on the front panel of the payShield 9000. This has been observed to happen after events such as a software load or a restart. If this error is encountered, it can be circumvented by connecting the console to a different USB port or re-starting the payShield 9000.

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 4.0.12, 4.1.0, 4.1.4

#### **Manuals**

- Issue 13 of the payShield 9000 manuals should be used with this release.

#### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description of Error</b>
CR 12165	"No such file or directory" when trying to view or add SNMP Community/User.
CR 12152	Cannot load AES LMK unless a multiple LMK license is installed.
CR 12150 CR 12073	Management port settings not applied correctly unless unit is restarted,
CR 12098	NC host command incorrectly returns Error Code 32 (LIC007 not present)

## payShield 9000 Software Release Notes

Ref.	Description of Error
CR 12083	Upgrading to v2.0 software from some versions of earlier software could require Ethernet port speeds to be set before the ports could be used.
CR 12072	Incorrect Microcontroller Version number reported when using HSM Manager.
CR 12043	payShield 9000 may become unresponsive, with Host 1 LED permanently illuminated.
CR 12011	FICON units experiencing a UE when a large number of blocks received without a rewind.
CR 12004	A Console command reports console authorization expires in 720 minutes even when a shorter timeout has been specified (e.g. for 120 minutes)
CR 11981 CR 11979	FG & OE Host commands return error code 15 when they should return 68
CR 11648	A0 Host command may incorrectly return error code 67 (command not licensed).

### 1346-0902 (v2.0b)

#### (Special request only)

#### Special Notes

- **Upgrading to v2.0b:** an additional step is required when upgrading to v2.0b on a payShield 9000 which has never run software v1.4a or later (or where v1.4a or later has been run in the past but the *Reset to Factory Settings* utility has been used since then). In such cases, after the v2.0b software has been loaded the console commands CH and CM should be used to set the Host and Management Ethernet port speeds (see reference to CR 10788 below): if this step is omitted the Ethernet ports will be inactive.
- Remote HSM Manager does not currently support the use of AES LMKs. Local HSM Manager or the Console should be used where AES LMKs are to be deployed.
- An intermittent error has been reported where the console may become unresponsive if connected to the left-hand USB port on the front panel of the payShield 9000. This has been observed to happen after events such as a software load or a restart. If this error is encountered, it can be circumvented by connecting the console to a different USB port or re-starting the payShield 9000.

#### PCI HSM Compliant?

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

#### HSM Manager Compatibility

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 4.0.12, 4.1.0, 4.1.4

## **Manuals**

- Issue 12 of the payShield 9000 manuals should be used with this release.

## **Enhancements to Existing Functions**

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 11965	CVC3 functionality now supports PINVC3
CR 11799	It is now possible to use all the commands required by AS2805 (enabled with LIC003) and APACS. Previously, the commands RI, RK, RU, RW, RM, RO, RQ, RS were used in both AS2805 and APACS, and as a result only one "meaning" of the commands was available, depending on the security setting to choose the transaction key scheme. Now, the alternative meaning of the commands can be used by using aliases HI, HK, HU, ...
CR 11777	It is now possible to audit commands where an error code is returned in the response. (Information and warning codes are not audited.)
CR 11474	GETCMDS modified to list commands that are (a) licensed, (b) not disabled by CONFIGCMDS, and (c) implemented in the installed software.
CR 10788	Host and Management port speeds and duplexity can now be set manually.
CR 10758	RR console command - error messages enhanced.
CR 9844	Audit log now has an entry when entries are erased.
CR 9374	HSM Manager can now cancel TRACERT
CR 9209	Retrieve settings function now does not ask you whether you want to load settings for a group when there are no saved settings.
CR 9112	If user is entering an LMK and the Default/Management LMKs are empty, user now asked if the new LMK should be the Default/Management LMK.

## **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description of Error</b>
CR 12025	Component generation using HSM Manager may incorrectly return an "Incompatible Key Length" error
CR 12012	Zero-length communities and strings should not be allowed in the SNMPADD console command.
CR 12008 CR 12006	An error reporting "Not Enough Memory" is entered into the error log; the payShield 9000 becomes unresponsive when the error log is viewed and requires rebooting. (Note: this affects only software versions 1.4d, 1.4e, and 2.0a.)
CR 11991	NG host command processing not checking for authorized state and clear PIN security setting. (Note: this affects only v2.0a software.)
CR 11960	VR console command does not detect presence of LIC030.
CR 11959	KK host command may incorrectly return error code 07.

## **payShield 9000 Software Release Notes**

<b>Ref.</b>	<b>Description of Error</b>
CR 11947	NY host command can result in an "Unprocessed Software" entry in the error log.
CR 11945	IK console command reports a "key masquerading" error instead of "key all zeroes".
CR 11936	D6 host command - if the imported TMK1 is X variant and/or the KP is X variant the HSM returns the wrong encrypted response.
CR 11931	SNMP MIB file incorrectly references NuDesign.
CR 11930	UTILSTATS console command goes into a loop when displaying host command volumes when there is data for more than 256 different commands.
CR 11929	Display of saved motion sensor settings did not show sensitivity level.
CR 11928	If there is no saved setting for self-test time, a value of "00:00" is assumed instead of "09:00".
CR 11924	IK Console command allows import of key type 000 (ZMK)
CR 11912	If incorrect time is entered in console SETTIME command, the message "The system time has been modified" is displayed. (The time has <b>not</b> been modified.)
CR 11905	Console command RY does not correctly display the RMK KCV.
CR 11865	Security setting prompt for the "Enable ZEK/TEK ..." item is sometimes truncated.
CR 11860	DU Command; when the security parameter "Variable length PIN offset" is set to YES the new length of the offset is being taken from the length of the old PIN, not the new one contained in the New PIN Block.
CR 11854	"RSA Not Licensed" is unnecessarily reported in the error log.
CR 11836	The HSM can become unresponsive when there is a high rate of host commands using too many connections.
CR 11813	Print function "Reverse CR/LF" not working.
CR 11798	Some commands running slower than expected
CR 11790	A0 command failing with Mode set to 'B'
CR 11762	Save settings function not handling the new security setting to Enable ZEK/TEK binary encryption.
CR 11729	MY host command: Padding mode 1 implemented incorrectly for MACing mode 3.
CR 11700	It is possible to change the IP address of a host port that will not work with the current default gateway.
CR 11683	In AUDITOPTIONS, the current value of the counter is displayed as 0.
CR 11665	Key types missing when trying to authorize FK console command.
CR 11604	Keyblock key usage for BDK Types 2 & 3 is not recognized in FK and KG console commands



## ***payShield 9000 Software Release Notes***

<b>Ref.</b>	<b>Description of Error</b>
CR 11568	KO host command can cause host comms port to become unresponsive.
CR 11566	RSA key generation occasionally returns error code 15.
CR 11490	Sub-Category for 'genprint' and 'component' doesn't list key types supported.
CR 11481	License for FICON card is deleted when the payShield Return to Factory Settings facility is used.
CR 11464	On a unit power-cycle the audit counter does not initialize to the expected value.
CR 11437	Need to change TKB Key Usage values 'B1' and 'B2' into '41' and '42' respectively.
CR 11388	Console message changed to refer to "HSM Manager" instead of "Management GUI"
CR 11320	In prompts for TRACERT command, "TRACEROUTE" changed to "TRACERT".
CR 10889	KE and KO commands performance is incorrect for the payShield 9000 model they are running on.
CR 10874	The host command FE should fail with error code 68 when key separation is set to Yes
CR 10845	The VA console command does not work while Multiple authorization is Off.
CR 10559	Alarm settings not included when settings are saved.
CR 10558	Adding an SNMP community starts the SNMP service even if it is disabled (and can cause an error to be logged)
CR 10137	ROUTE console command - User still asked to delete a persistent route even if it doesn't exist

### **1346-0900 (v2.0a)**

#### **(Special request only)**

##### **Special Notes**

- payShield 9000 v2.0a software should not be used because of important changes made in v2.0b software. Users who have not yet deployed v2.0a software should go directly to v2.0b or later. Users who have already deployed v2.0a software should immediately upgrade to v2.0b or later.
- Remote HSM Manager does not currently support the use of AES LMKs. Local HSM Manager or the Console should be used where AES LMKs are to be deployed.

##### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)

## **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 4.0.10

## **Manuals**

- Issue 10.3 of the payShield 9000 manuals should be used with this release.

## **New functions**

### **Description of Enhancement**

Software v2.0 introduces support for the AES cryptographic algorithm. The functionality that can utilize AES includes:

- 256-bit AES LMKs
- 128/192/256-bit AES key management keys (e.g. ZMK, TMK)
- 128/192/256-bit AES data encryption keys (TEK, ZEK, DEK)
- 128/192/256-bit AES data authentication keys (TAK, ZAK)

Note: the use of the AES algorithm requires the HSM9-LIC007 AES license.

## **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description of Error</b>
CR 11744	Changing state rapidly can cause the management port to lock, and any process that accesses the management port's IP address to fail.
CR 11584	With asynchronous host comms., if a stream of EI host commands is sent (with no other host commands during this period) the performance will degrade, and then the HSM stops responding.

## **Version 1.4 Development Stream**

### **Relationship to v1.3**

All fixes and enhancements in the v1.3 stream up to and including 1317-0915 (v1.3e ) are included in v1.4a. Changes in later versions in the v1.3 stream are not included in the v1.4 stream unless these Release Notes explicitly say that they have been included.

### **1317-0922 (v1.4g)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.8.2

#### **Manuals**

- Issue 8.3 of the payShield 9000 manuals should be used with this release.

#### **Security Enhancements and Fixes**

<b>Ref.</b>	<b>Description</b>
CR 13098	Addresses vulnerability outlined in Security Advisory TESA-2014-001.
CR 12992	Enhancement to certain console commands following updated best practise review.
CR 12884	-P option removed from NETSTAT console command to (a) ensure compliance with security advisory related to the NetBSD implementation, and (b) to remove option deemed unnecessary for HSM operations. [NOTE: the -p (lower case) option is still available.]
CR 12691	If Security Setting "Enable weak PIN checking" is set to NO, weak PIN checking is not performed if a local Weak PIN table is included in a command.
CR 11994	Temperature sensor/alarm is now permanently active.

### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description of Error</b>
CR 13130	SG console command may accept an invalid character
CR 13037	A0 Host Command returns response code when generating and exporting an IKEY/IPEK after 100+ iterations when using Keyblock LMKs

## **1317-0920 (v1.4e)**

### **(Limited release & special request only)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.8.1

#### **Manuals**

- Issue 8.2 of the payShield 9000 manuals should be used with this release.

### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description of Error</b>
CR 11947	NY host command can result in an "Unprocessed Software" entry in the error log.
CR 11936	D6 host command - if the imported TMK1 is X variant and/or the KP is X variant the HSM returns the wrong encrypted response.
CR 10874	The host command FE should fail with error code 68 when key separation is set to Yes
CR 10558	Adding an SNMP community starts the SNMP service even if it is disabled (and can cause an error to be logged)

## **1317-0919 (v1.4d)**

### **(Special request only)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

## **payShield 9000 Software Release Notes**

### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.8.1

### **Manuals**

- Issue 8.2 of the payShield 9000 manuals should be used with this release.

### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description of Error</b>
CR 11931	Errors caused by SNMP MIB referencing NuDesign
CR 11924	IK Console command allows import of key type 000 (ZMK)
CR 11905	Console command RY does not correctly display the RMK KCV.
CR 11836	The HSM can become unresponsive when there is a high rate of host commands using too many connections.
CR 11813	Print function "Reverse CR/LF" not working.
CR 11798	Some commands running slower than expected
CR 11790	A0 command failing with Mode set to 'B'
CR 11681	User storage cannot be accessed at offset F00.
CR 11665	Key types missing when trying to authorize FK console command.
CR 11604	Keyblock key usage for BDK Types 2 & 3 is not recognized in FK and KG console commands
CR 11568	KO host command can cause host comms port to become unresponsive.
CR 11566	RSA key generation occasionally returns error code 15.
CR 11490	Key types missing when authorizing component and genprint
CR 11437	Need to change TKB Key Usage values 'B1' and 'B2' into '41' and '42' respectively.
CR 11320	In prompts for TRACERT command, "TRACEROUTE" changed to "TRACERT".

## **1317-0917 (v1.4b)**

### **(Special request only)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.8.1

### **Manuals**

- Issue 8 of the payShield 9000 manuals should be used with this release.

### **Special Note**

Please see the note against CRs 11340 and 11346 for v1.4a in the section on *Enhancements to Existing Functions* for information relating to the new Default Gateway function for users upgrading from earlier versions.

### **Bugs and Errors Corrected**

Ref.	Description of Error
CR 11662	UDP host communications does not function if only one host Ethernet port is configured.
CR 11618	Cannot re-attach a payShield 9000 after detaching it from their host when using FICON and 3490 device emulation.

## **1317-0916 (v1.4a)**

### **(Special request only)**

### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.8.1

### **Manuals**

- Issue 8 of the payShield 9000 manuals should be used with this release.

### **New functions**

Ref.	Description of Enhancement
CR 11555	Support for MU and MW Host commands (for compatibility with legacy applications only). Requires HSM9-LIC034. ( <i>NOTE: the Release Notes issued with v1.3e incorrectly stated that this functionality was included in v1.3e.</i> )

### Enhancements to Existing Functions

Ref.	Description of Enhancement
CR 11132	Allow console command AuditOptions to work (in read-only mode) in Online state.
CR 11340 CR 11346	Ethernet ports now support default gateways. Ethernet ports can now be on the same subnet as each other. <b>(IMPORTANT NOTE: when upgrading from earlier versions of software, all static routes will be deleted, as a default gateway is now available for each interface. If an interface's IP address is set to A.B.C.D, then the default gateway for that interface is initially set to A.B.C.1. The default gateway for each interface may be changed using the console CM or CH or HSM Manager equivalent commands.</b> <b>If necessary, static routes may be re-entered using the console ROUTE and HSM Manager equivalent commands.)</b>
CR 11341	KO Host command enhanced to also provide clear public key modulus and exponent.
CR 11432	Audit log size increased to 50,000 records.
CR 11591	BU command modified to support generating check value of IPEK keys.

### Bugs and Errors Corrected

Ref.	Description of Error
CR 10930	Using a Remote Manager card with the RC console command causes the card to become un-ejectable.
CR 11102	Entering an incorrect PIN (e.g. RH Console command) causes a smartcard error response instead of asking to re-enter the PIN
CR 11106	When an asynchronous host connection is pulled from the USB socket on the payShield 9000, and put back again, the Host connection becomes blocked.
CR 11111	Incorrect PIN entry in HSM Manager - error message just says 'Card Error'
CR 11117	LW host commands sometimes returns keyblocks with an incorrect Exportability value
CR 11373 CR 11396	Inconsistencies in performance between different host interfaces.
CR 11395	Sending an Async host command with zero length command causes HSM's Host Async port to hang until HSM is rebooted or changed to offline and then back to online.
CR 11425	Unable to authorise the import of a ZMK on the Console command line
CR 11502	KO Host command returns encrypted public key exponent and modulus instead of encrypted private key exponent and modulus.



### ***payShield 9000 Software Release Notes***

<b>Ref.</b>	<b>Description of Error</b>
CR 11510	BW Host command returns BX33 when there is no old LMK loaded.
CR 11549	Changing state returns errlog entry with 'Failed to get host IP address, using any'.
CR 11565	ES Host command sometimes incorrectly returns error code 41.
CR 11588	Management Ethernet port might not function if Host 1 Ethernet port is not in use.

## **Version 1.3 Development Stream**

### **Relationship to v1.2**

All fixes and enhancements in the v1.2 stream up to and including 1317-0900 (v1.2a ) are included in v1.3a. Changes in later versions in the v1.2 stream are not included in the v1.3 stream unless these Release Notes explicitly say that they have been included.

### **1317-0915 (v1.3e)**

#### **(Special request only)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.7.2

#### **Manuals**

- Issue 7.1 of the payShield 9000 manuals should be used with this release.

#### **Enhancements to Existing Functions**

<b>Ref.</b>	<b>Description of Enhancement</b>
CR 10965	Prompt to enter a new card in RX Console command has been improved
CR 11193	TEK encrypted under a TMK can now be exported.
CR 11242	Diagnostics now report separately on temperature and fan speed. Fans are no longer stopped and re-started by the diagnostics.
CR 11253	New key scheme introduced for SEED (for HSM9-LIC020)
CR 11257	On-screen text for A Console command (multiple authorized activities state) improved to remind user that console authorizations are limited to 720 minutes.
CR 11259	When trying to disable a core command using CONFIGMDS console command, feedback is now provided that the request has not been actioned.
CR 11260	On-screen text for A Console command (multiple authorized activities state) improved to remind user that persistence can only be applied to host command authorizations. (Persistence required the authorization to be permanent, and console commands cannot now be permanently authorized.)

Ref.	Description of Enhancement
CR 11275	On-screen text for A5 Console command changed to make it clear that limits apply to PIN verification failures.

### **Bugs and Errors Corrected**

Ref.	Description of Error
CR 10548, CR 11139	LMK ID can be set higher than number of licensed LMKs
CR 11369, CR 11141	Import of binary keys allowed without authorization under some circumstances.
CR 11247	When using HSM9-LIC003 (AS2805), errors when importing/exporting keys in key scheme "H".
CR 11293	Requesting Health Check data using HSM Manager results in "Child not found: -1" error message.
CR 11298	With PCI HSM compliant key types implemented, BW Host commands returns error response 04.
CR 11306	DUKPT IPEK should not be parity-adjusted.
CR 11311	PE Host command may return error code 14 even with valid PIN
CR 11318	Diagnostic reporting temperature test failure because fans are turning at wrong speed, even if fan speed is within expected limits.
CR 11335	Corrected types of keyblock keys which can be exported using HSM Manager
CR 11342	Corrected on-screen text in CS & QS Console command relating to Minimum HMAC length.
CR 11368	RS Console command text may show irrelevant entries.

## **1317-0914 (v1.3d)**

### **(Special request only)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.6.1

#### **Manuals**

- Issue 7 of the payShield 9000 manuals is appropriate to this release.

### **Enhancements to Existing Functions**

<b>Ref.</b>	<b>Description</b>
CR 11283	Changes to on-screen messages concerning PCI HSM compliance
CR 11272	Added support for key type BDK-3.
CR 11249	Derivation of DUKPT IPEK keys is now supported by the A0 host command

### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description</b>
CR 11279	PIN with incorrect length causes corruption of printed output.

## **1317-0912 (v1.3b)**

### **(Special request only)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.5.3

#### **Manuals**

- Issue 6 of the payShield 9000 manuals is appropriate to this release.

### **Enhancements to Existing Functions**

<b>Ref.</b>	<b>Description</b>
CR 11073	MAC padding method 3 added.

### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description</b>
CR 11225	In DT Console Command, fan speed tolerances changed when reporting on Temperature.
CR 11147	Performance shaping and utilization statistics not working for FICON interface.
CR 11131	I4 Host Command not returning the Hash Modulus Identifier in the response.
CR 11129	Prompt text for FICONTEST Console command made clearer.

Ref.	Description
CR 11074	Host connections may be closed or fail to open.
CR11016	Authorised commands may not be persistent across re-boot.
CR 10966	Remote Operator smart cards may not eject when being managed at the HSM.
CR 10939	If a large number of Remote HSM Manager Administrator and Operator cards are stored in the HSM, then the HSM Manager "Remove card from Security Group" function does not work and may cause the link between the HSM and HSM Manager to terminate.

## **1317-0911 (v1.3a)**

### **(Special request only)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.5.3

#### **Manuals**

- Issue 6 of the payShield 9000 manuals is appropriate to this release.

#### **New functions**

Description
Support for FICON Host communications (preliminary release).

#### **Enhancements to Existing Functions**

Ref.	Description
CR 10336	Support for AmEx CSC v2 and AEVV.
CR 10155	Support for Discover D-PAS EMV chip-card transactions
	DUKPT data encryption (using PIN-variant of transaction key)
	Binary data encryption using any encryption key
CR 11001	FK modified to prompt user for correctness of key check value for component types X, E and S.
CR 9637	FK Console command now checks for authorization before components are entered.

## ***payShield 9000 Software Release Notes***

### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description</b>
CR 10539	Card does not become active for 2-3 seconds after being inserted.
CR 10613	VR command incorrectly reporting presence of some optional licenses when custom firmware is installed.
CR 10790	GO command does not allow PIN verification using BDK-2.
CR 10790	M2 command uses wrong key variant to decrypt a message encoded using BDK-2.
CR 10799	AG command returns parity error when PCI HSM compliant key types are being used.
CR 10862	HSM can freeze, with error LED blinking red.
CR 10870	TCP/IP keep-alive not working properly
CR 10988	EW (RSA signing) enforces use of DER encoding.
CR 11108	Turning off Alarm settings using HSM Manager does not delete LMKs (in the way that CL Console command does).
CR 9638	When using CL Console command, LMKs should not be erased if alarms are turned on (only if they are turned off).
CR 10699	Difficulty in connecting Remote HSM Manager to low-speed HSMs.

## Version 1.2 Development Stream

### 1317-0900 / 1317-1900 (v1.2a)

#### (Special request only)

#### PCI HSM Compliant?

- ***This software has been certified for PCI HSM compliance.*** PCI HSM compliance of the payShield 9000 is subject to appropriate user settings having compliant values – see manuals.
- Software number 1317-0900 applies if some security settings are not PCI HSM compliant. Software number 1317-1900 applies if all security settings are PCI HSM compliant. (See manuals)

#### HSM Manager Compatibility

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.4.7

#### Manuals

- Issue 5 of the payShield 9000 manuals is appropriate to this release.

#### Relationship to v1.1

All fixes and enhancements in the v1.0 stream up to and including 1110-0921 (v1.1b ) are included in v1.2a. Changes in later versions in the v1.1 stream are not included in the v1.2 stream unless these Release Notes explicitly say that they have been included.

#### New functions

Description
This release is certified to be compliant with the requirements of PCI HSM. This introduces the following new capabilities. Full information about these features is included in the manuals set
The ability to change the software revision number (as viewed using the VR Console report) from format nnnn-09nn to nnnn-19nn if the software is PCI HSM certified and all settings have compliant values.
Various indications on the Console and HSM Manager as to the PCI HSM status of the HSM.
New mode in the NO Host command to allow a Host computer to retrieve the PCI HSM status of the payShield 9000.
Minimum length of 5 digits for PINs used to authenticate Console and HSM Manager users.
60-second time-out when PIN entry is requested to authenticate users.

Description
Maximum of 12 hours allowed when authorizing Console commands.
Ability to switch to new key types required for PCI HSM compliant key separation, and extension of the BW Host command to allow keys to be migrated to the new key types.
Ability to switch on restrictions on PIN block usage and translation as required by PCI HSM and ISO 9564/X9.8.
Automated daily self-tests of the HSM, with a facility (e.g. using the ST Console command) to set the time of day when the self-test is run.
Serial numbers of smartcards used to authenticate users are automatically recorded in the Audit Log.
Certain sensitive events are automatically recorded in the Audit Log.
Certain legacy Console commands have been removed.
Certain legacy Host commands are disabled when the HSM is in a PCI HSM compliant state.

#### **Other Enhancements to existing functions**

Ref.	Description
CR 10801	Minor change to Random Bit Generator to allow for possible future application extensions.

#### **Bugs and Errors Corrected**

Ref.	Description
CR 10899	HSM Manager may fail to view the Audit Log.
CR 10804	Console may become unresponsive if HSM state is changed a large number of times.
CR 10785	Custom TR-31 key types may fail to Import.
CR 10764	With Keyblock LMKs, GK and EW commands incorrectly expect "FF" in certain fields.



## **Version 1.1 Development Stream**

### **1110-0921 (v1.1b)**

#### **(Special request only)**

##### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

##### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.3.16

##### **Manuals**

- Issue 4 of the payShield 9000 manuals is appropriate to this release with the following upgrades:
  - Host Command Reference Manual Issue 4.3
  - Console Reference Manual Issue 4.1
  - Local HSM Manager User's Guide Issue 4.1
  - Installation Manual Issue 4.1

##### **Relationship to v1.0**

All fixes and enhancements in the v1.0 stream up to and including 1110-0913 (v1.0e ) are included in v1.1a. Changes in later versions in the v1.0 stream are not included in the v1.1 stream unless these Release Notes explicitly say that they have been included.

##### **Enhancements to existing functions**

<b>Ref.</b>	<b>Description</b>
CR 10704	MAC commands now support
CR 10616	Printer flow control now allows: <ul style="list-style-type: none"><li>➤ Concurrent software and hardware flow control</li><li>➤ Hardware flow control allows selection of which line (RTS, CTS, DTR) to use for flow control.</li><li>➤ Configurable time-out when waiting for XON.</li></ul>

##### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description</b>
CR 10804	Console may become unresponsive if switching between Online and Secure states many times in succession.

## ***payShield 9000 Software Release Notes***

<b>Ref.</b>	<b>Description</b>
CR 10777	Printing commands that have 2 responses may return error 15 when working in EBCDIC.
CR 10776	When using parallel printers sometimes only 3 digits of the PIN are printed,
CR 10757	RT console command could hang when creating multiple cards and answering "N" to the prompt about overwriting a card.
CR 10755	RT console command incorrectly reports that a card that has been reset using the RX console command contains an LMK component.
CR 10729	Inability to add some cards to some Remote HSM Manager security groups
CR 10688	When trying to remove a smart card from a Remote HSM Manager security group, an incorrect error report is made that the card was used to connect to HSM Manager.
CR 10682	Settings for "CONFIGCMDS" console command are not being retained over a re-boot.
CR 10671	Loading of code fails
CR 10666	FK console command and HSM Manager give different results when forming a key.
CR 10663	An authorized activity that was previously made "permanent" cannot subsequently be made "persistent".
CR 10660	When unauthorizing a sub-category in a category which is authorized, the unauthorization is applied to all the other sub-categories.
CR 10659	Authorization of commands using HSM Manager does not pick up the setting disallowing persistence if that was made at the console.
CR 10658	When using HSM Manager, a modification to make an authorization persistent may be overridden by a subsequent new authorization which is not persistent.
CR 10620	JU command does not return correct response where Mode Flag is 3 or 4.
CR 10614	Occasional crashing of print resource manager.
CR 10593	Incorrect error code sometimes provided when printing.
CR 10572	EO host command (Import a Public Key) may change the ASN.1 encoding of the public key.

Ref.	Description
CR 10543	Authorization of Export for key types 300 and 400 results in "invalid entry" error.
CR10342	Authorization using LMK cards created on another version of HSM software may not work.

## **1110-0920 (v1.1a)**

### **(Special request only)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.3.15

#### **Manuals**

- Issue 4 of the payShield 9000 manuals has been created for this release. The following manuals are at Issue 4.1:
  - Local HSM Manager User's Guide
  - Installation Manual
  - Host Command Reference manual.

#### **Relationship to v1.0**

All fixes and enhancements in the v1.0 stream up to and including 1110-0913 (v1.0e ) are included in v1.1a. Changes in later versions in the v1.0 stream are not included in the v1.1 stream unless these Release Notes explicitly say that they have been included.

#### **New functions**

Description
Reset to factory (default) settings. <b>Important</b> -This function does not change the software and license installed on the HSM. Therefore any software and license installed since the HSM was delivered to the customer will remain on the HSM.
Use of DUKPT for general data encryption
Enhancements to EMV Card data preparation capabilities to allow the use of an Issuer RSA key set for multiple certificates, the ability to use pre-generated RSA keys for the creation of card certificates, and validation for CA self-signed certificates (KK Host command). <i>(This functionality requires Optional License</i>

## payShield 9000 Software Release Notes

Description
016.)
Enhancement to EMV Card data preparation to encompass Multos cards.
Card personalization based on EMV Common Personalization Specification (CPS) and Global Platform (GP) using Secure Channel Protocol 2 (SCP02). The Indirect/Explicit method is supported. Also support for the specific process required for MasterCard PayPass Magnetic Stripe Cards. Implemented in IE and IC Host commands. ( <i>This functionality requires Optional License 018.</i> )
Enablement of the second Host Ethernet port, allowing for 2 concurrently active ports, each with their own IP address and support for 64 threads/connections. This allows users to set up dual network paths to provide resilience against network failure.
Utilization Statistics, to enable users to see how heavily loaded the HSM is, and the volumes of all Host commands. Data is available via the Console, HSM-attached printer, Local HSM Manager, Remote HSM Manager, Host command, or SNMP.
Health Check Status and Statistics, to enable users to see the current health of their HSM and to access counters for health-related events. Data is available via the Console, HSM-attached printer, Local HSM Manager, Remote HSM Manager, Host command, or SNMP.
SNMP Agent Request/Response support to allow Utilization Statistics Health Check data to be retrieved by an SNMP Manager.

### Security Enhancements and Fixes

Ref.	Description
CR 10214	Invalid characters in filenames for code loaded onto the HSM are now handled gracefully.
CR 10307	HSM now handles LS host command with too much data.
CR 10312	HSM now handles multiple successive M0 host commands with large payloads.
CR 10352, CR 10353	Malformed host commands are handled gracefully.
CR 10487	Enhancement made to security relating to code loading. PLEASE NOTE: a side effect of this change is that any user downgrading their installed HSM software from v1.1 (or later) to v1.0 will have to re-load their LMK and recover their Remote HSM Management key data (in the same way as if a tamper had occurred).

**Other Enhancements to existing functions**

Ref.	Description
CR 10488	Enhanced printing performance.
CR 10535	Hardware and software flow control added to printing function.
CR 10545	HSM now checks the printer connection when trying to print.

**Bugs and Errors Corrected**

Ref.	Description
CR 9792	A6 Console command can cause the HSM to halt if input is too long.
CR 10163	Auditlog Console command can cause an error if the HSM time has been re-set to an earlier time.
CR 10206	Authorization for custom host commands does not work properly in multiple authorised activities mode.
CR 10308	A2 Host command not returning Key Check Value.
CR 10430	PE Host command returns invalid return code.
CR 10506	LMK selection by port number not working for some Host commands (inc. NC and A0).
CR 10611	VR console command now correctly identifies LIC018 and LIC023 licenses.
CR 10554	When the USB serial printing cable is disconnected and reconnected, sometimes the serial settings aren't set.
CR 10600	HSM Manager issue with scroll-bar button in authorization screen.
CR 10595	HSM Manager issue listing currently authorized activities.
CR 10529	HSM Manager issue with timeout value for authorized activities.
CR 10525	HSM Manager issue with Change PIN function after user login.
CR 10512	HSM Manager issue with changing the host configuration details from Offline state.
CR 10474	HSM Manager now supports authorization of custom host commands.
CR 10464	HSM Manager issue supporting for async host connection.

## ***payShield 9000 Software Release Notes***

<b>Ref.</b>	<b>Description</b>
CR 10403	HSM Manager now checks for unique subnets on all Ethernet interfaces.
CR 10203	HSM Manager now retains IP address after connection to the HSM is lost (e.g. cable disconnected, HSM reboot, etc.)
CR 10204	HSM Manager was occasionally missing an entry when displaying the error log.
CR 9945	RG console command now correctly ejects Multos card.

## **Version 1.0 Development Stream**

### **1110-0914 (v1.0f)**

#### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

#### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.2.27
- 3.2.22

#### **Relationship to v1.1**

All fixes and enhancements in this release are not included in the v1.1 stream unless these Release Notes explicitly say that they have been included.

#### **Manuals**

The manuals introduced for v1.0c (Issue 3) are applicable to this release.

#### **Enhancements to existing functions**

<b>Ref.</b>	<b>Description</b>
CR 10535	Hardware and software flow control added to printing function.

#### **Bugs and Errors Corrected**

<b>Ref.</b>	<b>Description</b>
CR 10620	JU command does not return correct response when mode flag is 3 or 4.
CR 10560	PIN printing does not resume if printer is reconnected after being disconnected
CR 10549	Intermittent corruption of PIN mailers.
CR10544	PIN mailer printing now supports UTF8 characters.
CR 10530	Certain Host commands (inc. M6, SA, JA), when iterated a number of times, can cause error reports and the HSM to halt.
CR 10477	BG Host command can cause the HSM to halt when encountering certain encrypted PIN values.

## **1110-0913 (v1.0e)**

### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.2.22

### **Manuals**

The manuals introduced for v1.0c (Issue 3) are applicable to this release.

### **Enhancements**

Description
Enhancements made to Gemalto ADK.

### **Bugs and Errors Corrected**

Ref.	Description
CR 9869	Corrected incorrect reporting of fans turning slowly.
CR 9873	Fan speed resumes at correct rate after use of DT console command.
CR 10441	A2 command using Key Blocks now returns a Key Check Value.

### **Special Note**

The JS and JU commands introduced in 1110-0904 (v1.0b) are now available in this release, and will be carried forward to future releases.

## **1110-0912 (v1.0d)**

### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)



### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.2.22

### **Manuals**

- The manuals introduced for v1.0c (Issue 3) are applicable to this release.

### **Enhancements**

Description
Support for new smartcards introduced December 2010.

### **Bugs and Errors Corrected**

Ref.	Description
CR 10163	Error light comes on when running AUDITLOG console command.
CR 10293	Key Type 207 failing with IC and IE commands.
CR10308	Key Check Value not returned with A2 Host Command.

### **Special Note**

The JS and JU commands introduced in 1110-0904 (v1.0b) are **not** available in this release.

## **1110-0911 (v1.0c)**

### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. (*Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.*)

### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 3.2.22

### **Enhancements to existing functions**

Ref.	Description
CR 8257	Modified console command CONFIGCMDS, such that it displays the list of currently enabled host/console commands when in Online & Offline state.

## ***payShield 9000 Software Release Notes***

<b>Ref.</b>	<b>Description</b>
CR 8256	Modified console command CONFIGPB, such that it displays the list of currently enabled PIN block formats when in Online & Offline state.
	Added new console command RD, which (in Secure state) deletes all remote management related configuration data.
	Modified console command RY, which (in Secure state) no longer prompts to delete all remote management related configuration data.
CR 9108	Modified HSM Manager to support persistent authorized activities.
CR 9576	Modified HSM Manager to support non-base key types.
	Modified HSM Manager to support download of new firmware into the HSM.
	Modified HSM Manager to support download of a new license into the HSM.
	Modified HSM Manager to allow Remote Configuration to be displayed.
	Modified Remote HSM Manager to allow current HSM's Security Group to be displayed.
CR 9819	Console ROUTE "show" command now displays a list of persistent routes, and avoids deletion of all persistent routes if "delete" command is entered without parameters.
CR 9848	When the HSM enters a tampered state, console/host commands are no longer available.

### **Bug Fixes and Error Corrections**

<b>Ref.</b>	<b>Description</b>
CR 9781	Fixed an issue with changing the Advanced Settings via Local/Remote HSM Manager. After changing these settings, the HSM will reboot- if appropriate.
CR 9806	Fixed problem where KO host command could hang HSM when using certain parameters.
CR 9872	Fixed an issue with authorizing activities, which was not permitting key type 002 to be authorized for export.
CR 9949, CR 9950, CR 9951	Fixed internal issues regarding the underlying protocol between HSM and HSM Manager.

## ***payShield 9000 Software Release Notes***

<b>Ref.</b>	<b>Description</b>
CR 10037	Removed undocumented console command QK, which displayed the HSM's current state.
CR 10088	Fixed an issue with console command RY, which was incorrectly formatting the output text.
CR 10104	Fixed an issue with copying LMK components using Local HSM Manager.
CR 9625	Fixed an issue with HSM Manager, where the Key Generation Wizard was failing to generate certain types of keys.
CR 9736	Management Port IP address change no longer requires a re-boot.
CR 9806	Fixed an issue in KO command where some parameter settings could cause the HSM to hang.
CR 9809	A8 command now allows TMK to be exported in TR-31 form, when key usage is K0.
CR 9920	Fixed issues in running PA and PC host commands with large amounts of data.
CR 10048	Prevent lost host connections when both left and right keys turned at the same time from Secure state.
CR 9898	Corrected a problem that was causing code loading by FTP to fail.

### **Special Note**

The JS and JU commands introduced in 1110-0904 (v1.0b) are **not** available in this release.

### **1110-0904 (v1.0b)**

#### **(Limited release only)**

### **PCI HSM Compliant?**

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 2.6.4

## Enhancements

Ref.	Description
SMO 1358, SMO 1359	Introduction of JS and JU commands (requiring HSM8-LIC031) for CUP.

## 1110-0902 (v1.0b)

### PCI HSM Compliant?

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

### HSM Manager Compatibility

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 2.3.9

### Bug Fixes and Error Corrections

Ref.	Description
	Fixed problem with DT console command, which was incorrectly reporting that fans were running slowly. (CR9869)
	Fixed problem with DT console command, which on exit, was setting the fans to high speed. (CR9873)
	Fixed problem where console operation was not being restored in the event of the management session being abnormally terminated. (CR9678)
	Fixed internal issue to do with state requirements for console commands. (CR9525)
	Fixed problem where Ethernet based host comms were still active when unit was configured for async connectivity. (CR9140)

## 1110-0901 (v1.0a)

Initial release of base software.

### PCI HSM Compliant?

This software has not been certified to the PCI HSM standard. *(Note that there is no requirement for HSMs currently in use to be PCI HSM certified or to become PCI HSM certified in the future.)*

### **HSM Manager Compatibility**

This version of HSM software is compatible with the following release(s) of Local/Remote HSM Manager:

- 2.3.9

# Known Significant Base Software Issues

The following table lists significant issues which are known to exist in HSM 8000 and payShield 9000 software and which are not yet resolved. The evaluation of an item as "significant" may change, resulting in items being added to or removed from the list. Items will be removed from the list as they are resolved, and the resolution will be reported in the appropriate Release Note:

Ref.	Description	HSM 8000	payShield 9000	HSM Mngr	Found in version
CR 13277	Vulnerability announced in Security Advisory TESA-2015-004.	No	Yes	No	2.0a-2.3c
CR 13098	Vulnerability announced in Security Advisory TESA-2014-001.	No	Yes	No	1.1a-2.3b
CR 12016	The console may become unresponsive if it is connected to the left-hand USB port on the front panel of the payShield 9000, following certain events (such as a software load). The problem has been observed only intermittently.	No	Yes	No	2.0a & 2.0b
CR 10160	RMK may not be retained when upgrading from v3.1a, b, or c.	Yes	No	No	3.1a-c

# Other Useful Information

## PCI HSM Certified versions of payShield 9000 base software

This table indicates which versions of payShield 9000 software have been formally certified. Note that:

- From v1.2a onwards, the functionality added for PCI HSM compliance exists in all software versions, including those which have not been formally certified.
- Even if certified software is installed on the payShield 9000, in order for the unit to be PCI HSM compliant the hardware must be certified, the security settings must have appropriate values, and the unit must have been delivered in a compliant manner.
- There is no requirement for HSMs currently being deployed to be PCI HSM compliant or to become PCI HSM compliant in the future.
- "Planned" means that the software is not yet certified, but it is planned to submit it for certification.
- In all PCI certified versions, the software number included in the PCI certificate is of the format xxxx-19xx (as opposed to xxxx-09xx). The software number automatically changes to the xxxx-19xx format when all security settings are PCI compliant. In addition, all software from v2.3c and software in then 2.1 stream from 2.1c onwards also modify their software number in this way, even if the software has not been PCI certified.

Version	PCI HSM Certified	Software Revision if security settings are <u>not</u> PCI HSM compliant	Software Revision if security settings <u>are</u> PCI HSM compliant
V1.0a – V1.1b	No	1110-09xx	N/A
<b>V1.2a</b>	<b>Yes</b>	<b>1317-0900</b>	<b>1317-1900</b>
V1.3a – V1.3e	No	1317-0911 to 1317-0915	N/A
V1.4a - V1.4e	No	1317-0916 to 1317-0920	N/A
V2.0a - V2.0c	No	1346-0900 to 1346-0904	N/A
<b>V2.1c</b>	<b>Yes</b>	<b>1346-0905</b>	<b>1346-1905</b>
<b>V2.1d</b>	<b>Yes</b>	<b>1346-0907</b>	<b>1346-1907</b>
V2.1e	No	1346-0908	1346-1908
V2.2a – V2.2b	No	1346-0910 to 1346-0911	N/A
V2.3a – V2.3b	No	1346-0912 to 1346-0913	N/A
<b>v2.3c</b>	<b>Yes</b>	<b>1346-0914</b>	<b>1346-1914</b>

### ***payShield 9000 Software Release Notes***

<b>Version</b>	<b>PCI HSM Certified</b>	<b>Software Revision if security settings are <u>not</u> PCI HSM compliant</b>	<b>Software Revision if security settings <u>are</u> PCI HSM compliant</b>
v2.3d – v2.3e	No	1346-0915 to 1346-0916	1346-1915 to 1346-1916
<b>v2.3f</b>	<b>Planned</b>	<b>1346-0917</b>	<b>1346-1917</b>
v2.4a	No	1346-0918	1346-1918
<b>v3.0b</b>	<b>Planned</b>	<b>1407-0901</b>	<b>1407-1901</b>

Further information about PCI HSM compliance and the payShield 9000 can be found in the following Thales documents:

- payShield 9000 General Information Manual (Chapter 10) – provided with software versions 1.2a onwards.
- Application Note: PWPR0521 Overview of PCI HSM Certification Requirements
- Application Note: PWPR0523 PCI HSM-compliant Shipping



## payShield 9000 vs. HSM 8000

The payShield 9000 HSM is functionally backward compatible with the Thales HSM 8000 and RG7000 product lines. The host-side functionality provided in payShield 9000 software v1.0 is identical to that provided by the HSM 8000 software v3.1a. However, in order to support some of the more advanced features of the payShield 9000, there are inevitably some differences between the two products. The table below identifies the most significant differences.

payShield 9000 vs HSM 8000			
	Function	HSM 8000	payShield 9000
Rear Panel	Power Sockets	x1	x1 or x2 (factory fit option)
	Ethernet Host Ports	x1 (10/100 Mbps)	x2 (10/100/1000 Mbps) <sup>1</sup>
	Management Port	x1 (10 Mbps)	x1 (10/100/1000 Mbps)
	Ethernet Printer Port	No	x1 (10/100/1000 Mbps) <sup>2</sup>
	Console Port	9-way 'D' Console Port	via USB-to-serial cable. Max. cable length may be different to HSM 8000.
	Async Host Port	via DTE-DCE cable dongle	via USB-to-serial cable. Max. cable length may be different to HSM 8000.
	ESCON Host Port	Option	No
	FICON Host Port	No	Option
	Serial Printer Port	25-way 'D' Auxiliary Port	via USB-to-serial cable. Max. cable length may be different to HSM 8000.
	Parallel Printer Port	25-way 'D' Printer Port	via USB-to-parallel cable. Max. cable length may be different to HSM 8000.
	Erase Sensitive Data	Red reset/erase button in Secure state (front panel)	Recessed Erase button
Front Panel	Console Port	9-way 'D' Console Port	via USB-to-serial cable. Max. cable length may be different to HSM 8000.
	Reset HSM	Red reset/erase button	Red reset button
	LMK(s) loaded indicator	Secure LED	LMK LED
	Host Activity indicator	Activity LED	Host 1 & Host 2 LED
	Management Activity indicator	No	Management LED
	Power supply indicator	Power LED (Green)	Power LED (various colours) <sup>3</sup>
	Unit serial number	Rear panel	Front & rear panel

<sup>1</sup> Only one Ethernet host port is functional in release v1.0. Dual host port capability became available with v1.1a.

<sup>2</sup> Ethernet printing is not currently supported. It may be implemented in the future, using the AUX Ethernet port.

<sup>3</sup> Colour indicates status of single/dual power supplies

## **payShield 9000 Software Release Notes**

<b>payShield 9000 vs HSM 8000</b>			
	<b>Function</b>	<b>HSM 8000</b>	<b>payShield 9000</b>
<b>Configuration</b>	Motion Detector (Sensitivity)	Off/On	Off/Low/Medium/High
	Console Port speed	300...38400 baud	1200...115200 baud
	Async Host Port speed	300...38400 baud	1200...115200 baud
	Serial Printer Port speed	300...38400 baud	1200...115200 baud
	IP routing	via gateway	via gateway or static route
	ROUTE console command	No	Yes
	CA, QA console commands	Yes	No
	Software Update	via ImageLoader utility	via FTP or USB
	Licence Update	via ImageLoader utility	via FTP
	Startup time	~2-3 mins	~20 seconds
	Maximum performance	800 tps <sup>4</sup>	1500 tps <sup>5</sup>
<b>Misc.</b>	PCI HSM certification	No	Yes (selected hardware & software versions). This introduces functionality differences to the HSM 8000 in payShield 9000 v1.2a onwards – see the payShield 9000 General Information Manual, Chapter 10.
	DB, DF, K, YC console command	Yes	Not available from v1.2a onwards
	AA, AE, FC, FE, FG, HC, KA, OE host command	Yes	Not available from v1.2a onwards depending on security settings – see General Information Manual, Chapter 10
	Functionality	n/a	From payShield 9000 v1.1a additional functionality has been added compared with the HSM 8000 – see the payShield 9000 Release Notes.

<sup>4</sup> Multi-threaded CA host command performance using Variant LMK

<sup>5</sup> Multi-threaded CA host command performance using Variant or Keyblock LMK

## Local & Remote HSM Manager Compatibility Information

This table lists the releases of HSM Manager, and indicates which software numbers/versions of HSM 8000 and payShield 9000 base software they are compatible with.

It is possible that other combinations will work, either completely or partially, but this should not be relied upon.

**Note: HSM Manager is not compatible with software v3.0 and above.**

### Part 1 – Versions 3.5.x and later

	Local & Remote HSM Manager Version ↓																	
HSM Software ↓	3.5.3	3.6.1	3.7.2	3.8.1	3.8.2	4.0.8	4.0.10	4.0.12	4.1.0	4.1.4	4.1.7	5.0.19	5.1.4	5.1.7				
HSM 8000																		
1110-0880-0887 (v3.3a-g)	☑																	
payShield 9000																		
1346-0918 (v2.4a)														☑				
1346-0912 to -0917 (v2.3a-f)														☑				
1346-0910 & -0911 (v2.2a-b)												☑	☑					
1346-0907 & -0908 (v2.1d-e)											☑							
1346-0905 & -1905 (v2.1c)									☑	☑								
1346-0902 to -0904 (v2.0b-c)								☑	☑	☑								
1346-0900 (v2.0a)						☑	☑											
1317-0922 (v1.4g)					☑													
1317-0916 to -0919 (v1.4a-d)				☑														
1317-0915 (v1.3e)			☑															
1315-0914 (v1.3d)		☑																
1317-0911 to -0913 (v1.3a-c)	☑																	

## Local & Remote HSM Manager Software Release Notes

### Part 2 – Versions up to 3.4.x

	Local & Remote HSM Manager Version ↓														
HSM Software ↓	2.1.4	2.1.5	2.1.15	2.3.9	2.6.4	2.6.5	3.2.17	3.2.19	3.2.21	3.2.22	3.2.27	3.3.14	3.3.15	3.3.16	3.4.7
<b>HSM 8000</b>															
1110-0870 (v3.2a)												☑			
1110-0864 to -0866 (v3.1g-i)										☑					
1110-0863 (v3.1f)								☑			☑				
1110-0862 (v3.1e)								☑							
1110-0861 (v3.1d)								☑							
1110-0860 (v3.1d <sup>1</sup> )								☑							
1110-0856 (v3.1c)					☑	☑									
1110-0854 (v3.1c)					☑	☑									
1110-0850 to 1110-0852 (v3.1c)					☑	☑									
1110-0831 to -0840 (v3.1a-b)	☑	☑	☑												
<b>payShield 9000</b>															
1317-0900 & -1900 (v1.2a)															☑
1110-0921 (v1.1b)														☑	
1110-0920(v1.1a)													☑		
1110-0914 (v1.0f)										☑	☑				
1110-0911 to -0913 (v1.0c-e)										☑					
1110-0910 (v1.0c)							☑								
1110-0904 (v1.0b)					☑										
1110-0901 to -0902 (v1.0a-b)				☑											

#### NOTES:

1. This table can also be used to determine compatibility between HSM Manager and Customised software, by using the version of base software that the customised software was developed from.
2. HSM Manager is designed to work with standard base software, and therefore additional or changed functionality introduced in customised software will not be available through HSM Manager.

## Technical support contacts

Our team of knowledgeable and friendly support staff is available from 8.30am to 5pm (local time), Mondays to Fridays. If your product is under warranty or you hold a support contract with Thales e-Security, do not hesitate to contact us. For more information, consult our standard Terms and Conditions for Warranty and Support.

Regional Support Centres
<b>Americas</b>  Tel: +1 954-888-6277 or: +1 800-521-6261 Fax: +1 954-888-6233 Email: <a href="mailto:support@thalesesec.com">support@thalesesec.com</a>
<b>Asia Pacific</b>  Tel: +852 2815 8633 Fax: +852 2815 8141 Email: <a href="mailto:asia.support@thales-esecurity.com">asia.support@thales-esecurity.com</a>
<b>Europe, Middle East, Africa</b>  Tel: +44 (0)1223 723666 Email: <a href="mailto:emea.support@thales-esecurity.com">emea.support@thales-esecurity.com</a>

## About Thales e-Security

Thales e-Security is a leading global provider of data encryption and cyber security solutions to the financial services, high technology manufacturing, government and technology sectors. With a 40-year track record of protecting corporate and government information, Thales solutions are used by four of the five largest energy and aerospace companies, 22 NATO countries, and they secure more than 80 percent of worldwide payment transactions. Thales e-Security has offices in Australia, France, Hong Kong, Norway, United Kingdom and United States. For more information, visit [www.thales-esecurity.com](http://www.thales-esecurity.com)

## Follow us on:

