

WM-SG-SM-42 Update Preloaded AT Command FW Application Note

Version: 1.2

Universal Scientific Industrial Co., Ltd.		Doc No.		Rev	1.2
Document release by WSS2/WP1/SW		Date.	2017/05/09	Page	2
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note				

Contents

1.	Preparation.....	3
2.	SWD interface connection on WM-SG-SM-42 EVB	4
3.	SWD interface connection on WM-SG-SM-42 Shield	5
4.	UART interface connection on WM-SG-SM-42 EVB.....	6
5.	UART interface connection on WM-SG-SM-42 Shield	7
6.	STLINK/V2-1 Connection	8
7.	The update procedure	9
7.1	Backup NV data.....	9
7.2	Update the preloaded firmware.....	10
7.3	Update the preloaded firmware with backup file	12
8.	The usage of sm42_backup.bat.....	13
9.	The usage of sm42_update.bat	14

Universal Scientific Industrial Co., Ltd.		Doc No.		Rev	1.2
Document release by WSS2/WP1/SW		Date.	2017/05/09	Page	3
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note				

1. Preparation

This document is for introduce how to update the firmware of WM-SG-SM-42 based on WM-SG-SM-42 EVB on windows PC. Please ensure the following items is on your hand or installed already.

1) **Windows PC for running the update tool.**


The FW update tool is a windows console mode program, so we need a windows PC for running the update tool.

2) **The WM-SG-SM-42 module/EVB.**

The module/EVB needed to be updated.

3) **The WM-SG-SM-42 FW update package.**

The FW update package is a zip file which contains a custom openocd program and a custom hex file, so all the WM-SG-SM-42 firmware only can be updated by the custom openocd program. The file structure would be as the below:



4) **FTDI VCP driver.**

The PC may need the FTDI VCP driver when the micro USB of WM-SG-SM-42 EVB connected on the PC, so the FTDI VCP driver can be downloaded from the web page below:

<http://www.ftdichip.com/Drivers/VCP.htm>

5) **ST-LINK/V2-1 Programmer and ST-LINK Utility tool.**



The ST-LINK utility tool can be downloaded from the web page below:

http://www.st.com/content/st_com/en/products/embedded-software/development-tool-software/stsw-link004.html

Universal Scientific Industrial Co., Ltd.		Doc No.		Rev	1.2
Document release by WSS2/WP1/SW		Date.	2017/05/09	Page	4
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note				

2. SWD interface connection on WM-SG-SM-42 EVB

The following shows how to connect the SWD of WM-SG-SM-42 EVB to ST-LINK/v2-1 programmer.




PIN NAME	ST-LINK/V2 PIN No.	WM-SG-BM-42 EVB PIN No.
VCC	JTAG/SWD-P1	JP35-P1
SWCLK	JTAG/SWD-P9	JP35-P2
GND	JTAG/SWD-P8	JP35-P3
SWDIO	JTAG/SWD-P7	JP35-P4

Universal Scientific Industrial Co., Ltd.		Doc No.		Rev	1.2
Document release by WSS2/WP1/SW		Date.	2017/05/09	Page	5
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note				

3. SWD interface connection on WM-SG-SM-42 Shield

The following shows how to connect the SWD of WM-SG-SM-42 Shield to ST-LINK/v2-1 programmer.




PIN NAME	ST-LINK/V2 PIN No.	WM-SG-BM-42 EVB PIN No.
VCC	JTAG/SWD-P1	JP6-P1
SWCLK	JTAG/SWD-P9	JP6-P2
GND	JTAG/SWD-P8	JP6-P3
SWDIO	JTAG/SWD-P7	JP6-P4


Universal Scientific Industrial Co., Ltd.	Doc No.		Rev	1.2
Document release by WSS2/WP1/SW	Date.	2017/05/09	Page	6
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note			

4. UART interface connection on WM-SG-SM-42 EVB

- 1) The following shows the UART setting and how to connect UART of WM-SG-SM-42 EVB to PC.



- 2) After connect WM-SG-SM-42 EVB to Windows PC, there are two continued serial port number would appear on the window of device manager as the following picture, the higher serial port number is connected to the UART of WM-SG-SM-42, please specify the higher serial port number at the command line of openocd.




The content of this document is to be treated as strictly confidential and is not to be disclosed, reproduced or used, except as authorized in writing by Universal Scientific Industrial Co.,Ltd.
Copyright(c) 2016 Universal Scientific Industrial Co.,Ltd.

Universal Scientific Industrial Co., Ltd.		Doc No.		Rev	1.2
Document release by WSS2/WP1/SW		Date.	2017/05/09	Page	7
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note				

5. UART interface connection on WM-SG-SM-42 Shield

- 1) The following shows the UART setting and how to connect UART of WM-SG-SM-42 shield to PC.



Universal Scientific Industrial Co., Ltd.		Doc No.		Rev	1.2
Document release by WSS2/WP1/SW		Date.	2017/05/09	Page	8
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note				

6. STLINK/V2-1 Connection

Please ensure that 'STMicroelectronics STLink dongle' appears on the window of device manager before run the openocd program.



Universal Scientific Industrial Co., Ltd.	Doc No.		Rev	1.2
Document release by WSS2/WP1/SW	Date.	2017/05/09	Page	9
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note			

7. The update procedure

7.1 Backup NV data

Since the nv data inside the module will be destroyed during the update, so please back up the NV data of module to local disk using 'sm42_backup.bat' before programming the preloaded AT command software or before programming your customize software. The backup NV file cannot be restored to other module and the filename is named with the device EUI. the preload AT command software provides an AT command 'AT+EUI' for EUI inquiry.

```
F:\sm42_fw_update_tool_v1.0\sm42_fw_update_tool\bin>sm42_backup.bat 16
F:\sm42_fw_update_tool_v1.0\sm42_fw_update_tool\bin>openocd-dev -B -S 16 -f ..\scripts -f interface\stlink-v2-1.cfg -f target\stm32l0.cfg -c "init" -c "reset" -
c "write_bin dummy reset exit"
Open On-Chip Debugger 0.9.0-dev-v1.2 (2017-02-27-12:14)
Licensed under GNU GPL v2
For bug reports, read
http://openocd.org/doc/doxygen/bugs.html
Info : starting to backup nv ...
.....
Info : backup nv is valid
Info : current fw version in module: 2.800000
Info : found eui: 343834334D367B08
Info : finish nv backup.
Info : auto-selecting first available session transport "hla_swd". To override use 'transport select <transport>'.
adapter speed: 300 kHz
adapter_nsrst_delay: 100
Info : The selected transport took over low-level target control. The results might differ compared to plain JTAG/SWD
none separate
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : clock speed 240 kHz
Info : STLINK v2 JTAG v27 API v2 SWIM v15 VID 0x0483 PID 0x374B
Info : using stlink api v2
Info : Target voltage: 3.277470
Info : stm32l0.cpu: hardware has 4 breakpoints, 2 watchpoints
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
adapter speed: 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
adapter speed: 240 kHz
target state: halted
target halted due to debug-request, current mode: Thread
xPSR: 0xf1000000 pc: 0x080000d4 msp: 0x20001830
STM32L0: Enabling HSI16
Info : Unable to match requested speed 2500 kHz, using 1800 kHz
Info : Unable to match requested speed 2500 kHz, using 1800 kHz
adapter speed: 1800 kHz
** Programming Started **
auto erase enabled
Info : ST32L flash size is 64KB, base address is 0x8000000
Info : Found unique device id = 343834334D367B08
Info : nv was backup in '343834334D367B08.bak'
** Programming Finished **
** Resetting Target **
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
adapter speed: 240 kHz
shutdown command invoked
F:\sm42_fw_update_tool_v1.0\sm42_fw_update_tool\bin>
```

16 is the number of uart shown in the device manager

backup the backup file to other path, and past the backup file here for restore the preloaded firmware. the backup file can not restore to other module, this number will be the same with the response of 'AT+EUI' command.

The content of this document is to be treated as strictly confidential and is not to be disclosed, reproduced or used, except as authorized in writing by Universal Scientific Industrial Co.,Ltd.
Copyright(c) 2016 Universal Scientific Industrial Co.,Ltd.

Universal Scientific Industrial Co., Ltd.		Doc No.		Rev	1.2
Document release by WSS2/WP1/SW		Date.	2017/05/09	Page	10
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note				

7.2 Update the preloaded firmware

Normally, the update tool will back up the nv data at first, and will restore the back up nv data automatically after programming the firmware.

Universal Scientific Industrial Co., Ltd.	Doc No.		Rev	1.2
Document release by WSS2/WP1/SW	Date.	2017/05/09	Page	11
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note			

```

F:\sm42_fw_update_tool_v1.0\sm42_fw_update_tool\bin>sm42_update.bat 16 wm-sg-sm-42_firmware_v2.7.hex
F:\sm42_fw_update_tool_v1.0\sm42_fw_update_tool\bin>openocd-dev -S 16 -f scripts -f interface\stlink-v2-1.cfg -f target\stm3210.c
ock 0" -c "reset" -c "write_bin wm-sg-sm-42_firmware_v2.7.hex reset exit"
Open On-Chip Debugger 0.9.0-dev-v1.2 (2017-02-27-12:14)
Licensed under GNU GPL v2
For bug reports, read
    http://openocd.org/doc/doxygen/bugs.html
Info : starting to backup nvm ...
.....
Info : backup nvm is valid
Info : current fw version in module: 2.800000
Info : found eui: 343834334D367B08
Info : finish nvm backup.
Info : auto-selecting first available session transport "hla_swd". To override use 'transport select <transport>'.
adapter speed: 300 kHz
adapter_nsrst_delay: 100
Info : The selected transport took over low-level target control. The results might differ compared to plain JTAG/SWD
none separate
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : clock speed 240 kHz
Info : STLINK v2 JTAG v27 API v2 SWIM v15 UID 0x0483 PID 0x374B
Info : using stlink api v2
Info : Target voltage: 3.279474
Info : stm3210.cpu: hardware has 4 breakpoints, 2 watchpoints
Info : STM32L flash size is 64kb, base address is 0x8000000
Info : found unique device id = 343834334D367B08
Info : nvm was backup in '343834334D367B08.bak'
Info : stm321x_write_rdp RDP=aa...
Info : stm321x_write_rdp OBL_LAUNCH...
STM32Lx unlocked, wait 1 sec.
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
adapter speed: 240 kHz
auto erase enabled
Info : loading file 'wm-sg-sm-42_firmware_v2.7.hex' ...
Info : loaded 166445 of 166445
found fw version 0 in 'wm-sg-sm-42_firmware_v2.7.hex'
Info : going erase & flash ...
Warn : couldn't use loader, falling back to page memory writes
wrote 61440 bytes from file wm-sg-sm-42_firmware_v2.7.hex in 8.931134s (6.718 KiB/s)
Info : stm321x_write_rdp RDP=0...
Info : stm321x_write_rdp OBL_LAUNCH...
driver protected
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
adapter speed: 240 kHz
** Programming Finished **
** Resetting Target **
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
adapter speed: 240 kHz
shutdown command invoked
Info : backup nvm is valid

NOTE!! nvm must be restored ...
DO NOT TERMINATE the process or the window.
to ensure target is in running state, please unplug SWD wire and REPOWER target
then please hit ENTER key while ready to continue ....

Info : restoring nvm ...
.....
fw updated successfully!please takes a reset for effect the new fw.
F:\sm42_fw_update_tool_v1.0\sm42_fw_update_tool\bin>

```

16 is the number of uart shown in the device manager

Please remove SWD wire and re-plug the power on the target when you see message.

Please reater your module when you see message.

Universal Scientific Industrial Co., Ltd.		Doc No.		Rev	1.2
Document release by WSS2/WP1/SW		Date.	2017/05/09	Page	12
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note				

7.3 Update the preloaded firmware with backup file

Please place the backup NV file in the same folder with update tool before run 'sm42_update.bat' if you want to programming the preloaded AT command software into the module from your customize firmware, or retry from the fail update. the example of update please also refer to the section 7.2.

```

F:\sm42_fw_update_tool_v1.0\sm42_fw_update_tool\bin>dir
磁碟區 F 中的磁碟是 Windows7_OS
磁碟區序號: 6CDA-D000
Place the backup NV file in the same folder
F:\sm42_fw_update_tool_v1.0\sm42_fw_update_tool\bin 的目錄
2017/05/09 下午 09:56 <DIR> .
2017/05/09 下午 09:56 <DIR> ..
2017/05/09 下午 08:41 4,112 343834334D367B08.bak
2016/06/14 下午 03:13 110,109 cyggcc_s-1.dll
2015/02/06 上午 10:39 14,877 cyghidapi-0.dll
2016/09/19 下午 02:13 313,373 cygncursesw-10.dll
2015/11/05 上午 04:13 141,853 cygusb-1.0.dll
2015/02/11 上午 09:42 82,461 cygusb0.dll
2016/12/16 下午 06:52 3,454,230 cygwin1.dll
2017/02/03 下午 01:55 163,184 fwx_v2.8.hex
2017/02/03 下午 01:55 163,168 fw_v2.8.hex
2016/11/06 下午 02:50 78,848 libgcc_s_seh-1.dll
2013/12/26 下午 12:53 80,384 libusb0.dll
2017/01/10 下午 06:16 53,779 libwinpthread-1.dll
2017/02/27 下午 03:13 9,245,927 openocd-dev.exe
2017/02/27 下午 03:08 427 openocd-dev.exe.stackdump
2017/02/26 下午 11:58 140 sm42_backup.bat
2017/01/23 上午 10:40 156 sm42_update.bat
2017/01/26 下午 06:43 166,464 wm-sg-sm-42_firmware_v2.7.hex
2017/02/03 下午 01:55 163,184 wm-sg-sm-42_firmware_v2.8x.hex
18 個檔案 14,236,676 位元組
2 個目錄 35,541,516,288 位元組可用
F:\sm42_fw_update_tool_v1.0\sm42_fw_update_tool\bin>

```

Universal Scientific Industrial Co., Ltd.		Doc No.		Rev	1.2
Document release by WSS2/WP1/SW		Date.	2017/05/09	Page	13
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note				

8. The usage of sm42_backup.bat

Since the nv data inside the module will be destroyed during the update procedure, so please back up the nv data of module to local disk by using sm42_backup.bat.

The syntax of sm42_backup.bat:

sm42_backup.bat <serial_port_number>

<serial_port_number> this is the serial port connected to the UART of WM-SG-SM-42, the serial port number will be the higher serial port number in the two continued serial port which appear on the window of device manager. But the serial port number may need to reconfigure within 1 to 50, because the update tool is running in cygwin environment, the available serial port number only can be from 1 to 50.

```

Info : Unable to match requested speed 300 kHz, using 240 kHz
adapter speed: 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
adapter speed: 240 kHz
target state: halted
target halted due to debug-request, current mode: Thread
xPSR: 0xf1000000 pc: 0x080000d4 msp: 0x20001830
STM32L0: Enabling HSI16
Info : Unable to match requested speed 2500 kHz, using 1800 kHz
Info : Unable to match requested speed 2500 kHz, using 1800 kHz
adapter speed: 1800 kHz
** Programming Started **
auto erase enabled
Info : STM32L flash size is 64kb, base address is 0x08000000
Info : Found unique device id = 343834334D367B08
Info : nv was backup in '343834334D367B08.bak'
** Programming finished **
** Resetting Target **
Info : Unable to match requested speed 300 kHz, using 240 kHz
Info : Unable to match requested speed 300 kHz, using 240 kHz
adapter speed: 240 kHz
shutdown command invoked

F:\sm42_fw_update_tool_v1.0\sm42_fw_update_tool\bin>_

```

The backup filename will be shown in the output message here.

Universal Scientific Industrial Co., Ltd.		Doc No.		Rev	1.2
Document release by WSS2/WP1/SW		Date.	2017/05/09	Page	14
Description	WM-SG-SM-42 Update Preloaded AT Command FW Application Note				

9. The usage of sm42_update.bat

sm42_update.bat is used for programming preload AT command software to the module, since the nv data inside the module will be destroyed during the update procedure, so it will back up the nv data of module to local disk by the uart of module before beginning of the update normally if the corresponding back NV file dose not in the same folder. Please refer to the example of update in section 7.2.

The syntax of sm42_update.bat:

sm42_update.bat <serial_port_number> <hex_file>

<serial_port_number> this is the serial port connected to the UART of WM-SG-SM-42, the serial port number will be the higher serial port number in the two continued serial port which appear on the window of device manager. But the serial port number may need to reconfigure within 1 to 50, because the update tool is running in cygwin environment, the available serial port number only can be from 1 to 50.

<hex_file> this is the hex file name to be updated into the module. It can be a file name with full path or related path. But please use '/' as the separate character of path instead.

===== END OF DOCUMENT =====