

① find low cycle line

$$S_{ec} = f S_{ut}$$

↑
Fig 6-18

② Endurance limit

$$S_e = \underbrace{\hspace{2cm}}_{\text{Modifying param}} S_e'$$

Ferrous

$$S_e' = \begin{cases} 0.5 S_{ut} & S_{ut} < 200 \text{ ksi} \\ 100 \text{ ksi} & S_{ut} > 200 \text{ ksi} \end{cases}$$

700 MPa

③ High Cycle fatigue

$$S_f = a N^b$$

$$a = \frac{(f S_{ut})^2}{S_e}$$

$$b = -\frac{1}{3} \log \left(\frac{f S_{ut}}{S_e} \right)$$

Stress Concentration Factors in Fatigue

- Static \Rightarrow stress concentration factors
(for brittle materials)

$$K_t, K_{ts}$$

- Fatigue: brittle and ductile materials
- Different Materials have different sensitivities to notches (stress con.)
- Fatigue stress concentration
$$\sigma_{max} = K_f \sigma_0 \quad \text{and} \quad \tau_{max} = K_{fs} \tau_0$$
- Fatigue concentration factor are smaller than K_t, K_{ts}
- $K_f = \frac{\text{max stress in a notched specimen}}{\text{stress in the notch-free specimen}}$

- $$K_f = 1 + q(K_t - 1)$$

q : notch sensitivity

Figs 6-20, 6-21 $\Rightarrow q$

- You can always use K_f and be conservative

- Cast irons $\Rightarrow q = 0.2$ for all grades

- For infinite life you ^{can use} $K_f = \frac{1}{K_f}$
 equivalent to $K_f \sigma_0$ K_f Marin
 σ_0 misc
 par
 * Does not apply for finite life *


$$K_f = \frac{1}{K_f}$$

Only for
infinite
life


$$\sigma_{max} = K_f \sigma_0$$

best to use
this all the time

Example Rotating Beam simply supported
at A & D with $P = 6.8 \text{ kN}$
Material: CD 1050 steel



Goal: Estimate the life of the part.



Solution

$$\left. \begin{aligned} \sum F = 0 &= R_1 + P + R_2 \\ \sum M_A = 0 &= (550)R_2 - (325)P \end{aligned} \right\} \begin{aligned} R_1 &= 2.782 \text{ kN} \\ R_2 &= 4.018 \text{ kN} \end{aligned}$$

$$M_B = 250 \cdot R_1 \Rightarrow M_B = 695.5 \text{ Nm}$$

$$S_e' = 0.5 S_{ut} \quad S_{ut} < 1400 \text{ MPa}$$

$$S_{ut} = 690 \text{ MPa}, \quad S_y = 580 \text{ MPa}, \quad \Rightarrow \text{Table A-20}$$

$$S_e' = 345 \text{ MPa}$$

Marin Parameters

Surface finish: K_a

Table-6-2

$$K_a = a S_{ut}^b = (4.51)(690)^{-0.265} = K_a = 0.798$$

Size k_b

$d < 51 \text{ mm}$

$$k_b = \left(\frac{d_i}{7.62} \right)^{-0.107} = 0.858$$

Other

$$K_c = K_d = K_e = K_f = 1$$

$$S_e = K_a k_b S_e' = 236 \text{ MPa}$$

Stress Concentration

$$\sigma_B = K_f \sigma_{Bo}$$

$$K_f = 1 + q(K_t - 1)$$

Chart A-15-9

$$r/d = \frac{3}{32} = 0.093$$

$$D/d = \frac{38}{32} = 1.19$$

From Fig 6-20

$$q \approx 0.85$$

$$K_t \approx 1.65$$

$$\sigma_B = (1 + (0.85)[1.65 - 1]) 216.2 \text{ MPa}$$

$$\boxed{\sigma_B = 335.1 \text{ MPa}}$$

$$\underline{\sigma_B > S_e \quad + \quad \sigma_B < S_y}$$

Fully reversed life High cycle regime.

$$\sigma_B = a N^b \Rightarrow N = \left(\frac{\sigma_B}{a} \right)^{1/b}$$

$$a = \frac{(f S_{ut})^2}{S_e} \quad b = -\frac{1}{3} \log \left(\frac{f S_{ut}}{S_e} \right)$$

$$S_{ec} = f S_{ut} = (0.85)(690 \text{ MPa}) = 582.4 \text{ MPa}$$


$$a = 1437 \text{ MPa} \quad b = -0.1308$$

$$\boxed{N = 68 \times 10^3 \text{ cycles}}$$

(6)

Fluctuating Stress

When the mean stress is non-zero.



$$\sigma_m = \frac{\sigma_{\max} + \sigma_{\min}}{2}, \quad \sigma_a = \left| \frac{\sigma_{\max} - \sigma_{\min}}{2} \right|$$


$$\sigma_r = |\sigma_{\max} - \sigma_{\min}| \quad A = \frac{\sigma_a}{\sigma_m} \quad \left(\begin{array}{l} \text{form load} \\ \text{line} \end{array} \right)$$

If $\sigma_m < 0$ (compressive): S_f is the same as the fully reversed case (but ^{check} yielding)

If $\sigma_m > 0$ (tensile): S_f is less than fully reversed case.

If $\sigma_a = 0 \Rightarrow$ the part fails at $\sigma_m = S_y$ or S_{ut}


If $\sigma_m = 0 \Rightarrow$ fully reversed case \Rightarrow failure $\sigma_a = S_e(S_f)$ or S_f



Design Relations


$$(1) \frac{\sigma_a}{S_e} + \frac{\sigma_m}{S_{ut}} < 1 \quad \text{for } \sigma_m > 0$$

$$(2) \frac{\sigma_a}{S_e} < 1 \quad \text{for } \sigma_m < 0$$



- I - immediate failure due to yielding
- II - finite life (fail by fatigue)
- III - infinite life
- IV - failure due to yielding, fracture, fatigue

Finite Life use S_f instead of S_e for specific boundary in zone II.



Gerber line

Relation: $\frac{\sigma_a}{S_e} + \left(\frac{\sigma_m}{S_{ut}}\right)^2 < 1$ for $\sigma_m > 0$

Factor of Safety

Stutz: $n = \frac{\text{load capacity}}{\text{actual load}} = \frac{S}{\sigma}$

σ_a and σ_m increase proportionally along the load line.

$$n = \frac{OC}{OP} = \frac{S_e}{\sigma_a} = \frac{S_m}{\sigma_m}$$

Goodman

$$n = \left(\frac{\sigma_a}{S_e} + \frac{\sigma_m}{S_{ut}} \right)^{-1}$$

fatigue

yielding

$$n = \frac{S_y}{\sigma_a + \sigma_m}$$

Gerber

$$\frac{n \sigma_a}{S_e} + \left(\frac{n \sigma_m}{S_{ut}} \right)^2 = 1$$

Example 1.5" diameter ¹/_{bar} CD 1050 steel

fluctuating load from 0-16000 lbs (tensile)

Assume $K_f = 1.85$ for 10^6 or longer life

Find σ_{int} using Goodman line

Solutions

$$S_e' = 0.5 S_{ut} \quad S_{ut} = 100 \text{ Kpsi}$$

$$S_y = 84 \text{ Kpsi}$$

$$S_e' = 50 \text{ Kpsi}$$

$$S_e = K_a K_b K_c S_e'$$

$$K_d = K_e = K_f = 1$$

$$K_a = 0.797$$

$$K_b = 1$$

$$K_c = 0.85$$

$$S_e = 33.87 \text{ Kpsi}$$

$$(\sigma_m)_0 = \frac{F_m}{A} = \frac{8000}{\frac{\pi (1.5)^2}{4}} = 4.53 \text{ Kpsi}$$

$$(\sigma_a)_0 = \sigma_m = 4.53 \text{ Kpsi}$$

$$\sigma_a = K_f \sigma_{a0} = 8.38 \text{ Kpsi} = \sigma_m$$

Goodman line

$$N_{inf} = \left(\frac{\sigma_a}{S_e} + \frac{\sigma_m}{S_{ut}} \right)^{-1}$$

$$N_{inf} = 3.02 \quad \checkmark$$

$$N_{yielding} = \frac{S_y}{\sigma_a + \sigma_m} \Rightarrow 5.01 \quad \checkmark$$