




GVS001 and GVS002

GVS101 and GVS102

GVS201 and GVS202

## Small Beam Diameter Scanning Galvo Systems

### User Guide



Original Instructions

## Table of Contents

|                  |   |           |
|------------------|---|-----------|
| <b>Chapter 1</b> | <b>Safety Information.....</b>                  | <b>1</b>  |
| 1.1              | General Warnings and Cautions.....              | 1         |
| 1.2              | EMC Compatibility and ESD Precautions.....      | 2         |
| <b>Chapter 2</b> | <b>Overview .....</b>                           | <b>3</b>  |
| 2.1              | Introduction.....                               | 3         |
| 2.2              | System Description.....                         | 3         |
| 2.2.1            | Introduction.....                               | 3         |
| 2.2.2            | The Galvanometer.....                           | 3         |
| 2.2.3            | The Mirror.....                                 | 4         |
| 2.2.4            | Servo Driver Board.....                         | 5         |
| <b>Chapter 3</b> | <b>Installation and Initial Setup.....</b>      | <b>6</b>  |
| 3.1              | Environmental Conditions.....                   | 6         |
| 3.2              | Dimensions .....                                | 6         |
| 3.2.1            | Motor Assembly Dimensions .....                 | 6         |
| 3.2.2            | Mirror Dimensions .....                         | 6         |
| 3.2.3            | Single Axis Mount Dimensions .....              | 7         |
| 3.2.4            | XY Mount Dimensions .....                       | 8         |
| 3.2.5            | Heatsink Dimensions .....                       | 8         |
| 3.2.6            | Servo Driver Board Baseplate Dimensions.....    | 9         |
| 3.3              | Mechanical Installation.....                    | 9         |
| 3.3.1            | Introduction.....                               | 9         |
| 3.3.2            | Fitting the Heatsinks.....                      | 10        |
| 3.3.3            | Typical System Setup .....                      | 11        |
| 3.4              | Electrical installation .....                   | 12        |
| 3.4.1            | Choosing a Power Supply .....                   | 12        |
| 3.4.2            | Using the GPS011 Linear Power Supply .....      | 12        |
| 3.4.3            | Electrical Connections .....                    | 13        |
| 3.4.4            | Diagnostic Signal Descriptions .....            | 17        |
| 3.4.5            | Setting the Volts/Degree Scaling Factor .....   | 17        |
| <b>Chapter 4</b> | <b>Operation .....</b>                          | <b>18</b> |
| 4.1              | General Operation.....                          | 18        |
| 4.2              | External Enabling of the Driver Board .....     | 18        |
| 4.3              | Using a DAQ card.....                           | 18        |
| 4.4              | Recommended Scanning Angles .....               | 19        |
| <b>Chapter 5</b> | <b>Troubleshooting .....</b>                    | <b>20</b> |
| 5.1              | Common Issues.....                              | 20        |
| 5.2              | Galvanometer Faults.....                        | 21        |
| 5.3              | Diagnostic.....                                 | 22        |
| 5.4              | Resettable Fuse.....                            | 23        |
| 5.5              | Error codes.....                                | 23        |
| <b>Chapter 6</b> | <b>Specifications and Associated Parts.....</b> | <b>24</b> |
| 6.1              | Associated Products .....                       | 25        |

---

---

|                   |   |           |
|-------------------|---|-----------|
| <b>Chapter 7</b>  | <b>Calculating the Power Dissipation .....</b>      | <b>26</b> |
| <b>7.1</b>        | <b>Motor Heatsink.....</b>                          | <b>26</b> |
| 7.1.1             | Calculating the Required Thermal Conductivity ..... | 26        |
| <b>Chapter 8</b>  | <b>Reasons for Image Distortion .....</b>           | <b>27</b> |
| <b>Chapter 9</b>  | <b>Certifications and Compliance.....</b>           | <b>28</b> |
| <b>Chapter 10</b> | <b>Thorlabs Worldwide Contacts.....</b>             | <b>29</b> |

## Chapter 1 Safety Information

For the continuing safety of the operators of this equipment, and the protection of the equipment itself, the operator should take note of the Warnings, Cautions and Notes throughout this handbook and, where visible, on the product itself.

**Warning: Risk of Electrical Shock**

Given when there is a risk of electrical shock.

**Warning**

Given when there is a risk of injury to users.

**Caution**

Given when there is a possibility of damage to the product.

**Note**

Clarification of an instruction or additional information.

### 1.1 General Warnings and Cautions

**Warning**

If this equipment is used in a manner not specified by the manufacturer, the equipment might malfunction. Excessive moisture may impair operation. Spillage of fluid, such as sample solutions, should be avoided. If spillage does occur, clean up immediately using absorbent tissue. Do not allow spilled fluid to enter the internal mechanism. Although the unit does not emit radiation it does redirect laser radiation emitted from other devices. Operators must follow all safety precautions provided by the manufacturer of any associated laser devices.

**Caution**

When connecting the driver boards and motors use only the cables supplied. Do not extend the cables. The driver boards and motors are calibrated with these cables. Using different cables will affect the performance of the system.

**Caution**

The driver circuit board is shipped calibrated and ready for use. The only adjustments necessary are setting the Volts/Degree Scaling factor (see section 3.4.5 and if required, setting the device for external enabling see section 4.2).

Do not attempt to make any other adjustments or remove/fit any other jumpers than those explicitly described in the following sections as this could invalidate the warranty.

**Warning**

Please install the metal covers GCE001 to prevent any damage to the motors and PCBs as the galvo boards contain electrostatic discharge-sensitive components.

## 1.2 EMC Compatibility and ESD Precautions

**Caution**

Galvos must be shielded from external interference, ground loops, and electrostatic discharge because they are components and not finished goods. If the covers are not used, a 4 kV ESD can touch the PCB and harm it. Please install covers to shield the boards from ESD.

**Note**

The customer must adhere to EMC and ESD best practices when integrating any galvo parts into their systems.

Motors can be sensitive to external radio frequency signals; the customer should protect the galvo and the PCB with shielding and/or ferrite beads if radio frequency signals are present in the system. For instance, a Würth Elektronik ferrite 742 711 31 S placed over the motor cable of the large galvo system can improve immunity between 105 and 115 MHz.

## Chapter 2 Overview

### 2.1 Introduction

The GVS series scanning galvo systems are board level, mirror positioning systems, designed for integration into OEM or custom laser beam steering applications. The single axis systems consist of a motor and mirror assembly, a mounting bracket, a tuned driver card and a heat sink. The dual axis systems comprise two mirror and motor assemblies, an X-Y mounting bracket, two driver cards and two heat sinks. The driver cards feature a small footprint, fixings for easy mounting to a heatsink and a simple analog command signal interface.


A choice of mirror coating is available as follows:

*GVS001 and GVS002: Single- and Dual-Axis Systems with Protected Silver Mirrors*

*GVS101 and GVS102: Single- and Dual-Axis Systems with Protected Gold Mirrors*

*GVS201 and GVS202: Single- and Dual-Axis Systems with 400 - 750 nm Broadband Dielectric Mirrors*

Typical applications include laser scanning, laser microscopy, and laser marking.



**Figure 1** GVS002 Dual-Axis Galvo System (Post Adapter and Post Not Included)

### 2.2 System Description

#### 2.2.1 Introduction

Galvo Scanners are widely used in applications such as laser etching, confocal microscopy, and laser imaging.

A galvanometer is a precision motor with a limited travel, usually much less than 360 degrees, whose acceleration is directly proportional to the current applied to the motor coils. When current is applied, the motor shaft rotates through an arc. Motion is stopped by applying a current of reverse polarity. If the current is removed, the motor comes to rest under friction.

Typically, the term 'Galvo' refers only to the motor assembly, whereas a 'Galvo Scanner' would include the motor, together with a mirror, mirror mount and driver electronics.

A description of each component in the system is contained in the following sections.

#### 2.2.2 The Galvanometer

The galvanometer consists of two main components: a motor that moves the mirror and a detector that feeds back mirror position information to the system.



**Figure 2** GVS002 Dual-Axis Galvo/Mirror Assembly

Our galvo motor features a moving magnet, which means that the magnet is part of the rotor and the coil is part of the stator. This configuration provides faster response and higher system-resonant frequencies when compared to moving coil configurations.

Mirror position information is provided by an optical position detector, which consists of two pairs of photodiodes and a light source. As the galvo and mirrors are moved, differing amounts of light are detected by the photodiodes and the current produced is relative to the galvo actuator position.

### 2.2.3 The Mirror

The mirror assembly is attached to the end of the actuator and deflects the light beam over the angular range of the motor shaft. Scanning galvo applications demand high speed and frequencies of the shaft rotation, and so the inertia of the actuator and mirror assembly can have a profound effect on the performance of the system. High resonant frequencies and enhanced stiffness in the mirror assembly also add to system performance by increasing bandwidth and response times.

Wavelength ranges and damage threshold of the different mirror coatings are detailed below:

**Table 1** Wavelength Ranges and Damage Threshold

| Part Number | Coating | Wavelength            | Damage Threshold                              |
|-------------|---------|-----------------------|---|
| GVS00x      | Silver  | 500 nm - 2.0 $\mu$ m  | 3 J/cm <sup>2</sup> at 1064 nm, 10 ns pulse   |
| GVS10x      | Gold    | 800 nm - 20.0 $\mu$ m | 2 J/cm <sup>2</sup> at 1064 nm, 10 ns pulse   |
| GVS20x      | E02     | 400 nm - 750 nm       | 0.25 J/cm <sup>2</sup> at 532 nm, 10 ns pulse |




**Figure 3** Mirror Assembly Detail

#### 2.2.4 Servo Driver Board

The servo circuit interprets the signals from the position detector, then uses positional error, speed and integral of current terms to output control voltages to drive the actuator to the demanded position.

The scanner uses a non-integrating, Class 0 servo, which enables higher system speeds compared to integrating servo systems and is ideal for use in applications that require vector positioning (e.g., laser marking) or raster positioning (printing or scanning laser microscopy). It can also be used in some step and hold applications.

Furthermore, the proportional derivative circuit gives excellent dynamic performance and includes an additional current term to ensure stability at high accelerations. The diagram below shows the architecture of the driver in more detail.



**Figure 4** Servo Driver Board Schematic Diagram




**Figure 5** Servo Driver Circuit Board






### 3.2.3 Single Axis Mount Dimensions



all dimensions in inches (mm)

**Figure 8** Single Axis Mounting Bracket Dimensions


### 3.2.4 XY Mount Dimensions



all dimensions in inches (mm)


**Figure 9 XY Mounting Bracket Dimensions**

### 3.2.5 Heatsink Dimensions



**Figure 10 Heatsink Dimensions**

### 3.2.6 Servo Driver Board Baseplate Dimensions



**Figure 11 Servo Driver Board Baseplate Dimensions**

## 3.3 Mechanical Installation

### 3.3.1 Introduction


#### Caution



The galvo motor assembly associated driver board and connecting cables are tuned at the factory before they are shipped, and further adjustment is not normally necessary. If the accuracy of the system is in doubt, e.g., due to accidental adjustment of trim pots, contact Thorlabs for information on the tuning procedure. Do not extend the cables as this will affect the system calibration.

During Installation, ensure that the motors are connected to the driver card to which they were tuned. Both the motor and the driver card should carry the same serial number.

The location of the serial number labels is shown below.



**Figure 12** Serial Number Label Location

It is essential that the user mounts heatsinks to the driver board and motor mounts which are suitable for their intended application. If this is not done the devices will overheat and permanent damage may occur. The choice of heatsink will primarily be determined by the power which the devices dissipate, a value which is dependent on the average speed at which the user moves the scanners. The larger the power the heatsink must dissipate, the larger the heatsink will need to be.

### 3.3.2 Fitting the Heatsinks

#### *Servo Driver Board Heatsink*

The servo driver board is supplied complete with a large heatsink, suitable for all applications, even those involving more vigorous usage and rapidly changing drive waveforms.

Secure the heatsink bracket to the heat sink using two M3 x 8 screws and two plain M3 washers (arrowed in the photo below)



**Figure 13** Driver Board Heatsink Screws

#### *Motor/Mirror Mount Heat Sink*




#### **Caution**

Due to the large torque to weight ratio, thermal management is crucial to the successful operation of galvo motors. Consequently, the galvo motors must be kept cool (<50 °C).

For most applications, the mounting bracket will provide adequate heat sinking, however for more vigorous applications, it may be necessary to fit some heatsinking in addition to the galvo motor mount. Thorlabs supplies a combined post adaptor and heatsink (GHS003) suitable for both single and dual axis applications.

If using a third party heatsink, please refer Chapter 7 for details on how to calculate the power dissipation in the motor.


Secure the heatsink to the motor/mirror mount using the two M3 X 5 screws supplied.



**Figure 14** XY Mount Heatsink Screws

### 3.3.3 Typical System Setup

1. Fit a GHS003 post adaptor to the XY mounting block.
2. Fit a lens post into the bottom of the post adaptor and clamp it to the breadboard.
3. Arrange a beam steering system such that a laser beam shines on to the X axis mirror, at right angles to the mount and is then reflected onto the screen, also at right angles to the mount.



Typical Example: If the optical scan angle  $\varnothing = \pm 25^\circ$

$I = 2d \times \tan 25^\circ$  (Note. In this case, the mechanical scan angle is  $\pm 12.5^\circ$ )

**Figure 15** Typical Beam Steering System

### 3.4 Electrical installation

#### 3.4.1 Choosing a Power Supply

Thorlabs recommends using the GPS011 linear power supply to power the galvo controller board(s) as this power supply has been specifically designed for this purpose. The GPS011 can power up to two driver cards under any drive conditions and is supplied with all the cables required to connect to the driver cards.

However, customers also have the option of using a third-party power supply or incorporate the boards into their existing system. In this case care must be taken to ensure that the power supply voltage and current ratings are within the limits specified.

The drive electronics require a split rail DC supply in the range  $\pm 15$  V to  $\pm 18$  V. The maximum current drawn by the driver cards will not exceed 1.25 A rms on each rail (the current depends on the application). In addition to this, for optimum performance the supply should be able to provide peak currents of up to 5 A on either rail.

#### Caution



Both switching and linear power supplies can be used with the Thorlabs galvo systems; however, it is important to limit the inrush current when the power supply is turned on, to ensure that the power supply reservoir capacitors on the board are not damaged by the large surge currents that can occur on power-up. Most power supplies naturally “soft start” when they are switched on at the mains side and provide inrush current limiting. If, however, the power supply is turned on at the output (DC) side, it can output its peak current instantaneously. In this case it is important to limit this peak current to less than 2 Amps. The unit can be damaged if the polarity of the power rails is reversed.

#### 3.4.2 Using the GPS011 Linear Power Supply

The unit must be connected only to an earthed (grounded) mains power outlet.

#### Note

The unit is supplied with the input voltage and fuses configured to be compatible in the region to which it was shipped. No further adjustment should be necessary.

1. Connect the power cord to the socket on the rear panel of the unit. Refer to Figure 16.




Figure 16 Rear Panel

2. Ensure that the correct voltage range and fuse rating for your region is selected.

**Caution**

Selecting the incorrect voltage range or fuse will damage the unit. Ensure that both switches are set to the correct position for your region and that the fuse fitted is of the correct rating, as indicated by the screen print on the rear panel.

3. Plug the power cord into the wall socket.

### 3.4.3 Electrical Connections

**Caution**


During the electrical installation, cables should be routed such that power and signal cables are separated so that electrical noise pick up is minimized.

**Caution**

This section is applicable only to driver card units, with a PCB at rev 11 or later.

PCB revisions can be identified as follows:

Up to and including issue 10.




Steps (1) to (3) are applicable only if using the Thorlabs GPS011 PSU.


1. Ensure the correct voltage range is selected on the PSU. Refer section 3.4.2.



2. The circular 3-pin connector on the power output cable and the OUTPUT socket on the PSU are fitted with alignment keyways to ensure connection in correct orientation. Make connection as referred in Figure 17.
3. Screw the outer casing of the plug clockwise until the connector is fully fastened.




**Figure 17** Connecting the Power Supply to the PSU



**Figure 18** Connector Identification

4. Identify connector J10 on each driver board and make power connections as shown below. Thorlabs supplies a suitable PSU (GPS011) for powering a single or dual axis system (refer section 3.4.1). A bare cable, crimp connectors (Molex Pt No 2478) and housings for use with general lab PSUs is supplied with each driver board. The unit can be damaged if the polarity of the power rails is reversed.




**Figure 19 J10 power Connector Pin Identification**

#### Caution




During steps (5) and (6) use only the cables supplied. Do not extend the cables. The driver boards and motors are calibrated with these cables. Using different cables will affect the performance of the system. Longer cables are available as a custom part, but the units will require re-calibration if these are not specified at time of order. Contact tech support for more details.

5. Connect a motor cable to the connector J9 on each driver board as shown below.



**Figure 20 J9 Motor Connector Pin Identification**

6. Note the serial numbers and then connect the galvo motors to their associated driver boards.



**Figure 21 Galvo Assemble Motor Connector Pin Identification**


7. Connect the command input (e.g., function generator) to J7 of each driver board as shown in Figure 22. J7 accepts Molex pins Pt No 56134-910

#### Note


The scanner accepts a differential analog command input. If the scaling is 0.8 Volt per degree mechanical movement (see section 3.4.5), -10 V to +10 V gives -12.5 to +12.5 degrees mechanical movement. The driver will attempt to set the mirror position to the command input value.

Pin 3 (DRV\_OK) is an open collector output that is active low, i.e., Low when the board is operating normally and floating if a fault occurs. To use Pin 3 as a fault indicator, connect a pull-up resistor to give a high signal when the fault occurs. DRV\_OK limits are 30 mA 30 V.

Do not connect a relay to this output.




Pin 1 Command Input +positive  
 Pin 2 Command Input -negative  
 Pin 3 DRV OK (Active Low)  
 Pin 4 External Enable  
 Pin 5 -12 V output (Low Impedance O/P)  
 Pin 6 +12 V output (Low Impedance O/P)  
 Pin 7 Ground  
 Pin 8 Ground



**Figure 22 J7 Command Input Connector Pin identification**

8. Using a suitable cable, connect the Diagnostic Terminal J6 to the diagnostic device (e.g., oscilloscope) in your application. Pin identification is given below, signal descriptions are added in the next section.



Pin 1 Scanner Position  
 Pin 2 Internal Command Signal  
 Pin 3 Positioning Error X 5  
 Pin 4 Motor Drive Current  
 Pin 5 Not Connected  
 Pin 6 Test Input (NC)  
 Pin 7 Motor + Coil Voltage/2  
 Pin 8 Ground

**Figure 23 J6 Diagnostics Connector Pin identification**

#### Note

All diagnostic signals from J6 have 1 k $\Omega$  output impedance except Pin 7 (Motor Coil Voltage/2) which has 5 k $\Omega$ .

#### J6 Diagnostics and J7 Command Input Mating Connector Details

Mating Connector body: Manufacturer: Molex, Mfr. P/N: 513530800

Example Vendor: Farnell, Vendor P/N: 1120387

Crimps (22-26AWG): Manufacturer: Molex, Mfr. P/N: 56134-8100

Example Vendor: Farnell, Vendor P/N: 1120545

Crimps (22-28AWG): Manufacturer: Molex, Mfr. P/N: 56134-9100

Example Vendor: Farnell, Vendor P/N: 1120546

### 3.4.4 Diagnostic Signal Descriptions

**Scanner Position** - This signal is proportional to the position of the scanner mirror, with a scaling of 0.5 Volt per degree of mechanical movement.

**Internal Command Signal** - The command signal following amplification by the input stage. The scaling is 0.5 Volt per degree of mechanical movement.

#### Note

The Scanner Position and Internal Command signals are scaled internally by the driver circuit and are essentially equivalent to the input signal /2.

**Positioning Error x 5** - This signal is proportional to the difference between the demanded and the actual positions - (Position - Command) x 5 (i.e. (Pin 1 - pin 2) x 5).

**Motor Drive Current** - The drive current of the motor (2 V per A), i.e., if drive signal is 2 V, the drive current is 1 A.

**Motor + Coil Voltage /2** - This pin outputs the drive voltage to the “+” side of the motor coil. It is scaled down by a factor of 2. The drive voltage determines the current, which then determines the acceleration. It is not required if the user only wants to monitor position.


### 3.4.5 Setting the Volts/Degree Scaling Factor

Servo driver cards manufactured after October 2015 have a jumper which is used to set the Volts per Degree scaling factor. The cards are shipped with the scaling set to 0.8 V/°, where the max scan angle is  $\pm 12.5^\circ$ , and is compatible with driver cards manufactured before October 2009. To set the scaling factor to 1 V/° and the maximum scan angle to  $\pm 10^\circ$ , proceed as follows:

1. Identify JP7 as shown in Figure 24 .
2. Set the jumper position for the corresponding scaling factor as shown below.

#### Note

The 0.5 V/° scaling factor is provided to allow the full scan angle to be achieved using small input signals. In this case, the input voltage should be limited to  $\pm 6.25$  V max.



**Figure 24** Setting the Volts/Degree Scaling Factor

## Chapter 4      Operation

### 4.1 General Operation

Perform the following installation steps:

1. Connect the system as described in section 3.4.
2. Apply power to the driver boards.
3. Input a command signal to each driver board to obtain the desired behavior.


#### Note

After applying power to the boards, there may be a delay of up to 10 seconds before the motors start to follow the command signal.


### 4.2 External Enabling of the Driver Board

Perform the following installation steps:

1. The drive electronics can be configured for external enabling by placing a jumper across pins 2 and 3 of



2. Once this has been done the user can enable or disable the drive electronics by applying a 5 V CMOS signal to J7 pin 4.



Pin 1 Command Input +positive  
 Pin 2 Command Input -negative  
 Pin 3 No Connect  
 Pin 4 External Enable  
 Pin 5 -12 V output  
 Pin 6 +12 V output  
 Pin 7 Ground  
 Pin 8 Ground

**Figure 25 J7 Command Input Connector Pin Identification**

If a logic high or no signal is applied, the drive electronics will be enabled. If a logic low signal is applied, then the driver will be disabled.

### 4.3 Using a DAQ card

Typically, users will deploy a DAQ card with DAC analogue outputs to drive the servo drivers supplied with the galvos. The specifications of the DAC depend on speed and resolution of the application. The minimum recommended specifications for the DAC outputs are: -


Dual bipolar -10 V to 10 V DAC analogue output channels (differential).

DAC clocking frequency higher than 20 kS/s (Kilo Samples/Second), higher sampling frequencies like 100 kS/s are recommended (inputs have a 7 kHz low pass filter).

16 Bit DAC resolution and low out impedance ( $\leq 50 \Omega$ ).

#### 4.4 Recommended Scanning Angles

The ideal scanning angle is dependent upon a number of conditions. Firstly, the larger the diameter of the input laser beam, the smaller the achievable scanning angle. Secondly, the applied input voltage causes the laser beam to move away from the center of the mirrors. The larger the input voltage then the greater the movement from the center, as shown below.



**Figure 26 Scanning Angles**

Lastly, on dual-axis systems, there is an offset alignment between the X and Y axis mirrors that also limits the scan angle.

The table below gives recommended scanning angles for various beam diameters.

| GVS001, GVS101, and GVS201 |                          |                        |
|----------------------------|--------------------------|------------------------|
| Input Beam Diameter        | Mechanical Scan Angle    | Optical Scan Angle     |
| 4mm and less               | $\pm 12.5^\circ$         | $\pm 25^\circ$         |
| 5 mm                       | $+10^\circ, -12.5^\circ$ | $+20^\circ, -25^\circ$ |

| GVS002, GVS102, and GVS202 |                            |                          |                         |                       |
|----------------------------|----------------------------|--------------------------|-------------------------|-----------------------|
| Input Beam Diameter        | Mechanical Scan Angle X    | Optical Scan Angle X     | Mechanical Scan Angle Y | Optical Scan Angle Y  |
| 1 mm                       | $+11.0^\circ, -12.5^\circ$ | $+22.0^\circ, -25^\circ$ | $\pm 12.5^\circ$        | $\pm 25^\circ$        |
| 2 mm                       | $+10^\circ, -11.5^\circ$   | $+20^\circ, -23^\circ$   | $\pm 12.5^\circ$        | $\pm 25^\circ$        |
| 3 mm                       | $+9.5^\circ, -10^\circ$    | $+19^\circ, -20^\circ$   | $\pm 12.5^\circ$        | $\pm 25^\circ$        |
| 4 mm                       | $\pm 8.5^\circ$            | $\pm 17^\circ$           | $\pm 12.5^\circ$        | $\pm 25^\circ$        |
| 5 mm                       | $\pm 8^\circ$              | $\pm 16^\circ$           | $+12.5^\circ, -3^\circ$ | $+25^\circ, -6^\circ$ |

**Table 2 Recommended Scanning Angles**



## Chapter 5 Troubleshooting

### 5.1 Common Issues

Some of the more common problems encountered when using galvanometers are details below.

**Scanner fails to respond to the command signal due to several reasons. The most common are:**

1. Power is not applied to the board.
2. One of the cables is faulty or not connected properly.
3. A fault has been triggered.
4. The device has been disabled either by placing a jumper across JP4 pins 1 and 2 or by placing a jumper across JP4 pins 2 and 3 and pulling J7 pin 4 to ground.

#### Note

After applying power to the boards, there may be a delay of up to 10 seconds before the motors start to follow the command signal.

#### Instability of the scanner

If uncontrolled, instability of the scanner will cause a whistling or screeching noise and uncontrolled movement of the scanner. It will also cause large current to be drawn by the motor and the motor will move spontaneously and unpredictably. If this occurs the user should turn off power to the driver boards immediately to prevent damage to the scanners.

However, under normal circumstances the instability should be detected by the fault control circuitry. In this case the behavior most likely to be observed by the user is the following: The mirror will suddenly jump from one position to another (probably with a short burst of whistling) and stop and remain still. After a delay of a few seconds the mirror will jump to another position and so on. Here when the mirror is stopped a fault has been triggered and the driver board is disabled. The only movement is during the brief period when the fault control circuitry tries to resume normal operation.

Instability can occur for several reasons. The most common is if the driver board is incorrectly tuned to the motor. This can occur if the board is connected to a different motor to the one it was originally sold with or if one of the potentiometers have been tampered with. Another common cause for instability is if the motor is driven at large amplitudes and high frequencies then the electronics may be unable to control the scanner.

#### Mirror periodically shoots off to one side and then stops

If the mirror suddenly shoots off to one side and then stops it is likely that either the position sensing circuitry is not functioning correctly, or the motor cable is incorrectly wired. When this happens most likely either the drive electronics will output a constant drive voltage, or the loop feedback will be positive. Consequently, the motor jumps to one extreme and an over position fault is triggered. Once the drive electronics are disabled the scanner will bounce freely backwards and come to rest. After a delay the electronics will attempt to resume operation and the process will repeat.

#### Galvo mostly behaves normally but periodically becomes unstable

If the galvo driver card is incorrectly tuned it is possible that the galvo system can appear to behave properly most of the time, but with a brief period where the system suddenly becomes unstable and it occurs repetitively. This can be caused if the maximum error signal value is exceeded.

### Oscillation in the galvo motor current

If the galvo system is drawing more current than expected, if the scanners or the driver cards are overheating, if the scanners are making a hissing noise or if the position accuracy is less than expected, this may be due to oscillations in the galvo motor current. This can be identified by viewing the coil current signal J6 pin 4 on an oscilloscope. The problem will manifest itself as a high frequency (>1 kHz) sinusoidal oscillation in the current, unrelated to the position signal. Normally the scanner will still appear to be correctly following the command signal, but the oscillation may show up in the position signal if the effect is very strong.

This effect is normally caused by crosstalk between the position sensing circuitry and the motor drive current. Repositioning the motor drive cable will normally help to avoid this problem. If the user replaces the motor cables with their own cables, they should ensure that they keep the wires as short as possible and use separate shielded cables for the position sensing and motor drive signals.

### Cross talk between axes

Cross talk between the two motors will normal show up as a slight movement in one axis when one motor is moved quickly. This typically occurs if both the motors are run off a same power supply and the power supply cannot deliver the peak currents demanded by the galvos. There will then be a drop in the power supply voltage which will then affect the behavior of the remaining axis. Choosing a different power supply with sufficient peak drive current capability should solve this problem.

### Overshoot in position signal which grows over time

It is possible that the position of the motor may show an overshoot when driven with a large square wave or similar, and that this overshoot will grow with time until a fault is triggered. There is usually a certain frequency and amplitude above which this starts to occur. This behavior is caused by choosing a power supply which cannot deliver enough current for the intended application. The oscillation builds up because the power supply voltage is dropping on the rising edge of the position signal and effecting the board's behavior. With every rising edge the effect becomes slightly greater as the overshoot grows.

## 5.2 Galvanometer Faults

The driver electronics monitor numerous signals to ensure the scanners operate safely and the fault protection circuitry will normally prevent damages.

However, the user should be aware that the galvanometer may become permanently damaged if the system becomes unstable (manifested by a screeching noise, self-excitation and unpredictable movement of the scanner). In addition the user should also be aware that the system has no protection against the galvanometer scanners overheating, and it is left to the user to ensure that they are fitted to an adequate heatsink (see section 3.3.1). A base firmware thermal protection is implemented from revision 5 (see the label on the PCB). It disables the motors if a persistent and high current is detected. The higher the current the earlier it acts by disabling the motor for 4 seconds.

It is worth noting that a fault state may be triggered on applying power to the driver boards and the power amplifier will be disabled. However, in this case the board will commence normal operation after a delay of a few seconds. The table below shows the various faults states which can be triggered in the fault control circuitry.




| Fault  | Possible Causes  | Action Taken by Fault Control Circuit |
|--|--|---------------------------------------|
| Maximum scanner position exceeded  | Drive signal too large, instability of scanner   | Power amplifier turned off            |
| Maximum peak current exceeded  | Incorrect tuning, instability of the scanner or overly vigorous drive waveforms                  | Power amplifier turned off            |
| Power supply voltage drops below minimum value of 14 V or rises above maximum limit of 20 V <sup>a</sup> | Poor choice of power supply  | Power amplifier turned off            |
| Maximum RMS coil current exceeded  | Incorrect tuning, instability of the scanner or overly vigorous drive waveforms                  | Power amplifier turned off            |
| Maximum junction temperature of power amplifier IC exceeded <sup>b</sup>                                 | Inadequate heatsinking of driver board. A short circuit could be present in motor or motor cable | Power amplifier turned off            |

**Table 3 Galvo System Faults and Associated Fault Protection Circuit Action**

### 5.3 Diagnostic

The diagnostic connector J1 on the galvo driver board revision 12 has the following pinout (see image below).



**Figure 27 J1 Connector**

Pin 3 of J1 is a 5 V serial port (UART) transmit line that is connected to the micro through a 1 kΩ resistor.

The data transmission rate is 9600 baud/s with an 8-bit data size, one start bit, and one stop bit. The line requires a level translator if it is connected to a standard RS232C serial port. The line is intended for diagnostics in the event of a fault, and it shouldn't be left connected permanently to prevent ground loop interference or harm from current from other items connected to the galvo. These dangers are minimized by connecting to the micro's serial port or using an isolated level translator for the RS232C.

The board's firmware revision, the Galvo model, and other error messages can all be sent over the serial ports. Below are some examples:

**Positive rail (VCC) under voltage!**  
**Positive rail (VCC) over voltage!**

<sup>a</sup> If the power rails are out of specifications (+/-14 V to +/-20 V) the board shuts down for 1 second

<sup>b</sup> This is a severed hardware protection which means that the board experienced a lot of voltage beyond its range or there is short circuit. The unit can be damaged.

***Negative rail (VEE) under voltage!***

***Negative rail (VEE) over voltage!***

***Thermal protection!***

***AGC out of range!***

***PCB temperature too high!***

***PCB temperature too low!***

***Overcurrent!***

When the PCB temperature rises above 65 to 70 °C or falls below 0 °C, a temperature sensor on the PCB shuts off the board for 16 seconds. The diagnostic signal is accessible via pin 3, however it shouldn't be loaded, shorted, forced to a signal, or left connected to other devices (otherwise, the thermal shutdown may trip and disable the power stage).

To prevent ground loops or board damage, the maximum relevant load should be greater than 100 kΩ, and it should be measured by an insulated interface like a multimeter.

The typical sensor response is: 19.5 mV/°C with an output voltage of 400 mV at 0 °C.

## 5.4 Resettable Fuse

The board has a resettable fuse that, after tripping, can be reset by shutting off the power and allowing for the component to cool. The fuse should return to its original state in less than 10 seconds at 20 °C. If the resettable fuse trips, it indicates a problem with the board's motor or power stage.

Temperature affects the time protection: at low temperatures the protection trip occurs later than it does at high temperatures.

Please contact Thorlabs if the fuse trips continuously: the motor or the board might have issues.

## 5.5 Error codes

The shut down time of the board is the error code.

A 16-second shut down could indicate that the PCB temperature is too high and at least one voltage rail is out of range.

### 1 second

*Positive rail (VCC) under voltage*

*Positive rail (VCC) over voltage*

*Negative rail (VEE) under voltage*

*Negative rail (VEE) over voltage*

### 2 seconds

*Overcurrent*

### 4 seconds

*AGC out of range*

### 8 seconds

*Thermal protection*

### 16 seconds

*PCB temperature too high*

*PCB temperature too low*

## Chapter 6 Specifications and Associated Parts

| Item #  | GVS001, GVS002, GVS101, GVS102,<br>GVS201, GVS202   |
|---|---|
| <b>Mirror</b>   |   |
| Maximum Beam Diameter   | 5 mm  |
| Finish  | GVS00x: Protected Silver Coated<br>GVS10x: Protected Gold Coated<br>GVS20x: Broadband, E02  |
| Damage Threshold <sup>c</sup>   | GVS00x: 3 J/cm <sup>2</sup> at 1064 nm, 10 ns pulse<br>GVS10x: 2 J/cm <sup>2</sup> at 1064 nm, 10 ns pulse<br>GVS20x: 0.25 J/cm <sup>2</sup> at 532 nm, 10 ns pulse |
| <b>Motor &amp; Position Sensor</b>                                    |   |
| Linearity   | 99.9%, range $\pm 20^\circ$   |
| Scale Drift   | 40 ppm/ $^\circ\text{C}$ (Max)  |
| Zero Drift  | 10 $\mu\text{Rad}/^\circ\text{C}$ (Max)   |
| Repeatability   | 15 $\mu\text{Rad}$  |
| Resolution<br>with GPS011 Linear PSU<br>with Standard Switch Mode PSU | 0.0008 $^\circ$ (15 $\mu\text{Rad}$ )<br>0.004 $^\circ$ (70 $\mu\text{Rad}$ )   |
| Average Current   | <1.25 A rms   |
| Peak Current  | 5 A   |
| Load Mirror Aperture  | 5 mm  |
| Coil Resistance   | 2.2 $\Omega \pm 10\%$   |
| Coil Inductance   | 150 $\mu\text{H} \pm 10\%$  |
| Rotor Inertia   | 0.02 g per cm <sup>2</sup>  |
| Maximum Scale Angle (Mechanical Angle)                                | $\pm 12.5^\circ$ (with 0.8 V/ $^\circ$ scaling factor)  |
| Motor Weight<br>(Including Cables, Excluding Bracket)                 | 50 g  |
| Operating Temperature Range   | 0 – 40 $^\circ\text{C}$   |

### Note

The lowest scale drift for the small beam galvo is generally achieved around 5 - 10  $^\circ\text{C}$ , stabilizing the temperature of the motor and of the PCB will keep the drift sensitivity under control.

The maximum speed is achieved when using triangular waveforms with 50% of duty cycle. If the signal has a different duty cycle (sawtooth) the maximum achievable speed is lower and determined by the slew rate. Max power bandwidth is measured with a 20 Vpp sinewaves when the output swing drops off -3 dB on the Y axis.

### Drive Electronics

<sup>c</sup> The way our mirrors are tested is continually updated, please consult [www.thorlabs.com](http://www.thorlabs.com) for more information.

| Item #   | Value   |
|--|---|
| Full Scan Bandwidth <sup>d</sup>                       | 100 Hz Square wave,<br>250 Hz Sine wave<br>175 Hz Sawtooth<br>175 Hz Triangular |
| Small Angle ( $\pm 0.2^\circ$ ) Bandwidth <sup>e</sup> | Typically, 1 kHz with Sine wave   |
| Small Angle Step Response                              | 300 $\mu$ s   |
| Power Supply   | $\pm 15$ V to $\pm 18$ V DC<br>(1.25 A rms, 5 A peak MAX)                       |
| Analog Signal Input Resistance                         | 20 k $\Omega$ $\pm 1\%$ (Differential Input)                                    |
| Position Signal Output Resistance                      | 1 k $\Omega$ $\pm 1\%$  |
| Analog Position Signal Input Range                     | $\pm 10$ V  |
| Mechanical Position Signal Input Scale Factor          | switchable: 0.5 V/ $^\circ$ , 0.8 V/ $^\circ$ or 1.0 V/ $^\circ$                |
| Mechanical Position Signal Output Scale Factor         | 0.5 V/ $^\circ$   |
| Operating Temperature Range                            | 0 - 40 $^\circ$ C   |
| Servo Board Size (L x W x H)                           | 85 mm x 74 mm x 44 mm<br>(3.35" x 2.9" x 1.73")                                 |

## 6.1 Associated Products

| Item #                                     | Part Number |
|--|-------------|
| 2D Galvo System - Protected Silver Mirrors | GVS002      |
| 1D Galvo System - Protected Silver Mirror  | GVS001      |
| 2D Galvo System - Protected Gold Mirrors   | GVS102      |
| 1D Galvo System - Protected Gold Mirror    | GVS101      |
| 2D Galvo System - Broadband E02 Mirrors    | GVS202      |
| 1D Galvo System - Broadband E02 Mirror     | GVS201      |
| Motor Assembly Heatsink                    | GHS003(/M)  |
| Galvo Power Supply                         | GPS011      |
| Servo Driver Card Cover                    | GCE001      |
| 1D Galvo Cage System Mount                 | GCM001      |
| 2D Galvo Cage System Mount                 | GCM002(/M)  |
| Tip/Tilt Mount Adapter                     | GTT001      |

<sup>d</sup> Using heatsink to keep temp <50  $^\circ$ C (see section 3.3.2)

<sup>e</sup> Using heatsink to keep temp <50  $^\circ$ C (see section 3.3.2)

## Chapter 7 Calculating the Power Dissipation

### 7.1 Motor Heatsink

The power dissipated in the motor can be estimated by measuring the RMS current drawn from the PSU and then using the following equation:

$$P_{\text{mot}} = R_{\text{mot}} \times [(I_{\text{rms}+} + I_{\text{rms}-} - I_{\text{q}+} - I_{\text{q}-}) / 2]^2$$

Where  $P_{\text{mot}}$  is the power dissipated in the motor,  $R_{\text{mot}}$  is the motor coil resistance ( $2.2 \Omega$ ),  $I_{\text{rms}+}$  is the rms current drawn from the positive supply rail,  $I_{\text{rms}-}$  is the rms current drawn from the negative supply rail,  $I_{\text{q}+}$  is the quiescent current drawn on the +ve rail (0.15 A under all circumstances) and  $I_{\text{q}-}$  is the quiescent current drawn on the -ve rail (0.10 A under all circumstances).

The power dissipated in the driver boards can be calculated using the following equation:

$$P_{\text{drv}} = (V_+ \times I_{\text{rms}+}) + (V_- \times I_{\text{rms}-}) - P_{\text{mot}}$$

Where  $P_{\text{drv}}$  is the power dissipated in the driver boards,  $V_+$  is positive supply voltage and  $V_-$  is the negative supply voltage.

Overheating can short the life of the motors or trip the thermal protection in the board.

#### 7.1.1 Calculating the Required Thermal Conductivity

The ability of a heatsink to transfer heat to its surroundings is parameterized either by its thermal conductivity,  $k$  or its thermal resistance,  $\emptyset$ . The lower the thermal resistance the more effectively the heatsink can transfer heat. The required thermal resistance can be calculated from the following equation:

$$\emptyset = 1/k = (T_{\text{hs}} - T_a) / P_{\text{max}}$$

In the above equation  $T_{\text{hs}}$  is the maximum permissible heatsink temperature,  $T_a$  is the ambient temperature and  $P_{\text{max}}$  is the maximum power the device being cooled will dissipate. For the motors it is desirable to keep  $T_{\text{hs}}$  below 45 °C.

The following equation can be used to calculate  $T_{\text{hs}}$  for the driver IC:


$$T_{\text{hs}} = T_j - P_{\text{max}} \times \emptyset_{\text{jhs}}$$

Here,  $\emptyset_{\text{jhs}}$  is the thermal resistance between the semiconductor junction of the power amplifier IC and the heatsink.  $T_j$  is the maximum temperature allowable at the junction, about 150 °C (although the lifetime of the driver IC will be longer if the junction is kept at a lower temperature). The value of  $\emptyset_{\text{jhs}}$  is 1.3 °C/W.

## Chapter 8 Reasons for Image Distortion

The deflection of a laser beam with a two-mirror system results in three effects:

(1) The arrangement of the mirrors leads to a certain distortion of the image field – see Figure 28 below.




**Figure 28** Field Distortion in a Two-way Mirror Deflection System

This distortion arises from the fact that the distance between mirror 1 and the image field depends on the size of the mechanical scan angles of mirror 1 and mirror 2. A larger scan angle leads to a longer distance.

(2) The distance in the image field is not proportional to the scan angle itself, but to the tangent of the scan angle. Therefore, the marking speed of the laser focus in the image field is not proportional to the angular velocity of the corresponding scanner.


(3) If an ordinary lens is used for focusing the laser beam, the focus lies on a sphere. In a flat image field, a varying spot size will result.

As a result, you will find the scanning field turns out to be a "pillow-shaped" image. Refer to Figure 29.



**Figure 29** Pillow Shaped Field Distortion Caused by the Arrangement of Mirrors

## Chapter 9      Certifications and Compliance



# THORLABS

www.thorlabs.com

### EU Declaration of Conformity

in accordance with EN ISO 17050-1:2010

**We:** Thorlabs Ltd.

**Of:** 204 Lancaster Way Business Park, Ely, CB6 3NX, UK

*in accordance with the following Directive(s):*

|                       |  |
|-----------------------|--|
| 2006/42/EC            | Machinery Directive (MD)                                   |
| 2014/30/EU            | Electromagnetic Compatibility (EMC) Directive              |
| 2011/65/EU + 2015/863 | Restriction of Use of Certain Hazardous Substances (Ro HS) |

*hereby declare that:*

**Model:** **GVSM00X Series**


**Equipment:** **1D or 2D Galvo System with accessories or metric accessories**

*is/are in conformity with the applicable requirements of the following documents:*

|   |  |      |
|---|--|------|
| EN ISO 12100  | Safety of Machinery. General Principles for Design. Risk Assessment and Risk Reduction   | 2010 |
| <p>Authorised to compile the technical file: Thorlabs GmbH<br/>Münchener Weg1, 85232 Bergkirchen, Deutschland</p> |  |      |
| EN 61326-1  | Electrical Equipment for Measurement, Control and Laboratory Use - EMC Requirements  | 2013 |
| EN 63000  | Technical documentation for the assessment of electrical and electronic products with respect to the restriction of hazardous substances | 2018 |

*and which, issued under the sole responsibility of Thorlabs, is/are in conformity with Directive 2011/65/EU of the European Parliament and of the Council of 8th June 2011 on the restriction of the use of certain hazardous substances in electrical and electronic equipment, for the reason stated below:*

*I hereby declare that the equipment named has been designed to comply with the relevant sections of the above referenced specifications, and complies with all applicable Essential Requirements of the Directives.*


**Signed:** 

**On:** 22 January 2014

**Name:** Keith Dhese

**Position:** General Manager

EDC - GVSM00X Series -2014-01-22



## Chapter 10 Thorlabs Worldwide Contacts

For technical support or sales inquiries, please visit us at for [www.thorlabs.com/contact](http://www.thorlabs.com/contact) our most up-to-date contact information.



### USA, Canada, and South America

Thorlabs, Inc.  
sales@thorlabs.com  
techsupport@thorlabs.com

### Europe

Thorlabs GmbH  
europe@thorlabs.com

### France

Thorlabs SAS  
sales.fr@thorlabs.com

### Japan

Thorlabs Japan, Inc.  
sales@thorlabs.jp

### UK and Ireland

Thorlabs Ltd.  
sales.uk@thorlabs.com  
techsupport.uk@thorlabs.com

### Scandinavia

Thorlabs Sweden AB  
scandinavia@thorlabs.com

### Brazil

Thorlabs Vendas de Fotônicos Ltda.  
brasil@thorlabs.com

### China

Thorlabs China  
chinasales@thorlabs.com



