





Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\svn_radni\.\Accel&Mag.SchDoc	Drawn By:




Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\svn_radni\AmbiLight.SchDoc	Drawn By:




Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\svn_radni\BLE.SchDoc	Drawn By:




Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\svn_radni\ExtConn.SchDoc	Drawn By:




Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\svn_radni\.\Flash.SchDoc	Drawn By:




Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\svn_radni\.\Gyro.SchDoc	Drawn By:





Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\svn_radni\Heart-Rate.SchDoc	Drawn By:

















Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\svn_radni\OLED.SchDoc	Drawn By:





Try not to use vibration motor and heart rate simultaneously. There is possibility of system instability in that case!

Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\svn_radni\PowerMng.SchDoc	Drawn By:



Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\_svn_radni\...\Pressure&Temp.SchDoc	Drawn By:



Title		
Size	Number	Revision
A4		
Date:	30/11/2015	Sheet of
File:	D:\svn_radni\...RGB_LED&VibroMot.SchDoc	Drawn By: