



Name :

Roll No. :

Invigilator's Signature :

CS/B.Tech(ME)/SEM-5/ME-504/2011-12

2011

TECHNOLOGY OF MACHINING

Time Allotted : 3 Hours

Full Marks : 70

The figures in the margin indicate full marks.

*Candidates are required to give their answers in their own words
as far as practicable.*

GROUP – A

(Multiple Choice Type Questions)

1. Choose the correct alternatives for the following :

$$10 \times 1 = 10$$

- i) A cutting tool can never have its
 - a) rake angle-positive
 - b) rake angle-negative
 - c) clearance angle-positive
 - d) clearance angle-negative.
- ii) Relief angle on HSS tool usually varies from

a) 3° to 10°	b) 11° to 15°
c) 16° to 20°	d) 22° to 27°.
- iii) In lathe, the spindle speed will be minimum in

a) plane turning	b) thread cutting
c) taper turning	d) finishing.

5409

[Turn over

CS/B.Tech(ME)/SEM-5/ME-504/2011-12



- iv) Backlash eliminator is used in
- upmilling
 - downmilling
 - gang milling
 - none of these.
- v) In machining Merchant's Circle diagram deals with
- tool geometry
 - mechanism of chip formation
 - mechanics of machining
 - tool life.
- vi) Taylor's tool life equation is expressed by
- $TV^n = C$
 - $VT^n = C$
 - $(VT)^n = C$
 - $VT = C$.
- vii) The straight teeth of internal spur gears can be produced in
- milling machine
 - gear shaping machine
 - hobbing machine
 - planing machine.
- viii) A cam shaft is always provided in
- centre lathes
 - capstan lathes
 - turret lathes
 - single spindle automatic lathes.
- ix) Broaching is primarily done for
- Better finishing
 - Mass production
 - Cylindrical work piece
 - Hard work piece.
- x) In grinding operation, which one acts as a cutting tool ?
- H.S.S. tips
 - Diamond tips
 - Carbide tips
 - Abrasive grains.

CS/B.Tech(ME)/SEM-5/ME-504/2011-12

**GROUP – B****(Short Answer Type Questions)**Answer any *three* of the following.

3 × 5 = 15

2. a) What is the combined effect of feed and nose radius on surface roughness ?
b) How does tool failure take place ? 2 + 3
3. Distinguish between Mass production and Batch production.
4. State the causes and effects of formation of built-up edge (BUE) in machining.
5. Sketch a plain milling cutter and show its orthogonal rake and orthogonal clearance.
6. A high speed steel tool is used for machining a job at a cutting speed of 35 m/min and has a tool life of 55 mins. Find the tool life at a cutting speed of 40 m/min. Assume $n = 0.13$.

GROUP – C**(Long Answer Type Questions)**Answer any *three* of the following.

3 × 15 = 45

7. a) The following data was obtained from the orthogonal cutting test :
 Rake angle = 20°
 Depth of Cut = 6 mm
 Feed rate = 0.25 mm/rev
 Chip length before cutting = 29.4 mm
 Chip length after cutting = 12.9 mm
 Vertical cutting force = 1050 N
 Horizontal cutting force = 620 N
 Using Merchant' analysis calculate :
 i) direction and magnitude of resultant force
 ii) shear plane angle
 iii) friction force and friction angle.

CS/B.Tech(ME)/SEM-5/ME-504/2011-12



- b) Find approximate time required to drill a 18 mm diameter hole in an M.S. Plate of 15 mm thickness having an approach length of 5 mm with no over travel permitted employing 212 rpm and feed of 0.2 mm/rev.
- c) What is machinability and machinability index ?
10 + 3 + 2
8. a) A hole of 25 mm diameter and 35 mm depth is to be drilled in a MS component. The cutting speed is 35 m/min and feed rate is 0.20 mm/rev. Calculate :
- Machining time
 - Material removal rate
- b) It is required to divide the periphery of a job into 50 equal divisions. The index plate supplied is 15, 16 17, 18, 19, 20 holes. Find the crank movement.
- c) Explain Honing and Lapping process. 5 + 5 + 5
9. a) Describe the working and construction of crank and slotted quick return mechanisms of a shaper.
- b) What is Jig boring machine ? Describe the different measuring systems employed in Jig boring machines.
- c) Obtain indexing for 51 divisions. 5 + 5 + 5
10. a) State the basic purposes of machining, grinding and super finishing.
- b) With the help of suitable diagram, briefly describe how external screw threads are produced by thread rolling and centreless grinding. 5 + 10
11. a) Describe the different types of chip formation during cutting operation.
- b) Describe "Geneva Mechanism" in Turret Lathe.
- c) Explain different types of job holding and supporting devices in a lathe. 5 + 5 + 5
-