

CNC General Codes

LAB 12

Haas Lathe G Codes List - Haas G Codes for CNC Lathes

G00: Rapid Position Motion

G01: Linear Interpolation Motion or Linear Motion, Chamfer and Corner Rounding – Modal

G02: CW Circulation Interpolation Motion – Modal

G03: CCW Circular Interpolation Motion – Modal

G04: Dwell (P) P=Seconds. Milliseconds

G05: Fine Spindle Control Motion (Live Tooling) – Optional

G09: Exact Stop

G10: Programmable Offset Setting

G14: Main-Spindal / Sub-Spindle Swap – Optional

G15: Main-Spindal / Sub-Spindle Swap Cancel – Optional

G17: Circular Motion XYZ Plane Selection Live Tooling
(G02, G03) – Modal, Optional

G18: Circular Motion ZX Plane Selection (G02, G03)

G19: Circular Motion YZ Plane Selection Live Tooling
(G02, G03) – Modal/Optional

G20: Verify Inch Coordinate Positioning

G21: Verify Metric Coordinate Positioning – Modal

G28: Rapid to machine zero return through Ref. Point

G29: Move to Location Through G29 Ref. Point

G31: Feed Until skip Function – Optional

G32: Thread cutting path – Modal

G40: Tool Nose Compensation Cancel G41/G42

G41: Tool Nose Compensation, Left – Modal

G42: Tool Nose Compensation, Right – Modal

G50: Spindle Speed Maximum RPM Limit (S) – Modal

G51: Rapid to Machine zero, Cancel offset

G52: Work offset Positioning Coordinate OR Global Work Offset Coordinate System Shift – Modal

G53: Machine Zero Positioning Coordinate

G54: Work Offset Positioning Coordinate #1

G55: Work Offset Positioning Coordinate #2 – Modal

G56: Work Offset Positioning Coordinate #3 – Modal

G57: Work Offset Positioning Coordinate #4 – Modal

G58: Work Offset Positioning Coordinate #5 – Modal

G59: Work Offset Positioning Coordinate #6 – Modal

G61: Exact Stop – Modal

G64: Exact Stop G61 Cancel

G65: Macro Sub-Routine Call – Optional

G70: Finishing Cycle

G71: O.D. / I.D. Stock Removal Cycle Example

G72: End Face Stock Removal Cycle

G73: Irregular Path Stock Removal Cycle

G74: Face Grooving OR High Speed Peck Drill Cycle

G75: Peck Grooving Cycle O.D. or I.D.

G76: Threading Cycle, Multiple Pass O.D. / I.D.

G77: Live Tooling Flatting Cycle – Optional

G80: Cancel Canned Cycle

G81: Drill Canned Cycle – Modal

G82: Spot Drill / Counterbore Canned Cycle – Modal

G83: Peck Drill Deep Hole Canned Cycle – Modal

G84: Tapping Canned Cycle – Modal

G85: Bore In-Bore Out Canned Cycle – Modal

G86: Bore In-Stop-Rapid Out Canned Cycle – Modal

G87: Bore In-Stop-Manual Retract Canned Cycle – Modal

G88: Bore In-Dwell-Manual Retract Canned Cycle – Modal

G89: Bore In-Dwell-Bore-out Canned Cycle – Modal

G90: O.D. / I.D. Turning Cycle – Modal

G92: Threading Cycle – Modal

G94: End Facing Cycle – Modal

G95: Live Tooling End Face Rigid Tap – Modal/Optional

G96: Constant Surface speed, CSS On – Modal

G97: Constant Non-Varying Spindle Speed, CSS Off (S)

G98: Feed Per Minute (F) – Modal

G99: Feed Per Revolution (F)

G100: Mirror Image Cancel G101

G101: Mirror Image
G102: Programmable Output to RS – 232
G103: Limit Block Lookahead
G105: Servo Bar Command – Optional
G110-G111: Work Offset-positioning Coordinate #7-#8 – Modal
G112: Cartesian to Polar Transformation – Optional
G113: Cartesian to Polar Transformation Cancel – Optional
G114-G129: Work Offset Positioning Coordinate #9-#24 – Modal
G154: Select Work Offset Positioning Coordinate P1-99 (P) – Modal
G159: Background Pickup / Part Return – Optional
G160: APL Axis Command On – Optional
G161: APL Axis Command Off – Optional
G184: Reverse Tapping Canned Cycle – Modal
G186: Live Tooling Reverse Rigid Tap – Optional
G187: Accuracy Control for High Speed Machining (E)
G194: Sub-Spindle / Tapping Canned Cycle – Modal
G195: Live Tooling Radial Tapping – Optional
G196: Live Tooling Radial Tapping Reverse – Optional
G200: Index on the Fly

Haas Lathe M Codes List - Haas M Codes for CNC Lathes

M00: Program Stop – Modal
M01: Optional Program Stop – Modal
M02: Program End – Modal
M03: Spindle on Forward (S) – Modal
M04: Spindle on Reverse (S) – Modal
M05: Spindle Stop – Modal
M08: Coolant On – Modal
M09: Coolant Off – Modal
M10: Chuck Clamp – Modal
M11: Chuck Unclamp – Modal
M12: Auto Air Jet On (P) – Modal/Optional
M13: Auto Air Jet Off – Modal/Optional
M14: Main Spindle Clamp – Modal/Optional

M15: Main Spindle Unclamp – Modal/Optional
M17: Rotate Turret Forward (T) – Modal
M18: Rotate turret Reverse (T) – Modal
M19: Orient Spindle – Modal/Optional Example
M21: Tailstock Advance – Modal/Optional
M22: Trailstock Retract – Modal/Optional
M23: Angle Out of Thread On – Modal
M24: Angle of Thread Off – Modal
M25-M28: Optional User M Code Interface with M-Fin Signal – Modal
M30: Program End and Reset – Modal
M31: Chip Auger Forward – Modal
M33: Chip Auger Stop – Modal
M36: Parts Catcher On – Modal/Optional
M37: Parts Catcher Off – Modal/Optional
M38: Specify Spindle Variation On – Modal
M39: Specify Spindle Variation Off – Modal
M41: Spindle Low Gear Override – Modal
M42: Spindle High Gear Override – Modal
M43: Turret Unlock – Modal
M44: Turret Lock – Modal
M51-M58: Optional User M Code Set – Modal
M59: Output Relay Set (N) – Modal
M61-M68: Optional User M Code Clear – Modal
M69: Output Relay Clear (N) – Modal
M76: Program Displays Inactive – Modal
M77: Program Displays Active – Modal
M78: Alarm in Skip Signal Found – Modal
M79: Alarm if Skip signal Not Found – Modal
M85: Automatic Door Open – Modal/Optional
M86: Automatic Door Close – Modal/Optional
M88: High Pressure Coolant ON – Modal/Optional
M89: High Pressure Coolant off – Modal/Optional
M93: Axis Position Capture Start – Modal/Optional
M94: Axis Position Capture Stop – Modal/Optional
M95: Sleep Mode – Modal
M96: Jump if no Signal – Modal
M97: Local Sub-Routine Call – Modal

M98: Sub-Program Call – Modal
M99: Sub-Program / Routine Return or Loop – Modal
M109: Inactive User Input (P) – Modal/Optional
M110: Tailstock Chuck Clamp – Modal/Optional
M111: Tailstock Chuck Unclamp – Modal/Optional
M119: Sub-Spindle Orient – Modal/Optional**
M121-M128: Optional User M Code Interface with M-Fin Signal – Modal
M133: Live tool Drive Forward (P) – Modal/Optional Example
M134: Live Tool Drive Reverse (P) – Modal/Optional
M135: Live Tool Drive Stop – Modal/Optional
M143: Sub-Spindle Forward (P) – Modal/Optional
M144: Sub-Spindle Reverse (P) – Modal/Optional
M145: Sub-Spindle Stop – Modal/Optional
M154: C Axis Engage – Modal/Optional Example
M155: C Axis Disengage – Modal/Optional
M164: Rotate APL Grippers To “n” Position – Modal/Optional
M165: Open APL Gripper 1 (Raw Material) – Modal/Optional
M166: Close APL Gripper 1 (Raw Material) – Modal/Optional
M167: Open APL Gripper 2 Finished Material) – Modal/Optional
M168: Close APL Gripper 2 (Finished Material) – Modal/Optional

Haas Mill G Codes List - Haas G Codes for CNC Milling

G00: Rapid Motion
G01: Linear Interpolation Motion
G02: CW Interpolation Motion
G03: CCW Interpolation Motion
G04: Dwell
G09: Exact Stop
G10: Programmable Offset Setting
G12: CW Circular Pock Milling (Yasnac)
G13: CCW Circular Pock Milling (Yasnac)
G17: XY Plane Selection
G18: ZX Plane Selection

G19: YZ Plane Selection
G20: Inch Programming Selection
G21: Metric Programming Selection
G28: Return to Machine Zero
G29: Move to Location Through G29 Reference
G31: Skip Function
G35: Automatic Tool Diameter Measurement
G36: Automatic Work Offset Measurement
G37: Automatic Tool Length Measurement
G40: Cutter Comp Cancel
G41: Cutter Compensation Left
G42: Cutter Compensation Right
G43: Tool Length Compensation +
G44: Tool Length Compensation –
G47: Engraving
G49: G43/G44 Cancel
G50: G51 Cancel
G51: Scaling
G52: Select Work Coordinate System G52 (Yasnac)
G52: Set Local Coordinate System (Fanuc)
G52: Set Local Coordinate System (HAAS)
G53: Non-Modal Machine Coordinate Selection
G54: Select Work Coordinate System 1
G55: Select Work Coordinate System 2
G56: Select Work Coordinate System 3
G57: Select Work Coordinate System 4
G58: Select Work Coordinate System 5
G59: Select Work Coordinate System 6
G60: Unidirectional Positioning
G61: Exact Stop Modal
G64: G61 Cancel
G65: Macro Subroutine Call
G68: Rotation
G69: G68 Cancel
G70: Bolt Hole Circle (Yasnac) Example1 Example2 Example3
G71: Bolt Hole Arc (Yasnac) Example
G72: Bolt Holes Along an Angle (Yasnac) Example

G73: High Speed Peck Drill Canned Cycle
 G74: Reverse Tap Canned Cycle
 G76: Fine Boring Canned Cycle
 G77: Back Bore Canned Cycle
 G80: Canned Cycle Cancel
 G81: Drill Canned Cycle Example1 Example2 Ex3 Ex4 Ex5
 G82: Spot Drill Canned Cycle Ex1
 G83: Peck Drill Canned Cycle Ex1 Ex2
 G84: Tapping Canned Cycle Example1 Peck Tapping
 G85: Boring Canned Cycle
 G86: Bore/Stop Canned Cycle
 G87: Bore/Manual Retract Canned Cycle
 G88: Bore/Dwell Canned Cycle
 G89: Bore Canned Cycle
 G90: Absolute
 G91: Incremental
 G92: Set Work Coordinates – FANUC or HAAS
 G92: Set Work Coordinates – YASNAC
 G93: Inverse Time Feed Mode ON
 G94: Inverse Time Feed Mode OFF/Feed Per Minute ON
 G98: Initial Point Return
 G99: R Plane Return
 G100: Disable Mirror Image
 G101: Enable Mirror Image
 G102: Programmable Output To RS-232
 G103: Block Look ahead Limit
 G107: Cylindrical Mapping
 G110: Select Coordinate System 7
 G111: Select Coordinate System 8
 G112: Select Coordinate System 9
 G113: Select Coordinate System 10
 G114: Select Coordinate System 11
 G115: Select Coordinate System 12
 G116: Select Coordinate System 13
 G117: Select Coordinate System 14
 G118: Select Coordinate System 15
 G119: Select Coordinate System 16

G120: Select Coordinate System 17
 G121: Select Coordinate System 18
 G122: Select Coordinate System 19
 G123: Select Coordinate System 20
 G124: Select Coordinate System 21
 G125: Select Coordinate System 22
 G126: Select Coordinate System 23
 G127: Select Coordinate System 24
 G128: Select Coordinate System 25
 G129: Select Coordinate System 26
 G136: Automatic Work Offset Center Measurement
 G141: 3D+ Cutter Compensation
 G143: 5 Axis Tool Length Compensation+
 G150: General Purpose Pocket Milling
 G153: 5 Axis High Speed Peck Drill Canned Cycle
 G154: P1-P99 Replaces G110-G129 on newer machines
 G155: 5 Axis Reverse Tapping Canned Cycle
 G161: 5 Axis Drill Canned Cycle
 G162: 5 Axis Spot Drill/Counterbore Canned Cycle
 G163: 5 Axis Peck Drill Canned Cycle (Setting 22)
 G164: 5 Axis Tapping Canned Cycle
 G165: 5 Axis Bore in, Bore out Canned Cycle
 G166: 5 Axis Bore in, Stop, Rapid out Canned Cycle
 G169: 5 Axis Bore, Dwell, Bore out Canned Cycle
 G174: Special Purpose Non-Vertical Rigid Tapping CCW
 G184: Special Purpose Non-Vertical Rigid Tapping CW
 G187: Accuracy Control for High Speed Machining
 G188: Get Program From PST (Program Schedule Table)

Haas Mill M Codes List - Haas M Codes for CNC Milling

M00: Program Stop
 M01: Optional Program Stop
 M02: Program End (Setting 39)
 M03: Spindle On, Clockwise (S) (Setting 144)
 M04: Spindle On, Counterclockwise (S) (Setting 144)
 M05: Spindle Stop
 M06: Tool Change (T) (Setting 42, 87, 155)

M08: Coolant On (Setting 32)	M75: Set G35 or G136 Reference Point
M09: Coolant Off	M76: Control Display Inactive
M10: 4th Axis Brake On	M77: Control Display Active
M11: 4th Axis Brake Release	M78: Alarm if Skip Signal Found
M12: 5th Axis Brake On	M79: Alarm if Skip Signal Not Found
M13: 5th Axis Brake Release	M80: Automatic Door Open (Setting 131)
M16: Tool Change (T) (Same as M06)	M81: Automatic Door Close (Setting 131)
M17: APC Pallet Unclamp and Open APC Door	M82: Tool Unclamp
M18: APC Pallet Clamp and Close APC Door	M83: Auto Air Jet On
M19: Orient Spindle (P, R values optional)	M84: Auto Air Jet Off
M21-M28: Optional User M Code Interface with M-Fin Signals	M86: Tool Clamp
M30: Program End and Reset (Setting 2, 39, 56, 83)	M88: Coolant Through the Spindle On
M31: Chip Auger Forward (Setting 114,115)	M89: Coolant Through the Spindle Off
M33: Chip Auger Stop	M93: Axis POS Capture Start (P, Q)
M34: Coolant Spigot Position Down, Increment (+1)	M94: Axis POS Capture Stop
M35: Coolant Spigot Position Up, Decrement (-1)	M95: Sleep Mode
M36: Pallet Part Ready (P)	M96: Jump if No Input (P, Q)
M39: Rotate Tool Turret (T#) (Setting 86)	M97: Local Sub-Program Call (P, L)
M41: Spindle Low Gear Override	M98: Sub Program Call (P, L)
M42: Spindle High Gear Override	M99: M97 Local Sub-Program or M98 Sub-Program Return or Loop Program (Setting 118)
M50: Execute Pallet Change (P) (Setting 121 thru,129)	M101: MOM (Minimum Oil Machining) CANNED CYCLE MODE (I)
M51-M58: Optional User M Code Set	M102: MOM (Minimum Oil Machining) MODE (I, J)
M59: Output Relay Set (N)	M103: MOM (Minimum Oil Machining) MODE CANCEL
M61-M68: Optional User M Code Clear	M109: Interactive User Input (P)
M69: Output Relay Clear (N)	