


# IEEE x FSAE Altium Workshop Week 6: Introduction to Soldering




Hosted by: Nick Howard & Adrian Sucahyo



# Soldering Overview


- Soldering is simply attaching two metal surfaces with a filler metal (solder)
  - Provides both electrical and mechanical connection
- Typically, soldering is performed with a hot iron or hot air
  - Irons are typically used for through-hole components or large SMDs
  - Hot air is typically used for SMDs
- The choice to use hot air or an iron is highly situation-dependent
  - Iron applies local heat
  - Hot air heats a large area





# Solder types

- Solder can have a variety of compositions
  - Can come as a spool (wire) or paste
- Pb (leaded) solder is very easy to use
  - Relatively low melting point ( $\sim 183^{\circ}\text{C}$ )
  - Flows very easily
  - Typically Sn 60% Pb 40%
- Pb-Free solder is a bit more difficult to work with
  - Typically used for RoHS compliance
  - Can be mostly tin (Sn 99% Cu 0.7% Ag 0.3%) or part Bi/In
  - Sn99 solder melts at  $\sim 217^{\circ}\text{C}$
  - Bi/In eutectics can melt as low as  $\sim 138/118^{\circ}\text{C}$







# Solder Stations

Temperature unit

Hot air  
power switch

Hot air  
temperature

Hot air  
"strength"

Soldering  
iron power  
switch

Soldering iron  
temperature





# Solder Stations



Temperature unit

Multipurpose  
temperature  
adjustment

Hot air  
"strength"

Hot air  
power switch

Soldering  
iron power  
switch



# Important Notes

- NEVER touch tip of soldering iron or hot air gun while in use or shortly after use
- NEVER unplug hot air station while in use
  - Allow heating element to auto-cool when done
  - Turn off hot air with switch on front panel to auto-cool off

On 6000 series stations, gun will auto-cool off when placed back in holder
- Solder in a well-ventilated area
- Don't leave soldering iron or hot air gun on and unattended
  - Leaving soldering iron on for extended periods can damage tip
- Clean and tin soldering iron tip regularly
  - Tin iron before powering off
- Keep temperatures reasonable
  - Start low, increase as needed
  - I typically solder Pb-free around 280-320°C





# Questions?



# Download Today's Project Files

- Navigate to the workshop GitHub and download today's files listed under **Week06**

**<https://github.com/AdrianSucahyo/IEEE-PCB-Workshop-Resources-2025>**