

REQUEST: This message has been generated automatically from the Marine Accident Investigation Website.

XXXX has sent the following comment:

Postal address: XXXX

Postcode: XXXX

Country: Monaco

Telephone: XXXX

Facsimile:

Email Address: XXXX

Website Address:

Company:

Job Title: Sales Manager

Industry Sector:

How did you reach our website? website

Enquiry: I would like to know the recorded accidents within the North Sea concerning tandem offloading vessels (i.e. like the Schiehallion collision. If you have records or statistics for the last 10 or 15 years or any records concerning this I would be interested.

Comment: Looks very good.

This email was received from the INTERNET and scanned by the Government Secure Intranet anti-virus service supplied by Cable&Wireless Worldwide in partnership with MessageLabs. (CCTM Certificate Number 2009/09/0052.) In case of problems, please call your organisation's IT Helpdesk.

Communications via the GSi may be automatically logged, monitored and/or recorded for legal purposes.

RESPONSE: Dear XXXX

Our reference: F0007193

I am writing to confirm that the Marine Accident Investigation Branch (MAIB) of the Department for Transport has now completed its search for the information which you requested on 16 December 2010.

We have reviewed all collisions and contacts involving a Drilling Rig, Platform or Floating Production Storage & Offloading vessel and supply details of those, in addition to the Schiehallion collision, where we can identify that loading or offloading was taking place. We also expanded the search to look for collisions and contacts between ships where text describing the incident indicated that there was a ship to ship transfer in process.

One of these cases resulted in a full investigation report:

http://www.maib.gov.uk/publications/investigation_reports/2010/saetta_conger.cfm

Details of the others are in the attached document.

Please note that MAIB's remit is limited to UK vessels and accidents in 12 mile territorial waters. We have included several cases that were outside the remit of MAIB but were reported to us anyway. More comprehensive data may be available from the World Offshore Accident Database operated by Det Norske Veritas (DNV) <http://www.dnv.com/services/software/products/safeti/safetiqla/woad.asp>

In keeping with the spirit and effect of the Freedom of Information Act, all information is assumed to be releasable to the public unless exempt. The Department may, therefore, be simultaneously releasing to the public the information you requested, together with any related information that will provide a key to its wider context.

If you are unhappy with the way the MAIB has handled your request or with the decisions made in relation to your request you may complain within two calendar months of the date of this mail by replying to me at the above address. Please see attached details of the Department for Transport's complaints procedure and your right to complain to the Information Commissioner.

If you have any queries about this letter, please contact me. Please remember to quote the reference number above in any future communications.

Yours sincerely

XXXX

Freedom of Information Officer
Marine Accident Investigation Branch
Mountbatten House
Grosvenor Square
Southampton
SO15 2JU
Tel +44 (0)23 XXXX XXXX
Fax+44 (0)23 XXXX XXXX
maib@dft.gsi.gov.uk

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	0249/2010	01/03/2010	Contact	Status	Closed	
Regulation	Outside MAIB Regulations					
Location	High seas		Non UK		6019.0 N	417.0 W
Natural Light	Light		Sea State		Moderate	
Visibility	Good (5 - 10)		Wind force Range		4-6	
Other commercial				Dead 0 Injured	0	
Associated with offshore industry				Flag	Bahamas	
Offshore supply					3017.00	gt
When: Other offshore operations				0.01	Reg. L	82.88 LOA
Machinery						
Main machinery						
Main engine control system						
Other						

Other commercial	Dead 0 Injured	0
Associated with offshore industry	Flag	Bahamas
FPSO		43279.00 gt
When: Other offshore operations	0.01	Reg. L 250.20 LOA

An offshore supply vessel was discharging fuel oil by cargo hose to a FPSO when the dynamic positioning system (DP) failed. The supply vessel transferred back into manual control but before it could clear, the starboard handrail was crushed under the transom of the FPSO. The fuelling operation was stopped and the hose recovered. There appeared to be no damage to the FPSO. Once clear the supply vessel returned to port where it is planned for an electronics engineer to examine the DP system.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	0409/2002	17/03/2002	Contact	Status	Closed		
Regulation	Accident						
Location	High seas		Unknown			5758.0 N	151.0 E
Natural Light	Light		Sea State				
Visibility	Good (5 - 10)		Wind force Range	4-6			
Other commercial				Dead 0	Injured 0	Minor Damage	
Associated with offshore industry				Flag		U.K.	
Offshore supply						1399.00	gt
When: Other offshore operations				0.01		Reg. L	65.21 LOA
Deck							
Contact							
Manoeuvrability							
Safety							
General shipboard activities							
Cargo/stores/catch handling							
Location: Navigation/communication control space							
Operator error							
Human factor							
People							
Fatigue and vigilance							
Technical factor							
Design & construction							
Characteristic defect							
Other commercial				Dead 0	Injured 0	0	
Associated with offshore industry				Flag		U.K.	
Drilling						0.01	gt
When: Unknown				0.01		Reg. L	0.01 LOA
While discharging cargo at a platform, the second officer was in control of the supply vessel was reporting the last lift up to the platform and the chief officer was trying to make contact with the deck operations, they saw that the vessel was closing one of the legs of the platform. The second officer went full ahead on the joystick and cleared the leg. Instead of the joystick being in zero thrust it was set with slight stern thrust.							

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	0631/1997	29/04/1997	Collision	Status	Closed				
Regulation	Accident								
Location	High seas		Non UK			6048.0 N	126.0 E		
Natural Light	Light		Sea State						
Visibility	Good (5 - 10)		Wind force Range	4-6					
Other commercial				Dead 0 Injured	0	No Damage			
Associated with offshore industry				Flag		Barbados			
Offshore supply						2145.00 gt			
				0.01		Reg. L	68.70	LOA	
Deck									
Collision									
Contact									
Machinery									
Other commercial				Dead 0 Injured	0				
Associated with offshore industry				Flag		Unknown			
Drilling						0.01 gt			
				0.01		Reg. L	0.01	LOA	
Deck									
Collision									
Contact									
Machinery									

WHILST ALONGSIDE BOW THRUST UNIT CONTROL WAS LOST CAUSING CONTACT WITH OIL RIG LEG. MINOR DAMAGE SUSTAINED. INVESTIGATION SHOWED THAT FEEDBACK CONTROL LINKAGE HAD VIBRATED LOOSE LEAVING THRUSTER IN PREVIOUS POSITION. POWER CONTROL RETAINED BUT NO DIRECTIONAL CONTROL. CONTROL LINKS RE-CONNECTED & VESSEL CONTINUED IN SERVICE.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	0905/2010	08/07/2010	Collision	Status	Closed	
Regulation	Accident					
Location	High seas		Non UK		7018.0 N	5932.0 W
Natural Light	Light		Sea State		Calm <2 ft	
Visibility	Good (5 - 10)		Wind force Range		0-3	
Other commercial				Dead	0 Injured	0 Minor Damage
Associated with offshore industry				Flag		U.K.
Drilling						58294.00 gt
When: Replenishment at sea operations				0.01		Reg. L 228.34 LOA
Other commercial				Dead	0 Injured	0 Minor Damage
Associated with offshore industry				Flag		Norway
Offshore supply						4260.00 gt
When: Replenishment at sea operations				0.01		Reg. L 85.00 LOA
Deck						
Contact						
Bridge procedures						
Location: Navigation/communication control space						
Navigation/communication-equipment						
Bridge Control Equipment						
Location: Navigation/communication control space						
Operator error						
Human factor						
People						
Competence						
Training which itself is inadequate						
System - Crew Factors						
Procedures inadequate						
System - Equipment						
Personnel unfamiliar with equipment/not trained in use						

A Norwegian registered platform supply ship was carrying out replenishment duties with a UK registered drilling ship off Greenland and was in dynamically positioning (DP) mode. The 63 year old relief master, who was trained in the operation of DP vessels, was in the wheelhouse at the time of the accident. He had been on board for 4 days familiarisation with the outgoing master.

Towards the end of the replenishment a higher priority was identified and the supply ship was asked to stand off. The master was in the middle of transferring control positions while about 40m off the drill ship. He selected 'DP Standby' which effectively switched off the DP control. The effects of wind and tide caused the supply ship to drift towards the drill ship. The master realised his mistake and eventually selected joystick control to take his ship away from the drill ship. Unfortunately this was too late to prevent a light contact with the drill ship.

Although he was DP qualified and his ticket was DP endorsed he had not served in a vessel with this particular type of system. The master indicated that the cause of the contact was due to a problem associated with the DP control system. The subsequent technical investigation failed to find any defects with the DP control system. The master eventually conceded that he made a DP control selection error and by the time he realised his mistake the contact could not be prevented. The error was also established by interrogation of the DP electronic records. The relief master held a DP endorsement but was not familiar with the particular DP model fitted to TA. It is intended to carry out Type Specific familiarisation training before a master takes command of the particular vessel. In addition the company are investigating all senior staffs who use the DP system to ensure they are correctly trained and, if not, training will be provided.

The relief master has since had his contract terminated.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	1125/2007	31/07/2007	Contact	Status	Closed		
Regulation	Outside MAIB Regulations		English		5336.0 N	109.0 E	
Location	High seas		Sea State				
Natural Light	Light		Wind force Range	0-3			
Visibility	Good (5 - 10)		Dead	0	Injured	0	
Other commercial			Flag		Vanuatu		
Associated with offshore industry					7179.00	gt	
Platform				0.01	Reg. L	74.60	LOA
When: Unknown			Dead	0	Injured	0	
Other commercial			Flag		Netherlands		
Associated with offshore industry					2311.00	gt	
Tug/anchor handling vessel				0.01	Reg. L	69.70	LOA
When: Loading/discharging cargo							
An offshore supply vessel made contact with an offshore installation during unloading.							

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	1239/1997	27/07/1997	Collision	Status	Closed				
Regulation	Accident								
Location	High seas		Non UK			5757.0 N	150.0 E		
Natural Light	Light		Sea State		Calm <2 ft				
Visibility	Good (5 - 10)		Wind force Range		4-6				
Other commercial				Dead	0 Injured	0	Material Damage		
Associated with offshore industry				Flag		U.K.			
Drilling						13002.00	gt		
					0.01	Reg. L	0.01	LOA	
Deck									
Collision									
Contact									
Other commercial				Dead	0 Injured	0	Material Damage		
Associated with offshore industry				Flag		Bahamas			
Offshore supply						1292.00	gt		
					0.01	Reg. L	63.89	LOA	
Deck									
Collision									
Contact									

CONTACT WITH DRILLING SHIP WHEN MANOEUVRING TO DISCHARGE CARGO. NO SERIOUS DAMAGE.
 CAUSE: ERROR OF JUDGEMENT BY OFFSHORE SUPPLY VESSEL. ACTION: WILL NOT ATTEMPT
 MANOEUVRE IN SIMILAR WEATHER/TIDAL CONDITIONS IN FUTURE.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	1384/2008	05/10/2008	Contact	Status	Closed		
Regulation	Accident						
Location	High seas		Non UK			5417.0 N	220.0 E
Natural Light	Light		Sea State		Moderate		
Visibility	Good (5 - 10)		Wind force Range		0-3		
Other commercial				Dead	0	Injured	0
Associated with offshore industry				Flag			Material Damage
Standby safety vessel						U.K.	
When: Loading/discharging cargo						1492.00	gt
Machinery					0.01	Reg. L	60.99 LOA
Auxiliary machinery							
Thrusters/nozzles							
Location: Engine room							
Hydraulic failure							
Technical factor							
Material/mechanical defect							
Fatigue							
Main machinery							
Hydraulic system							
Location: Engine room							
Lack of oil							
Other commercial				Dead	0	Injured	0
Associated with offshore industry				Flag			No Damage
Drilling						Liberia	
When: Unknown						12460.00	gt
					0.01	Reg. L	90.50 LOA

On Sunday 5th October 2008 a supply vessel was working deck cargo supplying a jack up platform. This operation required the vessel to hold station in the working radius of the crane. At approximately 13.50hrs, the vessel lost control of the bow thruster and collided with the bow leg of the rig, which resulted in significant damage to the starboard bow of the vessel, forward of the collision bulkhead. No persons were injured in the incident nor was there any loss of containment or pollutants to the sea.

The vessel had been requested to work deck cargo by after one o'clock in the afternoon of the 5th October. Before the vessel re-entered the 500M zone, all the critical equipment was checked. These checks include the operation of the main engines and bow thruster, all was functioning correctly. This final 335° heading was determined by the master to be a satisfactory heading on which to work cargo. The vessel was then manoeuvred astern so as to lie in a suitable position under the crane and thus work cargo. During these manoeuvring operations the vessel movements were controlled utilising the ship's position control system (poscon); this control brings together the main propulsion, bow thruster and steering elements into one control joystick. At the time of the incident the vessel was drifting off to port in an approximate south westerly direction. The master applied opposing thrust via the Poscon to bring the vessel back to its working position.

Having initially applied the thrust and eased off to 50% the vessel master very quickly realised that even though control/command had been reduced the movement to starboard continued. The master registered the continued movement, and noted that there had been no reduction of engine noise from the bow thruster or, loss of vibration, which are both normally experienced as thrust comes off the bow thruster. No audible alarm sounded, in particular the off course alarm which is an integral feature of the Poscon. Important to note that Poscon alarm may not have operated as when the Poscon is selected the heading is automatically corrected. The master changed control to manual, switching out of Poscon, and applied opposing thrust manually to the bow thrust control and engines were placed ahead in an attempt to clear the vessel away from the location. Neither of the actions by the master had the desired affect as the bow continued to move to Starboard and towards the ENSCO 100 bow/fwd leg. Cause of the incident was the failure of a pressure gauge sited on the top of the bow thruster hydraulic control system tank. The failure of the gauge resulted in hydraulic oil leaking from the system under pressure. As the oil level dropped the pressure reduced resulting in the control function of the bow thruster being lost. Bow thruster controls located upon the vessel's bridge have no clear visual or audible warnings indicating that a failure of the bow thrust had occurred.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	1490/2010	09/10/2010	Contact	Status	Closed		
Regulation	Accident						
Location	High seas		Non UK			5626.0 N	200.0 E
Natural Light	Light		Sea State		Moderate		
Visibility	Mod. 2 - 5 nm (3)		Wind force Range		4-6		
Other commercial				Dead	0	Injured	0
Associated with offshore industry				Flag			Minor Damage
Drilling							Marshall Islands
When: Other offshore operations						13451.00	gt
Machinery					0.01	Reg. L	108.20 LOA
Main machinery							
Main engine control system							
Location: Navigation/communication control space							
Electrical fault							
Other commercial				Dead	0	Injured	0
Associated with offshore industry				Flag			Minor Damage
Offshore supply							U.K.
When: Other offshore operations						2650.00	gt
Machinery					0.01	Reg. L	81.90 LOA
Main machinery							
Main engine control system							
Location: Engine control room							
Electrical fault							
Technical factor							
Design & construction							
Design Inadequate							
Other							
Human factor							
People							
Time pressures							
System - Equipment							
Equipment poorly designed for operational use							

While discharging at a drilling platform, a supply vessel lost control when the joystick control failed and subsequently the aft console position main engine and thruster controls. Once control of the main engines was taken at the forward console full control of the main engines was attained. The loss of control caused the vessel to make contact with the platform, damaging the rig and the vessel.

An investigation commissioned by the owners found that when the master moved the joystick to port to manoeuvre the vessel away from the rig he noticed that the vessel was not responding and changed over from joystick to manual control immediately. When this didn't respond the master instructed the 2/O to take command on the forward console and apply 50% pitch on the main engines to free the vessel from the rig.

It was concluded that loose connections in the joystick microprocessor cabinet caused a partial failure of the joystick. The master seeing that he had lost control of the vessel activated manual control by pressing a touch pad on the joystick control station; this touch pad does not provide a definitive on/off action. The partial failure of the joystick system appears to have prevented the complete transfer of control to manual, thus the reason why the master reported that he had no control over the thrusters or main engines.

In the confusion that ensued it is likely that the master did not fully take control of all manual systems, only when the 2/O pressed the main engines in command buttons on the forward console did full control of the main propellers take effect allowing him to manoeuvre the vessel away from the rig.

The recommendations in the report include the fitting of load indicators at the aft consol to give positive indication of thruster effect, more frequent checks of critical systems, an examination of the vibration within the control boxes and the touch control buttons to be replaced with positive control buttons

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	1515/1993	30/08/1993	Collision	Status	Closed				
Regulation	Accident								
Location	High seas		Non UK			5826.0 N	117.0 E		
Natural Light	Light		Sea State		Moderate				
Visibility	Good (5 - 10)		Wind force Range		4-6				
Other commercial				Dead	0	Injured	0		
Associated with offshore industry				Flag		U.K.			
Offshore supply						1399.00	gt		
				0.01		Reg. L	65.21	LOA	
Deck									
Collision									
Other commercial				Dead	0	Injured	0		
Associated with offshore industry				Flag		Panama			
Drilling						26500.00	gt		
				0.01		Reg. L	82.30	LOA	
Deck									
Collision									

ON 30/08/93 THE SUPPLY VESSEL WAS MANOEUVRING INTO POSITION TO LOAD FROM THE SEMI-SUBMERSIBLE DRILLING RIG. THERE WAS LOSS OF JOY STICK CONTROL OF THE AFTER BRIDGE CONSUL, THUS RESULTING IN LOSS OF STEERING BY THE TWO AFT AUAMASTER THRUSTERS. THE RESET SWITCHES TO REVERT TO JOY STICK CONTROL COULD NOT BE OPERATED IN TIME TO PREVENT THE VESSEL DRIFTING INTO THE LEG OF THE RIG. NO REPORTED INJURIES. THE REASONS FOR THE LOSS OF CONTROL HAVE NOT YET BEEN DETERMINED BY THE MANUFACTURERS.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	0890/2009	03/07/2009	Collision	Status	Closed		
Regulation	Accident						
Location	Coastal waters		English		5216.0 N	158.0 E	
Natural Light	Light		Sea State		Moderate		
Visibility	Good (5 - 10)		Wind force Range		4-6		
Tanker/combination carrier			Dead	0 Injured	0	Minor Damage	
Chemical tanker			Flag		Gibraltar		
					2262.00	gt	
When: Replenishment at sea operations				0.01	Reg. L	88.42	LOA
Deck							
Bridge procedures							
Environmental							
Conditions had greater effect than expected							
Collision							
Manoeuvrability							
Location: Navigation/communication control space							
Tanker/combination carrier			Dead	0 Injured	0	Minor Damage	
Oil tanker			Flag		Liberia		
Products					57325.00	gt	
When: At anchor			235.80		Reg. L	243.96	LOA
Deck							
Collision							

Two tankers had completed ship to ship bunkering operations at the anchorage. As the vessel supplying the bunkers cast off, she made contact with her starboard side stern railing with the hull of the other vessel, as she came under the influence of a strong wind and tide effect. The contact caused a slight indent into the water ballast tank of the other vessel. Both vessels departed the anchorage on confirmation of no serious damage and reported it to the coastguard.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	1019/2009	25/07/2009	Collision	Status	Closed		
Regulation	Accident						
Location	Coastal waters		English		5218.0 N	205.0 E	
	Southwold						
Natural Light	Light		Sea State		Moderate		
Visibility	Good (5 - 10)		Wind force Range		4-6		
Tanker/combination carrier				Dead	0 Injured	0	Material Damage
Oil tanker					Flag	Greece	
Crude/products						66919.00	gt
When: Mooring operations				0.01		Reg. L	249.90 LOA
Deck							
	Collision						
	Manoeuvrability						
Location:	Navigation/communication control space						
Ship							
	Manoeuvrability						
	Vessel does not respond to the helm						
	Interaction						
	Technical factor						
	External Causes						
	Other Vessel						
	Veers off course						
	Human factor						
	Working environment						
	Hazardous natural environment						
	Technical factor						
	External Causes						
	Other Vessel						
Tanker/combination carrier				Dead	0 Injured	0	Minor Damage
Oil/bulk/ore carrier					Flag	Bahamas	
Bulk/oil						45593.00	gt
When: Mooring operations				0.01		Reg. L	246.82 LOA
Deck							
	Bridge procedures						
	Communications/Orders						
	Communication failure, master/pilot						
	Poor Decision Making						
	Incorrect or insufficient action taken						
	Collision						
	Manoeuvrability						
Location:	Navigation/communication control space						
Ship							
	Manoeuvrability						
	Vessel does not respond to the helm						
	Interaction						
	Human factor						
	Working environment						
	Hazardous natural environment						
	Veers off course						
	Human factor						
	People						
	Situational awareness or communication inadequate						
	Working environment						
	Hazardous natural environment						

During mooring operations in a Ship to Ship transfer the manoeuvring vessel developed an un correctable swing towards the stand on vessel, resulting in contact and moderate damage to the stand on vessel.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

During the approach the stand on vessel was told to maintain course and speed, which she did so throughout the incident - until instructed by the mooring master to go full ahead and "get out of the way". The mooring master was stationed on the manoeuvring ship and the intention was to bring this vessel alongside the other and make fast. During the approach the vessel swung away to starboard - to 192. The mooring master requested hard a port. When the head was 173 he ordered steer 170. The helmsman may have confused by this order and kept the wheel on until 170 was reached, at this time the rate of turn was 15 deg / min to port. This was 3 min before contact. 1 min 40 sec before contact the mooring master realised there was still a considerable swing to port and head 165. He ordered hard to starboard but the helm was already on hard to starboard. Speed was increased in an attempt to avoid contact. This was insufficient and the vessels touched. There was little damage to the manoeuvring vessel but the stand on vessel suffered a penetration into a ballast tank and the operation was aborted.

The mooring master was unsupported by the bridge team on the vessel, there was a masters relief in progress and both masters were discussing hand over matters during the incident and seemed unaware of the deteriorating situation until just before the vessels touched. The helmsman and OOW should have provided more feedback to the mooring master and the mooring master was unaware of the helm and vessel swing until it was too late.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	1192/2009	27/08/2009	Collision	Status	Closed		
Regulation	Accident						
Location	Coastal waters		English			5220.0 N	148.0 E
Natural Light	Light		Sea State		Calm <2 ft		
Visibility	Good (5 - 10)		Wind force Range		4-6		
Tanker/combination carrier				Dead	0 Injured	0 Minor Damage	
Oil tanker				Flag		Singapore	
Crude oil						164251.00 gt	
When: Replenishment at sea operations				320.69		Reg. L	334.21 LOA
Deck							
Collision							
Manoeuvrability							
Tanker/combination carrier				Dead	0 Injured	0 Minor Damage	
Oil tanker				Flag		Greece	
Crude oil						61724.00 gt	
When: Replenishment at sea operations				0.01		Reg. L	244.60 LOA
Deck							
Bridge procedures							
Communications/Orders							
Location: Navigation/communication control space							
Communication failure, master/pilot							
Human factor							
People							
Inattention							
Collision							
Bridge procedures							
Location: Navigation/communication control space							

A 244m long tanker, with fenders made fast along the port side, was the manoeuvring ship and approaching a 334m long tanker, which was the constant heading ship, before making fast to one another and carrying out ship to ship transfer of cargo. The STS superintendent was on the port bridge wing of the manoeuvring ship with the master, who was relaying orders to the OOW and helmsman inside the bridge. When the two ships were parallel and 10m apart, the superintendent asked for stop engines. Shortly after the engine order, the master talked to the chief officer on the focsle by hand-held radio during which time the superintendent asked for dead slow ahead. However, the master misinterpreted the order and relayed dead slow astern. It was only when the ship's stern was moving towards the other ship that the superintendent realised that something was amiss and ordered hard to port and slow ahead, at which time he was told that the engine was dead slow astern. The superintendent ordered half ahead but before it could take effect, the corner of the boat deck made contact with the other ship's hull. The ships were then parted as it was agreed to abort the manoeuvre.

The manoeuvring ship's company was currently preparing its own STS procedures, which will contain requirements for bridge manning and communications as a result of this case.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	1433/2009	12/10/2009	Pollution	Status	Closed
Regulation	Accident				
Location	Coastal waters		Scottish		
	Cromarty				
Natural Light	Light		Sea State		Sheltered Waters
Visibility	Good (5 - 10)		Wind force Range	0-3	
Tanker/combination carrier			Dead	0 Injured	0
			Flag		Bahamas
					58911.00 gt
When: Loading/discharging cargo			0.01		Reg. L 246.86 LOA
Machinery					
Deck machinery					
Windlass					
Hydraulic failure					
Tanker/combination carrier			Dead	0 Injured	0
Oil tanker			Flag		Marshall Islands
Crude oil					62775.00 gt
When: Unknown			0.01		Reg. L 250.00 LOA

A ship to ship transfer operation was being carried out between two vessels while alongside an oil terminal. During the transfer the mooring ropes were being adjusted by the crew of the outbound vessel using a hydraulic windlass. During the operation a hydraulic pipe connection failed and hydraulic oil was sprayed over the deck. The scuppers were plugged and held the oil on the deck, but less than an estimated 1 litre went over the side and caused sheen on the surface. The Scottish Environmental Protection Agency also investigated.

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

Case Number	1659/2009	01/12/2009	Collision	Status	Closed		
Regulation	Outside MAIB Regulations						
Location	Coastal waters		Non UK		5216.0 N	157.0 E	
Natural Light	Semi-dark		Sea State		Unknown		
Visibility	Unknown		Wind force Range		4-6		
Tanker/combination carrier				Dead 0 Injured Flag	0	Material Damage	
						Hong Kong	
						60193.00 gt	
When: Other offshore operations				0.01		Reg. L	243.00 LOA
Deck							
Collision							
Manoeuvrability							
Tanker/combination carrier				Dead 0 Injured Flag	0	Minor Damage	
Oil tanker						Marshall Islands	
Products						26113.00 gt	
When: Other offshore operations				0.01		Reg. L	171.81 LOA
Deck							
Bridge procedures							
Communications/Orders							
Location: Navigation/communication control space							
Communications failure, master/watchkeeper/rating							
Verbal order or instruction not understood/misinterpreted							
Human factor							
People							
Diminished motivation							
Manning							
Lack of role monitoring							
Human factor							
People							
Vigilance							
Poor Decision Making							
Location: Navigation/communication control space							
Incorrect or insufficient action taken							
Human factor							
People							
Inattention							
Collision							
Bridge procedures							
Location: Navigation/communication control space							

Before cargo ship-to-ship transfer (STS) operations at sea could begin, two tankers had to make fast to one another while under way and making way.

The STS superintendent was on the manoeuvring ship and had the con, while standing at the outboard end of the port bridge wing. The master was close by him relaying orders by voice and by a hand-held radio to the third officer and helmsman inside the bridge. The third officer was relaying the ship's speed and acknowledging the helm orders by hand-held radio to and from the master and was also operating the telegraph as instructed. The helmsman had been at the wheel for an hour and a half and had been steering course orders rather than specific helm orders.

The exterior bridge wing helm indicator illumination was very poor and could not be seen from the superintendent's position.

When the manifolds of the two ships were in line, the superintendent began giving specific helm orders to bring the tankers closer to one another so that mooring lines could be passed between them. Initially, he gave a 'port 10' rudder order. As the bow began to swing to port and towards the other ship, the superintendent ordered 'midships' and then 'starboard 10' to counter the swing. However, the port swing did not stop. The superintendent then ordered the helm to 'starboard 20' and then to 'hard to starboard', and an increase in speed but the rate of turn to port increased. Realising that something was wrong, the master repeated the orders to the third officer and helmsman. The bridge wing indicator was checked at this time and found to be reading 'port 20'. The helmsman

Collisions contacts between ships or ships and platforms etc identified as occurring during loading/unloading 1991 to 2010

then applied starboard helm and the rate of turn to port decreased, stopped and then the ship began to swing to starboard.

However, after having made an alteration of course of nearly 30 degrees to port, the port side of the focsle inevitably made contact with the other ship, causing structural damage.