







65. Mounting the X-carriage-back



-  Push the cables from the Extruder **THROUGH** the X-carriage-back. Start with IR-sensor cable, then the extruder motor and hotend fan.
-  **There are two variants of the hotend fan cable**, see the detail. The connectors are the same.
-  Next, add the print fan and SuperPINDA sensor cables.
-  Cables from hotend are **NOT GOING** through the X-carriage-back!
-  Carefully insert the nylon filament and then slide the X-carriage-back towards the X-axis.



Next →

