







## 9. Placing the Z-axis-top parts (part 2)



-  Place the Z-axis-top-left part on the rods and align it with the frame.
-  Ensure the holes in the printed part are fully aligned with the holes on the frame.
-  Use two M3x10 screws to tighten the Z-axis-top-left part.
-  **Don't use excessive strength during tightening.** In case of increased resistance, try to place the screws from the other side to "clean up" the hole. Then return to the front side.
-  Repeat this step on the other side of the frame with Z-axis-top-right printed part.



Next →

