









Start > Knowledge > Milling > Troubleshooting

Milling troubleshooting


Milling troubleshooting tips about vibration issues, chip jamming, re-cutting of chips, un-satisfactory surface finish, burr formation, machine power and tool wear are presented in the following table.

	Cause	Solution
Vibration	<ul style="list-style-type: none">Weak fixture	<ul style="list-style-type: none">Assess the direction of the cutting forces and provide adequate support or improve the fixtureReduce the cutting forces by decreasing the cutting depth, a_pSelect a coarse and differentially pitched cutter with a more positive cutting actionSelect a geometry with a small corner radius and small parallel landSelect a fine-grain, uncoated insert, or a thinner coatingAvoid machining where the workpiece has poor support against the cutting forces
	<ul style="list-style-type: none">Axially weak workpiece	<ul style="list-style-type: none">Consider a square shoulder cutter (90-degree entering angle) with positive geometrySelect an insert with L-geometryDecrease axial cutting force – lower depth of cut, smaller corner radius and parallel landSelect a coarse-pitch cutter with differential pitchCheck tool wearCheck tool holder run-outImprove clamping of tool
	<ul style="list-style-type: none">Too long tool overhang	<ul style="list-style-type: none">Minimize overhangUse coarse-pitch cutters with differential pitchBalance radial and axial cutting forces – 45 degree entering angle, large corner radius or round insert cutterIncrease feed per toothUse a light-cutting insert geometryReduce axial depth of cut, a_xUse up milling in finishingUse oversized cutters and Coromant Capto® coupling adaptorsFor solid carbide end mills and exchangeable-head mills, try a tool with fewer teeth and/or a higher helix angle
	<ul style="list-style-type: none">Milling square shoulder with weak spindle	<ul style="list-style-type: none">Select smallest possible cutter diameterSelect a positive and light-cutting cutter and insertTry up millingCheck spindle deflection to see if acceptable for machine
	<ul style="list-style-type: none">Irregular table feed	<ul style="list-style-type: none">Try up millingTighten machine feed mechanism; adjust the feed screw on CNC machineAdjust the locking screw or replace the ball screw on conventional machines
	<ul style="list-style-type: none">Cutting data	<ul style="list-style-type: none">Reduce cutting speed, v_cIncrease feed, f_zChange cutting depth, a_p
	<ul style="list-style-type: none">Bad stability	<ul style="list-style-type: none">Reduce overhangImprove stability
	<ul style="list-style-type: none">Vibration in corners	<ul style="list-style-type: none">Program large corner radii with reduced feed rate
Chip jamming	<ul style="list-style-type: none">Insert corner damageEdge chipping and breakageRe-cutting of chips	<ul style="list-style-type: none">Improve chip evacuation by using rich and well directed cutting fluid or compressed airReduce feed, f_zSplit deep cuts into several passesTry up milling in deep slottingUse coarse pitch cuttersUse solid carbide end mills or exchangeable-head mills with two or maximum three cutting edges and/or a higher helix angle
Re-cutting of chips	<ul style="list-style-type: none">Cutting edge fracturesHarmful for tool life and securityChip jamming	<ul style="list-style-type: none">Evacuate chips effectively by compressed air or copious cutting fluid flow – preferably internal coolantChange cutter position and tool path strategyReduce feed, f_zSplit deep cuts into several passes
Un satisfactory surface finish	<ul style="list-style-type: none">Excessive feed per revolution	<ul style="list-style-type: none">Set cutter axially or classify inserts. Check height with indicatorCheck spindle run-out and cutter mounting surfacesDecrease feed per rev to max. 70% of the width of the parallel landUse wiper inserts if possible (for finishing operations)
  	<ul style="list-style-type: none">Vibration	<p>See section "Vibration" above</p>
	<ul style="list-style-type: none">Built-up edge formation	<ul style="list-style-type: none">Increase cutting speed, v_c, to elevate machining temperatureTurn off cutting fluidUse sharp cutting edge inserts, with smooth rake sideUse positive insert geometryTry a cermet grade with higher cutting data
	<ul style="list-style-type: none">Back-cutting	<ul style="list-style-type: none">Check spindle tilt (approx. 0.10 mm/1000 mm (0.004 inch/39.370 inch))Axial run-out, TIR, of spindle should not exceed 7 microns during finishingReduce the radial cutting forces (decrease the depth of cut, a_p)Select a smaller cutter diameterCheck the parallelism on the parallel lands and on wiper insert used (should not be standing on "heel or toe")Make sure the cutter is not wobbling – adjust the mounting surfaces
	<ul style="list-style-type: none">Workpiece fittering	<ul style="list-style-type: none">Decrease feed, f_zSelect a close or extra-close pitch cutterRe-position the cutter to give a thinner chip at exitSelect a more suitable entering angle (45-degrees) and lighter cutting geometryChoose a sharp insertMonitor flank wear to avoid excessive wear
	<ul style="list-style-type: none">Burr formation	<ul style="list-style-type: none">Material specific – HRSA/stainless steelNotch main wear mechanism
	<ul style="list-style-type: none">Material specific – HRSA/stainless steelNotch main wear mechanism	<ul style="list-style-type: none">Use large radius giving low insert entry angleKeep depth of cut below radius$a_p = 0.5 \times \text{radius}$



Machine power

Be aware of the power curve as the machine may lose efficiency if the rpm is too low.




The power requirements in milling vary with the:

- Amount of metal to be removed
- Average chip thickness
- Cutter geometry
- Cutter speed
- Go from close to coarse pitch, i.e. fewer teeth
- A positive cutter is more power efficient than a negative cutter
- Reduce cutting speed before table feed
- Use a smaller cutter and make several passes
- Reduce depth of cut, a_p


Insert wear

To achieve optimized cutting data, best possible component quality and tool life, always remember to check the insert/cutting edge after machining. Use this list of causes and solutions to different forms of insert wear as a reference for successful milling.

Cause	Solution
<p>Flank wear Rapid wear causing poor surface finish or out of tolerance.</p> 	<ul style="list-style-type: none"> • Cutting speed too high • Insufficient wear resistance • Feed, f_z, too low • Reduce cutting speed, v_c • Select a more wear-resistant grade • Increase feed, f_z
<p>Flank wear Excessive wear causing short tool life.</p> 	<ul style="list-style-type: none"> • Vibration • Re-cutting of chips • Burr formation on component • Poor surface finish • Heat generation • Excessive noise • Increase feed, f_z • Use down milling • Evacuate chips effectively using compressed air • Check recommended cutting data
<p>Flank wear Uneven wear causing corner damage.</p> 	<ul style="list-style-type: none"> • Tool run-out • Vibration • Short tool life • Bad surface finish • High noise level • Radial forces too high • Reduce run-out below 0.02 mm (0.0008 inch) • Check chuck and collet • Minimize tool protrusion • Use fewer teeth in cut • Choose a larger tool diameter • For solid carbide end mills and exchangeable-head mills, select a higher helix geometry ($g_2 \geq 45^\circ$) • Split axial cutting depth, a_{px}, into more than one pass • Reduce feed, f_z • Reduce cutting speed, v_c • HSM requires shallow passes • Improve clamping of tool and workpiece
<p>Crater wear Excessive wear causing a weakened edge. Cutting edge breakthrough on the trailing edge causes poor surface finish.</p> 	<ul style="list-style-type: none"> • Diffusion wear due to cutting temperatures that are too high on the rake face • Select an Al203 coated grade • Select a positive insert geometry • Reduce the speed to obtain a lower temperature, and then reduce the feed
<p>Plastic deformation Plastic deformation of edge, depression or flank impression, leading to poor chip control, poor surface finish and insert breakage.</p> 	<ul style="list-style-type: none"> • Cutting temperature and pressure too high • Select a more wear resistant (harder) grade • Reduce cutting speed, v_c • Reduce feed, f_z
<p>Chipping The part of the cutting edge not in cut is damaged by chip hammering. Both the top side and the support for the insert can be damaged, leading to poor surface texture and excessive flank wear.</p> 	<ul style="list-style-type: none"> • The chips are deflected against the cutting edge • Select a tougher grade • Select an insert with a stronger cutting edge • Increase cutting speed, v_c • Select a positive geometry • Reduce feed at the beginning of cut • Improve stability
<p>Chipping Small cutting edge fractures (frittering) causing poor surface finish and excessive flank wear.</p> 	<ul style="list-style-type: none"> • Grade too brittle • Insert geometry too weak • Built-up edge • Select a tougher grade • Select an insert with a stronger geometry • Increase cutting speed, v_c, or select a positive geometry • Reduce feed at the beginning of cut
<p>Notch wear Notch wear causing poor surface finish and risk of edge breakage.</p> 	<ul style="list-style-type: none"> • Work hardening materials • Skin and scale • Reduce cutting speed, v_c • Select a tougher grade • Use a stronger geometry • Use a cutting angle closer to 45 degrees • Use round inserts for best result • Use variable a_p technique to prolong the wear
<p>Thermal cracks Small cracks perpendicular to the cutting edge causing frittering and poor surface finish due to temperature variations.</p> 	<ul style="list-style-type: none"> • Intermittent machining • Varying cutting fluid supply • Select a tougher grade with better resistance to thermal shocks • Cutting fluid should be applied copiously or not at all
<p>Built-up edge (BUE) Built-up edge causing poor surface finish and cutting edge frittering when the BUE is torn away.</p> 	<ul style="list-style-type: none"> • Cutting zone temperature is too low • Very sticky material, such as low-carbon steel, stainless steels, and aluminium • Increase cutting speed, v_c • Change to a more suitable insert geometry



Built-up edge (BUE)
Workpiece material is welded to the cutting edge.



- Low cutting speed, v_c
- Low feed, f_z
- Negative cutting geometry
- Poor surface finish

- Increase cutting speed, v_c
- Increase feed, f_z
- Select a positive geometry
- Use oil mist or cutting fluid

Related information

- [Troubleshooting](#)
(Knowledge)
- [Troubleshooting](#)
(Knowledge)
- [Tool up for faster payback](#)
(Campaigns)
- [Drilling wear and troubleshooting](#)
(Knowledge)
- [Threading Application guide](#)
(Publications)