



Start > Knowledge > Threading > Thread milling > Troubleshooting

Troubleshooting for thread milling



Careful observation of the insert/cutting edge after machining can help to optimize results regarding tool life and thread quality. Use this list of causes and solutions for different types of insert wear as a reference for successful thread milling.

Chipping



Built-up edge (BUE)

Poor surface finish and cutting edge frttering when the built-up edge is torn away.



Crater wear



Thermal cracks



Plastic deformation

Plastic deformation of edge, depression or flank impression leading to poor chip control, poor surface finish and insert breakage.



Flank wear

Rapid wear causing poor surface finish or out of tolerance.



Excessive wear resulting in short tool life, burr formation on component, poor surface finish, heat generation and excessive noise.



Uneven wear resulting in corner damage, short tool life, bad surface finish and high noise



Vibration

Re-cutting of chips

Notch wear

Cause

- The part of the cutting edge which is not in cut is damaged by chip hammering, leading to poor surface and excessive flank wear

Cause

- Cutting zone temperature is too low
- Very sticky material, such as low-carbon steel, stainless steels and aluminium

Cause

- Excessive wear causing a weakened edge
- Cutting edge breakthrough on the trailing edge leading to poor surface finish

Cause

- Temperature variations from varying cutting fluid supply or intermittent machining leading to small cracks perpendicular to the cutting edge, insert frttering and poor surface finish

Cause

- Cutting temperature and pressure too high

Cause

- The part of the cutting edge which is not in cut is damaged by chip hammering, leading to poor surface and excessive flank wear

- Vibration
- Re-cutting of chips
- Burr formation on component
- Poor surface finish
- Heat generation
- Excessive noise

- Tool run-out
- Vibration
- Short tool life
- Bad surface finish
- High noise level
- Radial forces too high

Cause

- Weak fixturing
- Tool overhang too long

Cause

- Insufficient chip evacuation

Cause

Solution

- Increase cutting speed
- Reduce feed at the beginning of the cut
- Improve stability
- Increase number of passes
- Use a full-profile insert

Solution

- Increase cutting speed or feed
- Use oil mist or cutting fluid

Solution

- Reduce speed to reduce temperature
- Reduce feed

Solution

- Apply cutting fluid in large amounts, or not at all
- Reduce cutting speed

Solution

- Reduce cutting speed
- Reduce feed

Solution

- Increase cutting speed
- Reduce feed at the beginning of the cut
- Improve stability
- Increase number of passes
- Use a full-profile insert

- Increase feed, f_z
- Reduce speed
- Use down-milling
- Evacuate chips effectively using compressed air
- Check recommended cutting data

- Check chuck and collet
- Minimize tool overhang
- Fewer teeth in cut
- Split axial cutting depth, a_{ps} , into more than one pass
- Reduce feed, f_z
- Reduce cutting speed, v_c
- High speed machining requires shallow passes
- Improve clamping of tool and workpiece

Solution

- Check clamping of workpiece and tool
- Minimize overhang
- Check tool holder run out
- Choose a tool with fewer teeth
- Increase number of passes
- Increase feed per tooth
- Reduce cutting speed
- Use up-milling in finishing

Solution

- Use compressed air or large amounts of cutting fluid, preferably through the tool
- Reduce feed per tooth
- Increase number of passes

Solution



Machine inefficiency

Conical threads

Broken cutter/cutting edge

- Machining work-hardening materials
- Components with skin and scale

Cause

- Machine RPM is too low

Cause

- Cutting forces too high

Cause

- Bad chip evacuation
- Load too big
- Instability

- Reduce cutting speed
- Select a tougher grade
- Increase cutting speed

Solution

- Reduce cutting speed before table speed
- Use a smaller cutter and increase number of passes

Solution

- Reduce tool length
- Use up milling
- Reduce feed
- Increase number of passes
- Use single row insert

Solution

- Use compressed air, emulsion or internal coolant
- Divide cut into 2 or 3 passes
- Reduce feed
- Check/change tool holder

Related information

- [Troubleshooting](#)
(Knowledge)
- [Thread whirling application tips](#)
(Knowledge)
- [Threading Application guide](#)
(Publications)
- [Threading Application guide](#)
(Publications)
- [Knowledge](#)
(Knowledge)