




Start > Knowledge > Threading > Thread turning > Troubleshooting


## Troubleshooting for thread turning

Careful observation of the insert/cutting edge after machining can help to optimize results regarding tool life, thread quality and cutting speed. Use this list of causes and solutions to different forms of insert wear as a reference for successful threading.

### Plastic deformation



Starts as plastic deformation (A), which leads to edge chipping (B). Built-up edge (BUE)



BUE (A) and edge chipping (B) often occur in combination. Accumulate BUE is then ripped away together with small amounts of insert material, which leads to chipping.


### Insert breakage



### Rapid flank wear



### Abnormal flank wear



### Poor surface on one thread flank



#### Cause

1. Excessive temperature in cutting zone
2. Inadequate supply of coolant
3. Wrong grade

1. Often occurs in stainless steel and low-carbon steel
2. Unsuitable grade or cutting edge temperature too low

1. Wrong turned diameter prior to threading
2. Infeed series too tough
3. Wrong grade
4. Poor chip control
5. Incorrect centre height

1. Highly abrasive material
2. Cutting speed too high
3. Infeed depths too shallow
4. Insert is above centre line

1. Incorrect method for flank infeed
2. Insert inclination angle does not agree with the thread lead angle

1. Incorrect workpiece clamping
2. Incorrect tool set-up
3. Incorrect cutting data
4. Incorrect centre height

#### Solution

1. a) Reduce the cutting speed, increase the number of infeeds  
b) Reduce the largest infeed depth, check the diameter before threading
2. Improve coolant supply
3. Choose a grade with better resistance to plastic deformation

1. Increase cutting speed
2. Choose an insert with good toughness, preferably PVD coated

1. Turn to correct diameter before threading, 0.03–0.07 mm (0.001–0.003 inch) radially larger than max. diameter for thread
2. Increase number of infeeds. Reduce size of the largest infeed
3. Choose a tougher grade
4. Change to C-geometry and use modified flank infeed
5. Correct centre height

1. Wrong grade. Choose a more wear resistant grade
2. Reduce cutting speed
3. Reduce number of infeeds
4. Correct centre height

1. Change method of flank infeed for F- and A-geometry: 3–5° from flank, for C-geometry: 1° from flank
2. Change shim to obtain correct angle of inclination

1. a) Use soft jaws  
b) When using tail stock optimize component centering hole and check pressure of tail stock/face driver
2. a) Minimize tool overhang  
b) Make sure the clamping sleeve for bars is not worn  
c) Use anti-vibration bars dedicated for thread turning
3. Increase cutting speed; if this does not help, lower the speed dramatically and try F-geometry
4. Correct centre height

### Related information

- [Threading Application guide](#) (Publications)
- [Threading Application guide](#) (Publications)
- [Knowledge](#) (Knowledge)
- [Hard part turning with CBN](#) (Publications)