


Chapter 13

DESIGNING FEEDBACK CONTROLLERS FOR MOTOR DRIVES

- 13-1 Introduction
- 13-2 Control Objectives
- 13-3 Cascade Control Structure
- 13-4 Steps in Designing the Feedback Controller
- 13-5 System Representation for Small-Signal Analysis
- 13-6 Controller Design
- 13-7 Example of a Controller Design
- References
- Problems

Feedback Control Objectives




□ Feedback control

- ◆ makes system insensitive to disturbances and parameter variation

○ Control Objectives

- _ Zero steady-state error
- _ Good dynamic response
 - fast
 - small overshoot



Definitions

- Open loop

$$G_{OL}(s) = G_c(s)G_p(s)$$

- Closed loop

$$G_{CL}(s) = G_{OL}(s) / (1 + G_{OL}(s))$$

- Crossover frequency

$$f_c, \omega_c$$

- Gain Margin



- Phase Margin

$> 45^\circ$ for no oscillations

60° preferable



- Closed loop bandwidth $\square f_c$

desired high for fast response




Example

$$G_{OL}(s) = K_{OL} / s \quad ; \quad K_{OL} = 2 \times 10^3$$



closed loop step response

Cascaded Control



- ❑ Torque loop : fastest
- ❑ Speed loop : slower
- ❑ Position loop : slowest


Steps in Designing the Controller

- ❑ Assume system is linear about the steady state operating point → design controller using Linear Control Theory
- ❑ Simulate design under large signal conditions and “tweak” controller as necessary

System representation for small signal analysis


- Assume
 - _ Steady state system operating point = 0
 - _ Highest bandwidth at least an order of magnitude lower than switching frequency neglect switching frequency components

Averaged Representation of the PPU



$$\bar{v}_a(t) = k_{PWM} v_c(t)$$

$$V_a(s) = k_{PWM} V_c(s)$$



Modeling of DC Machines and Mechanical Load Combinations

$$\bar{v}_a(t) = e_a(t) + R_a \bar{i}_a(t) + L_a \frac{d\bar{i}_a(t)}{dt}$$



$$e_a(t) = k_E \omega_m(t)$$

$$V_a(s) = E_a(s) + (R_a + sL_a)I_a(s)$$


$$\Rightarrow I_a(s) = \frac{V_a(s) - E_a(s)}{(R_a + sL_a)} \quad ; \quad E_a(s) = k_E \omega_m(s)$$

$$T_{em}(s) = k_T I_a(s)$$

$$\omega_m(s) = \frac{T_{em}(s)}{sJ_{eq}}$$



PI Controller



$$\frac{v_c(s)}{E(s)} = k_p + \frac{k_i}{s} = \frac{k_i}{s} \left(1 + \frac{s}{k_i / k_p} \right)$$



- Proportional-Integral (PI) Controller
 - _ In the torque and speed loops, proportional control without integral control input leads to steady-state error

Controller Design


- Procedure
 - Design torque loop (fastest) first
 - Design speed loop assuming torque loop to be ideal
 - Design position loop (slowest) assuming speed loop to be ideal

Design of the Torque (Current) Loop

Simplifying assumptions




- Assuming J high enough, inner loop can be ignored



$$G_{I,OL}(s) = \underbrace{\frac{k_{iI}}{s} \left(1 + \frac{s}{k_{iI} / k_p} \right)}_{PI \text{ controller}} \underbrace{k_{PWM}}_{PPU} \underbrace{\frac{1/R_a}{1 + s\tau_e}}_{\text{motor}}$$

Design of the Torque (Current) Loop


Selecting Parameters




- Select zero of PI to cancel motor pole ; $\frac{k_{pI}}{k_{iI}} = \tau_e$

$$\Rightarrow G_{I,OL} = \frac{k_{I,OL}}{s}; \quad k_{i,OL} = \frac{k_{iI} k_{PWM}}{R_a}$$

- Choose k_{iI} to achieve desired cross-over frequency $k_{I,OL} = \omega_{CI}$




open loop




closed loop

Design of the Speed Loop




- Assume current loop to be ideal represent by unity
- Choose crossover frequency $\omega_{C\omega}$ an order of magnitude lower than ω_{CI}
- Choose a reasonable phase margin $\phi_{PM,\omega}$


open loop




closed loop




Design of the Position Loop



- Assume speed loop to be ideal
 - Proportional gain ($k_{p\theta}$) alone is adequate due to presence of pure integrator
- $$G_{\theta,OL} = \frac{k_{p\theta}}{s} \Rightarrow k_{p\theta} = \omega_{CP}$$



open loop



closed loop