

ME5005/ME4002 DESIGN FOR MANUFACTURE PRODUCTION ENGINEERING

Dr. Bill Wright
bill.wright@ucc.ie
Room 2.14 Tel: 490 2213

Lecture 15: Sheet Metal Working

Design for Manufacture: Lecture 15

1


Sheet metal working

- Sheet metal working applies to thin sheets of material typically between about 0.4 mm and 6 mm thick
 - Sheets more than 6mm thick are referred to as plate
- Usually carried out as cold working
 - Increases strength of thin components
 - A warm process may be used if the material is brittle
- Sheet metal working may be subdivided into three different processes:
 - Cutting:
 - Part of the sheet is separated or removed
 - Bending:
 - Part of the sheet is plastically deformed
 - Drawing:
 - Most of the material is plastically deformed
- Most sheet metal working is in steel, aluminium or brass

Design for Manufacture: Lecture 15

2

The shearing process

- 
- Cutting occurs using a shearing action between two sharp edges
 - The upper cutting edge (punch) sweeps down past a stationary cutting edge (die)
 - Plastic deformation occurs as the punch pushes into the workpiece
 - Penetration occurs as the punch compresses the workpiece and cuts into the metal producing a smooth surface
 - Fracture occurs at the two cutting edges, the two fracture lines meet and the material separates
 - Clearance between the die and punch is critical for a clean cut

Design for Manufacture: Lecture 15

3

Cut edges




- The sheared edges of the sheet and component have four very distinctive surfaces:
 - Rollover
 - Surface depression made by punch before cutting occurs
 - Burnish
 - Smooth surface from penetration of the punch into the workpiece before fracture begins
 - Fracture Zone
 - Surface along the fracture lines through the material
 - Burr
 - A sharp corner on the edge caused by stretching and elongation of the metal during final separation
- Sequence of surfaces is reversed on the other side of the cut

Design for Manufacture: Lecture 15

4

Effects of clearance




Metal Group	Allowance <i>a</i>
Soft Al alloys	0.045
Hard Al alloys; Brass; Soft steels	0.060
Hard steels	0.075

- Typical values of clearance c are between 4% and 8%
- If the sheet thickness t
 - If the clearance is too small, the fracture lines pass each other
 - Double burnishing
 - Higher cutting force
 - If the clearance is too large, material becomes pinched between the die and punch
 - Side wall fails by tearing
 - Excessive burring
- The clearance may be found using:


$$c = at$$

Open cutting operations




- Shearing
 - Metal is cut along a straight line, basic cut
- Cutoff
 - Shapes are fully nested (no waste)
 - Open cut (crosses the full width of the strip)
- Parting
 - Partially nested shapes (some waste)
 - Open cut still used
- Shaving
 - Precision post-cutting with small clearance (0.01t)

Closed cutting operations



- Blanking :
 - Cutting occurs on a closed contour
 - Removed shape is the required component
- Punching :
 - Identical to blanking but the remaining strip is the required component
- Notching :
 - Removed section is on the edge of the strip
- Semi-Notching :
 - Identical to punching but contour will be on the edge of the finished component


Other operations



- Fine blanking:
 - Used to produce close-tolerance blanks in a single cutting operation
 - A pressure pad with V-shaped projections holds the sheet in place with a holding force F_h
 - Sheet is compressed, prevents crushing at edges
 - Blanking punch velocity v is slower than for normal blanking
- Piercing:
 - Produces holes, but unlike punching a blank or slug is not produced
 - Sharp pointed punch used

Die size and clearance


- The die opening must always be larger than the punch size
- Location of clearances determined by whether the piece removed is the desired part (blank) or scrap (slug)
- To produce a round blank of diameter D_b :
 - Punch size = $D_b - 2c$
 - Die size = D_b
- To produce a round hole of diameter D_h :
 - Punch size = D_h
 - Die size = $D_h + 2c$



Design for Manufacture: Lecture 15

9

Die relief



- After plastic deformation and fracture, the material will elastically recover
- The hole in the strip will grip the punch
 - Stripper plate holds the sheet in place while punch is withdrawn
- The blank will expand in the die
- The die must be tapered to allow the blank or slug to drop out
- This angular clearance is known as die relief
 - Typically 0.25° to 1.5° all the way round

Design for Manufacture: Lecture 15

10

Calculating cutting force




- Maximum cutting force F_{max} can be estimated using either:
 - $F_{max} = GtL$
 - Or if shear strength G is not known:
 - $F_{max} = 0.7\sigma_{UTS}tL$
- Clearance may be neglected when calculating length of cut, L
- Cutting force will be reduced if either of the blades are inclined
 - typically 4°-10°
- An inclined punch results in perfect holes and distorted blanks
- An inclined die results in distorted holes and perfect blanks

Design for Manufacture: Lecture 15

11

Cutting dies




- Drop-through die is most common
 - Blanks simply fall through the die into a collector
- With large area blanks, a dishing defect often results where the blank is warped
 - blank is unsupported during cutting
 - remedied using a return-type die in which a sprung-loaded block supports the blank from underneath
- Compound dies can perform several operations simultaneously
 - e.g.: washers

Design for Manufacture: Lecture 15

12

Bending

- Requires a significant distance between the shearing forces to produce a bending moment about a linear bend axis.
- A neutral plane exists in the sheet where the tensile stresses on the top surface change to compressive stresses on the bottom
 - bending produces little or no change in the sheet thickness t
- Bend radius R is normally specified on the inside of the corner, rather than at the neutral plane
- The sheet is bent through the bend angle, A' resulting in a part with an included angle, $A' = A + 180^\circ$




13

Design for Manufacture: Lecture 15

Bending operations

- Most common types are V-bending and wiping
- V-bending requires the lowest loads as the distance between the shearing forces is largest
 - Used for low volume production
- Wiping or edge bending is more expensive due to the additional complexity
 - More precise
 - Used for high volume production
- Both methods can produce a range of included angles A' from very obtuse to very acute



Design for Manufacture: Lecture 15

14

Bend allowance


- If R is small compared to t , the metal will stretch during bending
- This stretch must be estimated for each bend to predict the final component geometry
- The bend allowance BA may be found using:

$$BA = 2\pi \frac{A}{360} (R + K_{ba} t)$$

where K_{ba} is a stretching factor:

If $R < 2t$, $K_{ba} = 0.33$

If $R \geq 2t$, $K_{ba} = 0.50$



- To estimate the starting blank length for the above component (all in mm):
 $R/t = 1.87/1.25 = 1.5 < 2$
- so $K_{ba} = 0.33$:
 $A = 180^\circ - A' = 60^\circ$
 $BA = 2\pi(60/360)(1.87 + 0.33 \times 1.25)$
 $BA = 2.39 \text{ mm}$
- $L_0 = 15.00 + 10.00 + 2.39 = 27.39 \text{ mm}$


15

Design for Manufacture: Lecture 15

Springback

- The stresses in the sheet during bending vary from tensile on the top surface to compressive on the bottom surface
 - Plastic deformation
- Either side of the neutral axis, the stress will be below the elastic limit
- This region will elastically recover when the bending force is removed, resulting in springback
- Defined as the increase in the included angle of the bent part relative to the included angle of the forming tool:

$$SB = \frac{A' - A'_b}{A'_b}$$



Design for Manufacture: Lecture 15

16


Compensating for springback

- Three common methods of springback compensation
 - Overbending
 - Springback in the final component is estimated
 - The punch angle is made smaller than the specified angle so that the part elastically recovers into the desired shape
 - Empirical, inaccurate
 - Bottoming
 - Sheet is squeezed locally at the bend
 - More of the material deforms plastically
 - Less material to elastically recover
 - Usually achieved with a small protuberance on the bend radius
 - Stretch forming
 - A tensile force is applied to the sheet to increase stresses near the neutral plane and reduce the size of the elastically recoverable region

Design for Manufacture Lecture 15

17

Bending force



- The force required for bending depends on material properties and die dimensions:

$$F = \frac{K_{bf} \sigma_T w t^2}{D}$$


- The bending force constant K_{bf} is determined by the type of bending:

- V-bending: $K_{bf} = 1.33$
- Wiping: $K_{bf} = 0.33$

Design for Manufacture Lecture 15

18

Edge bending operations




- Flanging is when the edge of a part is bent by 90° to form a rim
 - Strengthens or stiffens the part
- Flange may be (a) straight, (b) stretched or (c) shrunk
- Hemming is where the sheet edge is folded over itself in more than one bending operation
 - Eliminates sharp edges, increases strength, improves appearance
- Seaming is where two leaves are assembled together
- Curling or beading is where the edge is rolled rather than folded
 - Similar benefits as hemming
- Also forms other components, e.g. hinges

Design for Manufacture Lecture 15

19

Other bending operations



- A range of different shapes may also be formed by bending in dies similar to V-bending

- Channel bending
- U-bending
- Air bending
- Offset bending
- Corrugating
- Tube forming

Design for Manufacture Lecture 15

20

Drawing

- Drawing is used to form cup-shaped or other hollow parts
 - blank is held in place by a blankholder with holding force F_h
 - corners of punch and die must be radiused otherwise blanking occurs

- Clearance: $c = 1.1t$

- For drawing in a single operation :


- Drawing ratio DR should be ≤ 2 :

$$DR = \frac{D_b}{D_p}$$

- Reduction r should be ≤ 0.5 :

$$r = \frac{D_b - D_p}{D_b}$$


- Thickness to diameter ratio t/D_b should be $> 1\%$



21

Design for Manufacture: Lecture 15

Drawing sequence



Design for Manufacture: Lecture 15

22

Forces in drawing

- The force F required to perform a drawing operation may be estimated using:

$$F = \pi D_p t \sigma_T \left(\frac{D_b}{D_p} - 0.7 \right)$$

- The 0.7 is a friction correction factor
- The holding pressure should be set at 1.5 % of σ_y of the metal
- The holding force F_h is then found from the holding pressure and the area of the starting blank held by the blankholder:

$$F_h = 0.015 \sigma_y \pi [D_b^2 - (D_p + 2.2t + R_d)^2]$$

- To estimate the blank diameter (for cups and other axisymmetric shapes):


- Assume initial blank and final component volumes are equal
- Assume negligible wall thinning occurs
- Solve for D_b

Design for Manufacture: Lecture 15

23

Defects in drawing

- Wrinkles in the flange caused by compressive buckling
 - Blankholder force F_h insufficient
- Wrinkling in the wall occurs if the flange is drawn into the die
 - Tearing in the wall usually occurs near sharp corners
- Excessive blankholder force F_h
 - Earings produced by anisotropy in the sheet metal
- Surface scratches produced by insufficient lubrication, contaminants or rough dies



Design for Manufacture: Lecture 15

24

Other drawing processes

- Redrawing is essentially a two-stage drawing process used where the deformation required is too great for a single operation
 - amount of deformation should be about half the previous drawing ratio
- Drawing without using a bleedholder may also be achieved if:

$$\frac{D_b - D_p}{t} < 5$$

- The draw die must have a lead-in funnel or cone
 - reduced cost as tooling simpler

