

Common to EEE, ECE, Mechanical, Mechatronics and CSE

SRM Nagar, Kattankulathur – 603203, Chengalpattu District, Tamilnadu

Academic Year: 2021-22 (EVEN)

SET-C
Test: CLAT-2
Date: 03/06/2022
Course Code & Title: 18EES101J – Basic Electrical and Electronics Engineering

Duration: 100 Mins

Year & Sem: I & II

Max. Marks: 50




Course Articulation Matrix:

Course Outcomes	PO1	PO2	PO3	PO4	PO5	PO6	PO7	PO8	PO9	PO10	PO11	PO12	PSO1	PSO2	PSO3
CO1	H	M	L	L	M	-	M	M	M	M	-	M	-	-	-
CO2	H	M	L	L	M	-	M	M	M	M	-	M	-	-	-
CO3	H	-	L	L	M	-	M	M	M	M	-	M	-	-	-
CO4	H	-	L	M	M	-	M	M	M	M	-	M	-	-	-
CO5	H	M	M	M	M	-	M	M	M	M	-	M	-	-	-
CO6	-	-	L	2	M	-	M	M	M	M	-	M	-	-	-

Part - A
(10 x 1 Marks = 10 Marks)



Q. No	Answer all the questions	Marks	BL	CO	PO	PI Code
1	Emf is induced in a conductor when it cuts the magnetic flux	1	1	2	1,2	
2	Transformer is used to step down or up the AC voltages and currents	1	1	2	1,2	
3	Not self-starting	1	1	2	1,2	
4	It restricts the armature current as there is no back emf at starting	1	1	2	1,2	
5	$\frac{\phi_{PNZ}}{60 \times A}$	1	1	2	1,2	
6	Rectifier	1	1	3	1,2	
7	81.2%	1	1	3	1,2	
8	coal-salt mixture	1	1	3	1,2	
9	High voltage and current gain	1	1	3	1,2	
10	Base	1	1	3	1,2	

Part - B
(4 x 4 Marks = 16 Marks)

11	 <p style="text-align: right;">- 2marks</p> $P = (V_m \sin \omega t)(I_m \sin (\omega t + \pi/2))$ <p style="text-align: right;">- 1 mark</p> $i = \frac{d}{dt} C V_m \sin \omega t = C V_m \frac{d}{dt} \sin \omega t \quad \text{or}$ $i = \omega C V_m \cos \omega t = \frac{V_m}{1/\omega C} \sin(\omega t + \pi/2) \quad \text{or}$ $i = \frac{V_m}{X_C} \sin(\omega t + \pi/2) \dots \dots \dots (4)$ <p style="text-align: right;">-1 mark</p>	4	1	2	1,2	
12	 <p>(a) Positive Clipper (b) Output Waveform</p> <p>diagram -3M, explanation – 1M</p>	4	2	2	1,2	
13	<ol style="list-style-type: none"> The transformer works on the principle of Faraday's law of electromagnetic induction and mutual induction. There are usually two coils primary coil and secondary coil on the transformer core. The core laminations are joined in the form of strips. (2 marks) Used in high-voltage level applications such as distribution transformers, auto, and power transformers. (2 marks) 	4	1	3	1,2	
14	 <p>diagram -2 marks, explanation -2 marks</p>	4	2	3	1,2	
Part – B (2 x 12 Marks = 24 Marks)						
15(a)	The working of the three-phase induction motor is based on the principle of electromagnetic induction . When three-phase stator winding of an	12	2	2	1,2	

induction motor is energized from a 3 phase supply, a rotating magnetic field is set up which rotates around the stator at synchronous speed (N_s)- 4 M.

Rotor types- 1. Squirrel cage 2. Slip ring – 8M



(or)

15(b)
)

$$I_{rms} = \sqrt{\frac{1}{\pi} \int_0^\pi i^2 d\theta}$$

$$I_{rms}^2 = \frac{1}{\pi} \int_0^\pi i_m^2 \sin^2 \theta d\theta = \frac{I_m^2}{\pi} \int_0^\pi \sin^2 \theta d\theta$$

$$= \frac{I_m^2}{\pi} \int_0^\pi \left(\frac{1 - \cos 2\theta}{2} \right) d\theta = \frac{I_m^2}{2\pi} \int_0^\pi (1 - \cos 2\theta) d\theta$$

$$= \frac{I_m^2}{2\pi} \left[\theta - \frac{1}{2} \sin 2\theta \right]_0^\pi$$

$$= \frac{I_m^2}{2\pi} \left[\left(\pi - \frac{1}{2} \sin 2\pi \right) - \left(0 - \frac{1}{2} \sin 2 \times 0 \right) \right]$$

$$= \frac{I_m^2}{2\pi} [\pi - 0 - 0 + 0] = \frac{\pi}{2\pi} I_m^2 = \frac{I_m^2}{2}$$

$$I_{rms} = \sqrt{\frac{I_m^2}{2}} = \frac{I_m}{\sqrt{2}} = 0.707 I_m$$

- 4 M

Average Output Current

$$= \left(\frac{1}{2\pi} \right) \left[\int_0^\pi I_m \sin \omega t d(\omega t) + \int_\pi^{2\pi} 0 d(\omega t) \right]$$

$$= \left(\frac{1}{2\pi} \right) \int_0^\pi I_m \sin \omega t d(\omega t)$$

$$= \left(\frac{I_m}{2\pi} \right) \int_0^\pi \sin \omega t d(\omega t)$$

$$= \left(\frac{-I_m}{2\pi} \right) [\cos \pi - \cos 0]$$

$$= \left(\frac{I_m}{\pi} \right)$$

- 4 M

$$\text{Peak Factor} = \frac{\text{Peak value}}{\text{RMS Value}} = \frac{V_m}{0.707 V_m} = 1.414$$

-2M

12

2


2

1,2


$$\text{Form Factor} = \frac{\text{RMS value}}{\text{Average Value}} = \frac{0.707 V_m}{0.637 V_m} = 1.11$$

- 2M

16(a)
)




-3M



I/P characteristics CE configuration

-2M



O/P Characteristics CE Configuration

-2M

Explanation-5

12


2

3

1,2

(or)

16(b)
)



- 10 M

Moving coil instruments

1. It works on the principle of DC motor
2. Deflection torque is proportional to square of current
3. Damping is provided by eddy current damping
4. Spring controlled instrument
5. Controlling torque is proportional to angle of deflection
6. Scale is uniform
7. Delicate, sensitive and accurate.

Moving Iron instruments

1. It works on the principles of magnetism.
2. Deflection torque is proportional to current
3. Damping is provided by air
4. Gravity controlled instruments.
5. Controlling torque is proportional to $\sin \theta$
6. Non uniform scale.
7. Robust, reliable accurate.

-2M

12

2

3

1,2

Question Paper Setter

Approved by Audit Professor/
Course Coordinator