



AIRMARK OVERHAUL, INC.

Date: 4/16/2019

Work Order No. 47301

ENGINE ASSEMBLY AND FINAL INSPECTION REPORT DIRECT DRIVE AND 76 SERIES ENGINES

CUSTOMER'S NAME: S.A.G.A EURL C/O

ADDRESS: _____

LYCOMING

MODEL O-360-A4M
S/N L-30677-36AC

PROPELLER STRIKE INSPECTION AND REPAIR

THIS FORM IS USED IN CONJUNCTION WITH APPLICABLE FACTORY OVERHAUL
MANUAL AND SERVICE BULLETINS.

MAINTENANCE RELEASE

The aircraft engine identified above was ~~overhauled~~/repaired, inspected and functionally tested in accordance with current federal air regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under work order

NO: 47301

DATE: MAY 21, 2019

[Signature]

Authorized Signature

AIRMARK OVERHAUL, INC.
6001 N.W. 29th Avenue
Ft. Lauderdale, FL 33309
F.A.A. Approved Repair Station
No. JL4R288M

Technician [Signature]

Inspector: [Signature]

Note: All Ref. No's are from Manual SSP1776
unless otherwise noted

Form AO-102
4/10/12
Page 1 OF 5



AIRMARK OVERHAUL, INC.

ENGINE ASSEMBLY INSPECTION RECORD

47301

Work Order No.

LYCOMING DIRECT DRIVE AND 76 SERIES

CRANK PIN SIZE (Ref. No. 501)		Journal Size	Out of Round	
1. 2.1243	4. 2.1244	Standard	1. .0002	4. .0002
2. 2.1243	5. —	M. 003	2. .0001	5. —
3. 2.1242	6. —	M. 006	3. .0001	6. —
		M.010		

MAIN JOURNAL SIZE (Ref. No. 500 & No. 508)		Journal Size	Out of Round	
1. 2.3756	3. 2.3754	Standard	1. .0001	3. .0002
2. 2.3754	4. 2.3755	M. 003	2. .0001	4. .0001
	5. —	M. 006		5. —
		M.010		

CRANKSHAFT RUNOUT (Ref. No. 500)		
Mounted on Front and Rear Journal	FLANGE .001	
Mounted on # 1 and # 4 Journal	#2 .001	#3 .001
Mounted on # 2 and # 4 Journal	#3 .001	
Mounted on # / and # / Journal	# —	

CAMSHAFT RUNOUT (Ref. No. 516)	
Mounted on Front and Rear Journal	
CENTER .0005	

CRANK SHAFT S/N: 1537931

TAPPET BODY IN CRANKCASE GUIDE (Ref. No. 511)						
Int.	1. .002	2. .002	3. .002	4. .002	5. —	6. —
Exh.	1. .002	2. .002	3. .002	4. .002	5. —	6. —

Technician [Signature]

Inspector: [Signature]

Note: All Ref. No's are from Manual SSP1776
unless otherwise noted

Form AO-102
4/10/12
Page 2 OF 5



AIRMARK OVERHAUL, INC.

ENGINE ASSEMBLY INSPECTION RECORD

47301

Work Order No.

LYCOMING DIRECT DRIVE AND 76 SERIES

DESCRIPTION CONNECTING RODS	1	2	3	4	5	6
Conn Rod Bend & Twist (Ref. No. 503 and No. 504)	Ø	Ø	Ø	Ø	—	—
Bushing in Connection Rod Diameter (Ref. No. 600)	1.1257	1.1257	1.1257	1.1258	—	—
Conn Rod Bushing & Piston Pin Clearance (Ref. No. 602)	.0013	.0013	.0013	.0014	—	—
Conn Rod Bearing & Crank Pin Clearance (Ref. No. 501)	.002	.002	.002	.002	—	—
Conn Rod Side Clearance (Ref. No. 502)	.008	.007	.007	.007	—	—

CRANKCASE	1	2	3	4	5	6
Crankshaft in Main Bearing Diameter (Ref. No. 500)	.003	.003	.003	.003	—	—
Bushing in Counterweight Diameter (Ref. No. 521)	N/A	—	—	—	—	—
Bushing in Crankshaft Blades Diameter (Ref. Latest Revision of SI 1143)	N/A	—	—	—	—	—
Bushing in Propeller Flange Diameter & Location (Ref. Latest Revision of SI 1098)	ok	—	—	—	—	—
Counterweights on Crank Check Blades Side Clear (Ref. No. 519)	N/A	—	—	—	—	—
Crankshaft in Front Bearing End Clear (Ref. No. 506)	.009	—	—	—	—	—
Camshaft Flanges in Crankcase End Clear (Ref. No. 515)	.004	—	—	—	—	—

Technician

[Signature]

Inspector:

[Signature]

Note: All Ref. No's are from Manual SSP1776
unless otherwise noted

Form AO-102
4/10/12
Page 3 OF 5



AIRMARK OVERHAUL, INC.

ENGINE ASSEMBLY INSPECTION RECORD

47301

Work Order No.

LYCOMING DIRECT DRIVE AND 76 SERIES

	TECHNICIAN		COMMENTS	
Crankshaft Gear in Shaft Diameter (Ref. No. 60294-7 7-53)	AO		.0002 T	
Check Idler Gears, Crank Gear and Cam Gear for Wear (Ref. No. 60294-7 Section 3)	AO			
Install Crank Gear, Bolt Torque and Safety ^{205 in lbs} (Ref. Latest Rev. of S.B. 475 and O.H. Manual 60294-7 Section 7-65, Ref 927)	Tech. AO	Wrench No. AES383	Insp. LP	Wrench No. AES382
Torque and Safety Cam Gear bolts (Ref. No. 60294-7 Section 7-70) & Table 1	Tech. N/A	Wrench No. —	Insp. N/A	Wrench No. —
Torque and Safety Idler Shaft Bolts ^{150 in lbs nut 200 in lbs bolts} (Ref. No. 60294-7 Section 7-75 & Latest Revision of SI 1310)	Tech. AO	Wrench No. AES371	Insp. LP	Wrench No. AES357
Check crank gear to idler gear for internal timing	Tech. AO		Insp. LP	
Clean – Inspect Lifter Unit (Ref. No. 60294-7 Section 6-25)	AO			
Install Rocker Arms and Check Clearance (Ref. No. 618 SI – As applicable)	AO			
Install Covers and Torque Screws (Ref. No. 905)	AO			
Torque and Safety Rear Case Tie Bolt (Ref. 60294 –7 Section 7-93)	AO			
Install and Torque Piston Cooling Nozzles (Ref No. 913)	N/A		—	
Inspect – Install Oil Pump (Ref No. 703 Thru 707)	AO			
Oil Pump Gear In Housing Diameter (Ref. No. 703)	AO		.004	
Oil Pump Gear Shafts in Cover Diameter (Ref. No. 703)p	AO		.002	

Technician

Inspector:

ie: All Ref. No's are from Manual SSP1776
unless otherwise noted

Form AO-102
4/10/12
Page 4 OF 5



AIRMARK OVERHAUL, INC.

LYCOMING DIRECT DRIVE AND 76 SERIES

ENGINE ASSEMBLY INSPECTION RECORD

47301

Work Order No.

TECHNICIAN

COMMENTS

Magneto Brg. To Gear Diameter (Ref. No. 746)	NIA	—
Magneto Brg. In Case or Adapter Diameter (Ref. No. 747)	NIA	—
Crankshaft Gear to Idler Gear Backlash (Ref. No. 805)	AD	.009
Magneto Drive Gear to Idler Gear Backlash (Ref. No. 804)	AD	L .010 R .010
Camshaft Gear to Idler Gear Backlash (Ref. No. 803)	AD	.010
Propeller Governor Idler and Camshaft Backlash (Ref. No. 823)	NIA	—
Oil Pump Gear Backlash (Ref. No. 808)	AD	.009
Install Fuel System and Torque Lines and Nozzles C/W with S.B. on Line Clamping (Ref. Latest Rev. of SB 342)	NIA	—

	Mech.	Wrench No.	Insp.	Wrench No.
Torque Rod Bolts (Ref. No. 900 / Latest Revision of SI 1458) 480 in lbs	AD	AES383	LP	AES382
Torque and Safety Bolt Inside Pan. (Ref. Table 1)	AD	AES171	LP	AES357
Torque and Stripe Cylinder Hold Down Nuts (Ref. No. 929) 300 in lbs 600 in lbs	AD	AES383	LP	AES382
Torque Crankcase and Thru Bolts and Nuts	AD	AES383	LP	AES382

Technician

Inspector:

Form AO-102
4/10/12
Page 5 OF 5

Note: All Ref. No's are from Manual SSP1776
unless otherwise noted



AIRMARK OVERHAUL, INC.

FAA APPROVED REPAIR STATION #JL4R288M
6001 NORTHWEST 29TH AVENUE
FORT LAUDERDALE, FLORIDA 33309
(954) 970-3200 • (800) 282-3202
FAX: (954) 970-3400

MAGNETIC PARTICLE INSPECTION

47301

Work Order NO.
Certified Inspection

Customer SAGA, EURL

Address _____

Phone No. _____

Fax. No. _____

Make LYCOMING Model O-360-A4M S/N 30677-36AC Date 4/25/19

Quantity	Part No.	Description	Parts Accepted	Parts Rejected
(1)		Crankshaft	1	0
2 4 6		Counterweights	0	
1		Camshaft	0	
(4) 6		Connecting Rods & Caps	4	
(2)		Idler Gears	2	
(2)		Idler Shafts	2	
(2)		Magneto Drive Gears	2	
(1)		Crankshaft Gear	1	
(4) 6		Piston Pins	4	
(1)		Fuel Pump Shaft	1	
(1)		Oil Pump Drive	1	
(2)		Oil Pump Impeller	2	
(1)		Tach Shaft	1	
1		Pro. Gov. Drive	0	
2		Prop. Gov. Idler Gears	0	
(1)		Vacuum Pump Drive	1	
1		Hyd. Pump Drive	0	
(8) 12		Rocker Arms	8	
(4) 6 12		Rocker Shafts	4	
(8) 12		Push Rods	8	
1 2		Camshaft Gears	0	0

By : Inspector Sham R. D.

Form AO-112
9/14/00



NDT INSPECTION RECORD

Work Order No.

Certified Inspection

☐ MAGNETIC PARTICLE

 LIQUID PENETRANT




ULTRASONIC

[illegible]

Inspector: h r c

Form AO-113
05/12/06

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: DIV WDC #123758	
4. Organization Name and Address: DIVCO, INC., 2806 N. SHERIDAN ROAD, TULSA, OK 74115 (DB2R762K)						
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	5. Work Order/Contract/Invoice Number: INVOICE #123851	
1	LYC O-360 CRANKCASE	CASTING #72081	1	MATCH #328	11. Status/Work: REPAIRED	
12. Remarks: REPAIRED #2 CAM JOURNAL & LOWER FRONT #2 & 4 & LOWER REAR #2 CYLINDER CRANKCASE REPAIRED PER DIVCO APPROVED PROCESS SPECS 77-002 REV 6 18 JULY 2017. DATE COMPLETED: 14/FEB/2019 WDC #123758 WORK SPECIFIED IN BLOCKS 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND WITH RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NUMBER EASA 145-5286						
13a. Certifies the items identified above were manufactured in conformity to:		14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12		14b. Authorized Signature: 		
<input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.		Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14c. Approval/Certificate No.: DB2R762K		
13b. Authorized Signature:		13c. Approval/Authorization No.:		14d. Name (Typed or Printed): DARYLE WAYNE DOTSON		
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 14/FEB/2019		
User/Installer Responsibilities						
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.</p> <p>Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.</p> <p>Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>						



AIRMARK OVERHAUL, INC.

FAA APPROVED REPAIR STATION #JL4R288M
6001 NORTHWEST 29TH AVENUE
FORT LAUDERDALE, FLORIDA 33309
(954) 970-3200 (800) 282-3202
FAX: (954) 970-3400

CYLINDER ASSEMBLY INSPECTION RECORD

47301
WORK ORDER

Date 5/9/19 Work Required Cyl. Repair Engine Model # 0360/R4M Cyl. Class 12

CYLINDER POSITION NUMBER

	1	2	3	4	5	6
Cylinder Bore	5.1275	5.1275	5.1275	5.1285		
Out of Round	.0005	.0005	.0005	.0003		
Taper or Choke	.0015	.0015	.0015	.0009		
Condition of Ports						
Condition of Exhaust Studs						
Springs Outer						
Springs Intermediate	VALVES WERE NOT REMOVED					
Springs Inner						
Intake Valve to Guide						
Exhaust Valve to Guide						
Leak Check						
Liquid Penetrant Tested						
Magnafluxed Tested						
Part Number	2W/2427	2W/2427	2W/2427	2W/2427		
W/O # Stamped on Cylinder	47301.1	47301.2	47301.3	47301.4		
Type of Cylinder Barrel	NITRIDE	NITRIDE	NITRIDE	NITRIDE		
Type of Assembly	Comp	Comp	Comp	Comp		

RING SIDE CLEARANCE

	1	2	3	4	5	6
1. Ring	.005	.003	.003	.003		
2. Ring	.003	.003	.003	.003		
3. Ring	.004	.004	.004	.004		
4. Ring						
5. Ring						

RING GAP

	1	2	3	4	5	6
1. Ring	.045	.045	.045	.046		
2. Ring	.045	.045	.045	.046		
3. Ring	.021	.021	.022	.022		
4. Ring						
5. Ring						

Mechanic: [Signature]

Inspector: [Signature]

1. Approving Civil Aviation
Authority/Country: FAA/United States

2. **AUTHORIZED RELEASE CERTIFICATE**
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
7364757443 1000000051673509

4. Organization Name and Address: AVIAL SERVICES INC.
2750 REGENT BLVD
DALLAS, TX 75261

5. Work Order/Contract/Invoice Number:
10025213

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1.	MAGNETO	4371	1	17120862	NEW
12. Remarks: US JUL 1734					

THIS PMA PART IS NOT A CRITICAL COMPONENT.
AIRWORTHINESS APPROVAL
THE PRODUCT(S)/ARTICLE(S) SHIPPED UNDER THIS APPROVAL WERE PRODUCED BY CHAMPION AEROSPACE LLC.

13a. Certifies the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.	14a. <input type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.
13b. Authorized Signature: <i>Thomas Willis</i>	14b. Authorized Signature:
13c. Approval/Authorization No.: 127604222	14c. Approval/Certificate No.:
13d. Name (Typed or Printed): Thomas Willis	14d. Name (Typed or Printed):
13e. Date (dd/mm/yyyy): 11 MAR 2019	14e. Date (dd/mm/yyyy):

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/ article(s) from the airworthiness authority of the country specified in the Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Civil Aviation
Authority/Country: FAA/United States

2. **AUTHORIZED RELEASE CERTIFICATE**
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
7365117129 1000000051673508

4. Organization Name and Address: AVIAL SERVICES INC.
2750 REGENT BLVD
DALLAS, TX 75261

5. Work Order/Contract/Invoice Number:
10025213

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1.	MAGNETO	4370	1	19020874	NEW

12. Remarks:

US
JUL
1737

THIS PMA PART IS NOT A CRITICAL COMPONENT.
AIRWORTHINESS APPROVAL
THE PRODUCT(S)/ARTICLE(S) SHIPPED UNDER THIS APPROVAL WERE PRODUCED BY CHAMPION AEROSPACE LLC.

13a. Certifies the items identified above were manufactured in conformity to:

- ☒ Approved design data and are in a condition for safe operation.
☐ Non-approved design data specified in Block 12.

14a. ☐ 14 CFR 43.9 Return to Service

☐ Other regulation specified in Block 12
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

Thomas Willis

13c. Approval/Authorization No.:
127604222

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name (Typed or Printed):
Thomas Willis

13e. Date (dd/mm/yyyy):
11 MAR 2019

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/ article(s) from the airworthiness authority of the country specified in the Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

47301

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2.		3. Form Tracking Number: H-S101308	
AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG					
4. Organization Name and Address: HARTZELL ENGINE TECHNOLOGIES, 2900 SELMA HWY. MONTGOMERY, AL. 36108 PQ1383CE-D					
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	STARTER **** END ****	149NL	1	H-S101308	NEW
12. Remarks: AIRWORTHINESS APPROVAL- PARTS FOR PMA ELIGIBILITY SEE WWW.HARTZELL.AERO/PMA/					
13a. Certifies the items identified above were manufactured in conformity to:		14a. <input type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12			
<input checked="" type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.		Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:	13c. Approval/Authorization No.: PQ1383CE-D		14b. Authorized Signature:		14c. Approval Certificate No.:
13d. Name (Typed or Printed): Gary Hancock	13e. Date (dd/mm/yyyy): 18/Oct/2018		14d. Name (Typed or Printed):		14e. Date (dd/mm/yyyy):
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

47301

1. Approving Civil Aviation
Authority/Country:
FAA/UNITED STATES

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
INV #: 6365

4. Organization Name and Address:

Aerotech of Louisville, Inc. 2209 Watterson Trail Louisville, KY 40299

5. Work Order, Contract, or Invoice Number:
W/O: 129933

6. Item:	7. Description:	8. Part Number:	9. Quantity	10. Serial Number:	11. Status/Work:
1	Chrysler alternator	4111810	1	S/N H-H090568	Overhauled

12. Remarks:

COPY OF WORK ORDER AVAILABLE ON REQUEST FROM AEROTECH OF LOUISVILLE.

CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA APPROVAL CERTIFICATE NUMBER 145.6696 AND BY THE FAA AIR AGENCY CERTIFICATE NUMBER PU4R453M APPROVED FOR EXPORT. THE ORIGINAL EQUIP. MFG. DATA APPEARS ON THE I.D. PLATE IN THE LINES IDENTIFIED AS MOD/NO & ORIG. MFG. COMPLIES WITH OE-A2 OR TW5000 LATEST REVISION.

THE FOLLOWING SERVICE BULLETINS & AD NOTES HAVE BEEN COMPLIED WITH. RESEARCHED: and not applicable.

13a. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation
- ☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12

Certifies that unless otherwise specified in block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No:	14b. Authorized Signature:	14c. Approval/Certificate No:
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed):	14e. Date: (dd/mm/yyyy):
		John C. Evans	PU4R453M
			03/May/2019

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article..

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



AIRMARK OVERHAUL, INC.

FAA APPROVED REPAIR STATION #JL4R288M
6001 NORTHWEST 29TH AVENUE
FORT LAUDERDALE, FLORIDA 33309
(954) 970-3200 • (800) 282-3202
FAX: (954) 970-3400

LYCOMING ENGINE TEST PERFORMANCE

47301
Work Order No.

Model O-40-A4M S/N L-30677-36AC Operator Amel / J. H. H. Date 5/21/19

Run Time	RPM	Oil Temp.	Oil Pres.	Man. Pres.	Cylinder Head Temperature						Fuel Pres.	Remarks
					1	2	3	4	5	6		
10	1200	140	70	12					/	/		OK
10	1500	160	72	15	300	300	305	305	/	/		
10	1800	170	72	18	310	310	315	315	/	/		
10	2000	180	80	20	315	315	320	320	/	/		
10	2200	185	80	22	320	320	325	325	/	/		
10	2400	190	82	24	325	325	330	330	/	/		
15	2700	190	82	27	325	325	330	330	/	/		
*60	2200	190	80	22	325	325	330	330	/	/		
*Oil weight at start		14.7						All references per				
*Oil weight at end		14.3						overhaul manual no. 60294-7-14				

*Oil consumption run, check oil quantity weight before and after consumption run.

**Refer to geared engine run in schedule for run time and RPM variations.

Comp Check: #1 80/ 77 #2 80/ 78 #3 80/ 76 #4 80/ 78 #5 80/ / #6 80/ /

Oil Pressure Verification at Propeller Governor Pad	NA
Propeller Oil Control Leak Test Procedure	40 PSI/ NA
Check Oil Screen for Contamination	1 st Check: Clean
	2 nd Check: Clean
Check Engine for Leaks, Fuel and Oil	OK/Clean
Check Magneto Timing, Torque and Stripe	OK/complete

Inspector: W. H. H.

Form AO-115
01/31/04

AIRMARK OVERHAUL, INC.
FAA APPROVED REPAIR STATION #JL4R288M
6001 NW 29 AVENUE
FORT LAUDERDALE, FL 33309

SERVICE BULLETIN
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360

MODEL *0-360-A4M* SIN *L-30677-36ACWIO# 47301*

DATE *MAY 21, 2019*

ISSUE NO	DESCRIPTION	SIGNATURE
201F	INSPECTION OF C/S FLANGES <i>FLANGE NOT BENT, 0.437" THICK</i>	<i>[Signature]</i>
212B	REPLACING STRAIGHT THRU-STUDS WITH NECKED STUDS <i>P/C/W</i>	
222D	CRANKSHAFT RENITRIDING RECOMMENDATIONS <i>CRANKSHAFT NOT REWORKED</i>	
225B	REPLACEMENT OF VALVE ROCKER THRUST WASHERS <i>NA TO MODEL</i>	
238	MAGNETIZED CONDITION OF HYDRAULIC TAPPET PLUNGER ASSY. <i>ALL INSPECTED GOOD, NONE MAGNETIZED</i>	
240W (MANDATORY)	MANDATORY REPLACEMENT OF PARTS AT NORMAL OVERHAUL <i>PARTS REPLACED FOR PROP STRIKE + UPON REMOVAL</i>	
271A	CYLINDER PAINTING <i>NA TO WIDE DECK MODEL</i>	
272A	RETORQUEING OF CENTER MAIN THRU-STUDS <i>NA TO MODEL</i>	
273A	MODIFICATION OF CRANKCASE CENTER MAIN BEARINGS SUPPORT <i>NA TO MODEL</i>	
314C	LIMITED TRAVEL LIFTER REPLACEMENT <i>NA TO MODEL</i>	
357	ENGINE INSPECTION IN EVENT OF IMMERSION <i>NA- PROP STRIKE INSPECTION</i>	
366C (MANDATORY)	CARBURETOR THROTTLE BOWL SCREW INSPECTION <i>INSPECTED GOOD</i>	
367F	REQUIRED INSPECTION OF P/N 69650 PISTON PIN <i>(H) LW14078 PISTON PINS INSTALLED</i>	
367F SUPP 1	REQUIRED INSPECTION OF P/N 69650 PISTON PIN <i>(H) LW14078 PISTON PINS INSTALLED</i>	
369R	ENGINE INSPECTION AFTER OVERSPEED <i>NA- PROP STRIKE INSPECTION</i>	
370	OIL FILTER ATTACHING STUD REPLACEMENT <i>NEW CH48/10.1 FILTER INSTALLED</i>	
381C	OIL PUMP WOODRUFF KEY DRIVE & IMPELLER REPLACEMENT	S/S MSB524 <i>[Signature]</i>

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
FAA APPROVED REPAIR STATION #JL4R288M
6001 NW 29 AVENUE
FORT LAUDERDALE, FL 33309

SERVICE BULLETIN
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360

MODEL	0-360-A4M	S/N	L-30677-36A-WIO#	47301	DATE	MAY 21, 2019
ISSUE NO	DESCRIPTION	SIGNATURE				
385C	OIL PUMP IMPELLER & DRIVE REPLACEMENT	S/S MSB524				
385C SUPP 1	OIL PUMP IMPELLER & DRIVE REPLACEMENT	S/S MSB524				
388C	EXHAUST VALVE & GUIDE CONDITION					
	NOT REQ'D, ALL HI-CAROME EXH GUIDES					
398B	ACTION FOLLOWING USE OF INCORRECT FUEL					
	NA- PROP STRIKE INSPECTION					
400	INSTALLATION OF TEFLON THRUST BUTTONS					
	THRUST BUTTONS INSTALLED					
406A (MANDATORY)	ROMEC & TITAN FUEL PUMP INSPECTION					
	NA TO MODEL					
411D (MANDATORY)	O-360-A3A - A4A - A4J-IO-360-B4A MAGNETO ISOLATION					
	DRIVE NA TO MODEL					
419	EXHAUST VALVE REPLACEMENT					
	NA TO MODEL					
425C	REPRINT TCM SB 645 IMPULSE COUPLING					
	NEW CHAMPION MAGNETO KIT INSTALLED					
431	TEFLON FIRE HOSES WITH FIRE SLEEVE					
	HOSES NOT SUPPLIED					
439A	INSPECTION OF CONNECTING RODS FOR GALLING					
	ALL INSPECTED GOOD, NONE GALLED					
446E	USE OF LYCOMING LW-16702 OIL ADDITIVE					
	NA TO MODEL					
447B (MANDATORY)	INSPECTION OF UPPER EXHAUST VALVE SPRING					
	SEATS NA TO MODEL					
451	OIL LEVEL GAGE REWORK/REPLACEMENT					
	NA TO MODEL					
455D	REPLACEMENT OF OIL PUMP IMPELLERS	S/S MSB524				
456F	REPLACEMENT OF OIL PUMP IMPELLERS	S/S MSB524				
466	INSPECTION OF OIL FILTER BASE ADAPTER					
	INSPECTED GOOD					
468C	REPRINT OF SLICK SB2-88A 4200 SERIES MAGNETOS					
	NEW CHAMPION MAGNETO KIT INSTALLED					
475C AND SUPP 1	CRANKSHAFT GEAR MODIFICATION & ASSY.					
	INSPECTED/INSTALLED AS SPECIFIED					
	13 #19646 GEAR, NEW STD 2246 BOSS					







AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
FAA APPROVED REPAIR STATION #JL4R288M
6001 NW 29 AVENUE
FORT LAUDERDALE, FL 33309

SERVICE BULLETIN
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360

MODEL *0-360-A4M* S/N *L-30677-36ACWIO# 47301* DATE *MAY 21, 2019*

ISSUE NO	DESCRIPTION	SIGNATURE
477A	INSPECTION & REWORK OF P/N LW-18790 ROCKER ARM ASSY. <i>(4) 69444, (4) 74636 ROCKER ARMS</i>	
477A SUPP 1	ADDITION OF SERIAL NUMBERS TO THE ENGINE <i>(4) 69444, (4) 74636 ROCKER ARMS</i>	
480F (MANDATORY)	OIL AND FILTER CHANGE INTERVALS <i>NEW CH48110-1, NO OIL, WHEN SHIPPED</i>	
486	INSPECTION OF SINGLE BELT DRIVEN RING GEAR SUPPORT <i>SUPPORT NOT RECEIVED, NOT SUPPLIED</i>	
488A	PROPELLER GOVERNOR LINE SUPPORT <i>NA TO MODEL</i>	
488A SUPP 1	A/C BRACKET & HARDWARE <i>NA TO MODEL</i>	
495A	REPLACEMENT OF COMPOSITE FLOATS W/METAL (PRECISION AIRMOTIVE)	S/S MSB582
496	LEAR ROMEC RELIEF DIAPHRAGM REPLACEMENT <i>NA TO MODEL</i>	
501B	PISTON PIN RECALL (LW-14077) <i>(4) LW14078 PISTON PINS INSTALLED</i>	
502	REPLACEMENT OF LW-13262 INTAKE VALVE <i>NA TO MODEL</i>	
505B (MANDATORY)	INSPECTION OF PITTING ON CRANKSHAFTS <i>NA - SOLID SHAFT</i>	
508	TCM MAGNETO IMPULSE COUPLING INSTALLATION (TCM SB 639) <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
509	REPRINT AEROQUIP SB AA135 <i>HOSES NOT SUPPLIED</i>	
515 (MANDATORY)	REPRINT OF TCM'S SB 643 MAINTENANCE INTERVALS <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
516A (MANDATORY)	INSPECTION OF BENDIX/TCM MAGNETOS WITH IC. <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
517 (MANDATORY)	REPRINT OF TCM SBCSB 641 OPEN CONDITION IN THE CAPACITORS <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
517 SUPP 1	CORRECTION OF AFFECTED ENGINES FOR SB517 <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
518D (MANDATORY)	INSPECTION OF THERMOSTATIC BYPASS VALVE <i>SL53519600/45244 REINSTALLED</i>	

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
FAA APPROVED REPAIR STATION #JL4R288M
6001 NW 29 AVENUE
FORT LAUDERDALE, FL 33309

SERVICE BULLETIN
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360

MODEL *0-360-A4M* S/N *L-30677-36ACWIO# 47301*

DATE *MAY 21, 2019*

ISSUE NO	DESCRIPTION	SIGNATURE
519 (MANDATORY)	SHROUD TUBE RETAINING SPRINGS (LW-14995) <i>SPRINGS INSTALLED FROM GASKET SET</i>	<i>[Signature]</i>
520	INCORRECT PISTONS IN CERTAIN LYCOMING KITS <i>NOT FACTORY KITS</i>	
524 (MANDATORY)	REPLACEMENT OF OIL PUMP GEARS <i>AEL 78531 PUMP W/ AEL 18109-10 IMPELLERS</i>	
525A (MANDATORY)	LYCOMING LW-15473 HIGH PRESSURE FUEL PUMPS <i>NA TO MODEL</i>	
527C (MANDATORY)	RECALL OF PISTON PIN LW-14077 <i>(4) LW14078 PISTON PINS INSTALLED</i>	
528 (MANDATORY)	REPRINT TCM SERVICE BULLETIN SB 658 <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
529B (MANDATORY)	AN FUEL PUMPS LEAR ROMEC SB101 SB020 <i>NA TO MODEL</i>	
530B (MANDATORY)	APPLICATION OF PROTECTIVE COATING ON C/SHAFT REF. S.I. 1511A <i>NA - SOLID SHAFT</i>	
533C (MANDATORY)	PROP STRIKE INSPECTION (ATTACH CHECKLIST) <i>C/W - SEE ATTACHED CHECKLIST</i>	
539A (MANDATORY)	REPRINT OF CRANE/LEAR ROMEC S.B. <i>NA TO MODEL</i>	
540 (MANDATORY)	VALVE SEAT INSPECTION <i>P/C/W - TIME IN SERVICE</i>	
541 (MANDATORY)	REPRINT OF TCM CSB662A CAPACITOR REPLACEMENT AND DATE CODE INSPECTION <i>NA TO MODEL</i>	
SI1304J	ENGINE NAMEPLATE REPLACEMENT <i>P/C/W</i>	
TCM CSB662A	CAPACITOR REPLACEMENT & DATE CODE INSPECTION <i>NA TO MODEL</i>	
543C (MANDATORY)	OIL FILER BASE SEAL REPLACEMENT <i>NA TO MODEL</i>	
543A SUPP 1	OIL FILER BASE SEAL REPLACEMENT	S/S BY 543B
548A (MANDATORY)	DIAPHRAGM - TYPE FUEL PUMP INSP./REPLACEMENT <i>AERO ACCYS OH 2015 PUMP REINSTALLED</i>	
549 (MANDATORY)	CRANKSHAFT SERIAL NUMBER INSPECTION <i>NA BY CRANKSHAFT S/N</i>	<i>[Signature]</i>

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
FAA APPROVED REPAIR STATION #JL4R288M
6001 NW 29 AVENUE
FORT LAUDERDALE, FL 33309

SERVICE BULLETIN
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360

MODEL *0-360-A4m* SIN *L-30677-36ACWIO# 47301* DATE *MAY 21, 2019*

ISSUE NO	DESCRIPTION	SIGNATURE
SB549 SUPP 1	CRANKSHAFT SERIAL NUMBER INSPECTION <i>NA BY CRANKSHAFT S/N</i>	<i>[Signature]</i>
555A (MANDATORY)	OIL PUMP BODY PLUG INSPECTION P/N'S 78528, 78890, 51A22618 <i>NA- AEL78531 OIL PUMP HOUSING</i>	
555 SUPP 2	OIL PUMP BODY PLUG INSPECTION	SUPERCEDED BY SB555A
557 (MANDATORY)	RSA-5, RSA-10 FUEL SERVOS OVERHAULED BY PRECISION AIR MOTIVE <i>NA TO MODEL</i>	
559	KELLY AEROSPACE STARTER REPLACEMENT (KELLY AEROSPACE) S/B NO. A-112 REV A <i>NEW 149NL STARTER INSTALLED</i>	
565 (MANDATORY)	DIAPHRAGM TYPE FUEL PUMP INSPECTION <i>NA TO MODEL</i>	
566 (MANDATORY)	CRANKSHAFT REPLACEMENT <i>NA TO MODEL</i>	
566 SUPP NO. 1	CRANKSHAFT REPLACEMENT <i>NA TO MODEL</i>	
568 (MANDATORY)	REPRINT OF SLICK S/B NO SB1-88B LYCOMING ENGINE EQUIPPED WITH PRESSURIZED SLICK MAGS <i>NA TO MODEL</i>	
569A (MANDATORY) AND SUPP NO. 1	CRANKSHAFT RETIREMENT FOR CERTAIN LYCOMING ENGINES (SEE SERVICE LETTER L244 FOR KIT P/N) <i>NA TO MODEL</i>	
B06-01E (MANDATORY) SUPERIOR	REMOVAL OF SUPERIOR CYLINDERS WITH SOFT BARRELS <i>ALL CYLINDERS LYCOMING</i>	
573 (MANDATORY)	PRESSURIZED MAGNETO PRESSURE TESTS <i>NA TO MODEL</i>	
574A (MANDATORY)	CYLINDER STUD HOLE CROSS THREADED <i>NA BY LOT/DATE CODE OF ALL CYLS</i>	
576	TCM SB633A-TACH CIRCUIT INTEGRITY <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
577A	SKY TEC STARTER SKYTEC S/B 07-01 REV. D <i>NEW 149NL STARTER INSTALLED</i>	
MSB028A	KELLY AEROSPACE FUEL PUMP REPLACE DIAPHRAGM & PLUNGER REPLACEMENT (GEARED PUMPS) <i>NA TO MODEL</i>	<i>[Signature]</i>

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
FAA APPROVED REPAIR STATION #JL4R288M
6001 NW 29 AVENUE
FORT LAUDERDALE, FL 33309

SERVICE BULLETIN
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360

MODEL *D-360-A4M* SIN *L-30677-36ACWIO# 47301*DATE *MAY 21, 2019*

ISSUE NO	DESCRIPTION	SIGNATURE
578	INCORRECT CYLINDERS ASSEMBLIES SHIPPED W/CYLINDER KITS <i>NOT FACTORY KITS</i>	<i>[Signature]</i>
MSB: 08-1 REV 3 (MANDATORY)	ENGINE COMPONENTS INC. INSPECTION REMOVAL OR REPLACEMENT OF AEL65102 CYLINDER ASSEMBLY <i>ALL CYLINDERS LYCOMING</i>	
582A (MANDATORY) AND SUPP 1	REPLACEMENT OF BRASS OR POLYMER FLOAT WITH FOAM FLOAT PRECISION S/B MSA-13 <i>NO WORK ACCOMPLISHED</i>	
583A (MANDATORY)	REPRINT OF SLICK MAGNETO SB2-08A <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
584B (MANDATORY)	REPRINT OF SLICK MAGNETO SB3-08A <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
591A (MANDATORY)	REPRINT OF KELLY AEROSPACE MSB 039 REPLACEMENT OF TURBINE WHEEL <i>NA TO MODEL</i>	
CSB668	INSPECTION OF IGNITION HARNESS ATTACHMENT PLATE (TCM S-20/S-200) <i>NA - CHAMPION MAGNETOS</i>	
592	ENGINE INSPECTION AFTER OVERBOOST <i>NA - NOT OVERBOOST</i>	
SB-18 REV A	MARVEL SCHEBLER EMERGENCY SERVICE BULLETIME HA-6 CARBURETORS <i>NA TO MODEL</i>	
601	NON COMPLIANT OIL FILL TUBE P/N 77527 <i>NA TO MODEL</i>	
615	DIAPHRAGM TYPE FUEL PUMP REPLACEMENT	S/S SB621
617	DIAPHRAGM TYPE FUEL PUMP REPLACEMENT	S/S SB621
619	HARDNESS CHECK LW15014 ROCKER ARMS <i>NA TO MODEL</i>	
SB670 TCM	MAGNETO BLOCK INSPECTION (S-20,200,1200 SERIES) <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
SB621B	DIAPHRAGM TYPE FUEL PUMP REPLACEMENT <i>NA TO MODEL</i>	
622	SLICK LASAR MAGNETOS <i>NOT LASAR MAGNETOS</i>	
623	HARTZELL SB-062, LW14326 AND LW14338 ALTERNATORS, THRU BOLT REPLACEMENT <i>NA BY ALTERNATOR P/N</i>	<i>[Signature]</i>

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

**SERVICE BULLETIN
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360**

MODEL 0-360-44m SIN L-30677-36AC WIO# 47301

DATE MAY 21, 2019

[illegible]

ALPINE MARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

ADRIAN OVERHAUL, INC.
REPAIR STA. #14288M

AIRMARK OVERHAUL, INC.
FAA APPROVED REPAIR STATION #JL4R288M
6001 NW 29 AVENUE
FORT LAUDERDALE, FL 33309

AIRWORTHINESS DIRECTIVE
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360 (CONT.)

MODEL O-360-A4M S/N L-30677-36AC W/O# 47301

DATE MAY 21, 2019

ISSUE NO	DESCRIPTION	SIGNATURE
59-10-07	CYLINDER BAFFLE CLAMPS (O-360) SB 254A	<i>UP</i>
64-16-05	POSS. ENGINE OIL LOSS A/C FUEL PUMP (SB 298) <i>P/C/W</i>	
66-20-04	OIL FILTER ADAPTER GASKET (SB 307) <i>NA BY PUMP PART NUMBER</i>	
73-23-01	PISTON PINS (O-360) SB 367F <i>SL12795 INSTALLED FROM GASKET SET</i>	
74-26-09	DRIVE BUSHINGS BENDIX/TCM (SB 556B) <i>(4) LW14078 PISTON PINS INSTALLED</i>	
75-08-09R3	OIL PUMP FAILURES (O,HO-360) SB 381B/385C <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
78-09-07R3	IMPULSE MEASUREMENT BENDIX/TCM SB 645 <i>AEL 78531 PUMP W/ AEL 18109-10 IMPELLERS</i>	S/S BY 96-12-07
78-18-04	2000 SERIES MAGNETO (SB 590A) <i>NA TO MODEL</i>	
79-10-03R2	ENGINE MOUNT BRACKET ATTACH BOLTS (O-360) SI 1380 <i>NA TO MODEL</i>	
79-12-07	GREEN BLOCK 2000 SERIES (SB 606) <i>NA TO MODEL</i>	
79-15-02	INTERNAL ECONOMIZER CHANNEL PLUG REPLACEMENT <i>NA TO MODEL</i>	
79-18-06 R1	2000 SERIES MAGNET (SB 605A) <i>NA TO MODEL</i>	
80-02-13	TURBO OIL DRAIN FLANGE (TO-360-C) SB 426 <i>NA TO MODEL</i>	
80-04-03R2	UPPER SPRING SEATS (SB 435) <i>NA TO MODEL</i>	
80-14-07	UPPER SPRING SEATS (O,LO-360) SB 447 <i>NA TO MODEL</i>	
80-17-14	2000 SERIES MAGNET (SB 605A) <i>NA TO MODEL</i>	
81-12-06R1	3000 SERIES GEAR INSPECTION (SB 618/619) <i>NA TO MODEL</i>	
81-18-04R2	FAILURE OF OIL PUMP GEARS (SB 455A/456)	S/S 96-09-10
82-11-05	2000 SERIES GEAR INSPECTION (SB 617B) <i>NA TO MODEL</i>	
82-13-01	GREEN BLOCK 1200 SERIES (SB 613) <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	<i>UP</i>

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
FAA APPROVED REPAIR STATION #JL4R288M
6001 NW 29 AVENUE
FORT LAUDERDALE, FL 33309

AIRWORTHINESS DIRECTIVE
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360 (CONT.)

MODEL *D-360-A4M* S/N *L-30677-36ACN10# 47301*

DATE *MAY 21, 2019*

ISSUE NO	DESCRIPTION	SIGNATURE
82-20-01	IMPULSE CAM SOFTNESS BENDIX/TCM (SB 623) <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	<i>[Signature]</i>
87-10-06R1	ROCKER ARM FAILURE (LW-18790) SB 477A <i>(4) 67444, (4) 74636 ROCKER ARMS</i>	
90-04-06R1	PROP. GOVERNOR LINE (ALL 4 CYLINDER ENGINES) SB 488A <i>NA TO MODEL</i>	
91-14-22	PREV. LOOSENING/FAILURE OF CRANKSHAFT BOLTS (SB 475C)	S/S 2004-10-14
92-12-05	PISTON PIN LW-14077 (SB 501) <i>(4) LW14077 PISTON PINS INSTALLED</i>	
92-20-07	FUEL PUMPS AERO ACCY	S/S 93-05-21
93-02-05	INJECTION LINES (SB 342D & SUPPLEMENT No. 1)	S/S 2002-26-01
93-05-21	FUEL PUMPS AERO ACCY	S/S 93-11-11
93-11-11	FUEL PUMPS AERO ACCY <i>NA TO MODEL</i>	
94-01-03R2	COIL AND MAGNET INSPECTION MSB 644 <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
94-06-09	CAPACITOR BATCH CODES (CSB 641) BENDIX/TCM <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
94-14-13	DETONATION DUE TO LOW OCTANE FUEL	S/S 95-26-02
94-25-04	HA-6 SERIES CARBURETOR <i>NA TO MODEL</i>	
95-07-01	75060 SUSPECT UNAPPROVED CONNECTING ROD BOLT <i>(8) NEW 5274694 BOLTS INSTALLED</i>	
95-26-02	DETONATION DUE TO LOW OCTANE FUEL <i>NA - PROP STRIKE INSPECTION</i>	
96-09-10C	REPLACEMENT OF OIL PUMP GEARS <i>AE47853: PUMP W/AE418109-10 IMPELLERS</i>	
96-12-07	INSPECTION OF TCM IMPULSE COUPLINGS	S/S 2005-12-06
96-23-03	LYCOMING LW-15473 HIGH PRESSURE FUEL PUMPS SB 525A <i>NA TO MODEL</i>	
97-01-03	RECALL OF PISTON PIN LW-14077 SB 527C	S/S 97-15-11 <i>[Signature]</i>

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
FAA APPROVED REPAIR STATION #JL4R288M
6001 NW 29 AVENUE
FORT LAUDERDALE, FL 33309

AIRWORTHINESS DIRECTIVE
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360 (CONT.)

MODEL *0-360-A4M* S/N *L-30677-36ACWIO# 47301*

DATE *MAY 21, 2019*

ISSUE NO	DESCRIPTION	SIGNATURE
97-15-11	RECALL OF PISTON PIN LW-14077 SB 527C <i>(4) LW14078 PISTON PINS INSTALLED</i>	<i>[Signature]</i>
98-01-06	ONE PIECE VENTURI & FUEL NOZZLE <i>P/C/W</i>	
98-02-08	PRECISION SB MSA -2,-7,-8,-9 <i>NA - SOLID SHAFT</i>	
98-17-11	INSPECTION OF PITTING ON CRANKSHAFTS MSB505B	
98-18-12	CRANKSHAFTS REPAIRED BY NELSON BALANCING SERVICE <i>SHAFT NOT REPAIRED BY NELSON</i>	
2000-18-53	AN FUEL PUMP LEAR ROMEC (MSB 529A)	S/S 2003-14-03
2002-12-07	OIL FILER BASE SEAL REPLACEMENT (MSB543A)	S/S 2002-12-07
2002-26-01	OIL FILTER SEAL REPLACEMENT (MSB543A) <i>NA TO MODEL</i>	S/S 2008-14-07
2003-14-03	INJECTION LINES	
2004-10-14C	LEAR ROMEC FUEL PUMP (SB529B) <i>NA TO MODEL</i>	
2005-0023R3	PREVENT LOOSENING OF CRANKSHAFT GEAR BOLT (MSB475C) <i>INSPECTED/INSTALLED PER</i> <i>MSB475C + SUPPL, 13519646 GEAR,</i> <i>NEW STD 2246 BOLT</i>	
2005-12-06	EASA EXHAUST VALVE AND GUIDE INSPECTION <i>NA - ALL H1-CHROME GUIDES</i>	
2005-19-11	INSPECTION OF TCM IMPULSE COUPLINGS <i>NEW CHAMPION MAGNETO KIT INSTALLED</i>	
2005-26-10	CRANKSHAFT REPLACEMENT (MSB566) <i>NA TO MODEL</i>	S/S 2006-12-07
2006-06-16	ECI CLASSIC CAST CYLINDERS	
2006-10-21 C2	CRANKSHAFT REPLACEMENT CMSB566 SUPP NO 1 TABLE 2 <i>NA TO MODEL</i>	
2006-12-07	REPLACEMENT OF CERTAIN AEL11750 CONN RODS <i>(4) 74502 RODS REINSTALLED</i>	
2006-20-09	ECI CLASSIC CAST CYLINDERS <i>ALL CYLINDERS ARE LYCOMING</i>	S/S 2012-19-01

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
FAA APPROVED REPAIR STATION #JL4R288M
6001 NW 29 AVENUE
FORT LAUDERDALE, FL 33309

AIRWORTHINESS DIRECTIVE
TEXTRON LYCOMING
O, HO, LO, TO, LTO-360 (CONT.)

MODEL <i>0-360-A4m</i> S/N <i>L-30677-36ACWIO# 47301</i>		DATE <i>MAY 31, 2019</i>
ISSUE NO	DESCRIPTION	SIGNATURE
2007-04-19R1	REMOVAL OF SUPERIOR CYLINDER WITH SOFT BARRELS. SUPERIOR B06-01E	<i>[Signature]</i>
	<i>ALL CYLINDERS ARE LYCOMING</i>	
2008-14-07	INJECTION LINES	S/S 2011-26-04
2008-19-05	INSPECTION & REPLACEMENT OF ECI TITAN CYLINDERS	S/S 2009-26-12
2008-08-14	PRECISON AIRMOTIVE MSB N. PRS107 REV 1 AND PEX-1	S/S 2009-02-03
2009-02-03	PRECISION AIRMOTIVE MSB NO. PRS107 REV. 4 & PEX-1 INSPECT BRASS PLUG S/N 383493 SEE SI 1520	
2009-26-12	<i>NA TO MODEL</i> INSPECTION & REPLACEMENT OF ECI TITAN CYLINDERS <i>ALL CYLINDERS ARE LYCOMING</i>	
2010-07-08	REMOVAL OF TURBOCHARGERS AS PER KELLY AEROSPACE SB NO. 039	
2011-13-03	<i>NA TO MODEL</i> CLEANING OF MACHINING DEBRIS FROM TURBOCHARGER CENTER HOUSINGS (HARTZELL S.B. NO. 040 REV.A)	
2011-15-10	<i>NA TO MODEL</i> AVSTAR SERVO DIAPHRAGM REPLACEMENT	S/S 2012-03-06
2011-26-04	INJECTION LINES (SB 342 F)	S/S 2015-19-07
2011-26-07	MANDATORY REPLACEMENT OF CERTAIN SLICK MAGNETOS	
2012-03-06	<i>NEW CHAMPION MAGNETO KIT INSTALLED</i> AVSTAR SERVO DIAPHRAGM REPLACEMENT	
2012-03-07	<i>NA TO MODEL</i> BILLET HA-6 CARBURETOR REPLACEMENT	
2012-19-01	<i>NA TO MODEL</i> CRANKSHAFT REPLACEMENT (MSB569A)	
2015-02-07	<i>NA TO MODEL</i> PROPELLER GOVERNOR SET SCREW INSTALLATION	
2017-16-11	<i>NA TO MODEL</i> CONNECTING ROD BUSHINGS MSB 632B <i>ALL RODS REBUSHED, HAZEL 13923 BUSHINGS</i>	<i>[Signature]</i>

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

AIRMARK OVERHAUL, INC.
REPAIR STA. #JL4R288M

Engine Inspection Checklist After Propeller Strike for All Lycoming Engines - Except Geared Engines

Engine Model: 0-360-A4M

Engine Serial Number: L-30677-36AC

Date Inspection Started: 4-16-19

Date Inspection Completed: MAY 21, 2019

Sequential Task		Additional Information	Corrective Action Done/Comments
1.	Examine the propeller for extent of damage; record condition of propeller.	Condition of Propeller/Corrective Action: <input type="checkbox"/> Propeller satisfactory <input type="checkbox"/> Repair propeller in accordance with propeller manufacturer's instructions <input type="checkbox"/> Replace propeller in accordance with the airframe manufacturer's instructions.	<i>CUSTOMER RESPONSIBILITY</i>
2.	Remove the propeller.	As per the airframe and propeller manufacturer's instructions.	
3.	Remove the engine.	In accordance with the airframe manufacturer's instructions.	

CRANKCASE P/N:

MATCH NO:

4.	Disassemble the engine - remove the crankshaft, camshaft, connecting rods, crankshaft gear, and internal steel parts.	In accordance with the applicable Lycoming engine manual.	OK
5.	Complete blast cleaning of the crankcase with 17 grit walnut shells or equivalent at 35 to 45 psi (241 to 310 kPa); remove all coatings on the crankcase and engine mount bosses.	Make sure there is no dirt, debris, sludge, paint, or any other substance that could prevent reliable Fluorescent Penetrant Inspection (FPI) or subsequent oil flow.	OK
6.	Complete blast cleaning of the oil sump and engine mount bosses with 17 grit walnut shells or equivalent at 35 to 45 psi (241 to 310 kPa).	Make sure there is no dirt, debris, sludge, paint, or any other substance that could prevent reliable FPI or subsequent oil flow.	OK
7.	Complete blast cleaning of the engine mount brackets (on six-cylinder engines) and, if used, the lower mount rings (on helicopter engines) with 17 grit walnut shells or equivalent at 35 to 45 psi (241 to 310 kPa).	Make sure there is no dirt, debris, sludge, paint, or any other substance that could prevent reliable FPI or subsequent oil flow.	NA- INTEGRAL TO CRANKCASE
8.	Complete blast cleaning of the accessory housing with 17 grit walnut shells or equivalent at 35 to 45 psi (241 to 310 kPa).	Make sure there is no dirt, debris, sludge, paint, or any other substance that could prevent reliable FPI or subsequent oil flow.	OK

ISSUED			REVISED			PAGE NO.	REVISION	S.B. 533
MO	DAY	YEAR	MO	DAY	YEAR	3 of 16	C	
06	29	98	10	18	16			

Engine Inspection Checklist After Propeller Strike for All Lycoming Engines - Except Geared Engines (Cont.)

Sequential Task		Additional Information	Corrective Action Done/Comments
9.	Remove and discard the existing crankshaft gear retaining bolt and lockplate.		OK
10.	Examine the crankshaft.	Refer to the applicable Lycoming engine manual and the latest revision of the Service Table of Limits - SSP-1776 for the crankshaft disassembly and inspection procedures.	INSPECTED GOOD LP
11.	Examine, the crankshaft counter-bored recess, the alignment dowel especially at the base where it goes into the crankshaft, the bolt hole threads, and the crankshaft gear for wear, galling, corrosion, and fretting.	Refer to the latest revision of Service Bulletin No. SB-475. If the bolt hole threads are damaged, they cannot be repaired. Replace the crankshaft.	INSPECTED GOOD LP
12.	Clean the crankshaft, camshaft, crankshaft gear, counterweights, rollers and bushings.	Make sure there is no dirt, debris, sludge, paint, or any other substance that could prevent reliable magnetic particle inspection or subsequent oil flow.	OK
13.	Clean the following internal parts made of steel: <ul style="list-style-type: none"> • Connecting rods • Tappets (not roller tappets) • Piston pins • Rocker shafts • Accessory drive gears • Magneto drive gears • Idler and oil pump shafts • Shaft gears and impellers 		OK

⚠ CAUTION: BASED UPON THE ACCUMULATED ENGINEERING, TECHNICAL, AND HISTORICAL DATA AVAILABLE, LYCOMING ENGINES PROHIBITS STRAIGHTENING OR GRINDING OF BENT CRANKSHAFT PROPELLER FLANGES TO RESTORE MAXIMUM RUN-OUT SPECIFICATION AS NOTED IN THE LATEST REVISION OF THE SERVICE TABLE OF LIMITS - SSP-1776. IF THE CRANKSHAFT PROPELLER FLANGE IS BENT, REPLACE THE CRANKSHAFT. DO NOT TRY TO STRAIGHTEN OR GRIND THE CRANKSHAFT PROPELLER FLANGE.

ISSUED			REVISED			PAGE NO.	REVISION	S.B. 533
MO	DAY	YEAR	MO	DAY	YEAR	4 of 16	C	
06	29	98	10	18	16			


**Engine Inspection Checklist After Propeller Strike for All Lycoming Engines - Except Geared Engines
(Cont.)**

CRANKSHAFT P/N: 13B27134

S/N: V537931

Sequential Task		Additional Information	Corrective Action Done/Comments
14.	Measure the flange run-out on the crankshaft.	Refer to the latest revisions of both Service Bulletin No. SB-240 and the Service Table of Limits - SSP-1776 for crankshaft flange run-out tolerance. Record the crankshaft flange run-out measurement.*	<input checked="" type="checkbox"/> Use crankshaft <input type="checkbox"/> Replace crankshaft <i>REFER TO AD-108</i>
15.	Measure the main bearing run-out on the crankshaft.	Refer to the latest revision of the Service Table of Limits - SSP-1776 for the main bearing run-out tolerance Record the main bearing run-out measurement.*	<input checked="" type="checkbox"/> Use crankshaft <input type="checkbox"/> Replace crankshaft <i>REFER TO AD-108</i>
16.	Measure the polished dimensions on the main journals.	Refer to the latest revision of the Service Table of Limits - SSP-1776 for the dimensions on the main journals Record the dimensions of the main journals.* <i>REFER TO AD-108</i>	<input checked="" type="checkbox"/> Main journals within acceptable limits - use crankshaft <input type="checkbox"/> Replace crankshaft
17.	Measure the polished dimensions on the pin journals.	Refer to the latest revision of the Service Table of Limits - SSP-1776 for the dimensions on the pin journals Record the dimensions of the pin journals.* <i>REFER TO AD-108</i>	<input checked="" type="checkbox"/> Pin journals within acceptable limits - use crankshaft <input type="checkbox"/> Replace crankshaft

* If the measurement or dimension is out of tolerance, discard the crankshaft and replace it with a serviceable crankshaft. Install the crankshaft per the applicable Lycoming manual and the latest revision of the Service Table of Limits - SSP-1776.

18.	Complete a check of connecting rod parallelism.	Refer to the section "Connecting Rod Parallelism/Squareness Check" in this Service Bulletin. Record the parallelism measurement for each connecting rod. Replace all connecting rods not in compliance with measurements in the latest revision of the Service Table of Limits - SSP-1776 (Reference 503).	Parallelism Measurement	
			Connecting Rod 1	.0000
			Connecting Rod 2	.0000
			Connecting Rod 3	.0000
			Connecting Rod 4	.0000
			Connecting Rod 5	
			Connecting Rod 6	
			Connecting Rod 7	
			Connecting Rod 8	

ISSUED			REVISED			PAGE NO.	REVISION	S.B. 533
MO	DAY	YEAR	MO	DAY	YEAR	5 of 16	C	
06	29	98	10	18	16			

Engine Inspection Checklist After Propeller Strike for All Lycoming Engines - Except Geared Engines (Cont.)

Sequential Task		Additional Information	Corrective Action Done/Comments	
19.	Complete a check of connecting rod squareness.	Refer to the section "Connecting Rod Parallelism/Squareness Check" in this Service Bulletin. Record the squareness measurement for each connecting rod. Replace all connecting rods not in compliance with measurements in the latest revision of the Service Table of Limits - SSP-1776 (Reference 504).	Squareness Measurement	
			Connecting Rod 1	0000
			Connecting Rod 2	0000
			Connecting Rod 3	0000
			Connecting Rod 4	0000
			Connecting Rod 5	
			Connecting Rod 6	
			Connecting Rod 7	
			Connecting Rod 8	

NOTICE: The magnetic particle inspection must be done by a certified technician as per the latest revision of Service Instruction No. SI-1285.

20.	Complete a magnetic particle inspection on the crankshaft.	Record test results.	<input checked="" type="checkbox"/> Use crankshaft <input type="checkbox"/> Replace crankshaft	REFER TO AD-112
21.	Complete a magnetic particle inspection on the crankshaft counterweights. Examine the counterweight bushing bores in both the counterweights and the crankshaft.	Record test results.	Replace all counterweight pins, bushings, end plates and snap rings - regardless of their condition.	
22.	Complete a magnetic particle inspection on the camshaft.	Record test results.	<input checked="" type="checkbox"/> Use camshaft <input type="checkbox"/> Replace camshaft	SENT FOR REGRIND
23.	Complete a magnetic particle inspection on the connecting rods.	Record test results. OK REFER TO AD-112	Replace connecting rod bolts and nuts - regardless of condition. Refer to the latest revision of Service Instruction No. SI-1458 for assembly instructions.	
24.	Complete a magnetic particle inspection on the crankshaft gear; examine the gear end as per the latest revision of Service Bulletin No. SB-475.	Record test results.	<input checked="" type="checkbox"/> Use crankshaft gear <input type="checkbox"/> Replace crankshaft gear	REFER TO AD-112
25.	Complete a magnetic particle inspection on the following internal parts made of steel: <ul style="list-style-type: none"> Accessory drive gears Magneto drive gears Idler and oil pump shafts Shaft gears and impellers Piston pins Connecting rods 	Record test results. REFER TO AD-112	Use Replace <input checked="" type="checkbox"/> <input type="checkbox"/> Accessory drive gears <input checked="" type="checkbox"/> <input type="checkbox"/> Magneto drive gears <input checked="" type="checkbox"/> <input type="checkbox"/> Idler and oil pump shafts <input checked="" type="checkbox"/> <input type="checkbox"/> Shaft gears and impellers <input checked="" type="checkbox"/> <input type="checkbox"/> Piston pins <input checked="" type="checkbox"/> <input type="checkbox"/> Connecting rods	

ISSUED			REVISED			PAGE NO.	REVISION	
MO	DAY	YEAR	MO	DAY	YEAR	6 of 16	C	S.B. 533
06	29	98	10	18	16			

Engine Inspection Checklist After Propeller Strike for All Lycoming Engines - Except Geared Engines (Cont.)

Sequential Task		Additional Information	Corrective Action Done/Comments
26.	Complete the visual inspection and Fluorescent Penetrant Inspection (FPI) on the crankcase. Refer to the latest revision of Service Instruction No. SI-1285. Closely examine the forward crankcase bearing support and adjacent structure.	Record test results. <i>REFER TO AO-113</i>	<input checked="" type="checkbox"/> Use crankcase <input type="checkbox"/> Replace crankcase
27.	Complete the visual inspection and FPI on the oil sump.	Record test results. <i>REFER TO AO-113</i>	<input checked="" type="checkbox"/> Use oil sump <input type="checkbox"/> Replace oil sump
28.	Complete the visual inspection and FPI on the engine mounts and, if used, the lower mount rings (on helicopter engines).	Record test results. <i>NA</i>	<input type="checkbox"/> Use engine mounts <input type="checkbox"/> Replace engine mounts
29.	Complete the visual inspection and FPI on the accessory housing.	Record test results. <i>REFER TO AO-113</i>	<input checked="" type="checkbox"/> Use accessory housing <input type="checkbox"/> Replace accessory housing
30.	Complete the visual inspection on the oil pump impeller.	Record test results.	<input checked="" type="checkbox"/> Use impeller <input type="checkbox"/> Replace impeller

NOTICE: Roller tappets, counterweight rollers, and bushings must be replaced.

31.	Complete the visual inspection and FPI on the tappets (not roller tappets) and lifters. Refer to the latest revision of Service Instruction No. SI-1011.	Record test results. <i>REPLACED FOR PITTING</i>	<input type="checkbox"/> Tappets/lifters acceptable <input checked="" type="checkbox"/> Replace tappets/lifters
32.	Examine each magneto in accordance with the magneto manufacturer's instructions.	Record test results.	<input checked="" type="checkbox"/> Replace magneto
33.	Examine the pistons as per instructions in the applicable Lycoming manual and the latest revision of the Service Table of Limits - SSP-1776.	Record test results.	<input checked="" type="checkbox"/> Pistons acceptable <input type="checkbox"/> Replace pistons
34.	Refer to the latest revision of Service Bulletin No. SB-240 to identify any parts that must be replaced during engine assembly.	Record parts that must be replaced.	<i>REFER TO PARTS LIST</i>
35.	Install a new crankshaft gear retaining bolt and lockplate.	Refer to the latest revision of Service Bulletin No. SB-475.	<i>OK</i>

ISSUED			REVISED			PAGE NO.	REVISION	S.B. 533
MO	DAY	YEAR	MO	DAY	YEAR	7 of 16	C	
06	29	98	10	18	16			

**Engine Inspection Checklist After Propeller Strike for All Lycoming Engines - Except Geared Engines
(Cont.)**

Sequential Task		Additional Information	Corrective Action Done/Comments
36.	Review the documents of all other engine-mounted accessories on the engine, propeller governor (if installed), etc. for instructions on what to do for components exposed to sudden engine stoppage.		<i>CUSTOMER RESPONSIBILITY</i>
37.	Assemble and install the engine. Install the propeller and test the engine. Complete an operational check of the engine.	In accordance with instructions in the applicable Lycoming engine manuals, the latest revisions of the Service Table of Limits - SSP-1776 and Service Instruction No. SI-1427.	<i>TEST RUN GOOD REFER TO AD-115.</i>
38.	Record maintenance findings and any corrective action in the engine logbook.		<i>OK</i>

UNAIRWORTHY PARTS:

NO UNAIRWORTHY PARTS RESULTING FROM PROPELLER STRIKE.

ADDITIONAL WORK/INSPECTIONS NECESSARY:

NONE FOR ENGINE AS SHIPPED.

OUTCOME OF INSPECTION- SUMMARY NOTES:

ENGINE, AS SHIPPED, IS AIRWORTHY.

ISSUED			REVISED			PAGE NO.	REVISION	S.B. 533
MO	DAY	YEAR	MO	DAY	YEAR			
06	29	98	10	18	16	8 of 16	C	



652 Oliver Street
Williamsport, PA 17701 U.S.A.

Telephone +1 (800) 258-3279 (U.S. and Canada)

Telephone +1 (570) 323-6181 (International)

Facsimile +1 (570) 327-7101

www.lycoming.com

MANDATORY SERVICE BULLETIN

DATE: October 18, 2016

Service Bulletin No. 533C
(Supersedes Service Bulletin No. 533B)
Engineering Aspects are
FAA Approved

SUBJECT: Recommended Action for Sudden Engine Stoppage, Propeller/Rotor Strike or Loss of Propeller/Rotor Blade or Tip

MODELS AFFECTED: All Lycoming reciprocating aircraft engines

TIME OF COMPLIANCE: BEFORE FURTHER FLIGHT

REASON FOR REVISION Applies to all Lycoming aircraft engines (not just direct drive engines); added checklist specific for Lycoming geared engines; updated checklist which applies to all other Lycoming aircraft engines, added check for connecting rod squareness to the checklists.

NOTICE: Incomplete review of all the information in this document can cause errors. Read the entire Service Bulletin to make sure you have a complete understanding of the requirements.

This Service Bulletin identifies propeller/rotor damage conditions and gives corrective action recommendations for aircraft engines that have had propeller/rotor damage as well as any of the following:

- Separation of the propeller/rotor blade from the hub
- Loss of a propeller or rotor blade tip
- Sudden stoppage

A propeller strike includes:

- Any incident, whether or not the engine is operating, where repair of the propeller is necessary
- Any incident during engine operation where the propeller has impact on a solid object. This incident includes propeller strikes against the ground. Although the propeller can continue to turn, damage to the engine can occur, possibly with progression to engine failure
- Sudden RPM drop on impact to water, tall grass, or similar yielding medium where propeller damage does not usually occur

A propeller strike can occur at taxi speeds and during touch-and-go operations with propeller tip ground contact. In addition, propeller strikes also include situations where an aircraft is stationary and a landing gear collapse occurs causing one or more blades to be bent, or where a hangar door (or other object) hits the propeller blade. These instances are cases of sudden engine stoppage because of potentially severe side loading on the crankshaft propeller flange, front bearing, and seal.



General Aviation
Manufacturers Association

ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR	1 of 16	C
06	29	98	10	18	16		

©2016 by Avco Corporation. All Rights Reserved.
Lycoming Engines is a division of Avco Corporation

⚠ CAUTION: BASED UPON THE ACCUMULATED ENGINEERING, TECHNICAL, AND HISTORICAL DATA AVAILABLE, LYCOMING ENGINES **PROHIBITS** STRAIGHTENING OR GRINDING OF BENT CRANKSHAFT PROPELLER FLANGES TO RESTORE MAXIMUM RUN-OUT SPECIFICATION AS NOTED IN THE LATEST REVISION OF THE SERVICE TABLE OF LIMITS - SSP-1776. IF THE CRANKSHAFT PROPELLER FLANGE IS BENT, REPLACE THE CRANKSHAFT. **DO NOT TRY TO STRAIGHTEN OR GRIND THE CRANKSHAFT PROPELLER FLANGE.**

Recommended Corrective Action for Propeller Strikes


⚠ CAUTION: DAMAGE TO A PROPELLER IS SERIOUS AND CAN CAUSE THE ENGINE TO BE UNAIRWORTHY.

Circumstances of a propeller strike cannot always be used as predictors for the extent of engine damage or its future reliability. There can be varying degrees of damage to an engine and propeller from a propeller strike. The initial damage can be hidden but could become progressively worse with time and wear.

Given these possibilities and the fact that there is no identified clear, quantifiable threshold limit or gradient standard to reliably measure the extent of damage to an engine, Lycoming Engines can only recommend BEFORE FURTHER FLIGHT, that you complete the tasks in the sequential order shown in the applicable "Inspection Checklist After a Propeller Strike" included in this Service Bulletin as the corrective action for a propeller strike. One checklist applies specifically to Lycoming geared engines (GO-435, GO-480, GSO-480, IGO-480, IGO-540, IGSO-540, and TIGO-541) while the other checklist is for all other Lycoming aircraft engines. Make a copy of the checklist that applies to your engine model, complete it and keep it as a service record. Record all results and any corrective action taken in compliance as per the revision of this Service Bulletin in the engine logbook.

NOTICE: The agency that returns the aircraft to service is responsible for the decision to operate an engine that had a propeller strike. Lycoming Engines does not take the responsibility for the decision to return the engine to service after a propeller strike.


ISSUED			REVISED			PAGE NO.	REVISION	S.B. 533
MO	DAY	YEAR	MO	DAY	YEAR	2 of 16	C	
06	29	98	10	18	16			

1. Approving Civil Aviation Authority/Country: FAA/United States		2.		3. Form Tracking Number: 47301	
4. Organization Name and Address: AIRMARK OVERHAUL, INC. * 6001 N.W. 29 TH AVENUE * FT. LAUDERDALE, FL 33309 (JL4R288M)				5. Work Order/Contract/Invoice Number: W/O: 47301	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
001	ENGINE	O-360-A4M	1/EA	L-30677-36AC	REPAIRED
12. Remarks: THIS TEXTRON LYCOMING ENGINE WAS REPAIRED AS NEEDED DUE TO A PROPELLER STRIKE ONLY IN ACCORDANCE WITH TEXTRON LYCOMING OVERHAUL MANUAL 60294-7, REV. #14. SEE FULL DETAILS OF WORK AND A.D.'s CARRIED OUT PER WORK ORDER NUMBER 47301. TIME SINCE MAJOR OVERHAUL 1126.1 HOURS.					
<div>13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.</div>			<div>14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.</div>		
13b. Authorized Signature:		13c. Approval/Authorization No.:		14c. Approval/Certificate No.:	
<div>13d. Name (Typed or Printed):</div>		<div>14b. Authorized Signature: </div>		JL4R288M	
<div>13e. Date (dd/mm/yyyy):</div>		<div>14d. Name (Typed or Printed): WILLIAM POLLARD</div>		<div>14e. Date (dd/mm/yyyy): 21/MAY/2019</div>	
User/Installer Responsibilities					
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.</p> <p>Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>					

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: JDM19031-81365133	
4. Organization Name and Address: LORD Corporation, 124 Grant Street, Cambridge Springs, PA 16403 USA (PQ0466NE)					5. Work Order/Contract/Invoice Number: 2558716	
6. Item: 1	7. Description: Mounting Kit	8. Part Number: J-9613-40	9. Quantity: 250 pcs.	10. Serial Number: N/A	11. Status/Work: NEW	
12. Remarks: Reference Lord FAA/PMA Supplement No. 25. Batch No.: 0011922544 Cure Date (mm-yy): 214 pcs at (07-18) and 36 pcs at (10-18) Shelf Life: Five (5) years from cure date when stored in the manner prescribed in order to minimize deterioration due to such factors as temperature, humidity, ozone, sunlight, oils, solvents, corrosive liquids and fumes, insects and rodents. Reference MIL-HDBK-695.						
13a. Certifies the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> Approved design data and are in condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.						
13b. Authorized Signature: <i>Jason MacQuarrie</i>		13c. Approval/Authorization No.: PQ0466NE		14a. <input type="checkbox"/> 14 GFR 4B.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
14b. Authorized Signature: <i>Jason MacQuarrie</i>		14c. Approval/Certificate No.:		14d. Name (Typed or Printed):		
14d. Name (Typed or Printed): Jason MacQuarrie		13e. Date (dd/mm/yyyy): 13/Feb/2019		14e. Date (dd/mm/yyyy):		
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: ST0930426	
4. Organization Name and Address: Piper Aircraft, Inc. 2926 Piper Drive Vero Beach, FL 32960 USA		PC 206			5. Work Order / Contract / Invoice Number: ST0930426 / 210008000 / SH0148369 Page 1 of 1	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work Order:	
10	NUT	404-891	200	N/A	NEW	
12. Remarks: Airworthiness Approval						
13a. Certifies the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> Approved design data and are in condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.		14a. <input type="checkbox"/> 14 CFR 43.9 Return to Service/ <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 1 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.				
13b. Authorized Signature: <i>James Wilson</i>		13c. Approval/Authorization No: PC206		14c. Approval/Certificate No.:		
13d. Name (Typed or Printed): Wilson, James		13e. Date (dd/mm/yyyy): 08/Nov/2018		14d. Name (Typed or Printed):		
14e. Date (dd/mm/yyyy):						
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: ST0925915	
4. Organization Name and Address: Piper Aircraft, Inc. 2926 Piper Drive Vero Beach, FL 32960 USA		PC 206		5. Work Order / Contract / Invoice Number: ST0925915 / 210008000 / SH0134764 Page 1 of 1	
6. Item: 10	7. Description: WASHER	8. Part Number: 690-630	9. Quantity: 500	10. Serial Number: N/A	11. Status/Work Order: NEW
12. Remarks: Airworthiness Approval					
13a. Certifies the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> Approved design data and are in condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.			14a. <input type="checkbox"/> 14 CFR 43.9 Return to Service/ <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 12 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature: <i>James Wilson</i>		13c. Approval/Authorization No: PC206		14c. Approval/Certificate No.	
13d. Name (Typed or Printed): Wilson, James		13e. Date (dd/mm/yyyy): 07/Jun/2018		14d. Name (Typed or Printed):	
14e. Date (dd/mm/yyyy):					
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.					
Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: ST0931735	
4. Organization Name and Address: Piper Aircraft, Inc. 2926 Piper Drive Vero Beach, FL 32960 USA		5. Work Order / Contract / Invoice Number: ST0931735 / 210008000 / SH0148110		Page 1 of 1	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work Order:
10	BOLT STEEL HEX HEAD PLATED	401-543	10	N/A	NEW
12. Remarks: Airworthiness Approval					
13a. Certifies the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> Approved design data and are in condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.			14a. <input type="checkbox"/> 14 CFR 43.9 Return to Service / <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 12 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature: 		13c. Approval/Authorization No: PC206		14c. Approval/Certificate No.:	
13d. Name (Typed or Printed): Wilson, James		13e. Date (dd/mm/yyyy): 07/Nov/2018		14e. Date (dd/mm/yyyy):	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.					
Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1. Approving Civil Aviation
Authority/Country:
FAA/UNITED STATES

2. **AUTHORIZED RELEASE CERTIFICATE**
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
ST0931735

4. Organization Name and Address:
**Piper Aircraft, Inc.
2926 Piper Drive
Vero Beach, FL 32960 USA**

PC 206

5. Work Order / Contract / Invoice Number:
ST0931735 / 210008000 / SH0148110
Page 1 of 1

6. Item:

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

10 BOLT STEEL HEX HEAD PLATED

401-543

10 N/A

NEW

12. Remarks: Airworthiness Approval

13a. Certifies the items identified above were manufactured in conformity to:

☒ Approved design data and are in condition for safe operation.

☐ Non-approved design data specified in Block 12.

13b. Authorized Signature:

13d. Name (Typed or Printed):
Wilson, James

13c. Approval/Authorization No:
PC206

14b. Authorized Signature:

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

14a. ☐ 14 CFR 43.9 Return to Service / ☐ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 12 and described in Block 12 was accomplished in accordance with title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

14c. Approval/Certificate No.

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Civil Aviation
Authority/Country:
FAA/UNITED STATES

2. **AUTHORIZED RELEASE CERTIFICATE**
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
ST0925370

4. Organization Name and Address:
Piper Aircraft, Inc.
2926 Piper Drive
Vero Beach, FL 32960 USA

PC 206

5. Work Order / Contract / Invoice Number:
ST0925370 / 210008000 / SH0146294
Page 1 of 1

6. Item: 7. Description: 8. Part Number:

10 BULKHEAD ASSY-SPINNER (181)

65804-000

9. Quantity: 6

10. Serial Number: N/A

11. Status/Work:

NEW

12. Remarks: Airworthiness Approval

13a. Certifies the items identified above were manufactured in conformity to:

☒ Approved design data and are in condition for safe operation.

☐ Non-approved design data specified in Block 12.

14a. ☐ 14 CFR 43.9 Return to Service/ ☐ Other regulation specified in Block 12

☐ Certifies that unless otherwise specified in Block 12, the work identified in Block 14a and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

James Wilson

13c. Approval/Authorization No:

PC206

14b. Authorized Signature:

14d. Name (Typed or Printed):

13d. Name (Typed or Printed):
Wilson, James

13e. Date (dd/mm/yyyy):
16/Oct/2018

14c. Approval/Certificate No.

14e. Date (dd/mm/yyyy):

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.