


Lecture 15

Powder Processing

Agglomeration:

↳ agglomerated particle would always reduce packing density because of irregular shape.

→ Cohesive forces causes agglomeration.



$\theta > 45^\circ \Rightarrow$ high cohesive forces
high agglomeration tendency

θ low \Rightarrow good flowability,
{ $0-20^\circ$ } low cohesive force
low agglomeration tendency

→ De-Agglomeration can be accomplished by
a combination of drying, milling &
surface treatments.

Functionalised surface: surface treatment

- 2) Calculate X_c that would yield best packing fraction, if it known that smaller particles pack in loose random packing and larger particles acquire dense random packing, when required.

$$PF_{\text{fine}} = 0.6$$

$$PF_{\text{coarse}} = 0.64$$

$$\leftarrow PF_{\text{app}} = PF_c + PF_f (1 - PF_c)$$

$$PF_{\text{app}} = 0.64 + 0.6 (0.34) \\ = 0.844$$

$$PF_{\text{app}} = PF_f + X_c (1 - PF_f)$$


$$0.844 = 0.6 + X_c (0.4)$$

$$0.244 = X_c \times 0.4$$

$$\boxed{X_c = 0.61}$$

Powder Compaction:

Stages in Compaction: tapping, rearrangement,
↳ 3rd stage = fracture
in case of ceramics.





→ Saturation (decrease in slope)
due to Work Hardening

→ Hot/Warm Compaction:

↳ dynamic recovery & dynamic recrystallization can happen which soften and allow increase in strain.


→ not popular as high surface area allows for rapid oxidation.



↳ Typical green density :

- Metals $> 85\%$
- Ceramics $< 60\%$

★ Al - softest (fcc)
 Steel \rightarrow Hardest (bcc)
 Mg \rightarrow brittle (hcp)






Hardness \propto Melting Temperature.

Friction Analysis

→ friction can cause varying pressure across the pattern along the depth & radius.

→ friction decides spatial distribution of pressure.



$$P_T > P_B \Rightarrow P_T - P_B = dP$$

$$F_f = \mu F_N$$

↳ coefficient of restitution.

$$F_N = z(P_T)(\pi D)(dH)$$

$$F_f = \mu z P_T \pi D dH$$

Apply force balance:

$$A(P_T - P_B) + \mu F_N = 0$$

$$A dP = -\mu F_N$$

$$\frac{\pi D^2}{4} dP = -\mu Z P_T \pi D dh$$

$$\int_{P_T}^P dP = - \int_0^H \frac{4\mu Z P_T}{D} dh$$

$$\ln\left(\frac{P}{P_0}\right) = -\frac{4\mu Z h}{D}$$

$$P = P_0 \exp\left(-\frac{4\mu Z h}{D}\right)$$

decaying of pressure.

→ not acceptable as
for low pressure
more shrinkage
takes place.

→ tapered compact formed
after sintering.

