

## Lecture 17

# Polymer Processing

→ Defects in injection molded parts:

▷ Sink marks:

- small depressions or recesses
- occur on flat and consistent surfaces
- shrinkage of solidifications.

\* Volumetric change of plastic from melt to solid is about 25%

↳ In injection molding compressibility is only 15%.

To reduce sink marks:

↳ reduce the thick wall size of the mold material


↳ increase holding time and pressure:

2) Jetting:

↳ depicts behaviour of how molten material is entering mold by jet.



low injection  
speed



high injection  
speed.

→ The jet of

3) **Short Shot**: incomplete mold

→ molten material does not flow into all sections of mold.

- common for high viscosity melts,
- trapped air pockets hinder melt flow.

\* 5 parts/min for complex geometries

100 parts/min for simple geometries

↳ hence industrially favourable for mass production of thermoplasts.

↳ has minimal wastage of material, minimal tolerances.

# Compression Moulding:

- ↳ typically used for thermosets.
- ↳ low cost molding methods.
- ↳ high pressure forming process.
- ↳ The charge (thermosets) is heated by means of the hot mold to polymerize under heat and pressure.

Lubricants used: Teflon / silicone.

## Disadvantages:


- ↳ Low production rate
- ↳ reject parts cannot be reprocessed.
- limited largely to simple geometries with no undercuts. (flat products)

# Blow Moulding:

↳ Extruder + Air hose

↓  
produce charge (molten materials)  
for the moulding unit.

\* Parison: charge for blow moulding.



↳ hollow parts are made like bottle or sphere

→

Disadvantages:

↳ Limited to hollow parts

↳ Thick parts can't be manufactured.

Blow-Up ratio:  $BUR = \frac{D_{final}}{D_{parison}}$



area ratio =  $BUR^2$

↳ relation between stretch and thickness  
(incompressible material)

$$t_f = \frac{t_0}{\lambda_1 \lambda_2}$$

## Thermofforming:

↳ restricted to thermoplastics.



↳ Disadvantages:

↳ limited shape complexity



↳ internal stresses are produced.

↳ Trimming is required.

## Resume

# Powder Compaction

$$P(h) = P_0 \exp\left(-4\frac{\mu z h}{D}\right)$$




heat  
(sinter)



Shrinkage  
due to  
solidification.


→ can be minimized by  $h/D$  is low.




green density gradient:



\* End Chipping:



→ easily chips off  
called end chipping.



→ Surface distribution of pressure.

\* Complex stress state generated on surface.

↳ trying to negate two friction forces.


{ combination of tensile + compression }

↳ Activation of stress state upon release of pressure results in chipping of sample.

↳ Can be taken care of by controlling 'u'.

# Sintering:

↳ coalescence of particles (densification may or may not occur). Effectively it is joining of particles.




\* How to justify densification  
If  $d$  reduces  $\Rightarrow$  it implies densification.

$\rightarrow$  does not mean sintering has occurred.

$\rightarrow$  Sintering is a coalescence process.

↳ Occurs by mass transport



\* Plastic Flow: compressive stresses induced due to Surface Tension (ST) when



powder is heated by sintering.



(uses) Neck  $\rightarrow$  grows as sintering continues.  
eventually neck disappears.

\* liquid & solid phase sintering:

{  
one phase is liquid  
or amorphous phase

particles of two  
kinds (crystalline  
+ polycrystalline phases)

Why do particles coalesce?

\* Surface Tension is the driving force for coalesce  
{thermodynamic aspect}

\* underlying atomic mechanisms. (how atoms  
move around).

$$\sigma(st) = \frac{2\gamma}{R}$$


$$\sigma = \gamma \left[ \frac{1}{R_1} + \frac{1}{R_2} \right]$$

radius of  
neck.

radius of 2 adjacent  
powder particles

$$r_n = \frac{x^2}{4D} \rightarrow \text{neck length}$$

$$\sigma_2 = \gamma \left[ \frac{2}{D} + \left( -\frac{4D}{x^2} \right) \right]$$



$$\sigma_1 = \gamma \left[ \frac{2}{D} + \frac{2}{D} \right] = \frac{4\gamma}{D}$$

$$D = 10 \mu m, x = 2 \mu m, \gamma = 1 \text{ Mpa} \cdot m$$

$$\sigma_1 = \frac{4 \times 1 \text{ Mpa} \cdot m}{10 \times 10^{-6}} = 4 \times 10^5 \text{ Mpa} = 0.4 \times 10^6$$

$$\begin{aligned} \sigma_2 &= 1 \text{ Mpa} \cdot m \left[ \frac{2}{10 \times 10^{-6}} - \frac{4 \times 10 \times 10^{-6}}{4 \times 10^{-12}} \right] \\ &= 1 \text{ Mpa} \cdot m \left[ \sqrt{0.98 \times 10^6} \right] \end{aligned}$$