

Notes

1. PCB

- a. The PCB does not reflect the digipot connections.
- b. There did not exist a 3d model for the STM board nor the linear pots and USB connector.
- c. Decoupling capacitors were excluded for simplicity but in implementation, did not make a noticeable difference in system operation.
- d. The USB connection lacks protection measures.
- e. It was not clear to me which pin the USB power should be connected to.
- f. There was a body of errors in the PCB which prescribed that I connect all my GND vias. I am unsure of why the software required this.
- g. There are holes in the PCB enclosure that serve as pilot holes for mounting the PCB.
- h. Because the linear pots lacked 3d models, it was moot to define the enclosure height with certainty.

2. Code

- a. The code does not account for the SPI digipot control, this will be completed in the future, then implemented on PCB.
- b. An external code library was utilized to control the LCD. This library can be found with explanation at <https://controllerstech.com/interface-lcd-16x2-with-stm32-without-i2c/>
- c. There is an error in the LCD string where the whole body of text shifts if a pot value decreases by a decimal place
- d. The code was unable to be integrated by the deadline. I suspect that it was an issue with the debugger driver or the system memory of the STM board. I was unable to find a conclusive answer as to this malfunction.