

VoltMeter (Arduino Uno) — Command & Setup Manual

Firmware Version: VoltMeter v1.2 (Memory Optimized)

1. Introduction

This manual explains all available **serial commands** for the VoltMeter firmware and provides a clear step-by-step guide to set up, calibrate, and operate the system. The commands are entered through the **Serial Monitor** (or any serial terminal) at **115200 baud** with **newline** line endings.

2. Basic Setup Procedure

Hardware Connection

1. **Voltage Divider Wiring:**
2. Connect the input voltage (Vin) → Top resistor (RTOP)
3. Connect midpoint between RTOP and RBOT → **A0**
4. Connect bottom resistor (RBOT) → **GND**
5. Make sure A0 never exceeds **5 V** (for DEFAULT reference) or **1.1 V** (for INTERNAL reference).
6. Power the Arduino from a stable USB or regulated 5 V supply.

Software Setup

1. Upload the VoltMeter firmware to your Arduino Uno.
2. Open **Serial Monitor** at **115200 baud**.
3. Set **line ending** to **Newline**.
4. You should see the startup report and the line:

Type HELP for commands.

3. Command Reference Table

Command	Function	Example	Description
HELP	Show help list	<div>HELP</div>	Lists all available commands with basic usage examples.

Command	Function	Example	Description
SETREF DEFAULT	Set ADC reference to Vcc (5V)	SETREF DEFAULT	Use the Arduino's operating voltage as reference. Suitable for mid-to-high voltage dividers.
SETREF INTERNAL	Set ADC reference to 1.1V	SETREF INTERNAL	Uses the internal bandgap reference for higher accuracy when A0 voltage \leq 1.1V.
SETREF AUTO	Auto-select reference	SETREF AUTO	The firmware tests the signal level and automatically picks DEFAULT or INTERNAL.
CAL <volts>	Calibrate using a known voltage	CAL 12.000	Runs calibration assuming the applied input is 12.000V. Calculates scale factor (K) and saves to EEPROM.
CAL <volts> RBOT <ohms>	Calibrate with known bottom resistor	CAL 12.000 RBOT 10000	Uses known RBOT to estimate RTOP from measured K.
CAL <volts> RTOP <ohms>	Calibrate with known top resistor	CAL 12.000 RTOP 22000	Uses known RTOP to estimate RBOT from measured K.
CAL <volts> [RBOT/RTOP] SAMPLES <n>	Calibrate with custom sample size	CAL 12.000 RBOT 10000 SAMPLES 512	Performs calibration using <n> samples for more precision.
PRINTCAL	Print current calibration data	PRINTCAL	Displays stored calibration info (K, vref, resistors, stats, CRC).
CLEARCAL / RESETCAL	Erase calibration	CLEARCAL	Clears calibration block from EEPROM. The voltmeter will require recalibration.
MEASURE	Take one reading	MEASURE	Captures a single ADC measurement and prints full stats and computed Vin.
LOG ON	Enable continuous logging	LOG ON	Starts automatic measurement every second (default interval: 1000 ms).
LOG OFF	Disable continuous logging	LOG OFF	Stops periodic measurement output.

Command	Function	Example	Description
FACTORYRESET <i>(optional)</i>	Reset calibration, settings, and counters	<code>FACTORYRESET</code>	Clears EEPROM calibration and resets counters to default values. <i>(Only available if added to sketch)</i>
FULLRESET <i>(optional, dangerous)</i>	Wipe entire EEPROM	<code>FULLRESET</code>	Erases all EEPROM memory (including boot counter). Use only for recovery. <i>(Optional, must be added manually)</i>

4. Step-by-Step Setup & Calibration

Step 1 — Power & Verify Communication

- Open Serial Monitor at **115200 baud**.
- You should see a startup banner like:

```

===== Voltmeter Startup =====
Firmware: VoltMeter v1.2 (mem-opt)
Boot Cnt: 5
EEPROM: No valid calibration (CRC fail or empty).
Run CAL <volts> [RBOT|RTOP] to calibrate.
=====

```

Step 2 — Choose Reference Mode

Depending on your divider ratio and input voltage range: - For **0-5 V ADC range**, type:

```
SETREF DEFAULT
```

- For **0-1.1 V ADC range**, type:

```
SETREF INTERNAL
```

- Or let the firmware decide automatically:

```
SETREF AUTO
```

Step 3 — Run Calibration

1. Apply a stable, known voltage (measured with a DMM) to the divider input (Vin).
2. Enter a calibration command such as:

```
CAL 12.000 RBOT 10000
```

3. The system will sample and calculate ratio $K = V_{in} / V_{adc}$, then save it to EEPROM.
4. Wait for the confirmation message:

```
[CAL] Calibration saved.
```

5. To verify calibration:

```
PRINTCAL
```

Step 4 — Start Measuring

To measure once:

```
MEASURE
```

To enable continuous measurement (logging):

```
LOG ON
```

To stop logging:

```
LOG OFF
```

5. Understanding Measurement Output

Example output:

```
t=10233 ms, ADC_raw_mean=682.35 (min=676, max=689), vref=5.000000,  
Vadc=3.333100, Vin=11.936821 V ±0.012, Vin_IIR=11.940832, ref=DEFAULT, cal=YES
```

Explanation: - `t` — time since boot (ms) - `ADC_raw_mean` — average ADC value (trimmed) - `vref` — active ADC reference voltage - `Vadc` — measured voltage at A0 - `Vin` — actual computed input voltage

(calibrated) - \pm — uncertainty derived from ADC noise - `Vin_IIR` — filtered Vin (IIR smoothing) - `ref` — reference source (DEFAULT/INTERNAL) - `cal` — calibration status (YES = valid calibration loaded)

6. EEPROM & Persistence

- Calibration and counters are stored in EEPROM and loaded automatically at startup.
 - If CRC fails or calibration was cleared, the system requests recalibration.
 - Boot counter increments each power-up.
-

7. Factory Reset & Recovery

If calibration or EEPROM data becomes invalid: - Run:

CLEARCAL

to remove calibration only. - Or (if added):

FACTORYRESET

to restore all settings to default.

8. Tips for Reliable Operation

- Ensure **A0 voltage never exceeds Vref**.
 - Use **metal film resistors (1% or better)** for long-term stability.
 - Keep **divider impedance < 100 k Ω** total.
 - Recalibrate after hardware changes or if voltage readings drift.
 - Use a **stable power supply** when operating in DEFAULT mode.
 - Minimize EEPROM writes — avoid frequent unnecessary calibrations.
-

9. Example Workflow Summary

1. Upload firmware and open Serial Monitor.
2. Enter `SETREF DEFAULT`.
3. Apply a known voltage (e.g., 12.000 V).
4. Type `CAL 12.000 RBOT 10000`.
5. Wait for `[CAL] Calibration saved`.
6. Type `PRINTCAL` to confirm.
7. Type `LOG ON` to begin continuous voltage readings.

10. Command Quick Reference

HELP	– Show all commands.
SETREF DEFAULT INTERNAL AUTO	– Set ADC reference mode.
CAL <volts> [RBOT RTOP] [SAMPLES <n>]	– Calibrate.
PRINTCAL	– Show stored calibration data.
CLEARCAL / RESETCAL	– Clear calibration.
MEASURE	– Take one measurement.
LOG ON / OFF	– Toggle periodic logging.
FACTORYRESET (optional)	– Reset calibration, counter, and settings.
FULLRESET (optional)	– Erase all EEPROM data (dangerous).

End of Command Manual