

# A7672M7\_F Firmware Release Note

**Latest Version: A011B04A7672M7\_F**

## General Notes

SIMCom offers this information as a service to its customers, to support applications and engineering efforts that use SIMCom products. The information provided is based upon requirements specifically provided to SIMCom by the customers. SIMCom has not undertaken any independent search for additional relevant information, including any information that may be in the customer's possession. Furthermore, system validation of this SIMCom product within a larger electronic system remains the responsibility of the customer or the customer system's integrator. All specifications supplied herein are subject to change.

## Copyright

This document contains proprietary technical information which is the property of SIMCom Limited., copying of this document and giving it to others and the using or communication of the contents thereof, are forbidden without express authority. Offenders are liable to the payment of damages. All rights reserved in the event of grant of a patent or the registration of a utility model or design. All specification supplied herein are subject to change without notice at any time.

***Copyright © SIMCom Wireless Limited. 2022***

# A7672M7\_F LTE

## 1 Preamble

This Release Note introduces A7672M7\_F Firmware versions and briefly describes the benefits over preceding release. Also you can find differences compared with preceding release.

**New Features:** list features or AT commands which are newly developed compared with the preceding version.

**Improved Features:** list features or parameters that have been changed or improved compared with the preceding version.

### Related documents

- [1] A76XX Series\_AT Command Manual\_V1.06.docx
- [2] A76XX Series\_TCPIP\_Application Note\_V1.02.docx
- [3] A76XX Series\_HTTP(S)\_Application Note\_V1.02.docx
- [4] A76XX Series\_FTP(S)\_Application Note\_V1.02.docx
- [5] A76XX Series\_MQTT(S)\_Application Note\_V1.02.docx
- [6] A76XX Series\_SSL\_Application Note\_V1.02.docx
- [7] A76XX Series\_LBS\_Application Note\_V1.02.docx
- [8] A76XX Series\_UART\_Application Note\_V1.02.docx
- [9] A76XXSeries\_Sleep Mode\_Application Note\_V1.02.docx
- [10] A76XX Series\_UIM HOT SWAP\_Application Note\_V1.01.docx
- [11] A76XX 系列\_云平台协议\_应用文档\_V1.01.docx
- [12] A76XX Series\_Audio\_Application Note\_V1.02.docx
- [13] A7600 Series\_Linux\_USB\_Application Note\_V1.02.docx
- [14] A76XX Series\_FOTA\_Application Note\_V1.00.docx
- [15] A76XX Series\_Android\_Linux\_Upgrade\_Manual\_V1.01.docx

### Version: A011B04A7672M7\_F

#### [New Features]

1. Add the Jamming Detection function.

#### [Improved Features]

1. Fixed the issue: [AUDIO] The module freezes when an incoming call is placed during AUDIO playback.
2. Fixed the issue: [SSL] In transparent transmission mode, enter two + signs and restart.
3. Fixed the issue: Enter [HTTP] continuously: continue +HTTPACTION, +HTTPDATA, +HTTPREAD. Wait half an hour for the module to restart.
4. Fixed the issue: [PPP] PPP repeatedly dials, and the module crashes at a probability.
5. Fixed the issue: [SSL] If there is too much data in the CCH buffer, connect to the server again to receive data, and the module restarts.

**Version: A011B03A7672M7\_F****[New Features]**

1. Added AT instruction AT+CNII for traffic statistics.
2. Added the AT+FSPRESET command to export the recording file from the USB port.

**[Improved Features]**

1. Fixed the issue: Change the AT+CTBURST default output to 33 dBm from 27dBm.
2. Fixed the issue: [SIMCard] When SIM card 2 is disconnected, data services TCP, FTP, SSL, and HTTP cannot be connected.
3. Fixed the issue: False alarm occurs when there is no signal at all.
4. Fixed the issue: [SSL] In transparent transmission mode, enter two + signs (+) to restart the system.
5. Fixed the issue: AT+CNETCI? No information can be obtained from frequency scanning.
6. Fixed the issue: [TCPIP] Failed to connect to UDP.
7. [MQTT] CMQTTSUB Subscription topic exceeds a certain amount of data, query again will cause the module to crash.

**Version: A011B02A7672M7\_F****[New Features]****[Improved Features]**

8. Optimized some command formats and return results.
9. Fixed the issue: When the broadcast packet of the remote Bluetooth device is large, the module cannot display the scan result of Bluetooth correctly.
10. Fixed the issue: Error message returned from "at+reset" command.
11. Fixed the issue: [SSL] If the CCH buffer contains too much data, connect to the server again to receive data, module reboot.
12. Fixed the issue: The module may restart after a period of time by executing the "+HTTPACTION、+HTTPDATA、+HTTPREAD" command in large numbers.

**Contact us:****Shanghai SIMCom Wireless Solutions Limited.**

Address: SIMCom Headquarters Building, Building 3, No. 289 Linhong Road, Changning District,  
Shanghai P.R.China 200335

Email: [simcom@simcom.com](mailto:simcom@simcom.com)

Website: [www.simcom.com](http://www.simcom.com)

SIMCOM CONFIDENTIAL FILE