

DEPARTMENT OF MECHANICAL ENGINEERING  
SUB CODE & NAME  
18MES103L-BASIC CIVIL & MECHANICAL ENGINEERING  
WORKSHOP

EXPERIMENT 3

SMITHY - CHISEL MAKING

## INTRODUCTION

- A smithy's work involves heating of a metal stock to a desired temperature, enable it to obtain sufficient plasticity, followed by the operations like hammering, bending, pressing etc., to give it the desired shape. **This is known as forging.**
- The above operations can either be carried out by **hand hammering**, by **power hammers**, or by **forging machines**..



# Forging

- **Hand forging** is the term used for the process when it is done by hand tools. Similarly, forging done with the help of power hammers is known as **power forging**, when carried out by means of drop hammers as **drop forging**, and when by forging machines as **machine forging**.
- Applying pressure for shaping the metal, the primary requirement always is to heat the metal to a definite temperature to bring in into the **plastic state**.
- ❖ This may be done either in an open hearth, known as **smith's forge**, or in closed furnace. Small jobs are normally heated in the Smith's forge and larger jobs in **closed furnaces**.
- ❖ The Hand forging process is employed for relatively small components, machine forging for medium sized and large articles requiring very heavy blows and drop forging for mass production of identical parts.

## Smith's forge or hearth

**It has a robust cast iron or steel structure consisting of 4 leg supports, an iron bottom known as hearth, a hood at the top and tuyere opening into the hearth either from the rear or from the bottom.**

**The hearth carries the coal and provided with fire bricks lining to withstand the extensive heat produced due to the combustion of coal.**

**In the absence of this lining the heat produced, as started above, will directly effect the metal structure of the hearth, so that the body, particularly the bottom and the surrounding walls, may even melt.**

**With the result, the entire structure will collapse and the hearth will no more be useful.**

# Hearth

- Air, under pressure is supplied by the blower, suitably placed somewhere near the forge, through the tuyere opening in the hearth.
- This blower can either be hand operated or power driven. The latter is preferable, but in the absence of availability of power supply choice of the former has no alternative.
- If hand blowers are to be used, they are usually mounted at the rear of the forge itself. In case the power driven units are to be employed the blower is suitably placed in one corner of the shop and all the forges are connected with it by means of a well-laid pipe running underground all around the hearths.





# Hearth

- At suitable points auxiliary pipes are used to connect the tuyere with the main pipe line.
- A valve is incorporated in the auxiliary pipe, just before the place where it is connected with the tuyere, to control the supply of air to the furnace.
- The chimney provided at the top enables as easy escape of smoke and gases produced due to the burning of coal.
- A water tank is provided, in front of the forge, which carries water for the purpose of quenching.
- These hearths can also be made to have masonry construction provided with all the attachments like chimney, tuyere, blower, water tank, etc.



www.shutterstock.com · 112001009

## AIM

To make a chisel of given size from a given rod by hand forging

## APPLICATION

Chisels are special kinds of cutting tools that widely used to sharpen, shape, re-shape and carve hard materials like metal, stone or wood.

## SUPPLIED MATERIAL SPECIFICATION

Mild steel rod of diameter 16mm and length 300 mm



# TOOLS REQUIRED

- 1. Caliper and Steel rule
- 2. Anvil
- 3. Bold header
- 4. Tongs
- 5. Sledge hammer
- 6. Bottom swage
- 7. Hand hammer
- 8. Smoother
- 9. Hot chisel



# SEQUENCE OF OPERATIONS

- I. Preparing
- II. Upsetting
- III. Swaging
- IV. Finishing
- V. Checking


# Anvil or Bench plate

To carry out the forging operations successfully, a proper supporting device is needed which should be capable of withstanding heavy blows rendered to the job.

An anvil stands as the most appropriate choice for this purpose.

Its body is generally made of cast steel, wrought iron or mild steel provided with a hardened top, about 20 to 25 mm thick.

This hardened plate is welded to the body on the top.



# Anvil


- The horn or beak is used in bending the metal or forming curved shapes. The flat step provided, between the top and the horn, is used to support jobs during cutting and is known as chipping block.
- The flat projecting piece at the back of the anvil is known as tail.
- It carries a square hole to accommodate the square shank of the bottom part of various hand tools like swages, fuller. It is called a hardie hole.
- The circular hole provided near the hardie hole is known as pritchel hole.
- The commonly used size of an anvil weighs approximately 50-150 kg although it is manufactured in various sizes.
- The top face of the anvil should stand at about 0.75 m from the floor.

# Hammer

- The classification of hammers is largely according to the size and weight of the hammers used in forging.
- A smith's hand hammer is a small sized hammer used by the smith himself and the sledge hammer is comparatively larger in size, heavier in weight and is used by the smith's helper, known as hammer man.
- The smith's hand hammer is normally a small sized ball peen hammer.
- A smith's hammer is usually a ball peen hammer or a straight peen sledge type hammer of relatively small size. Its weight normally varies between 1.0 kg and 1.8 kg

# Hammer

- A ball peen hammer is used for all general work and its peen is employed when light blows at a faster speed are needed, such as in fullering a rivet head in a countersunk hole.
- Sledge hammers are comparatively 3 to 4 times heavier than the hand hammers. They are available in varying sizes and weights from 3 kg to 8 kg.
- They are employed when heavy blows are needed in forging and other operations done on heavy jobs.






# Swage block

- It is usually a block of cast steel or cast iron carrying a number of slots of different shapes and sizes along its four side faces and through holes from its top face to bottom face.
- This is used as a support in punching holes and forming different shapes.
- The job to be given a desired shape is kept on a similar shaped slot, which acts as a bottom swage, and then the top swage is applied on the other side of the job.

# Swage block

- The holes in the top and bottom face are used in punching.
- Their use prevents the punch from spoiling by striking against a hard surface after the hole




# Tongs

- They are used to hold the jobs in position and turning over during forging operation. They are made of mild steel.
- Tongs are usually made in two pieces, riveted together to form a hinge. Smaller length on one side of the hinge carries the holding jaws, which are made in different shapes and sizes to suit the corresponding shapes and sizes of the jobs, and the longer portions on the other side of the hinge form the arms which are held in hand by the smith.
- Overall sizes of the tongs vary according to the size and shape of the job to be held, but the commonly used lengths of the tongs in hand forging vary from 400 mm to 600 mm with the jaws' opening ranging from 6mm to 55 mm.
- Tongs are usually named after the inside shapes of the jaws.
- Flat tongs are used for gripping thin section and small flat pieces


# Tongs

- Round hollow tongs, with curved surface inside, are used for holding round work.
- Hollow tongs with square jaws are used to hold square or hexagonal work.
- Pick up tongs have their jaws so shaped that even small sections can be easily picked up. They are not used for holding the work.



# Flatters


- These are also known as smoothers. They are made of high carbon steel and consist of a square body, fitted with a handle, and a flat square bottom.
- They are used for leveling and finishing a flat surface after drawing out or any other forging operation.






# Fullers

- These tools are made of high carbon steel in different sizes to suit the various types of jobs.
- They are usually used in pairs, consisting of a top and a bottom filler. Their working edges are normally rounded.
- They, are employed for making necks by reducing the cross-section of a job and also in drawing out.



# swages

- Like fullers, they are also made of high carbon steel in two parts called the top and bottom swages.
- Their working faces carry circular grooves to suit the size of the work. They are available in various sizes.
- The top swage carries a handle and the bottom swage a square shank to fit the hardie hole of the anvil during the operation.
- They are used for increasing the length of a circular rod or for finishing the circular surface of a job after forging.



# Chisels

- Chisels are used to cut metals in hot or cold state.
- Those which are used for cutting the metal in hot state are termed as hot chisels and the others used for cutting in cold state are known as cold chisels.
- The main difference between these chisels is in the included angle at the cutting edge.
- A cold chisel carries an included angle of  $60^\circ$  at the cutting edge and the latter is well hardened and tempered. It is made of high carbon steel.
- A hot chisel can be made of medium carbon steel as there is no need of hardening. It is used to cut the metal in plastic state. The included angle of its cutting edge is  $30^\circ$ .



# Punches

- Punches are tapered tools made in various shapes and sizes.
- They are used for producing holes in red hot jobs. A larger tapered punch is called a drift.
- The job is placed on the anvil and the punch is hammered through it up to about half its depth.
- It is then turned over and the punch made to pass through it. Completion of this operation in two stages prevents the job from splitting and full to bursting.





# CHIESL MAKING

- AIM
  - To Make a square chisel from given work piece

- TOOLS REQUIRED

1. Caliper and Steel rule
2. Anvil
3. Bold header
4. Tongs
5. Sledge hammer
6. Bottom swage
7. Hand hammer
8. Smoother
9. Hot chisel





# WORKING STEPS- I. Preparing

- 1. Take a given work piece and check the given dimensions as per requirements using steelrule and caliper.
- 2. Place the work piece in hearth / forge until it becomes red hot. (Heating the work pieces the process of upsetting)
- 3. Take the hot stock out of forge, place it on anvil, measure 280mm from one end of stock using steel rule and cut off with hot chisel.

# Procedure

- Measure the dimension of given work piece
- Place the work piece inside the furnace and heat upto 1000deg C
- Remove the work piece and place it on anvil
- Strike all the sides of work piece using sledge hammer to get square shape.
- Heat the work piece again to real hot
- Strike the portion of the work piece on water and cool it

## II. Upsetting

- 1. Again heat one end of the stock to a length of 90mm.
- 2. Grip the hot stock with tongs, Place it vertically on anvil such that the hot portion is at bottom. Strike the top portion with sledge hammer. This will cause increase in diameter of the bottom portion. Keep upsetting until the edge portion becomes slightly larger than the required size of the head.
- 3. Fix a bolt header over anvil inline with hardie hole in anvil. Upset the head of the bolt with hand hammer.
- 4. Withdraw bolt from bolt header and with hand hammer round the bolt head on anvil face. This is called as Fullering

# III. Swaging

- 1. Heat the bolt head in hearth again.
- 2. Insert bottom swage of required hexagonal bolt head dimension in hardie hole of anvil.
- 3. Remove bolt from forge; place the head on the bottom swage.
- 4. Strike with hand hammer to give required shape to the head.
- 5. Turn the head by 60 degree about its axis and repeat the step4. Repeat this for all six sides
- of the hexagon.



# IV Finishing & V. Checking

- 1. Insert the shank of bolt in bolt header, place stock on anvil so that its shank passes through hardie hole in anvil.
- 2. Place smoother on bolt head and make top portion of head spherical in shape by striking the smoother with hand hammer
- 3. Straighten the shank of the bolt by placing it on the face of the anvil.
- V. Checking
- 1. Check the length of the shank. If it is more than 200mm long, heat the end and cut off surplus with hot chisel.

# RESULT

- Thus the required Chisel is made out of the given stock.