

COMPUTER AND DATA NETWORK

EC4060



NETWORK INFRASTRUCTURE DESIGN

FACULTY OF ENGINEERING NETWORK SYSTEM

(INDEPENDENT LEARNING AND IMPLEMENTATION ASSIGNMENT)

BY

LIYANAWATHTHAGE L.B.K

(2022/E/083)

FACULTY OF ENGINEERING

UNIVERSITY OF JAFFNA

Network Infrastructure Report Faculty of Engineering

Network System

Project Description

The Faculty of Engineering requires a robust, scalable, and secure network infrastructure to support its five academic departments—Computer Engineering, Electrical & Electronic Engineering, Civil Engineering, Mechanical Engineering, and Interdisciplinary Studies (IDS)—along with the Administration section. The goal of this project is to design and implement a structured network system that ensures efficient communication, optimized traffic management, and high security while allowing future scalability.

The network is structured using Virtual Local Area Networks (VLANs) to segment traffic and ensure logical separation among different departments and device types. A Layer 3 core switch interconnects the departmental Layer 3 switches, providing inter-VLAN routing, while Layer 2 switches manage local connections within each department. Unique subnets are assigned to each section, considering a 30% expansion for future growth.

Critical devices such as computers, printers, and engineering-related equipment are connected within their respective VLANs, while a centralized CCTV subnet (VLAN 180) under the Administration switch enhances security monitoring across the campus. IP addressing is managed using a combination of static allocations and DHCP to ensure optimal utilization.

This project also includes a detailed simulation of the network using Cisco Packet Tracer, along with rigorous testing and validation procedures to ensure seamless connectivity, security, and scalability.

Design Task

The network design task involves the following key steps:

1. Categorization of Subnets:

- Allocate unique subnets for each department and section.
- Justify the need for each subnet.

2. Virtual LAN (VLAN) Planning:

- Identify and categorize VLANs based on departments and device types.
- Align VLAN assignments with subnets for logical separation and optimized routing.

3. Subnet Calculation Table:

- Calculate subnet masks, network addresses, usable IP range, and broadcast addresses for each subnet.

4. Topology Design:

- Define the network topology with routers and switches.
- Assign IP addresses to virtual networks and physical devices.

5. Simulation and Configuration:

- Build the network using Cisco Packet Tracer or GNS3.
- Configure subnets, VLANs, and inter-VLAN routing on network devices.
- Implement security policies such as ACLs.

6. Testing and Validation:

- Perform connectivity tests (ping and traceroute) to verify:
 - Communication between staff devices and printers.
 - Communication between student devices within the same subnet.
 - Connectivity of CCTV cameras with administrative computers.

7. Scalability Consideration:

- Add additional devices to validate network expansion capabilities.


8. Final Report Preparation:

- Include subnet calculations, VLAN mapping, topology diagram, simulation results, and scalability assessment.

VLAN IP Allocation Table


Department	VLAN ID	Device Type	Total Devices	Future Growth (30%)	Subnet Mask	Network Address	Usable IP Range
Computer Eng	10	Students	250	325	255.255.254.0 (/23)	192.168.0.0	192.168.0.1 - 192.168.1.254
Computer Eng	20	Staff	50	65	255.255.255.128 (/25)	192.168.2.0	192.168.2.1 - 192.168.2.126
EE Eng	40	Students	150	195	255.255.255.0 (/24)	192.168.3.0	192.168.3.1 - 192.168.3.254
EE Eng	50	Staff	50	65	255.255.255.128 (/25)	192.168.4.0	192.168.4.1 - 192.168.4.126
Civil Eng	70	Students	75	98	255.255.255.128 (/25)	192.168.5.0	192.168.5.1 - 192.168.5.126
Civil Eng	80	Staff	25	33	255.255.255.192 (/26)	192.168.5.128	192.168.5.129 - 192.168.5.190
Mech Eng	100	Students	75	98	255.255.255.128 (/25)	192.168.6.0	192.168.6.1 - 192.168.6.126
Mech Eng	110	Staff	25	33	255.255.255.192 (/26)	192.168.6.128	192.168.6.129 - 192.168.6.190
IDS	130	Students	15	20	255.255.255.224 (/27)	192.168.7.0	192.168.7.1 - 192.168.7.30
IDS	140	Staff	25	33	255.255.255.192 (/26)	192.168.7.32	192.168.7.33 - 192.168.7.94
Admin	160	Staff	25	33	255.255.255.192 (/26)	192.168.8.0	192.168.8.1 - 192.168.8.62
CCTV	180	Cameras	50	65	255.255.255.128 (/25)	192.168.9.0	192.168.9.1 - 192.168.9.126

Topology Diagram




Simulation Results


1. Computer Department




2. Electrical Department



3. Civil Department



4. Mechanical Department



5. IDS Department

aculty

Device Name: IDSL3Switch
Device Model: 3560-24PS
Hostname: Switch

Port	Link	VLAN	IP Address	IPv6 Address	MAC Address
FastEthernet0/1	Down	1	<not set>	<not set>	0001.C9B0.A401
FastEthernet0/2	Down	1	<not set>	<not set>	0001.C9B0.A402
FastEthernet0/3	Down	1	<not set>	<not set>	0001.C9B0.A403
FastEthernet0/4	Down	1	<not set>	<not set>	0001.C9B0.A404
FastEthernet0/5	Down	1	<not set>	<not set>	0001.C9B0.A405
FastEthernet0/6	Down	1	<not set>	<not set>	0001.C9B0.A406
FastEthernet0/7	Down	1	<not set>	<not set>	0001.C9B0.A407
FastEthernet0/8	Down	1	<not set>	<not set>	0001.C9B0.A408
FastEthernet0/9	Down	1	<not set>	<not set>	0001.C9B0.A409
FastEthernet0/10	Down	1	<not set>	<not set>	0001.C9B0.A40A
FastEthernet0/11	Down	1	<not set>	<not set>	0001.C9B0.A40B
FastEthernet0/12	Down	1	<not set>	<not set>	0001.C9B0.A40C
FastEthernet0/13	Down	1	<not set>	<not set>	0001.C9B0.A40D
FastEthernet0/14	Down	1	<not set>	<not set>	0001.C9B0.A40E
FastEthernet0/15	Down	1	<not set>	<not set>	0001.C9B0.A40F
FastEthernet0/16	Down	1	<not set>	<not set>	0001.C9B0.A410
FastEthernet0/17	Down	1	<not set>	<not set>	0001.C9B0.A411
FastEthernet0/18	Down	1	<not set>	<not set>	0001.C9B0.A412
FastEthernet0/19	Down	1	<not set>	<not set>	0001.C9B0.A413
FastEthernet0/20	Down	1	<not set>	<not set>	0001.C9B0.A414
FastEthernet0/21	Down	1	<not set>	<not set>	0001.C9B0.A415
FastEthernet0/22	Down	1	<not set>	<not set>	0001.C9B0.A416
FastEthernet0/23	Down	1	<not set>	<not set>	0001.C9B0.A417
FastEthernet0/24	Down	1	<not set>	<not set>	0001.C9B0.A418
GigabitEthernet0/1	Up	--	<not set>	<not set>	0001.C9B0.A419
GigabitEthernet0/2	Up	--	<not set>	<not set>	0001.C9B0.A41A
Vlan1	Down	1	<not set>	<not set>	0090.0C26.D901
Vlan130	Up	130	192.168.7.1/27	<not set>	0090.0C26.D902
Vlan140	Up	140	<not set>	<not set>	0090.0C26.D903
Vlan150	Up	150	192.168.7.97/28	<not set>	0090.0C26.D904

Physical Location: Intercity > Home City > Corporate Office > Main Wiring Closet > Rack > IDSL3Switch

ELECTRICAL DEPARTMENT

CIVIL DEPARTMENT

MECHANICAL DEPARTMENT

IDS DEPARTMENT

6. Administration

Device Name: AdminL3Switch
Device Model: 3560-24PS
Hostname: Switch

Port	Link	VLAN	IP Address	IPv6 Address	MAC Address
FastEthernet0/1	Down	1	<not set>	<not set>	000B.BE09.6701
FastEthernet0/2	Down	1	<not set>	<not set>	000B.BE09.6702
FastEthernet0/3	Down	1	<not set>	<not set>	000B.BE09.6703
FastEthernet0/4	Down	1	<not set>	<not set>	000B.BE09.6704
FastEthernet0/5	Down	1	<not set>	<not set>	000B.BE09.6705
FastEthernet0/6	Down	1	<not set>	<not set>	000B.BE09.6706
FastEthernet0/7	Down	1	<not set>	<not set>	000B.BE09.6707
FastEthernet0/8	Down	1	<not set>	<not set>	000B.BE09.6708
FastEthernet0/9	Down	1	<not set>	<not set>	000B.BE09.6709
FastEthernet0/10	Down	1	<not set>	<not set>	000B.BE09.670A
FastEthernet0/11	Down	1	<not set>	<not set>	000B.BE09.670B
FastEthernet0/12	Down	1	<not set>	<not set>	000B.BE09.670C
FastEthernet0/13	Down	1	<not set>	<not set>	000B.BE09.670D
FastEthernet0/14	Down	1	<not set>	<not set>	000B.BE09.670E
FastEthernet0/15	Down	1	<not set>	<not set>	000B.BE09.670F
FastEthernet0/16	Down	1	<not set>	<not set>	000B.BE09.6710
FastEthernet0/17	Down	1	<not set>	<not set>	000B.BE09.6711
FastEthernet0/18	Down	1	<not set>	<not set>	000B.BE09.6712
FastEthernet0/19	Down	1	<not set>	<not set>	000B.BE09.6713
FastEthernet0/20	Down	1	<not set>	<not set>	000B.BE09.6714
FastEthernet0/21	Down	1	<not set>	<not set>	000B.BE09.6715
FastEthernet0/22	Down	1	<not set>	<not set>	000B.BE09.6716
FastEthernet0/23	Down	1	<not set>	<not set>	000B.BE09.6717
FastEthernet0/24	Down	1	<not set>	<not set>	000B.BE09.6718
GigabitEthernet0/1	Up	--	<not set>	<not set>	000B.BE09.6719
GigabitEthernet0/2	Up	--	<not set>	<not set>	000B.BE09.671A
Vlan1	Down	1	<not set>	<not set>	0006.2A50.9474
Vlan160	Up	160	192.168.8.1/26	<not set>	0006.2A50.9401
Vlan170	Up	170	192.168.8.65/28	<not set>	0006.2A50.9402
Vlan180	Up	180	192.168.9.1/25	<not set>	0006.2A50.9403

Physical Location: Intercity > Home City > Corporate Office > Main Wiring Closet > Rack > AdminL3Switch

CIVIL DEPARTMENT


MECHANICAL DEPARTMENT

IDS DEPARTMENT


ADMINISTRATION

Testing & Validation

Here I sent a data packet from a staff device to an End device in Civil Department.



Here I ping Staff PC device to CCTV device in Administration. (0% loss)



The screenshot shows a Cisco Packet Tracer PC window for PC11. The 'Desktop' tab is active, displaying a Command Prompt. The user has entered the command 'ping 192.168.9.1'. The output shows four successful replies from 192.168.9.1, each with 32 bytes of data, a time of less than 1ms, and a TTL of 255. The ping statistics for 192.168.9.1 indicate that 4 packets were sent, 4 were received, and 0 were lost, resulting in 0% loss. The approximate round trip times in milliseconds are also shown as 0ms for minimum, maximum, and average.

```
Cisco Packet Tracer PC Command Line 1.0
C:\>ping 192.168.9.1


Pinging 192.168.9.1 with 32 bytes of data:

Reply from 192.168.9.1: bytes=32 time<1ms TTL=255
Reply from 192.168.9.1: bytes=32 time<1ms TTL=255
Reply from 192.168.9.1: bytes=32 time<1ms TTL=255
Reply from 192.168.9.1: bytes=32 time<1ms TTL=255

Ping statistics for 192.168.9.1:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 0ms, Maximum = 0ms, Average = 0ms

C:\>
```

Here I tried to ping from Student PC in Civil Dep to CCTV in Administration. (100% loss)



The screenshot shows a Cisco Packet Tracer PC window for PC4. The 'Desktop' tab is active, displaying a Command Prompt. The user has entered the command 'ping 192.168.9.1'. The output shows four failed replies from 192.168.5.1, each with the message 'Destination host unreachable'. The ping statistics for 192.168.9.1 indicate that 4 packets were sent, 0 were received, and 4 were lost, resulting in 100% loss.

```
Cisco Packet Tracer PC Command Line 1.0
C:\>ping 192.168.9.1


Pinging 192.168.9.1 with 32 bytes of data:

Reply from 192.168.5.1: Destination host unreachable.
Reply from 192.168.5.1: Destination host unreachable.
Reply from 192.168.5.1: Destination host unreachable.
Reply from 192.168.5.1: Destination host unreachable.

Ping statistics for 192.168.9.1:
    Packets: Sent = 4, Received = 0, Lost = 4 (100% loss),

C:\>
```

Here I tried to ping from Student PC in Elec Dep to Printer Device in it. (100% loss)



The screenshot shows a window titled "PC2" with tabs for "Physical", "Config", "Desktop", "Programming", and "Attributes". The "Desktop" tab is active, displaying a "Command Prompt" window. The command prompt shows the following text:

```
Cisco Packet Tracer PC Command Line 1.0
C:\>ping 192.168.4.129

Pinging 192.168.4.129 with 32 bytes of data:

Reply from 192.168.3.1: Destination host unreachable.
Reply from 192.168.3.1: Destination host unreachable.
Reply from 192.168.3.1: Destination host unreachable.
Reply from 192.168.3.1: Destination host unreachable.

Ping statistics for 192.168.4.129:
    Packets: Sent = 4, Received = 0, Lost = 4 (100% loss),

C:\>
```

Summary

During the simulation and testing phase, most devices successfully communicated as expected. Connectivity was verified through ping tests, where the majority of packets reached their destinations, confirming proper VLAN segmentation and routing configurations. However, some data packets failed to reach their intended destinations, indicating possible misconfigurations in subnetting, VLAN assignment, or routing rules. Despite these minor issues, the overall network functioned effectively under the provided instructions and met most of the expected outcomes.

Further troubleshooting is required to resolve the remaining connectivity issues. Possible areas of improvement include verifying VLAN trunking, adjusting routing protocols, and ensuring proper device configurations. Overall, the project successfully demonstrated network segmentation, inter-departmental communication, and scalability while highlighting areas for optimization and refinement.