


ProtoBot Bump Sensor Soldering Guide



You will need:

Parts:


- 2 x Limit Switches
- 1 set of two DuPont Female-Female jumper wires

Tools:

- Wire cutters/Strippers
- Soldering Iron with Fine tip
- Helping Hands, or something to hold the bump sensors in place (I used tape)




Copyright © 2018, Jacob Field. This work is licensed under a [Creative Commons Attribution 4.0 International License](https://creativecommons.org/licenses/by/4.0/).



- Cut your pair of wires in half




- Use your wire strippers to strip about 5MM or 1/4" insulation off the ends




- Split the ends apart, then twist the loose strands on each wire end together





- Tin the wire ends, by holding them over the solder, then applying your tinned iron tip




- Secure the sensors so they won't move around




- Bend the tinned ends of each wire so the wires are 180 degrees apart from each other



- Insert the wires into the correct metal tabs on each of the sensors, as shown.



- Solder each of the wires to the metal tabs



Your bump sensors are now ready to be used on a ProtoBot!