




# hackCNC

## Frame Assembly Manual



## Section 1 : Z Axis Carriage




## Section 1 : Step 1

### Parts

1 x 3D Printed Z Axis Bracket


2 x CNC Z Axis Plate



## Section 1 : Step 2

### Parts


1 x 8mm Long Nut




## Section 1 : Step 3

### Parts


1 x 3D Printed Z Axis Bracket



## **Section 1 : Complete!**




## **Section 2 : Y Axis Carriage**



## Section 2 : Step 1

### Parts


1 x 3D Printed Y Axis Coupler  
1 x 8mm nut




## Section 2 : Step 2

### Parts

1 x Nema 17 Stepper Motors  
1 x CNC Y Axis Motor Mount  
4 x 3mm Machine Screws




## Section 2 : Step 3




## Section 2 : Step 4

### Parts

1 x 210 mm Long 8mm all-thread  
Part from Section 1



## Section 2 : Step 4 - complete




## Section 2 : Step 5

### Parts

1 x 8mm nuts

Part from Section 2 : Step 4






## Section 2 : Step 6


### Parts

1 x CNC Carriage Side


Part from Section 2 : Step 3



## Section 2 : Step 7



## Section 2 : Step 8




## Section 2 : Step 9


### Parts

1 x CNC Y Axis Bearing Mount


1 x 608 bearing



## Section 2 : Step 10




## Section 2 : Step 11



## Section 2 : Step 12

### Parts


1 x CNC Y Axis Mount



## Section 2 : Step 13

### Parts


2 x 3D Printed X Axis Nut Bracket



## Section 2 : Step 14

### Parts

2 x 8mm Long Nut




## Section 2 : Step 15


### Parts

1 x CNC Carriage Side


2 x 3D Printed X Axis Nut Bracket



## Section 2 : Step 16




## Section 2 : Step 16 - Complete




## Section 2 : Step 17


Put a dab of glue before turning the nut



## Section 2 : Complete!



## Section 3 : X Axis Rails




## Section 3 : Step 1

### Parts

2 x 8mm nuts


2 x 3D Printed X Axis Gears

X 2





## Section 3 : Step 1 - Complete



## Section 3 : Step 2

Parts


2 x 310mm long 8mm all-thread



## Section 3 : Step 3

Parts


Part from Section 2




## Section 3 : Step 4

Parts


2 x 8mm nuts



## Section 3 : Complete!



## Section 4 : Top Frame




## Section 4 : Step 1


### Parts

- 1 x Nema 17 Stepper Motor
- 4 x 3mm machine screws
- 1 x CNC Back Bulkhead

These should be somewhat loose.



## Section 4 : Step 1 - Complete




## Section 4 : Step 2

### Parts

1 x CNC Front Bulkhead

1 x CNC Side Plate


1 x CNC Front Plate



## Section 4 : Step 3

### Parts


2 x 608 bearings



## Section 4 : Step 4

Parts


2 x 8mm Washers



## Section 4 : Step 5

Parts


Section 3



## Section 4 : Step 6

Parts


2 x T5 Belts



## Section 4 : Step 7

Parts


2 x 8mm Washers



## Section 4 : Step 8

### Parts

2 x 608 Bearings




## Section 4 : Step 9

### Parts

Section 4 : Step 1

You will need to wiggle these together a bit






## Section 4 : Step 10


### Parts

1 x CNC Side Plate




## Section 4 : Complete!

(Belts removed from view)



## Section 5 : The Whole Frame


(Belts removed from view)




## Section 5 : Step 1

Parts


1 x CNC Base Plate



## Section 5 : Step 2




## Section 5 : Step 3




## Section 5 : Step 4

Small dab of glue before doing up




## Section 5 : Step 5

Small dab of glue before doing up  
There should be no slop, but the all-thread should move smoothly.




## Section 5 : Step 6

Line up the teeth with the ones on the all-thread




## Section 5 : Step 7

You will have to turn the belt on.




## Section 5 : Step 8

This belt will need turning on too. Before turning on, try to get the gantry level by rotating the all-thread. Turn on by rotating the stepper.



## Section 5 : Step 9


(Belts magically invisible!)  
Slide the stepper down to increase the tension on the belts.




## Section 5 : Step 10

### Parts

1 x CNC Top Plate.



## Section 5 : Complete!



# **Frame Complete!**

## **Now to Assemble the Electronics.**

## **Thank You**

A big thank you to everyone who helped develop this project.  
Without everyone's contribution, it simply wouldn't be possible.

Andy Geleme  
Jon Oxe  
Shane Rogers  
John Bosua  
Dave Chanter  
Rob Brittan  
Bob Powers  
Michael Sullivan  
Stuart Young  
Luke Weston

And all the crew at CCHS.