

A319/A320/A321

TROUBLE SHOOTING MANUAL

HIGHLIGHTS

REVISION NO. 54 May 01/08

Pages which have been revised are outlined below, together with the Highlights of the Revision

CH/SE/SU C
PAGES

REASON FOR CHANGE

EFFECTIVITY

CHAPTER 35

L.E.P. 1- 1 REVISED TO REFLECT THIS REVISION INDICATING
NEW,REVISED, AND/OR DELETED PAGES

T. OF C. REVISED TO REFLECT THIS REVISION
2

35-10-00 EFFECTIVITY UPDATED

206- 207,
209, 211,
213, 215-
216, 220,
222, 226,
234, 239,
241, 250

EFFECTIVITY UPDATED (THROUGHOUT THE TEXT)

201-225, 227-227, 229-299,
426-499, 503-549, 551-599,
701-749,

OXYGEN

LIST OF EFFECTIVE PAGES

N, R or D indicates pages which are New, Revised or Deleted respectively
Remove and insert the affected pages and complete the Record of Revisions and the Record of Temporary Revisions as necessary

CH/SE/SU	C	PAGE	DATE	CH/SE/SU	C	PAGE	DATE	CH/SE/SU	C	PAGE	DATE
RECORD				35-10-00	R	220	May01/08	35-23-00		210	Nov01/04
OF TEMP.				35-10-00		221	Nov01/05	35-23-00		211	May01/05
REVISION				35-10-00	R	222	May01/08	35-23-00		212	May01/05
				35-10-00		223	Feb01/08	35-23-00		213	Nov01/04
L.E.P.	R	1-	1 May01/08	35-10-00		224	Aug01/98	35-23-00		301	Aug01/94
T. of C.			1 Nov01/06	35-10-00		225	Aug01/98	35-23-00		302	Aug01/94
T. of C.	R		2 May01/08	35-10-00	R	226	May01/08				
				35-10-00		227	Feb01/08				
35-ECAM		101	Nov01/06	35-10-00		228	May01/06				
35-ECAM		102	Nov01/06	35-10-00		229	Nov01/02				
				35-10-00		230	Nov01/02				
35-LOCAL		101	Feb01/03	35-10-00		231	Nov01/02				
35-LOCAL		102	Feb01/03	35-10-00		232	Nov01/02				
				35-10-00		233	Nov01/02				
35-OBSV		101	Nov01/06	35-10-00	R	234	May01/08				
35-OBSV		102	Aug01/98	35-10-00		235	Feb01/08				
35-OBSV		103	Nov01/06	35-10-00		236	Nov01/02				
35-OBSV		104	Nov01/06	35-10-00		237	Nov01/02				
35-OBSV		105	Feb01/03	35-10-00		238	Nov01/06				
35-OBSV		106	Feb01/03	35-10-00	R	239	May01/08				
				35-10-00		240	Nov01/06				
35-CFDS		101	Aug01/07	35-10-00	R	241	May01/08				
				35-10-00		242	Nov01/06				
35-10-00		201	Feb01/96	35-10-00		243	Nov01/06				
35-10-00		202	May01/96	35-10-00		244	Nov01/06				
35-10-00		203	Feb01/96	35-10-00		245	Nov01/06				
35-10-00		204	Aug01/95	35-10-00		246	Nov01/06				
35-10-00		205	Nov01/05	35-10-00		247	Nov01/06				
35-10-00	R	206	May01/08	35-10-00		248	Nov01/06				
35-10-00	R	207	May01/08	35-10-00		249	Nov01/06				
35-10-00		208	Feb01/08	35-10-00	R	250	May01/08				
35-10-00	R	209	May01/08	35-10-00		251	Feb01/08				
35-10-00		210	Feb01/08								
35-10-00	R	211	May01/08	35-23-00		201	Nov01/04				
35-10-00		212	Feb01/08	35-23-00		202	Nov01/04				
35-10-00	R	213	May01/08	35-23-00		203	May01/05				
35-10-00		214	Feb01/08	35-23-00		204	May01/05				
35-10-00	R	215	May01/08	35-23-00		205	May01/05				
35-10-00	R	216	May01/08	35-23-00		206	May01/05				
35-10-00		217	Aug01/98	35-23-00		207	May01/05				
35-10-00		218	Aug01/98	35-23-00		208	May01/05				
35-10-00		219	Nov01/05	35-23-00		209	Nov01/04				

OXYGEN**TABLE OF CONTENTS**

<u>SUBJECT</u>	<u>CH/SE/SU</u>	<u>C</u>	<u>PAGE</u>	<u>EFFECTIVITY</u>
FAULT SYMPTOMS	35-ECAM		101	ALL
	35-LOCAL		101	ALL
	35-OBSV		101	ALL
	35-CFDS		101	ALL
CREW OXYGEN	35-10-00			
FAULT ISOLATION PROCEDURES			201	ALL
Loss of the Oxygen Pressure			201	ALL
Indication on the D00R/OXY Page				
REGUL LO PR with Oxygen			205	ALL
Consumption without the Use of the Oxygen Mask				
Loss of the 100 % Selection on the Oxygen Mask			207	ALL
Loss of the Emergency Overpressure Knob on the Oxygen Mask			209	ALL
PRESS TO TEST AND RESET Button Inoperative			211	ALL
No Inflation of the Oxygen Mask Harness			213	ALL
Crew Oxygen Mask Dirty			215	ALL
Oxygen Cylinder Valve Closing not Possible			218	ALL
OXY ON flag on the Mask Stowage Box Inoperative			219	ALL
No Oxygen at the Full-Face/Quick-Donning Oxygen-Mask			222	ALL
Crew Oxygen Indication less than 400PSI on the D00R/OXY page			224	ALL
Flap Door of the Mask Stowage-Box Inoperative			226	ALL
Fast Loss of Crew Oxygen			228	ALL
Fast Loss of Crew Oxygen with Overboard Discharge Indicator Yellow			232	ALL
Failure of the Oxygen Flow Indicator			234	ALL
Disagree between the OXY Indication on the SD page and the OFF legend on the Pushbutton Switch			236	ALL
Overboard Discharge Indicator Yellow			237	ALL
Crew Oxygen Pressure Indication between 401 and 1499PSI with an			238	ALL

OXYGENTABLE OF CONTENTS

<u>SUBJECT</u>	<u>CH/SE/SU</u>	<u>C</u>	<u>PAGE</u>	<u>EFFECTIVITY</u>
Amber Half Frame on the DOOR/OXY Page				
Oxygen Cylinder Refilling not possible			241	201-225, 227-227 229-299, 426-450 476-499, 503-549 551-599, 701-749
REGUL LO PR Indication with no Oxygen Pressure Value on the DOOR/OXY Page			242	ALL
REGUL LO PR indication on the DOOR/OXY Page			245	ALL
No Oxygen to the Crew Oxygen Masks with REGUL LO PR Indication			248	ALL
Deterioration of the Flexible Supply-Hose Assembly			250	ALL
CONTROL AND INDICATING	35-23-00			
FAULT ISOLATION PROCEDURES			201	ALL
Automatic System Activation Fault			201	ALL
OXYGEN/PASSENGER P/BSW SYS ON Legend Fault			203	ALL
OXYGEN/TMR RESET P/BSW FAULT Legend Fault			205	ALL
Power Supply Line Fault			208	ALL
Manual System Activation Fault			210	ALL
PAX Announcement Activation Fault			211	ALL
Emergency Oxygen Container Fault			213	ALL
CONTROL AND INDICATING	35-23-00			
TASK SUPPORTING DATA			301	ALL

WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
	SOURCE	MESSAGE	ATA	C	

Lower ECAM DU Flags- DOOR/OXY

	OXY CREW - OXY in amber with P/B SW pushed (off legend comes on)				351000 P 236 T 810 816
	OXY CREW - OXY in white with P/B SW pushed (off legend goes off)				351000 P 236 T 810 816
	OXY CREW - OXY pressure between 401 and 1499 PSI half rectangular amber				351000 P 238 T 810 818
	OXY CREW - OXY, oxygen PRESS<400 PSI and half rectangular in amber				351000 P 224 T 810 811
	OXY CREW - oxygen PRESS IND replaced by amber crosses				351000 P 201 T 810 801
R	OXY CREW - oxygen PRESS IND replaced by amber crosses associated with <u>Lower ECAM DU Advisories</u> <u>DOOR/OXY</u> REGUL LO PR				351000 P 242 T 810 820

EFF : ALL

SR0S

35-ECAM

Page 101
Nov 01/06

WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
	SOURCE	MESSAGE	ATA	C	

Lower ECAM DU Advisories
DOOR/OXY

R	REGUL LO PR associated with <u>Lower ECAM DU Flags-</u> <u>DOOR/OXY</u> OXY CREW - oxygen PRESS IND replaced by amber crosses				351000 P 242 T 810 820
R	REGUL LO PR				351000 P 245 T 810 821
	REGUL LO PR with OXY consumption and not use the mask				351000 P 205 T 810 802

EFF : ALL

SR05

35-ECAM

Page 102
Nov 01/06

WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
	SOURCE	MESSAGE	ATA	C	

MAINTENANCE Pnl (50VU)

R	OXYPEN-TMR RES FAULT lt				352300 P 205
R	comes on and goes off				T 810 803
R	after approx. 30 sec				
R	OXYPEN-TMR RES FAULT lt				352300 P 205
R	comes on and goes off				T 810 803
R	after pushing p/bsw 14WR				
R	OXYPEN-TMR RESET p/bsw				352300 P 205
R	FAULT lt comes on after				T 810 803
R	approx. 30 sec				

FUSELAGE (Z 125)

OVERBOARD discharge					351000 P 237
indicator yellow					T 810 817
OXYP CREW - rapid loss of					351000 P 232
oxygen with yellow OORB					T 810 814
discharge IND is yellow					

OXYPEN Pnl (21VU)

R	OXYPEN-PASSENGER SYS ON				352300 P 201
R	lt off				T 810 801
R	associated with				
R	OXYPEN PAX auto sys				
R	release - all masks do				
R	not drop				
R	and				
R	OXYPEN PAX no PAX				
R	announcement				
R	OXYPEN-PASSENGER SYS ON				352300 P 203
R	lt off				T 810 802

EFF : ALL

SROS

	WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
		SOURCE	MESSAGE	ATA	C	
R R R R R R	OXYGEN-PASSENGER SYS ON lt off associated with OXYGEN PAX man sys release - all masks do not drop and OXYGEN PAX no PAX announcement					352300 P 210 T 810 805
R R R R	OXYGEN-PASSENGER SYS ON lt on associated with OXYGEN PAX no PAX announcement					352300 P 211 T 810 806
R R R R	OXYGEN-PASSENGER SYS ON lt on associated with OXYGEN PAX one mask does not drop					352300 P 213 T 810 807

EFF : ALL

SR0S

	WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
		SOURCE	MESSAGE	ATA	C	
	OXY CREW - captain oxygen stowage box flap door inoperative					351000 P 226 T 810 812
	OXY CREW - captain "OXY ON" flag oxygen stowage box inoperative					351000 P 219 T 810 809
	OXY CREW - captain PRESS to test and reset inoperative					351000 P 211 T 810 805
R	OXY CREW - degradation of the captain flexible supply hose assembly					351000 P 250 T 810 823
R	OXY CREW - degradation of the F/O flexible supply hose assembly					351000 P 250 T 810 823
R	OXY CREW - degradation of the fourth occupant flexible SPLY hose ASSY					351000 P 250 T 810 823
R	OXY CREW - degradation of the third occupant flexible SPLY HOSE ASSY					351000 P 250 T 810 823
	OXY CREW - F/O "OXY ON" flag oxygen stowage box inoperative					351000 P 219 T 810 809
	OXY CREW - F/O oxygen stowage box flap door inoperative					351000 P 226 T 810 812
	OXY CREW - F/O PRESS to test and reset inoperative					351000 P 211 T 810 805
	OXY CREW - fourth "OXY ON" flag oxygen stowage box inoperative					351000 P 219 T 810 809

EFF : ALL

SR0S

35-OBSV

Page 101
Nov 01/06

	WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
		SOURCE	MESSAGE	ATA	C	
R R R	OXY CREW - fourth oxygen stowage box flap door inoperative					351000 P 226 T 810 812
R R R	OXY CREW - fourth PRESS to test and reset inoperative					351000 P 211 T 810 805
R	OXY CREW - loss of emergency over pressure knob at CAPT oxygen mask					351000 P 209 T 810 804
R	OXY CREW - loss of emergency over pressure knob at F/O oxygen mask					351000 P 209 T 810 804
R	OXY CREW - loss of emergency over pressure knob at 3rd oxygen mask					351000 P 209 T 810 804
R R R	OXY CREW - loss of emergency over pressure knob at 4th oxygen mask					351000 P 209 T 810 804
R	OXY CREW - loss of harness inflation at the captain oxygen mask					351000 P 213 T 810 806
R	OXY CREW - loss of harness inflation at the F/O oxygen mask					351000 P 213 T 810 806
R R R	OXY CREW - loss of harness inflation at the fourth oxygen mask					351000 P 213 T 810 806
R	OXY CREW - loss of harness inflation at the third oxygen mask					351000 P 213 T 810 806
	OXY CREW - loss of 100% selection to the captain oxygen mask					351000 P 207 T 810 803

EFF : ALL

SR0S

35-OBSV

Page 102
Aug 01/98

WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
	SOURCE	MESSAGE	ATA	C	
OXY CREW - loss of 100% selection to the F/O oxygen mask					351000 P 207 T 810 803
OXY CREW - loss of 100% selection to the fourth occupant oxygen mask					351000 P 207 T 810 803
OXY CREW - loss of 100% selection to the third occupant oxygen mask					351000 P 207 T 810 803
R OXY CREW - no oxygen to the crew oxygen masks with REGUL LO PR					351000 P 248 T 810 822
OXY CREW - third "OXY ON" flag oxygen stowage box inoperative					351000 P 219 T 810 809
OXY CREW - third oxygen stowage box flap door inoperative					351000 P 226 T 810 812
OXY CREW - third PRESS to test and reset inoperative					351000 P 211 T 810 805
OXY CREW captain oxygen mask dirty					351000 P 215 T 810 807
OXY CREW F/O oxygen mask dirty					351000 P 215 T 810 807
OXY CREW failure of fourth oxygen flow indicator					351000 P 234 T 810 815
OXY CREW failure of third oxygen flow indicator					351000 P 234 T 810 815
OXY CREW failure of CAPT oxygen flow indicator					351000 P 234 T 810 815

EFF : ALL

SR0S

35-OBSV

Page 103
Nov 01/06

WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
	SOURCE	MESSAGE	ATA	C	
OXY CREW failure of F/O oxygen flow indicator					351000 P 234 T 810 815
OXY CREW fourth oxygen mask dirty					351000 P 215 T 810 807
OXY CREW impossibility to close the cylinder valve					351000 P 218 T 810 808
R OXY CREW impossibility to refill the oxygen cylinder					351000 P 241 T 810 819
OXY CREW no oxygen to captain oxygen mask					351000 P 222 T 810 810
OXY CREW no oxygen to F/O oxygen mask					351000 P 222 T 810 810
OXY CREW no oxygen to fourth oxygen mask					351000 P 222 T 810 810
OXY CREW no oxygen to third oxygen mask					351000 P 222 T 810 810
OXY CREW rapid loss of oxygen					351000 P 228 T 810 813
OXY CREW third oxygen mask dirty					351000 P 215 T 810 807
OXYGEN PAX auto sys release - all masks do not drop associated with <u>OXYGEN Pnl (21VU)</u> OXYGEN-PASSENGER SYS ON lt off and OXYGEN PAX no PAX announcement					352300 P 201 T 810 801

EFF : ALL

SR0S

35-OBSV

Page 104
Nov 01/06

	WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
		SOURCE	MESSAGE	ATA	C	
R R R R R R	OXYGEN PAX man sys release - all masks do not drop associated with <u>OXYGEN Pnl (21VU)</u> OXYGEN-PASSENGER SYS ON lt off and OXYGEN PAX no PAX announcement					352300 P 210 T 810 805
R R R R R R R	OXYGEN PAX no PAX announcement associated with <u>OXYGEN Pnl (21VU)</u> OXYGEN-PASSENGER SYS ON lt off and OXYGEN PAX auto sys release - all masks do not drop					352300 P 201 T 810 801
R R R R R R R	OXYGEN PAX no PAX announcement associated with <u>OXYGEN Pnl (21VU)</u> OXYGEN-PASSENGER SYS ON lt off and OXYGEN PAX man sys release - all masks do not drop					352300 P 210 T 810 805
R R R R R	OXYGEN PAX no PAX announcement associated with <u>OXYGEN Pnl (21VU)</u> OXYGEN-PASSENGER SYS ON lt on					352300 P 211 T 810 806
R R R R	OXYGEN PAX one mask does not drop associated with <u>OXYGEN Pnl (21VU)</u> OXYGEN-PASSENGER SYS ON lt on					352300 P 213 T 810 807

EFF : ALL

SROS

35-OBSV

Page 105
Feb 01/03

	WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
		SOURCE	MESSAGE	ATA	C	
R R	OXYGEN PAX one set of masks does not drop					352300 P 208 T 810 804
R R R	OXYGEN PAX one set of masks drop after approx. 6 sec					352300 P 208 T 810 804

EFF : ALL

SR0S

35-OBSV

Page 106
Feb 01/03

A319/A320/A321

TROUBLE SHOOTING MANUAL

OXYGEN - FAULT SYMPTOMS

R
R
R
R

WARNINGS/MALFUNCTIONS	CFDS FAULT MESSAGES				FAULT ISOLATION PROCEDURE
	SOURCE	MESSAGE	ATA	C	
	ECAM 1	SDAC1 : 0X PRESS REG XMTR 4HT	351315	1	315400 P 247 T 810 845
	IDENT: ECAM 2				
	ECAM 1	SDAC2 : 0X PRESS REG XMTR 4HT	351315	1	315400 P 248 T 810 846
	IDENT: ECAM 2				
	ECAM 2	SDAC1 : 0X PRESS REG XMTR 4HT	351315	1	315400 P 247 T 810 845
	ECAM 2	SDAC2 : 0X PRESS REG XMTR 4HT	351315	1	315400 P 248 T 810 846

EFF : ALL

SR0S

35-CFDS

Page 101
Aug 01/07

TASK 35-10-00-810-801

Loss of the Oxygen Pressure Indication on the D00R/OXY Page

1. Possible Causes

- XMTR/PRESS REG-OXY (4HT)
- wiring from the pressure regulator/transmitter (4HT) pin A/A, B to the first terminal block
- wiring from the pressure regulator/transmitter (4HT) pin A/D to the ground terminal
- wiring from the pressure regulator/transmitter (4HT) to the circuit breaker (1HT)
- C/B-OXYGEN/CREW/OXY/SPLY (1HT)
- wiring from the circuit breaker (1HT) to the pressure regulator/transmitter (4HT)
- wiring from the pressure regulator/transmitter (4HT) pins A/A, B to the first terminal block
- C/B-OXYGEN/CREW/OXY/SPLY

2. Job Set-up Information

A. Referenced Information

REFERENCE		DESIGNATION
-----		-----
AMM	24-41-00-861-002	Energize the Aircraft Electrical Circuits from the External Power
AMM	24-41-00-862-002	De-energize the Aircraft Electrical Circuits Supplied from the External Power
AMM	31-60-00-860-001	EIS Start Procedure
R	AMM	35-13-15-000-001 Removal of the Oxygen Pressure Regulator/Transmitter (4HT)
R		
R	AMM	35-13-15-400-001 Installation of the Oxygen Pressure Regulator/Transmitter (4HT)
R		
ASM	35-13/01	

3. Fault Confirmation

A. Aircraft Maintenance Configuration

- (1) Energize the aircraft electrical circuits (Ref. AMM TASK 24-41-00-861-002).
- (2) Do the EIS start procedure (Upper ECAM DU and lower ECAM DU only) (Ref. AMM TASK 31-60-00-860-001).

EFF : ALL

SR0S

35-10-00

Page 201
Feb 01/96

TROUBLE SHOOTING MANUAL

- (3) On the panel 21VU, push the OXYGEN/CREW SUPPLY pushbutton switch (the OFF legend goes off).

B. Make sure that this(these) circuit breaker(s) is(are) closed:

PANEL DESIGNATION		IDENT. LOCATION	
R	49VU OXYGEN/CREW/OXY/SPLY	1HT	HA01
R			

C. Test

- (1) On the ECAM control panel:
- push the DOOR key to get the DOOR/OXY page.
- (2) Make sure that the oxygen pressure indication is replaced by amber crosses on the DOOR/OXY page.
- (3) If the circuit breaker (1HT) trips:
- refer to Para. 4.A.(2).

4. Fault Isolation

A. If the test confirms the fault:

- do a check of the circuit breaker (1HT) status:

- (1) If the circuit breaker (1HT) is closed:
- do a check for 28VDC at pin A/C of the pressure regulator/transmitter (4HT) (Ref. ASM 35-13/01).

(a) If there is 28VDC:

- replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001).

- 1 If the fault continues:
- do a check and repair the wiring from the pressure regulator/transmitter (4HT) pin A/A, B to the first terminal block (Ref. ASM 35-13/01).

(b) If there is no 28VDC:

- do a check for a ground signal at pin A/D of the pressure regulator/transmitter (4HT) (Ref. ASM 35-13/01).

EFF : ALL

SR0S

35-10-00

Page 202
May 01/96

TROUBLE SHOOTING MANUAL

- 1 If there is no ground signal:
 - repair the wiring from the pressure regulator/transmitter (4HT) pin A/D to the ground terminal (Ref. ASM 35-13/01).
 - 2 If there is a ground signal:
 - do a check of the wiring from the pressure regulator/transmitter (4HT) to the circuit breaker (1HT) pin A/C to pin 2 (Ref. ASM 35-13/01).
 - a If there is no continuity:
 - repair the above wiring.
 - b If there is continuity:
 - replace the C/B-OXYGEN/CREW/OXY/SPLY (1HT) (Ref. ASM 35-13/01).
- (2) If the circuit breaker is open:
 - close it.
- (a) If it trips:
 - replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001).
- 1 If the fault continues:
 - do a check for a short to ground at the wiring from the circuit breaker (1HT) to the pressure regulator/transmitter (4HT) pin 2 to pin A/C (Ref. ASM 35-13/01).
 - a If there is a short to ground.
 - repair the above wiring.
 - b If there is no short to ground.
 - do a check for a short to ground at the wiring from the pressure regulator/transmitter (4HT) pins A/A, B to the first terminal block (Ref. ASM 35-13/01).
 - 2 If there is a short to ground:
 - repair the above wiring.
 - 3 If there is no short to ground:
 - replace the C/B-OXYGEN/CREW/OXY/SPLY (Ref. ASM 35-13/01).
- (b) If the circuit breaker is still closed and if the fault continues:
 - replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001).

B. Test

- (1) Make sure that the oxygen pressure indication comes on the DOOR/OXY page.

R

EFF : ALL

SR0S

35-10-00

Page 203
Feb 01/96

5. Close-up

A. Put the aircraft back to its initial configuration.

- (1) On the ECAM Control Panel, set the LOWER DISPLAY and the UPPER DISPLAY potentiometers to OFF.**
- (2) On the panel 21VU:**
 - release the OXYGEN/CREW SUPPLY pushbutton switch. The OFF legend comes on.**
- (3) De-energize the aircraft electrical circuits (Ref. AMM TASK 24-41-00-862-002).**

EFF : ALL

SR05

35-10-00

Page 204
Aug 01/95

R

TASK 35-10-00-810-802

REGUL LO PR with Oxygen Consumption without the Use of the Oxygen Mask

1. Possible Causes

- STOWAGE BOX-OXY MASK, CAPT (10RN1)
- STOWAGE BOX-OXY MASK, F/O (10RN2)
- STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3)
- HOSE-STOWAGE BOX (5764HM)
- HOSE-STOWAGE BOX (5765HM)
- HOSE-STOWAGE BOX (5766HM)
- MANIFOLD-OXY DISTRIBUTION (5753HM)
- TEST PORT-OXY SYS (5755HM)
- HOSE-OXY SPLY (5763HM)
- XMTR/PRESS REG-OXY (4HT)
- SOL VALVE-LP OXY SPLY (3HT)
- PRESS SW-OXYGEN LO PR (4WV)
- BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM)
- HOSE-STOWAGE BOX (5768HM)

2. Job Set-up Information**A. Referenced Information**

REFERENCE		DESIGNATION
R	AMM 35-10-00-790-001	Leakage Test of the LP Oxygen System for the Crew
	AMM 35-12-41-000-001	Removal of the Oxygen-Mask Stowage-Box
	AMM 35-12-41-400-001	Installation of the Oxygen-Mask Stowage-Box
	AMM 35-13-14-000-001	Removal of the Press Sw-Oxygen LO PR (4WV)
	AMM 35-13-14-400-001	Installation of the Press Sw-Oxygen LO PR (4WV)
	AMM 35-13-15-000-001	Removal of the Oxygen Pressure Regulator/Transmitter (4HT)
	AMM 35-13-15-400-001	Installation of the Oxygen Pressure Regulator/Transmitter (4HT)
	AMM 35-13-51-000-001	Removal of the Sol Valve-LP Oxy Sply (3HT)
	AMM 35-13-51-400-001	Installation of the LP Oxygen-Supply Solenoid-Valve (3HT)

3. Fault Confirmation**A. Test**

- (1) Do a leakage test of the LP oxygen system for the crew: (Ref. AMM TASK 35-10-00-790-001).

EFF : ALL

SROS

35-10-00Page 205
Nov 01/05

4. Fault Isolation

R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,

A. If the pressure decreases during the leakage test

- replace the defective component: STOWAGE BOX-OXY MASK, CAPT (10RN1) or STOWAGE BOX-OXY MASK, F/O (10RN2) or STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001) or HOSE-STOWAGE BOX (5764HM) or HOSE-STOWAGE BOX (5765HM) or HOSE-STOWAGE BOX (5766HM) or MANIFOLD-OXY DISTRIBUTION (5753HM) or TEST PORT-OXY SYS (5755HM) or HOSE-OXY SPLY (5763HM) or XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001) or SOL VALVE-LP OXY SPLY (3HT) (Ref. AMM TASK 35-13-51-000-001) and (Ref. AMM TASK 35-13-51-400-001) or PRESS SW-OXYGEN LO PR (4WV) (Ref. AMM TASK 35-13-14-000-001) and (Ref. AMM TASK 35-13-14-400-001).

**ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553,555-555,

A. If the pressure decreases during the leakage test

- replace the defective component: STOWAGE BOX-OXY MASK, CAPT (10RN1) or STOWAGE BOX-OXY MASK, F/O (10RN2) or STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) or BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001) or HOSE-STOWAGE BOX (5764HM) or HOSE-STOWAGE BOX (5765HM) or HOSE-STOWAGE BOX (5766HM) or HOSE-STOWAGE BOX (5768HM) or MANIFOLD-OXY DISTRIBUTION (5753HM) or TEST PORT-OXY SYS (5755HM) or HOSE-OXY SPLY (5763HM) or XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001) or SOL VALVE-LP OXY SPLY (3HT) (Ref. AMM TASK 35-13-51-000-001) and (Ref. AMM TASK 35-13-51-400-001) or PRESS SW-OXYGEN LO PR (4WV) (Ref. AMM TASK 35-13-14-000-001) and (Ref. AMM TASK 35-13-14-400-001).

**ON A/C ALL

B. Do the test given in Para. 3.A.

EFF : ALL

SROS

35-10-00

Page 206
May 01/08

TASK 35-10-00-810-803

Loss of the 100 % Selection on the Oxygen Mask

1. Possible Causes

- MASK-FULL FACE/Q.D. OXY, CAPT (5759HM)
- MASK-FULL FACE/Q.D. OXY, F/O (5758HM)
- MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM)
- MASK-FULL FACE/Q.D. OXY, 4TH OCCPNT (5760HM)

2. Job Set-up Information**A. Referenced Information****REFERENCE****DESIGNATION**

AMM 35-12-41-000-002	Removal of the Full-Face/Quick-Donning Oxygen-Mask
AMM 35-12-41-400-002	Installation of the Full-Face/Quick-donning Oxygen-Mask
AMM 35-12-41-710-001	Operational Test of the Full Face/Quick Donning Oxygen Masks (5757HM,5758HM,5759HM,5760HM)

3. Fault Confirmation**A. Test**

- (1) Do the operational test of the full face/quick donning oxygen masks (Ref. AMM TASK 35-12-41-710-001).

4. Fault Isolation

R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,

A. If during the operational test

- (1) The 100 % selection on the Captain oxygen mask is inoperative:
- replace the MASK-FULL FACE/Q.D. OXY, CAPT (5759HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (2) The 100 % selection on the First Officer oxygen mask is inoperative:
- replace the MASK-FULL FACE/Q.D. OXY, F/O (5758HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (3) The 100 % selection on the Third Occupant oxygen mask is inoperative:
- replace the MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

EFF : ALL

SR0S

35-10-00

Page 207
May 01/08

R **ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553,555-555,

A. If during the operational test

- (1) The 100 % selection on the Captain oxygen mask is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, CAPT (5759HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (2) The 100 % selection on the First Officer oxygen mask is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, F/O (5758HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (3) The 100 % selection on the Third Occupant oxygen mask is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (4) The 100 % selection on the Fourth Occupant oxygen mask is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, 4TH OCCPNT (5760HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

R EFF : 251-251, 254-275, 503-549, 553-553,
555-555, 701-749,

SR0S

35-10-00

Page 208
Feb 01/08

****ON A/C ALL****TASK 35-10-00-810-804**

Loss of the Emergency Overpressure Knob on the Oxygen Mask

1. Possible Causes

- MASK-FULL FACE/Q.D. OXY, CAPT (5759HM)
- MASK-FULL FACE/Q.D. OXY, F/O (5758HM)
- MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM)
- MASK-FULL FACE/Q.D. OXY, 4TH OCCPNT (5760HM)

2. Job Set-up Information**A. Referenced Information****REFERENCE****DESIGNATION**

AMM 35-12-41-000-002	Removal of the Full-Face/Quick-Donning Oxygen-Mask
AMM 35-12-41-400-002	Installation of the Full-Face/Quick-donning Oxygen-Mask
AMM 35-12-41-710-001	Operational Test of the Full Face/Quick Donning Oxygen Masks (5757HM,5758HM,5759HM,5760HM)

3. Fault Confirmation**A. Test**

- (1) Do the operational test of the full face/quick donning oxygen mask (Ref. AMM TASK 35-12-41-710-001).

4. Fault Isolation**R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,****A. If during the operational test**

- (1) The emergency overpressure knob on the Captain oxygen mask is inoperative:
- replace the MASK-FULL FACE/Q.D. OXY, CAPT (5759HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (2) The emergency overpressure knob on the First Officer oxygen mask is inoperative:
- replace the MASK-FULL FACE/Q.D. OXY, F/O (5758HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

EFF : ALL**SROS****35-10-00**Page 209
May 01/08

(3) The emergency overpressure knob on the Third Occupant oxygen mask is inoperative:

- replace the MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

R **ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553,555-555,

A. If during the operational test

(1) The emergency overpressure knob on the Captain oxygen mask is inoperative:

- replace the MASK-FULL FACE/Q.D. OXY, CAPT (5759HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

(2) The emergency overpressure knob on the First Officer oxygen mask is inoperative:

- replace the MASK-FULL FACE/Q.D. OXY, F/O (5758HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

(3) The emergency overpressure knob on the Third Occupant oxygen mask is inoperative:

- replace the MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

(4) The emergency overpressure knob on the Fourth Occupant oxygen mask is inoperative:

- replace the MASK-FULL FACE/Q.D. OXY, 4TH OCCPNT (5760HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

R EFF : ALL

SR0S

35-10-00

Page 210
Feb 01/08

****ON A/C ALL****TASK 35-10-00-810-805****PRESS TO TEST AND RESET Button Inoperative****1. Possible Causes**

- STOWAGE BOX-OXY MASK, CAPT (10RN1)
- STOWAGE BOX-OXY MASK, F/O (10RN2)
- STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3)
- BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM)

2. Job Set-up Information**A. Referenced Information****REFERENCE****DESIGNATION**

AMM 35-12-41-000-001	Removal of the Oxygen-Mask Stowage-Box
AMM 35-12-41-400-001	Installation of the Oxygen-Mask Stowage-Box
AMM 35-12-41-710-001	Operational Test of the Full Face/Quick Donning Oxygen Masks (5757HM,5758HM,5759HM,5760HM)

3. Fault Confirmation**A. Test**

- (1) Do the operational test of the full-face/quick-donning oxygen mask (Ref. AMM TASK 35-12-41-710-001).

4. Fault Isolation**R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,****A. If during the operational test**

- (1) The Captain PRESS TO TEST AND RESET button is inoperative:
- replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (2) The First Officer PRESS TO TEST AND RESET button is inoperative:
- replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (3) The Third occupant PRESS TO TEST AND RESET button is inoperative:
- replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).

EFF : ALL**SR05****35-10-00****Page 211
May 01/08**

A319/A320/A321

TROUBLE SHOOTING MANUAL

R **ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553, 555-555,

A. If during the operational test

- (1) The Captain PRESS TO TEST and RESET button is inoperative:
 - replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (2) The First Officer PRESS TO TEST AND RESET button is inoperative:
 - replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (3) The Third occupant PRESS TO TEST AND RESET button is inoperative:
 - replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (4) The Fourth occupant PRESS TO TEST AND RESET button is inoperative:
 - replace the BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).

**ON A/C ALL

B. Do the test given in Para. 3.A.

EFF : ALL

SR0S

35-10-00

Page 212
Feb 01/08

TASK 35-10-00-810-806**No Inflation of the Oxygen Mask Harness****1. Possible Causes**

- MASK-FULL FACE/Q.D. OXY, CAPT (5759HM)
- MASK-FULL FACE/Q.D. OXY, F/O (5758HM)
- MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM)
- MASK-FULL FACE/Q.D. OXY, 4TH OCCPNT (5760HM)

2. Job Set-up Information**A. Referenced Information****REFERENCE****DESIGNATION**

AMM 35-12-41-000-002	Removal of the Full-Face/Quick-Donning Oxygen-Mask
AMM 35-12-41-200-001	Detailed Inspection of Oxygen Masks (out of box) with Harness Inflated
AMM 35-12-41-400-002	Installation of the Full-Face/Quick-donning Oxygen-Mask

3. Fault Confirmation**A. Test**

- (1) Do the visual inspection of the flight crew oxygen mask (out of box) (Ref. AMM TASK 35-12-41-200-001).

4. Fault Isolation

R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,

A. If during the visual inspection:

- (1) The Captain harness inflation is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, CAPT (5759HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (2) The First Officer harness inflation is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, F/O (5758HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (3) The Third Occupant harness inflation is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

EFF : ALL

SR05

35-10-00

**Page 213
May 01/08**

R **ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553,555-555,

A. If during the visual inspection

- (1) The Captain harness inflation is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, CAPT (5759HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (2) The First Officer harness inflation is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, F/O (5758HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (3) The Third Occupant harness inflation is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (4) The Fourth Occupant harness inflation is inoperative:
 - replace the MASK-FULL FACE/Q.D. OXY, 4TH OCCPNT (5760HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

R EFF : 251-251, 254-275, 503-549, 553-553,
555-555, 701-749,

SR0S

35-10-00

Page 214
Feb 01/08

****ON A/C ALL**

TASK 35-10-00-810-807

Crew Oxygen Mask Dirty

1. Possible Causes

- MASK-FULL FACE/Q.D. OXY, CAPT (5759HM)
- MASK-FULL FACE/Q.D. OXY, F/O (5758HM)
- MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM)
- MASK-FULL FACE/Q.D. OXY, 4TH OCCPNT (5760HM)

2. Job Set-up Information

A. Referenced Information

REFERENCE

DESIGNATION

AMM 24-41-00-861-002	Energize the Aircraft Electrical Circuits from the External Power
AMM 35-12-41-100-001	Cleaning of the Mask-Full Face / Q.D, Oxygen (5757HM,5758HM,5759HM,5760HM)

3. Fault Confirmation

A. Job Set Up

(1) Aircraft Maintenance Configuration

(a) Energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-861-002).

(b) Make sure that this(these) circuit breaker(s) is(are) closed:
1HT.

(c) On the panel 21VU push the OXYGEN/CREW SUPPLY pushbutton switch
(the OFF legend goes off).

B. Make sure that this(these) circuit breaker(s) is(are) closed:

PANEL DESIGNATION

IDENT. LOCATION

49VU OXYGEN/CREW/OXY/SPLY

1HT

HA01

EFF : ALL

SR0S

35-10-00

Page 215
May 01/08

C. Test

- (1) Remove the oxygen mask from the flight crew oxygen box.
- (2) Make sure that the mask is dirty.

4. Fault Isolation

R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,

A. If during the test:

- (1) The Captain Oxygen mask is dirty:
 - clean the MASK-FULL FACE/Q.D. OXY, CAPT (5759HM) (Ref. AMM TASK 35-12-41-100-001).
- (2) The First Officer mask is dirty:
 - clean the MASK-FULL FACE/Q.D. OXY, F/O (5758HM) (Ref. AMM TASK 35-12-41-100-001).
- (3) The Third Occupant oxygen mask is dirty:
 - clean the MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM) (Ref. AMM TASK 35-12-41-100-001).

**ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553,555-555,

A. If during the test:

- (1) The Captain Oxygen mask is dirty:
 - clean the MASK-FULL FACE/Q.D. OXY, CAPT (5759HM) (Ref. AMM TASK 35-12-41-100-001).
- (2) The First Officer mask is dirty:
 - clean the MASK-FULL FACE/Q.D. OXY, F/O (5758HM) (Ref. AMM TASK 35-12-41-100-001).
- (3) The Third Occupant oxygen mask is dirty:
 - clean the MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM) (Ref. AMM TASK 35-12-41-100-001).
- (4) The Fourth Occupant oxygen mask is dirty:
 - clean the MASK-FULL FACE/Q.D. OXY, 4TH OCCPNT (5760HM) (Ref. AMM TASK 35-12-41-100-001).

EFF : ALL

SR0S

35-10-00

Page 216
May 01/08

R **ON A/C ALL

5. Close-up

A. Put the aircraft back to its initial configuration.

(1) After you have examined the last oxygen mask, release the OXYGEN/CREW SUPPLY pushbutton switch (the OFF legend comes on).

(2) De-energize the aircraft electrical circuits

EFF : ALL

SR0S

35-10-00

Page 217
Aug 01/98

TASK 35-10-00-810-808

Oxygen Cylinder Valve Closing not Possible

1. Possible Causes

- CYLINDER-OXYGEN STORAGE (5750HM)

2. Job Set-up Information**A. Referenced Information**

REFERENCE**DESIGNATION**

AMM 35-11-41-000-001

Removal of the Crew Oxygen-Storage Cylinder (5750HM)

AMM 35-11-41-400-001

Installation of the Crew Oxygen-Storage Cylinder
(5750HM)**3. Fault Confirmation****A. Test**

Not applicable, the fault is evident.

4. Fault Isolation**A. If the test confirms the fault:**

- replace the CYLINDER-OXYGEN STORAGE (5750HM) (Ref. AMM TASK 35-11-41-000-001) (Ref. AMM TASK 35-11-41-400-001).

EFF : ALL

SR0S

35-10-00Page 218
Aug 01/98

TASK 35-10-00-810-809

OXY ON flag on the Mask Stowage Box Inoperative

1. Possible Causes

- STOWAGE BOX-OXY MASK, CAPT (10RN1)
- STOWAGE BOX-OXY MASK, F/O (10RN2)
- STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3)
- BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM)

2. Job Set-up Information**A. Referenced Information**

REFERENCE	DESIGNATION
AMM 24-41-00-861-002	Energize the Aircraft Electrical Circuits from the External Power
AMM 24-41-00-862-002	De-energize the Aircraft Electrical Circuits Supplied from the External Power
AMM 35-12-41-000-001	Removal of the Oxygen-Mask Stowage-Box
AMM 35-12-41-400-001	Installation of the Oxygen-Mask Stowage-Box

3. Fault Confirmation**A. Job Set Up****(1) Aircraft Maintenance Configuration**

(a) Energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-861-002).

(b) On the panel 21VU push the OXYGEN/CREW SUPPLY pushbutton switch
(the OFF legend goes off).

B. Make sure that this(these) circuit breaker(s) is(are) closed:

PANEL	DESIGNATION	IDENT.	LOCATION
49VU	OXYGEN/CREW/OXY/SPLY	1HT	HA01

C. Test

(1) Remove the oxygen mask.

(2) Make sure that the OXY ON flag on the mask stowage box is inoperative.

EFF : ALL

SR0S

35-10-00Page 219
Nov 01/05

4. Fault Isolation

R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,

A. If the OXY ON flag:

- (1) On the Captain mask stowage box is inoperative with the mask out of the box:
 - replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (2) On the First Officer mask stowage box is inoperative with the mask out of the box:
 - replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (3) On the Third Occupant mask stowage box is inoperative with the mask out of the box:
 - replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).

**ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553, 555-555,

A. If the OXY ON flag:

- (1) On the Captain mask stowage box is inoperative with the mask out of the box:
 - replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (2) On the First Officer mask stowage box is inoperative with the mask out of the box:
 - replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (3) On the Third Occupant mask stowage box is inoperative with the mask out of the box:
 - replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (4) On the Fourth Occupant mask stowage box is inoperative with the mask out of the box:
 - replace the BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).

EFF : ALL

SR0S

35-10-00

Page 220
May 01/08

****ON A/C ALL**

B. Test

(1) Remove the oxygen mask.

(2) Make sure that the OXY ON flag on the mask stowage box is shown.

5. Close-up

A. Put the aircraft back to its initial configuration.

(1) On the panel 21VU, release the OXYGEN/CREW SUPPLY pushbutton switch (the OFF legend comes on).

(2) De-energize the aircraft electrical circuits (Ref. AMM TASK 24-41-00-862-002).

R

EFF : ALL

SR0S

35-10-00

Page 221
Nov 01/05

TASK 35-10-00-810-810**No Oxygen at the Full-Face/Quick-Donning Oxygen-Mask****1. Possible Causes**

- STOWAGE BOX-OXY MASK, CAPT (10RN1)
- STOWAGE BOX-OXY MASK, F/O (10RN2)
- STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3)
- BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM)

2. Job Set-up Information**A. Referenced Information****REFERENCE****DESIGNATION**

AMM 35-12-41-000-001	Removal of the Oxygen-Mask Stowage-Box
AMM 35-12-41-400-001	Installation of the Oxygen-Mask Stowage-Box
AMM 35-12-41-710-001	Operational Test of the Full Face/Quick Donning Oxygen Masks (5757HM,5758HM,5759HM,5760HM)

3. Fault Confirmation**A. Test**

- (1) Do the operational test of the full-face/quick-donning oxygen masks:
(Ref. AMM TASK 35-12-41-710-001).

4. Fault Isolation**R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,****A. If during the operational test:**

- (1) There is no oxygen at the Captain mask stowage box:
- replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (2) There is no oxygen at the F/O mask stowage box.
- replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (3) There is no oxygen at the Third Occupant mask stowage box:
- replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).

EFF : ALL**SROS****35-10-00****Page 222
May 01/08**

A319/A320/A321

TROUBLE SHOOTING MANUAL

R **ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553,555-555,

A. If during the operational test:

- (1) There is no oxygen at the Captain mask stowage box:
 - replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (2) There is no oxygen at the F/O mask stowage box:
 - replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (3) There is no oxygen at the Third Occupant mask stowage box:
 - replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (4) There is no oxygen at the Fourth Occupant mask stowage box:
 - replace the BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).

**ON A/C ALL

B. Do the test given in Para. 3.A.

EFF : ALL

SR0S

35-10-00

Page 223
Feb 01/08

TASK 35-10-00-810-811

Crew Oxygen Indication less than 400PSI on the D00R/OXY page

1. Possible Causes

- CYLINDER-OXYGEN STORAGE (5750HM)
- XMTR/PRESS REG-OXY (4HT)

2. Job Set-up Information**A. Referenced Information**

REFERENCE	DESIGNATION
AMM 24-41-00-861-002	Energize the Aircraft Electrical Circuits from the External Power
AMM 24-41-00-862-002	De-energize the Aircraft Electrical Circuits Supplied from the External Power
AMM 31-60-00-860-001	EIS Start Procedure
AMM 31-60-00-860-002	EIS Stop Procedure
AMM 35-10-00-040-001	OXY High Pressure Indication-Direct Reading.
AMM 35-11-41-000-001	Removal of the Crew Oxygen-Storage Cylinder (5750HM)
AMM 35-11-41-400-001	Installation of the Crew Oxygen-Storage Cylinder (5750HM)
AMM 35-13-15-000-001	Removal of the Oxygen Pressure Regulator/Transmitter (4HT)
AMM 35-13-15-400-001	Installation of the Oxygen Pressure Regulator/Transmitter (4HT)

3. Fault Confirmation**A. Job Set Up****(1) Aircraft Maintenance Configuration**

- (a) Energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-861-002).
- (b) Do the EIS start procedure (Upper ECAM DU and lower ECAM DU only)
(Ref. AMM TASK 31-60-00-860-001).

B. Make sure that this(these) circuit breaker(s) is(are) closed:

PANEL	DESIGNATION	IDENT.	LOCATION
49VU	OXYGEN/CREW/OXY/SPLY	1HT	HA01

R EFF : ALL

SROS

35-10-00Page 224
Aug 01/98

C. Test

- (1) On the ECAM control panel:
 - push the **DOOR** key to get the **DOOR/OXY** page.
- (2) Make sure that the **OXY** pressure indication is less than **400PSI**.
- (3) Do an **OXY** high-pressure indication direct reading (Ref. **AMM TASK 35-10-00-040-001**).

4. Fault Isolation

A. If during the check of the pressure of the crew cylinder, the value is:

- (1) The same as the value on the **SD**, on the **DOOR/OXY** page:
 - replace the **CYLINDER-OXYGEN STORAGE (5750HM)** (Ref. **AMM TASK 35-11-41-000-001**) and (Ref. **AMM TASK 35-11-41-400-001**).
- (2) Different from the value on the **SD**, on the **DOOR/OXY** page.
 - replace the **XMTR/PRESS REG-OXY (4HT)** (Ref. **AMM TASK 35-13-15-000-001**) and (Ref. **AMM TASK 35-13-15-400-001**).
- (a) If the fault continues:
 - replace the **CYLINDER-OXYGEN STORAGE (5750HM)** (Ref. **AMM TASK 35-11-41-000-001**) and (Ref. **AMM TASK 35-11-41-400-001**).

B. Test

- (1) Make sure that the **OXY** pressure indication is normal (more than **1500PSI**) on the **DOOR/OXY** page.

5. Close-up

A. Put the aircraft back to its initial configuration.

- (1) On the ECAM control panel, set the **UPPER DISPLAY** and **LOWER DISPLAY** potentiometers to **OFF**.
(Ref. **AMM TASK 31-60-00-860-002**).
- (2) De-energize the aircraft electrical circuits
(Ref. **AMM TASK 24-41-00-862-002**).

R

EFF : ALL

SR0S

35-10-00

Page 225
Aug 01/98

TASK 35-10-00-810-812**Flap Door of the Mask Stowage-Box Inoperative****1. Possible Causes**

- STOWAGE BOX-OXY MASK, CAPT (10RN1)
- STOWAGE BOX-OXY MASK, F/O (10RN2)
- STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3)
- BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM)

2. Job Set-up Information**A. Referenced Information****REFERENCE****DESIGNATION**

AMM 35-12-41-000-001	Removal of the Oxygen-Mask Stowage-Box
AMM 35-12-41-200-001	Detailed Inspection of Oxygen Masks (out of box) with Harness Inflated
AMM 35-12-41-400-001	Installation of the Oxygen-Mask Stowage-Box

3. Fault Confirmation**A. Test**

- (1) Do the visual inspection of the flight crew oxygen mask (out of box) (Ref. AMM TASK 35-12-41-200-001).

4. Fault Isolation

R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,

A. If during the inspection:

- (1) The flap door of the Captain mask stowage-box is deteriorated or inoperative:
- replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (2) The flap door of the First Officer mask stowage-box is deteriorated or inoperative:
- replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (3) The flap door of the Third Occupant mask stowage-box is deteriorated or inoperative:
- replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).

EFF : ALL

SR0S

35-10-00

Page 226
May 01/08

R **ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553, 555-555,

A. If during the inspection:

- (1) The flap door of the Captain mask stowage-box is deteriorated or inoperative:
 - replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (2) The flap door of the First Officer mask stowage-box is deteriorated or inoperative:
 - replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (3) The flap door of the Third Occupant mask stowage-box is deteriorated or inoperative:
 - replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (4) The flap door of the Fourth Occupant mask stowage-box is deteriorated or inoperative:
 - replace the BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).

**ON A/C ALL

B. Do the test given in Para. 3.A.

EFF : ALL

SR0S

35-10-00

Page 227
Feb 01/08

TASK 35-10-00-810-813

Fast Loss of Crew Oxygen

WARNING : KEEP ALL HYDROCARBONS (FUELS, LUBRICANTS, ETC.) AWAY FROM ALL SOURCE OF OXYGEN. OXYGEN BECOMES EXPLOSIVE WHEN IT TOUCHES HYDROCARBONS.

WARNING : CLEAN THE TOOLS AND MAKE SURE YOUR HANDS ARE CLEAN TO PREVENT CONTAMINATION OF THE OXYGEN SYSTEM.

CAUTION : PUT DRY, CLEAN, METAL OR PLASTIC PLUGS ON ALL PIPES OR UNITS REMOVED TEMPORARILY. PUT EACH PIPE OR UNIT IN A SEALED VINYL BAG.

1. Possible Causes

- CYLINDER-OXYGEN STORAGE (5750HM)
- XMTR/PRESS REG-OXY (4HT)
- low pressure circuit
- high pressure circuit

2. Job Set-up Information

A. Consumable Materials

REFERENCE

DESIGNATION

R Material No. 05-004 USA MIL-PRF-25567 TYPE I
 OXYGEN LEAK DETECTOR (Ref. 20-31-00)

B. Referenced Information

REFERENCE

DESIGNATION

AMM 24-41-00-861-002	Energize the Aircraft Electrical Circuits from the External Power
AMM 24-41-00-862-002	De-energize the Aircraft Electrical Circuits Supplied from the External Power
AMM 31-60-00-860-001	EIS Start Procedure
AMM 31-60-00-860-002	EIS Stop Procedure
AMM 35-11-41-000-001	Removal of the Crew Oxygen-Storage Cylinder (5750HM)
AMM 35-11-41-400-001	Installation of the Crew Oxygen-Storage Cylinder (5750HM)
AMM 35-12-41-000-001	Removal of the Oxygen-Mask Stowage-Box
AMM 35-12-41-400-001	Installation of the Oxygen-Mask Stowage-Box
AMM 35-13-15-000-001	Removal of the Oxygen Pressure Regulator/Transmitter (4HT)

EFF : ALL

SROS

35-10-00

Page 228
May 01/06

REFERENCE	DESIGNATION
-----------	-------------

AMM 35-13-15-400-001 Installation of the Oxygen Pressure Regulator/Transmitter (4HT)

3. Fault Confirmation

A. Job Set Up

(1) Aircraft Maintenance Configuration

(a) Energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-861-002).

(b) Do the EIS start procedure (Upper ECAM DU and lower ECAM DU only)
(Ref. AMM TASK 31-60-00-860-001)

R
R

(c) Remove the oxygen-mask stowage box (Ref. AMM TASK 35-12-41-000-001).

R
R

B. Make sure that this(these) circuit breaker(s) is(are) closed:

PANEL	DESIGNATION	IDENT.	LOCATION
49VU	OXYGEN/CREW/OXY/SPLY	1HT	HA01

C. Test

R

(1) Make sure that all the masks are not supplied with oxygen.

R

(2) On the OXYGEN section of the overhead panel 21VU, push the CREW SUPPLY pushbutton switch (the OFF legend comes on).

R
R

(3) Close the valve of the oxygen-cylinder valve assembly.

R

(4) On the ECAM control panel:
- push the DOOR key to get the DOOR/OXY page.

R
R

(5) Do a check of the oxygen pressure indication.

R

EFF : ALL

SR05

35-10-00

Page 229
Nov 01/02

4. Fault Isolation

R **A. If the low pressure indication comes into view on the ECAM System Display**
R **in less than 20 minutes:**

R **(1) Do a leak test of the low pressure circuit with the SPECIAL MATERIALS**
R **(Material No. 05-004).**

R **(a) If leaks are found:**
R **- replace the damaged components of the low pressure circuit.**

R **(b) If leaks are not found:**
R **- refer to Para. C.**
R

R **B. If the low pressure indication does not come into view on the ECAM SD,**
R **but the pressure value decreases:**

R **(1) Do a leak test of the high pressure circuit with the SPECIAL**
R **MATERIALS (Material No. 05-004).**

R **(a) If leaks are found:**
R **- replace the damaged components of the high pressure circuit.**

R **(b) If leaks are not found:**
R **- refer to Para. C.**

R **C. If the fault continues:**

R **(1) If the oxygen pressure indication is the same on the SD and on the**
R **pressure gage:**
R **- make sure that the oxygen cylinder and the connection are in the**
R **correct condition.**
R **If not:**

R **(a) Replace the CYLINDER-OXYGEN STORAGE (5750HM) (Ref. AMM TASK 35-**
R **11-41-000-001) and (Ref. AMM TASK 35-11-41-400-001).**

R **(2) If the oxygen pressure indication is different on the SD and on the**
R **pressure gage:**
R **- make sure that the pressure regulator/transmitter and the**
R **connection are in the correct condition.**
R **If not:**

R **(a) Replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-**
R **001) and (Ref. AMM TASK 35-13-15-400-001).**

R **D. Test**

R **(1) Make sure that the OXY pressure indication is sufficient for the**
R **scheduled flight.**

EFF : ALL

SR0S

35-10-00

Page 230
Nov 01/02

5. Close-up

A. Put the aircraft back to its initial configuration.

- R** (1) Install the oxygen-mask stowage box (Ref. AMM TASK 35-12-41-400-001).
- R** (2) On the OXYGEN section of the overhead panel 21VU, release the CREW
R SUPPLY pushbutton switch (the OFF legend goes off).
- R** (3) On the ECAM control panel, set the UPPER DISPLAY and LOWER DISPLAY
potentiometers to OFF.
(Ref. AMM TASK 31-60-00-860-002).
- R** (4) De-energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-862-002).

EFF : ALL

SR05

35-10-00

Page 231
Nov 01/02

TASK 35-10-00-810-814

Fast Loss of Crew Oxygen with Overboard Discharge Indicator Yellow

1. Possible Causes

- CYLINDER-OXYGEN STORAGE (5750HM)
- XMTR/PRESS REG-OXY (4HT)

2. Job Set-up Information**A. Referenced Information**

REFERENCE	DESIGNATION
AMM 24-41-00-861-002	Energize the Aircraft Electrical Circuits from the External Power
AMM 24-41-00-862-002	De-energize the Aircraft Electrical Circuits Supplied from the External Power
AMM 31-60-00-860-002	EIS Stop Procedure
AMM 35-10-00-040-001	OXY High Pressure Indication-Direct Reading.
AMM 35-11-41-000-001	Removal of the Crew Oxygen-Storage Cylinder (5750HM)
AMM 35-11-41-400-001	Installation of the Crew Oxygen-Storage Cylinder (5750HM)
AMM 35-13-15-000-001	Removal of the Oxygen Pressure Regulator/Transmitter (4HT)
AMM 35-13-15-400-001	Installation of the Oxygen Pressure Regulator/Transmitter (4HT)
AMM 35-13-22-920-001	Replacement of the Overboard Discharge Indicator (5756HM)

3. Fault Confirmation**A. Job Set Up****(1) Aircraft Maintenance Configuration**

- (a) Energize the aircraft electrical circuits (Ref. AMM TASK 24-41-00-861-002).
- (b) Do the EIS start procedure (Upper ECAM DU and lower ECAM DU only)
- (c) On the panel 21VU, push the OXYGEN/CREW SUPPLY pushbutton switch (the OFF legend goes off).

EFF : ALL

SR05

35-10-00Page 232
Nov 01/02

B. Make sure that this(these) circuit breaker(s) is(are) closed:

PANEL	DESIGNATION	IDENT.	LOCATION
49VU	OXYGEN/CREW/OXY/SPLY	1HT	HA01

C. Test

- (1) On the ECAM control panel:
 - push the DOOR key to get the DOOR/OXY page.
- (2) Make sure that the OXY pressure indication is minimum on the DOOR/OXY page.
- (3) Do an OXY high-pressure indication direct reading (Ref. AMM TASK 35-10-00-040-001).
- (4) Make sure that the overboard discharge indicator is yellow.

4. Fault Isolation

A. If the oxygen pressure indication is the same on the SD and on the pressure gage with the overboard discharge indicator yellow:

- replace the CYLINDER-OXYGEN STORAGE (5750HM) (Ref. AMM TASK 35-11-41-000-001) and (Ref. AMM TASK 35-11-41-400-001) and replace the overboard discharge indicator (5756HM) (Ref. AMM TASK 35-13-22-920-001).

- (1) If the oxygen pressure indication is different on the SD and on the pressure gage with the overboard discharge indicator yellow:
 - replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001) and replace the overboard discharge indicator (5756HM) (Ref. AMM TASK 35-13-22-920-001).

B. Test

- (1) Make sure that the OXY pressure indication is normal (more than 1500PSI) on the DOOR/OXY page.

5. Close-up

A. Put the aircraft back to its initial configuration.

- (1) On the panel 21VU, release the OXYGEN/CREW SUPPLY pushbutton switch (the OFF legend comes on).
- (2) On the ECAM control panel, set the UPPER DISPLAY and LOWER DISPLAY potentiometers to OFF.
(Ref. AMM TASK 31-60-00-860-002)
- (3) De-energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-862-002).

R

EFF :	ALL
SROS	

35-10-00

Page 233
Nov 01/02

TASK 35-10-00-810-815**Failure of the Oxygen Flow Indicator****1. Possible Causes**

- STOWAGE BOX-OXY MASK, CAPT (10RN1)
- STOWAGE BOX-OXY MASK, F/O (10RN2)
- STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3)
- BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM)

2. Job Set-up Information**A. Referenced Information****REFERENCE****DESIGNATION**

AMM 35-12-41-000-001	Removal of the Oxygen-Mask Stowage-Box
AMM 35-12-41-400-001	Installation of the Oxygen-Mask Stowage-Box
AMM 35-12-41-710-001	Operational Test of the Full Face/Quick Donning Oxygen Masks (5757HM,5758HM,5759HM,5760HM)

3. Fault Confirmation**A. Test**

- (1) Do the operational test of the full-face/quick-donning oxygen masks (Ref. AMM TASK 35-12-41-710-001).

4. Fault Isolation

R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,

A. If during the operational test:

- (1) The Captain oxygen flow-indicator is inoperative
 - replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (2) The First Officer oxygen flow-indicator is inoperative:
 - replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (3) The Third Occupant oxygen flow-indicator is inoperative
 - replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).

EFF : ALL

SR0S

35-10-00

Page 234
May 01/08

R **ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553, 555-555,

A. If during the operational test:

- (1) The Captain oxygen flow-indicator is inoperative
 - replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (2) The First Officer oxygen flow-indicator is inoperative:
 - replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (3) The Third Occupant oxygen flow-indicator is inoperative
 - replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).
- (4) The Fourth Occupant oxygen flow-indicator is inoperative
 - replace the BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001).

****ON A/C ALL**

B. Test

- (1) Do the test given in Para. 3.A.

EFF : ALL

SR0S

35-10-00

Page 235
Feb 01/08

TASK 35-10-00-810-816

Disagree between the OXY Indication on the SD page and the OFF legend on the Pushbutton Switch

1. Possible Causes

- P/BSW- OXYGEN/CREW SUPPLY(2HT)
- ground signal at pin A/A3 of the pushbutton switch (2HT)
- P/BSW-OXYGEN/CREW SUPPLY (2HT)
- wiring from the pushbutton switch (2HT) pin A/A2 to the first terminal block

2. Job Set-up Information

A. Referenced Information

REFERENCE

DESIGNATION

ASM 35-13/01

3. Fault Confirmation

- A. Test**
Not applicable.

4. Fault Isolation

- A. If the OFF legend is on and the OXY indication is shown in white (DOOR/OXY Page)**
- replace the P/BSW- OXYGEN/CREW SUPPLY(2HT).

(1) If the fault continues:

- do a check of the wiring from the pushbutton switch (2HT) pin A/A2 to the first terminal block (Ref. ASM 35-13/01).

- (a) If there is no continuity:**
- repair the above wiring.

- (b) If there is continuity:**
- do a check and repair the ground signal at pin A/A3 of the pushbutton switch (2HT) (Ref. ASM 35-13/01).

- B. If the OXY indication is shown in amber (DOOR/OXY Page) and the OFF legend is off (pushbutton switch pushed).**
- replace the P/BSW-OXYGEN/CREW SUPPLY (2HT) >

(1) If the fault continues

- do a check and repair the wiring from the pushbutton switch (2HT) pin A/A2 to the first terminal block (Ref. ASM 35-13/01).

EFF : ALL

SR05

35-10-00

Page 236
Nov 01/02

TASK 35-10-00-810-817

Overboard Discharge Indicator Yellow

1. Possible Causes

- IND-OXY OVERBOARD DISCH (5756HM)
- XMTR/PRESS REG-OXY (4HT)

2. Job Set-up Information**A. Referenced Information**

REFERENCE**DESIGNATION**

AMM 35-13-15-000-001	Removal of the Oxygen Pressure Regulator/Transmitter (4HT)
AMM 35-13-15-400-001	Installation of the Oxygen Pressure Regulator/Transmitter (4HT)
AMM 35-13-22-920-001	Replacement of the Overboard Discharge Indicator (5756HM)

3. Fault Confirmation**A. Test**

Not applicable, the fault is evident.

4. Fault Isolation**A. If the overboard discharge indicator is yellow:**

- replace the IND-OXY OVERBOARD DISCH (5756HM) (Ref. AMM TASK 35-13-22-920-001).

(1) If the fault continues:

- replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001) and replace the IND-OXY OVERBOARD DISCH (5756HM) (Ref. AMM TASK 35-13-22-920-001).

EFF : ALL

SR0S

35-10-00Page 237
Nov 01/02

TASK 35-10-00-810-818

- R Crew Oxygen Pressure Indication between 401 and 1499PSI with an Amber Half
R Frame on the DOOR/OXY Page

1. Possible Causes

- CYLINDER-OXYGEN STORAGE (5750HM)
- XMTR/PRESS REG-OXY (4HT)

2. Job Set-up Information

A. Referenced Information

REFERENCE		DESIGNATION
R	AMM 12-14-35-600-001	Servicing of the Oxygen-Replenishing
	AMM 24-41-00-861-002	Energize the Aircraft Electrical Circuits from the External Power
	AMM 24-41-00-862-002	De-energize the Aircraft Electrical Circuits Supplied from the External Power
	AMM 31-60-00-860-001	EIS Start Procedure
	AMM 31-60-00-860-002	EIS Stop Procedure
R	AMM 35-10-00-200-001	Inspection of oxygen pressure for the flight crew
	AMM 35-11-41-000-001	Removal of the Crew Oxygen-Storage Cylinder (5750HM)
	AMM 35-11-41-400-001	Installation of the Crew Oxygen-Storage Cylinder (5750HM)
	AMM 35-13-15-000-001	Removal of the Oxygen Pressure Regulator/Transmitter (4HT)
	AMM 35-13-15-400-001	Installation of the Oxygen Pressure Regulator/Transmitter (4HT)

3. Fault Confirmation

A. Job Set Up

(1) Aircraft Maintenance Configuration

- (a) Energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-861-002).

- (b) Do the EIS start procedure (Upper ECAM DU and lower ECAM DU only)
(Ref. AMM TASK 31-60-00-860-001).

B. Make sure that this(these) circuit breaker(s) is(are) closed:

PANEL	DESIGNATION	IDENT.	LOCATION
	49VU OXYGEN/CREW/OXY/SPLY	1HT	HA01

EFF : ALL

SR0S

35-10-00

Page 238
Nov 01/06

C. Test

- (1) On the ECAM control panel:
 - push the DOOR key to get the DOOR/OXY page:
- (2) Make sure that the OXY pressure indication is between 401 and 1499PSI on the DOOR/OXY page.
- (3) Do an inspection of oxygen pressure for the flight crew (Ref. AMM TASK 35-10-00-200-001).

4. Fault Isolation

R **ON A/C 201-225, 227-227, 229-299, 426-450, 476-499, 503-549, 551-599,
R 701-749,

A. If during the check of the pressure of the crew cylinder, the values is:

- (1) The same as the value on the lower ECAM display unit, on the DOOR/OXY page and more than the minimum pressure found during the inspection:
 - no action is necessary.
 - (2) The same as the value on the lower ECAM display unit, on the DOOR/OXY page and less than the minimum pressure found during the inspection:
 - replenish or replace the CYLINDER-OXYGEN STORAGE (5750HM) (Ref. AMM TASK 12-14-35-600-001), (Ref. AMM TASK 35-11-41-000-001) and (Ref. AMM TASK 35-11-41-400-001).
 - (3) Different from the value on the lower ECAM display unit, on the DOOR/OXY page:
 - replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) (Ref. AMM TASK 35-13-15-400-001).
- (a) If the fault continues:
 - replace the CYLINDER-OXYGEN STORAGE (5750HM) (Ref. AMM TASK 35-11-41-000-001) and (Ref. AMM TASK 35-11-41-400-001).

**ON A/C 451-475,

A. If during the check of the pressure of the crew cylinder, the value is:

- (1) The same as the value on the lower ECAM display unit, on the DOOR/OXY page and more than the minimum pressure found during the inspection:
 - no action is necessary.
- (2) The same as the value on the lower ECAM display unit, on the DOOR/OXY page and less than the minimum pressure found during the inspection:
 - replace the CYLINDER-OXYGEN STORAGE (5750HM) (Ref. AMM TASK 35-11-41-000-001) and (Ref. AMM TASK 35-11-41-400-001).

EFF : ALL

SR05

35-10-00

Page 239
May 01/08

TROUBLE SHOOTING MANUAL

- R (3) Different from the value on the lower ECAM display unit, on the
R DOOR/OXY page:
R - replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-
R 001) (Ref. AMM TASK 35-13-15-400-001).
- (a) If the fault continues:
- replace the CYLINDER-OXYGEN STORAGE (5750HM) (Ref. AMM TASK 35-11-41-000-001) and (Ref. AMM TASK 35-11-41-400-001).

R ****ON A/C ALL**

B. Test

- (1) Make sure that the OXY pressure indication is normal on the DOOR/OXY page:

5. Close-up

A. Put the aircraft back to its initial configuration.

- (1) On the ECAM control panel, set the UPPER DISPLAY and LOWER DISPLAY potentiometers to OFF.
(Ref. AMM TASK 31-60-00-860-002).
- (2) De-energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-862-002).

R EFF : ALL

SR0S

35-10-00

Page 240
Nov 01/06

R **ON A/C 201-225, 227-227, 229-299, 426-450, 476-499, 503-549, 551-599,
R 701-749,

TASK 35-10-00-810-819

Oxygen Cylinder Refilling not possible

1. Possible Causes

- FILL PORT-OXY SYS (5769HM)
- XMTR/PRESS REG-OXY (4HT)

2. Job Set-up Information

A. Referenced Information

REFERENCE

DESIGNATION

AMM 35-11-42-000-001	Removal of the Oxygen Fill Port (5769HM)
AMM 35-11-42-400-001	Installation of the Oxygen Fill Port (5769HM)
AMM 35-13-15-000-001	Removal of the Oxygen Pressure Regulator/Transmitter (4HT)
AMM 35-13-15-400-001	Installation of the Oxygen Pressure Regulator/Transmitter (4HT)

3. Fault Confirmation

A. Test

- (1) Not applicable, the fault is evident.

4. Fault Isolation

A. If it is not possible to refill the oxygen cylinder:

- replace the FILL PORT-OXY SYS (5769HM) (Ref. AMM TASK 35-11-42-000-001) and (Ref. AMM TASK 35-11-42-400-001).

(1) If the fault continues:

- replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001).

R EFF : 201-225, 227-227, 229-299, 426-450,
476-499, 503-549, 551-599, 701-749,

SR0S

35-10-00

Page 241
May 01/08

****ON A/C ALL**

TASK 35-10-00-810-820

REGUL LO PR Indication with no Oxygen Pressure Value on the DOOR/OXY Page

1. Possible Causes

- XMTR/PRESS REG-OXY (4HT)
- SOL VALVE-LP OXY SPLY (3HT)
- C/B-OXYGEN/CREW/OXY/SPLY (1HT)
- wiring from the circuit breaker (1HT) pin 2 to the first terminal block
- P/BSW-OXYGEN/CREW SUPPLY (2HT)
- short to ground at the wiring between the circuit breaker (1HT) pin 2 and the first terminal block

2. Job Set-up Information

A. Referenced Information

REFERENCE

DESIGNATION

AMM	24-41-00-861-002	Energize the Aircraft Electrical Circuits from the External Power
AMM	31-60-00-860-001	EIS Start Procedure
AMM	35-13-15-000-001	Removal of the Oxygen Pressure Regulator/Transmitter (4HT)
AMM	35-13-15-400-001	Installation of the Oxygen Pressure Regulator/Transmitter (4HT)
AMM	35-13-51-000-001	Removal of the Sol Valve-LP Oxy Sply (3HT)
AMM	35-13-51-400-001	Installation of the LP Oxygen-Supply Solenoid-Valve (3HT)
ASM	35-13/01	

3. Fault Confirmation

A. Job Set Up

(1) Aircraft Maintenance Configuration

- (a) Energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-861-002).
- (b) Do the EIS start procedure (Upper ECAM DU and lower ECAM DU only)
(Ref. AMM TASK 31-60-00-860-001).
- (c) On the panel 21VU push the OXYGEN/CREW SUPPLY pushbutton switch
(the OFF legend goes off).

EFF : ALL

SR0S

35-10-00

Page 242
Nov 01/06

B. Make sure that this(these) circuit breaker(s) is(are) closed:

PANEL DESIGNATION		IDENT. LOCATION	
49VU OXYGEN/CREW/OXY/SPLY		1HT	HA01

C. Test

- (1) On the ECAM control panel:
 - push the **DOOR** key to get the **DOOR/OXY** page:
- (2) Make sure that the **REGUL LO PR** indication comes into view and the oxygen pressure indication is replaced by amber crosses on the **DOOR/OXY** page.
- (3) If the circuit breaker (1HT) trips:
 - refer to Para. 4.A.(2).

4. Fault Isolation

- A. If the test confirms the fault:**
- do a check for the circuit breaker (1HT) status:
- (1) If the circuit breaker is closed
 - do a check for continuity between the circuit breaker (1HT) pin 2 and the first terminal block (Ref. ASM 35-13/01).
 - (a) If there is continuity:
 - replace the **C/B-OXYGEN/CREW/OXY/SPLY (1HT)** (Ref. ASM 35-13/01).
 - (b) If there is no continuity:
 - repair the wiring from the circuit breaker (1HT) pin 2 to the first terminal block (Ref. ASM 35-13/01).
 - (2) If the circuit breaker (1HT) is open:
 - close it.
 - (a) If it trips:
 - replace the **XMTR/PRESS REG-OXY (4HT)** (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001).
 - 1 If the fault continues:
 - replace the **SOL VALVE-LP OXY SPLY (3HT)** (Ref. AMM TASK 35-13-51-000-001) and (Ref. AMM TASK 35-13-51-400-001).
 - 2 If the fault continues:
 - replace the **P/BSW-OXYGEN/CREW SUPPLY (2HT)**.

EFF : ALL

SR05

35-10-00

Page 243
Nov 01/06

- 3 If the fault continues:
 - do a check for a short to ground at the wiring between the circuit breaker (1HT) pin 2 and the first terminal block (Ref. ASM 35-13/01).
 - a If there is a short to ground:
 - repair the above wiring.
 - b If there is no short to ground:
 - replace the C/B-OXYGEN/CREW/OXY/SPLY (1HT) (Ref. ASM 35-13/01).
- (b) If the circuit breaker is held closed and if the fault continues.
 - replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001).
- 1 If the fault continues:
 - replace the SOL VALVE-LP OXY SPLY (3HT) (Ref. AMM TASK 35-13-51-000-001) and (Ref. AMM TASK 35-13-51-400-001).
- 2 If the fault continues:
 - replace the P/BSW-OXYGEN/CREW SUPPLY (2HT).

B. Test

- (1) Make sure that the REGUL LO PR indication goes out of view and the oxygen pressure indication comes on on the DOOR/OXY page.

5. Close-up

A. Put the aircraft back to its initial configuration.

- (1) On the ECAM Control Panel, set the LOWER DISPLAY and the UPPER DISPLAY potentiometers to OFF.
- (2) On the panel 21VU:
 - release the OXYGEN/CREW SUPPLY pushbutton switch. The OFF legend comes on.

TASK 35-10-00-810-821

REGUL LO PR indication on the DOOR/OXY Page

1. Possible Causes

- PRESS SW-OXYGEN LO PR (4WV)
- XMTR/PRESS REG-OXY (4HT)
- SOL VALVE-LP OXY SPLY (3HT)
- wiring from the pressure switch (4WV) pin A/B to the first terminal block
- P/BSW-OXYGEN/CREW SUPPLY (2HT)
- wiring from the pushbutton switch (2HT) pin A/B3 to the first terminal block
- wiring from the pushbutton switch (2HT) to the solenoid valve (3HT)

2. Job Set-up Information

A. Referenced Information

REFERENCE	DESIGNATION
AMM 24-41-00-861-002	Energize the Aircraft Electrical Circuits from the External Power
AMM 24-41-00-862-002	De-energize the Aircraft Electrical Circuits Supplied from the External Power
AMM 31-60-00-860-001	EIS Start Procedure
AMM 31-60-00-860-002	EIS Stop Procedure
AMM 35-12-41-710-001	Operational Test of the Full Face/Quick Donning Oxygen Masks (5757HM,5758HM,5759HM,5760HM)
AMM 35-13-14-000-001	Removal of the Press Sw-Oxygen LO PR (4WV)
AMM 35-13-14-400-001	Installation of the Press Sw-Oxygen LO PR (4WV)
AMM 35-13-15-000-001	Removal of the Oxygen Pressure Regulator/Transmitter (4HT)
AMM 35-13-15-400-001	Installation of the Oxygen Pressure Regulator/Transmitter (4HT)
AMM 35-13-51-000-001	Removal of the Sol Valve-LP Oxy Sply (3HT)
AMM 35-13-51-400-001	Installation of the LP Oxygen-Supply Solenoid-Valve (3HT)
ASM 35-13/01	

3. Fault Confirmation

A. Job Set Up

(1) Aircraft Maintenance Configuration

- (a) Energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-861-002).

EFF : ALL

SR0S

35-10-00

Page 245
Nov 01/06

TROUBLE SHOOTING MANUAL

(b) Do the EIS start procedure (Upper ECAM DU and lower ECAM DU only)
(Ref. AMM TASK 31-60-00-860-001)

(c) On the panel 21VU push the OXYGEN/CREW SUPPLY pushbutton switch
2HT (the OFF legend goes off).

B. Make sure that this(these) circuit breaker(s) is(are) closed:

PANEL	DESIGNATION	IDENT. LOCATION	
49VU	OXYGEN/CREW/OXY/SPLY	1HT	HA01

C. Test

- (1) On the ECAM control panel:
 - push the DOOR key to get the DOOR/OXY page:
- (2) Make sure that the REGUL LO PR indication comes into view on the DOOR/OXY page.
- (3) Do the operational test of the full-face/quick-donning mask (Ref. AMM TASK 35-12-41-710-001).

4. Fault Isolation

- A. If during the operational test the flow rate indicator comes into view for a short time and if you hear the oxygen flow rate:
- replace the PRESS SW-OXYGEN LO PR (4WV) (Ref. AMM TASK 35-13-14-000-001) and (Ref. AMM TASK 35-13-14-400-001).
- (1) If the fault continues:
- replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001).
- (a) If the fault continues:
- do a check and repair the wiring from the pressure switch (4WV) pin A/B to the first terminal block.
- B. If during the operational test the flow rate indicator does not come into view and you do not hear the oxygen flow rate:
- disconnect the plug of the solenoid valve (3HT) and do a check for 28VDC at pin A/A (pushbutton switch 2HT on).
- (1) If there is 28VDC:
- replace the SOL VALVE-LP OXY SPLY (3HT) (Ref. AMM TASK 35-13-51-000-001) and (Ref. AMM TASK 35-13-51-400-001).
- (a) If the fault continues:
- replace the XMTR/PRESS REG-OXY (4HT) (Ref. AMM TASK 35-13-15-000-001) and (Ref. AMM TASK 35-13-15-400-001).

EFF : ALL

SR0S

35-10-00

Page 246
Nov 01/06

- (2) If there is no 28VDC:
 - replace the P/BSW-OXYGEN/CREW SUPPLY (2HT)
- (a) If the fault continues:
 - do a check of the wiring from the pushbutton switch (2HT) pin A/B3 to the first terminal block (Ref. ASM 35-13/01).
- 1 If there is no continuity:
 - repair the above wiring.
- 2 If there is continuity:
 - do a check and repair the wiring from the pushbutton switch (2HT) to the solenoid valve (3HT) pin A/B1, B2 to pin A/A,C (Ref. ASM 35-13/01).

C. Test

- (1) Make sure that the REGUL LO PR indication goes out of view on the DOOR/OXY page.

5. Close-up

A. Put the aircraft back to its initial configuration.

- (1) On the ECAM control panel, set the UPPER DISPLAY and LOWER DISPLAY potentiometers to OFF.
(Ref. AMM TASK 31-60-00-860-002)
- (2) On the panel 21VU:
 - release the OXYGEN/CREW SUPPLY pushbutton switch 2HT. (the OFF legend comes on)
- (3) De-energize the aircraft electrical circuits
(Ref. AMM TASK 24-41-00-862-002)

TASK 35-10-00-810-822

No Oxygen to the Crew Oxygen Masks with REGUL LO PR Indication

1. Possible Causes

- SOL VALVE-LP OXY SPLY (3HT)
- P/BSW-OXYGEN/CREW SUPPLY (2HT)
- wiring from the LP oxygen supply solenoid valve (3HT) pin A/B to the ground terminal
- wiring from the LP oxygen supply solenoid valve (3HT) to the pushbutton switch (2HT)

2. Job Set-up Information

A. Referenced Information

REFERENCE

DESIGNATION

AMM 35-12-41-710-001	Operational Test of the Full Face/Quick Donning Oxygen Masks (5757HM,5758HM,5759HM,5760HM)
AMM 35-13-51-000-001	Removal of the Sol Valve-LP Oxy Sply (3HT)
AMM 35-13-51-400-001	Installation of the LP Oxygen-Supply Solenoid-Valve (3HT)
ASM 35-13/01	

3. Fault Confirmation

A. Test

- (1) Do the operational test of the full-face/quick-donning oxygen masks (Ref. AMM TASK 35-12-41-710-001).

4. Fault Isolation

A. If during the operational test there is no oxygen at each mask with REGUL LO PR indication:

- make sure that there is 28VDC on the LP oxygen supply solenoid valve (3HT) pin A/A.

(1) If there is 28VDC:

- replace the SOL VALVE-LP OXY SPLY (3HT) (Ref. AMM TASK 35-13-51-000-001) and (Ref. AMM TASK 35-13-51-400-001).

(2) If there is no 28VDC:

- replace the P/BSW-OXYGEN/CREW SUPPLY (2HT) (Ref. ASM 35-13/01).

EFF : ALL

SR05

35-10-00

Page 248
Nov 01/06

(3) If the fault continues:

- do a check for a ground signal at the pin A/B of the LP oxygen supply solenoid valve (3HT) (Ref. ASM 35-13/01).

(a) If there is no ground signal:

- repair the wiring from the LP oxygen supply solenoid valve (3HT) pin A/B to the ground terminal (Ref. ASM 35-13/01).

(b) If there is a ground signal:

- do a check and repair the wiring from the LP oxygen supply solenoid valve (3HT) to the pushbutton switch (2HT) pin A/A (Ref. ASM 35-13/01).

B. Test

(1) Do the test given in Para. 3.A.

EFF : ALL

SR0S

35-10-00

Page 249
Nov 01/06

TASK 35-10-00-810-823

Deterioration of the Flexible Supply-Hose Assembly

1. Possible Causes

- STOWAGE BOX-OXY MASK, CAPT (10RN1)
- MASK-FULL FACE/Q.D. OXY, CAPT (5759HM)
- STOWAGE BOX-OXY MASK, F/O (10RN2)
- MASK-FULL FACE/Q.D. OXY, F/O (5758HM)
- STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3)
- MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM)
- BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM)
- MASK-FULL FACE/Q.D. OXY, 4TH OCCPNT (5760HM)

2. Job Set-up Information**A. Referenced Information**

REFERENCE	DESIGNATION
AMM 35-12-41-000-001	Removal of the Oxygen-Mask Stowage-Box
AMM 35-12-41-000-002	Removal of the Full-Face/Quick-Donning Oxygen-Mask
AMM 35-12-41-200-001	Detailed Inspection of Oxygen Masks (out of box) with Harness Inflated
AMM 35-12-41-400-001	Installation of the Oxygen-Mask Stowage-Box
AMM 35-12-41-400-002	Installation of the Full-Face/Quick-donning Oxygen-Mask

3. Fault Confirmation**A. Test**

- (1) Do the visual inspection of the flight crew oxygen mask (out of box)
(Ref. AMM TASK 35-12-41-200-001).

4. Fault Isolation

R **ON A/C 201-225, 227-227, 229-250, 252-253, 276-299, 426-499, 551-599,

A. If during the inspection:

- (1) The Captain flexible supply-hose assembly is deteriorated:
- replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001) or the MASK-FULL FACE/Q.D. OXY, CAPT (5759HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

EFF : ALL

SROS

35-10-00Page 250
May 01/08

TROUBLE SHOOTING MANUAL

- (2) The First Officer flexible supply-hose assembly is deteriorated:
- replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001) or the MASK-FULL FACE/Q.D. OXY, F/O (5758HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (3) The Third Occupant flexible supply-hose assembly is deteriorated.
- replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001) or the MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

R **ON A/C 251-251, 254-275, 503-549, 553-553, 555-555, 701-749,

Post SB 25-1259 For A/C 553-553,555-555,

A. If during the inspection:

- (1) The Captain flexible supply-hose assembly is deteriorated:
- replace the STOWAGE BOX-OXY MASK, CAPT (10RN1) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001) or the MASK-FULL FACE/Q.D. OXY, CAPT (5759HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (2) The First Officer flexible supply-hose assembly is deteriorated:
- replace the STOWAGE BOX-OXY MASK, F/O (10RN2) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001) or the MASK-FULL FACE/Q.D. OXY, F/O (5758HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (3) The Third Occupant flexible supply-hose assembly is deteriorated.
- replace the STOWAGE BOX-OXY MASK, 3RD OCCPNT (10RN3) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001) or the MASK-FULL FACE/Q.D. OXY, 3RD OCCPNT (5757HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).
- (4) The Fourth Occupant flexible supply-hose assembly is deteriorated:
- replace the BOX ASSY-STOWAGE, 4TH OCCPNT (5774HM) (Ref. AMM TASK 35-12-41-000-001) and (Ref. AMM TASK 35-12-41-400-001) or the MASK-FULL FACE/Q.D. OXY, 4TH OCCPNT (5760HM) (Ref. AMM TASK 35-12-41-000-002) and (Ref. AMM TASK 35-12-41-400-002).

R EFF : ALL

SR0S

35-10-00

Page 251
Feb 01/08

TASK 35-23-00-810-801

Automatic System Activation Fault

1. Possible Causes

- PRESS SW (16WR)
- RELAY-SYS OFF (8WR)
- RELAY-SYS OFF (9WR)
- RELAY-PWR SPLY (10WR)
- wiring

2. Job Set-up Information

A. Referenced Information

REFERENCE	DESIGNATION
AMM 35-23-00-720-002	Functional Test of the Passenger Emergency-Oxygen System
AMM 35-23-15-000-001	Removal of the Altitude Switch (16WR)
AMM 35-23-15-400-001	Installation of the Altitude Switch (16WR)
ASM 35-23/01	

3. Fault Confirmation

- A. Do the functional test of the passenger emergency-oxygen system (Ref. AMM TASK 35-23-00-720-002).

4. Fault Isolation

- A. If the test confirms the fault:
- R - Replace the PRESS SW (16WR) (Ref. AMM TASK 35-23-15-000-001) and (Ref. AMM TASK 35-23-15-400-001).
- (1) If the fault continues:
- R - Do a check of the RELAY-SYS OFF (8WR) and replace it if necessary (Ref. ASM 35-23/01).
- R
- (2) If the fault continues:
- R - Do a check of the RELAY-SYS OFF (9WR) and replace it if necessary (Ref. ASM 35-23/01).
- R
- (3) If the fault continues:
- R - Do a check of the RELAY-PWR SPLY (10WR) and replace it if necessary (Ref. ASM 35-23/01).
- R

EFF : ALL

SR0S

35-23-00

Page 201
Nov 01/04

(4) If the fault continues:

R

R

(a) Do a check and repair the wiring if necessary between:

R

- SW (16WR) connector A/A and CB (1WR)

R

- SW (16WR) connector A/C and RELAY (8WR) connector A/X1

R

- RELAY (8WR) connector A/X2 and GND

R

- SW (16WR) connector A/C and RELAY (9WR) connector A/X1

R

- RELAY (9WR) connector A/X2 and GND

R

- SW (16WR) connector A/C and RELAY (10WR) connector A/X1

R

- RELAY (10WR) connector A/X2 and GND,

R

(Ref. ASM 35-23/01).

B. Do the test as given in the Para. 3.A.

5. Close-up

A. Put the aircraft back to its initial configuration.

EFF : ALL

SR0S

35-23-00

Page 202
Nov 01/04

TASK 35-23-00-810-802

OXYGEN/PASSENGER P/BSW SYS ON Legend Fault

1. Possible Causes

- PUSHBUTTON SW-OXYGEN/PASSENGER (12WR)
- RELAY-CTL PWR SPLY (11WR)
- wiring

2. Job Set-up Information**A. Referenced Information**

REFERENCE**DESIGNATION**

AMM 33-14-00-710-001	Operational Test of the Annunciator Light Test System in the Cockpit
AMM 35-23-00-710-001	Operational Check of Manual Mask Release
ASM 35-23/01	

3. Fault Confirmation

- A. Do the operational test of the manual mask release (Ref. AMM TASK 35-23-00-710-001).**

4. Fault Isolation

- A. If the SYS ON legend on the pushbutton switch OXYGEN/PASSENGER, which is installed on the panel 21VU, does not come on during the test:**

- Do a check of the PUSHBUTTON SW-OXYGEN/PASSENGER (12WR) and replace it if necessary (Ref. ASM 35-23/01).

(1) If the fault continues:

- Do a check of the RELAY-CTL PWR SPLY (11WR) and replace it if necessary (Ref. ASM 35-23/01).

(2) If the fault continues:

(a) Do a check and repair the wiring if necessary between:

- RELAY (6LP) connector A/37 and PB SW (12WR) connector A/7
- RELAY (6LP) connector A/39 and CB (1WR)
- RELAY (6LP) connector A/38 and GND
- RELAY (11WR) connector A/X1 and CB (7WR)
- RELAY (11WR) connector A/X2 and GND,
(Ref. ASM 35-23/01).

EFF : ALL

SR0S

35-23-00Page 203
May 01/05

(3) If the fault continues:

- Do the operational test of the annunciator-light test system (Ref. AMM TASK 33-14-00-710-001).

R
R
R
R

(a) If the test gives a different maintenance message:

- Do the trouble shooting procedure related to the maintenance message.

B. Do the test as given in the Para. 3.A.

5. Close-up

A. Put the aircraft back to its initial configuration.

EFF : ALL

SR0S

35-23-00

Page 204
May 01/05

TASK 35-23-00-810-803

OXYGEN/TMR RESET P/BSW FAULT Legend Fault

1. Possible Causes

- PUSBUTTON SW-OXYGEN/TMR RESET (13WR)
- RELAY-SYS OFF (8WR)
- RELAY-SYS OFF (9WR)
- wiring
- RELAY-TIME DELAY (15WR)

2. Job Set-up Information

A. Referenced Information

REFERENCE	DESIGNATION
AMM 33-14-00-710-001	Operational Test of the Annunciator Light Test System in the Cockpit
AMM 35-23-00-710-001	Operational Check of Manual Mask Release
ASM 35-23/01	

3. Fault Confirmation

- #### **A. Do the operational test of the manual mask release (Ref. AMM TASK 35-23-00-710-001).**

4. Fault Isolation

- #### **A. If the FAULT legend on the pushbutton switch OXYGEN/TMR RESET, which is installed on the panel 50VU, comes on after approx. 30 seconds:**
- Do a check of the PUSBUTTON SW-OXYGEN/TMR RESET (13WR) and replace it if necessary (Ref. ASM 35-23/01).

(1) If the fault continues:

- Do a check of the RELAY-SYS OFF (8WR) and replace it if necessary (Ref. ASM 35-23/01).

(2) If the fault continues:

- Do a check of the RELAY-SYS OFF (9WR) and replace it if necessary (Ref. ASM 35-23/01).

(3) If the fault continues:

(a) Do a check and repair the wiring if necessary between:

- RELAY (6LP) connector A/17 and PB SW (13WR) connector A/7
- RELAY (6LP) connector A/33 and CB (1WR)
- RELAY (6LP) connector A/31 and GND
- RELAY (11WR) connector A/X1 and CB (7WR)

EFF : ALL

SR05

35-23-00

Page 205
May 01/05

TROUBLE SHOOTING MANUAL

- RELAY (11WR) connector A/X2 and GND,
(Ref. ASM 35-23/01).

(4) If the fault continues:

- Do the operational test of the annunciator light test system (Ref. AMM TASK 33-14-00-710-001).

R
R
R
R

(a) If the test gives a different maintenance message:

- Do the trouble shooting procedure related to the maintenance message.

B. If the FAULT legend on the pushbutton switch OXYGEN/TMR RESET, which is installed on the panel 50VU, comes on and goes off after approx. 30 seconds:

- Do a check of the RELAY-TIME DELAY (15WR) and replace it if necessary (Ref. ASM 35-23/01).

(1) If the fault continues:

(a) Do a check and repair the wiring if necessary between:

- RELAY (6LP) connector A/17 and PB SW (13WR) connector A/7
- RELAY (6LP) connector A/33 and CB (1WR)
- RELAY (6LP) connector A/31 and GND
- RELAY (15WR) connector A/X1 and CB (1WR)
- RELAY (15WR) connector A/X2 and GND,
(Ref. ASM 35-23/01).

(2) If the fault continues:

- Do the operational test of the annunciator light test system (Ref. AMM TASK 33-14-00-710-001).

R
R
R
R

(a) If the test gives a different maintenance message:

- Do the trouble shooting procedure related to the maintenance message.

C. If the FAULT legend on the pushbutton switch OXYGEN/TMR RESET, which is installed on the panel 50VU, comes on and goes off after pushing the OXYGEN/MASK MAN ON pushbutton switch:

- Do a check of the RELAY-TIME DELAY (15WR) and replace it if necessary (Ref. ASM 35-23/01).

(1) If the fault continues:

(a) Do a check and repair the wiring if necessary between:

- RELAY (6LP) connector A/17 and PB SW (13WR) connector A/7
- RELAY (6LP) connector A/33 and CB (1WR)
- RELAY (6LP) connector A/31 and GND
- RELAY (15WR) connector A/X1 and CB (1WR)
- RELAY (15WR) connector A/X2 and GND,
(Ref. ASM 35-23/01).

EFF : ALL

SR0S

35-23-00

Page 206
May 01/05

(2) If the fault continues:

- Do the operational test of the annunciator light test system (Ref. AMM TASK 33-14-00-710-001).

R
R
R
R

(a) If the test gives a different maintenance message:

- Do the trouble shooting procedure related to the maintenance message.

D. Do the test as given in the Para. 3.A.

5. Close-up

A. Put the aircraft back to its initial configuration.

EFF : ALL

SR0S

35-23-00

Page 207
May 01/05

TASK 35-23-00-810-804

Power Supply Line Fault

1. Possible Causes

- RELAY-PWR SPLY (10WR)
- wiring
- RELAY-TIME DELAY (25WR)

2. Job Set-up Information

A. Referenced Information

REFERENCE**DESIGNATION**

AMM 35-23-00-710-001

Operational Check of Manual Mask Release

ASM 35-23/01

3. Fault Confirmation

A. Do the operational test of the manual mask release (Ref. AMM TASK 35-23-00-710-001).

4. Fault Isolation

A. If one set of masks (approx. half of the installed masks) drops after approx. 6 seconds:

- Do a check of the RELAY-PWR SPLY (10WR) and replace it if necessary (Ref. ASM 35-23/01).

(1) If the fault continues:

(a) Do a check and repair the wiring if necessary between:

- RELAY (10WR) connector A/D1 and CB (4WR)
 - RELAY (10WR) connector A/D2 RELAY (25WR) connector A/A2
 - RELAY (10WR) connector A/C1 and CB (5WR)
 - RELAY (10WR) connector A/C2 RELAY (25WR) connector A/A1
 - RELAY (10WR) connector A/B1 and CB (6WR)
 - RELAY (10WR) connector A/B2 RELAY (25WR) connector A/B1
 - RELAY (10WR) connector A/A1 and CB (7WR)
 - RELAY (10WR) connector A/A2 RELAY (25WR) connector A/B2,
- (Ref. ASM 35-23/01).

EFF : ALL

SR0S

35-23-00Page 208
May 01/05

R B. If one set of masks (approx. half of the installed masks) does not fall
R during the test:
R - Do a check of the RELAY-PWR SPLY (10WR) and replace it if necessary
R (Ref. ASM 35-23/01).

(1) If the fault continues:
R - Do a check of the RELAY-TIME DELAY (25WR) and replace it if
R necessary (Ref. ASM 35-23/01).

(2) If the fault continues:
R

(a) Do a check and repair the wiring if necessary between:
R - RELAY (10WR) connector A/D1 and CB (4WR)
R - RELAY (10WR) connector A/D2 and RELAY (25WR) connector A/A2
R - RELAY (10WR) connector A/C1 and CB (5WR)
R - RELAY (10WR) connector A/C2 and RELAY (25WR) connector A/A1
R - RELAY (10WR) connector A/B1 and CB (6WR)
R - RELAY (10WR) connector A/B2 and RELAY (25WR) connector A/B1
R - RELAY (10WR) connector A/A1 and CB (7WR)
R - RELAY (10WR) connector A/A2 and RELAY (25WR) connector A/B2
R - RELAY (25WR) connector A/X1 and CB (3WR)
R - RELAY (25WR) connector A/X1 and CB (2WR)
R - RELAY (25WR) connector A/X2 and GND,
R (Ref. ASM 35-23/01).

C. Do the test as given in the Para. 3.A.

5. Close-up

A. Put the aircraft back to its initial configuration.

EFF : ALL

SR0S

35-23-00

Page 209
Nov 01/04

TASK 35-23-00-810-805

Manual System Activation Fault

1. Possible Causes

- PUSHBUTTON SW-OXYGEN/MAN ON (14WR)
- wiring

2. Job Set-up Information

A. Referenced Information

REFERENCE

DESIGNATION

R **AMM 35-23-00-710-001** **Operational Check of Manual Mask Release**
R **ASM 35-23/01**

3. Fault Confirmation

A. Do the operational test of the manual mask release (Ref. AMM TASK 35-23-00-710-001).

4. Fault Isolation

A. If the test confirms the fault:

R - Do a check of the PUSHBUTTON SW-OXYGEN/MAN ON (14WR) and replace it if
R necessary (Ref. ASM 35-23/01).

(1) If the fault continues:

R

R **(a) Do a check and repair the wiring if necessary between:**

- R - PB SW (14WR) pin 8 and CB (7WR)
- R - PB SW (14WR) pin 7 and RELAY (25WR) connector A/B2
- R - PB SW (14WR) pin 6 and CB (6WR)
- R - PB SW (14WR) pin 5 and RELAY (25WR) connector A/B1
- R - PB SW (14WR) pin 4 and CB (3WR)
- R - PB SW (14WR) pin 3 and RELAY (25WR) connector A/A1
- R - PB SW (14WR) pin 2 and CB (4WR)
- R - PB SW (14WR) pin 1 and RELAY (25WR) connector A/A2,
- R (Ref. ASM 35-23/01).

B. Do the test as given in the Para. 3.A.

5. Close-up

A. Put the aircraft back to its initial configuration.

EFF : ALL

SR05

35-23-00

Page 210
Nov 01/04

TASK 35-23-00-810-806

PAX Announcement Activation Fault

1. Possible Causes

- RELAY-PASS INFO (19WR)
- wiring

2. Job Set-up Information**A. Referenced Information**

REFERENCE**DESIGNATION**

AMM 23-32-00-700-001	Test of the Prerecorded Announcement Operation of the Prerecorded Announcement and Boarding Music (PRAM) Reproducer
AMM 35-23-00-710-001	Operational Check of Manual Mask Release
ASM 23-32/01	
ASM 35-23/01	

3. Fault Confirmation

- A. Do the operational test of the manual mask release (Ref. AMM TASK 35-23-00-710-001).**

4. Fault Isolation**A. If the test confirms the fault:**

- Do a check of the RELAY-PASS INFO (19WR) and replace it if necessary (Ref. ASM 35-23/01).

(1) If the fault continues:**(a) Do a check and repair the wiring if necessary between:**

- RELAY (19WR) connector A/X and CB (1WR)
- RELAY (19WR) connector A/Z and GND
- RELAY (19WR) connector A/2 and REPRODUCER (10RX) connector AB/A11
- RELAY (19WR) connector A/A and GND,
(Ref. ASM 35-23/01) and (Ref. ASM 23-32/01).

(2) If the fault continues:

- Do the test of the prerecorded announcement operation of the prerecorded announcement and boarding music (PRAM) reproducer (Ref. AMM TASK 23-32-00-700-001).

EFF : ALL

SR0S

35-23-00Page 211
May 01/05

R (a) If the test gives a different maintenance message:
R - Do the trouble shooting procedure related to the maintenance
R message.
R

B. Do the test as given in the Para. 3.A.

5. Close-up

A. Put the aircraft back to its initial configuration.

EFF : ALL

SR0S

35-23-00

Page 212
May 01/05

TASK 35-23-00-810-807

Emergency Oxygen Container Fault

1. Possible Causes

- OXYGEN BOX
- wiring

2. Job Set-up Information

A. Referenced Information

REFERENCE	DESIGNATION

AMM 35-21-41-000-001	Removal of the Emergency Oxygen Containers
AMM 35-21-41-400-001	Installation of the Emergency Oxygen Containers
R AMM 35-23-00-710-001	Operational Check of Manual Mask Release
ASM 35-23/01	
ASM 35-23/02	
ASM 35-23/02	

3. Fault Confirmation

- A. Do the operational test of the manual mask release (Ref. AMM TASK 35-23-00-710-001).

4. Fault Isolation

- A. If the test confirms the fault:
- Replace the related OXYGEN BOX (Ref. AMM TASK 35-21-41-000-001) and (Ref. AMM TASK 35-21-41-400-001).

- (1) If the fault continues:

- (a) Do a check and repair the wiring if necessary between:
- The related OXYGEN BOX and the related CB
 - The related OXYGEN BOX and GND,
- (Ref. ASM 35-23/01), (Ref. ASM 35-23/02) and (Ref. ASM 35-23/02).

- B. Do the test as given in the Para. 3.A.

5. Close-up

- A. Put the aircraft back to its initial configuration.

EFF : ALL

SR05

35-23-00

Page 213
Nov 01/04

A319/A320/A321

TROUBLE SHOOTING MANUAL


CONTROL AND INDICATING - TASK SUPPORTING DATA

EFF : ALL

SR0S

35-23-00

Page 301
Aug 01/94



Passenger Oxygen System - Block Diagram
Figure 301

EFF : ALL

SR0S

35-23-00

Page 302
Aug 01/94