

---

# **Touchstone<sup>®</sup> Gateway Firmware**



## **Release 9.1.80A**

Release Notes and  
Letter of Operational  
Considerations

---

# Touchstone® Gateway Firmware

---

## Release 9.1.80A

### Release Notes and Letter of Operational Considerations

---

Document release	Approved, v1.0
Document date	April 29, 2015

---

© 2015 ARRIS Group, Inc.  
All Rights Reserved

Printed in the USA

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. User must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to ARRIS Group, Inc.

ARRIS, ARRIS Group, Inc. and Voice Port are trademarks of ARRIS Group, Inc. Cornerstone is a registered trademark of ARRIS Group, Inc.

The firmware described in this document is furnished under a license agreement and may only be used in accordance with the terms of that license.

## Publication History

**April 22, 2015**

Draft, v0.1

**April 29, 2015**

Approved, v1.0

# Table of Contents

<b>1</b>	<b>OBJECTIVES OF THIS DOCUMENT</b>	<b>1</b>
1.1	ARRIS COMMITMENT	1
1.2	PURPOSE AND SCOPE OF THIS DOCUMENT	1
1.3	PRODUCT IDENTIFICATION AND PURPOSE OF RELEASE	1
1.4	FIRMWARE FILENAME VARIANT INFORMATION	2
1.5	MINIMUM FIRMWARE BASELINE FOR HARDWARE	3
1.6	PRODUCT DOCUMENTATION	4
<b>2</b>	<b>RELEASE NOTES</b>	<b>5</b>
2.1	NEW PRODUCT FEATURES	5
2.2	RESOLVED FIELD BULLETIN(S)	12
2.3	RESOLVED PRODUCT DEFICIENCIES	13
<b>3</b>	<b>LETTER OF OPERATIONAL CONSIDERATIONS</b>	<b>26</b>
3.1	OPERATIONAL CONSIDERATIONS	26
3.2	UNSUPPORTED FEATURES	31
3.3	UPGRADE CONSIDERATIONS	32
<b>4</b>	<b>CUSTOMER SERVICE AND SUPPORT</b>	<b>40</b>

# 1 Objectives of This Document

## 1.1 ARRIS Commitment

ARRIS is committed to developing high quality, value-added products and services to the Multiple System Operator (MSO). ARRIS continually strives toward meeting our customer's needs with solutions that will help achieve their business objectives.

## 1.2 Purpose and Scope of This Document

This document describes the value-added features and anomaly resolutions associated with this release. It also informs operators of known Operational Considerations associated with this product release that have been identified either through ARRIS' testing or field operations.

## 1.3 Product Identification and Purpose of Release

Described in this document is the Touchstone Gateway Firmware. This Touchstone Firmware release is intended for ARRIS manufactured E-MTAs. Information pertaining to support for this specific release is detailed in the table below.

<b>Product Description</b>	<b>GA – TS 9.1.80A</b>
<b>Validation Sequence</b>	<ul style="list-style-type: none"><li>• <b>Generally Available (GA)</b></li></ul>
<b>Supported DOCSIS Standard(s)</b>	<ul style="list-style-type: none"><li>• <b>DOCSIS® 3.0</b></li><li>• <b>Euro-DOCSIS® 3.0</b></li></ul>
<b>Supported Signaling Protocol(s)</b>	<ul style="list-style-type: none"><li>• <b>Network-Based Call Signaling (NCS)</b></li><li>• <b>Session Initiation Protocol (SIP)</b></li></ul>
<b>Supported PacketCable Standards</b>	<ul style="list-style-type: none"><li>• <b>PacketCable® 1.5</b></li><li>• <b>PacketCable® 2.0</b></li></ul>
<b>Firmware Filename</b>	<b>TS090180A_042315</b>
<b>SysDescriptor</b>	<b>SW_REV: 9.1.80A</b>
<b>PacketACE</b>	<b>DOCSIS 3.0 PacketACE Release 3.66 or later</b>

## 1.4 Firmware Filename Variant Information

The table below presents the filename extensions used on Touchstone products.

FILENAME EXTENSION	PURPOSE OF EXTENSION
_NA	North America signed firmware image
852	Supports the TG852 hardware platform
862	Supports the TG862 hardware platform
MODEL_860	Supports the DG860 hardware platform
MODEL_7_8	Supports the TM702/TM722/TM802/TM822/TM804 hardware platforms
WBM760_CM820	Supports WBM760/CM820 hardware platforms
MONO	Monolithic P5 image containing both eRouter and DOCSIS images
1602	Supports the TM1602 hardware platform
16XX	Supports the TG1672/DG1670/TG1662/DG1660 hardware platforms
24XX	Supports the DG2460/TG2472/DG2470/TG2492/DG3260/DG3270 hardware platforms
GW.ATOM	Monolithic (atomic) P6-image containing both eRouter and DOCSIS images
MAC14	Used to validate upgrades and downgrades
SIP	Session Initiation Protocol (SIP) firmware image
PC20	PacketCable 2.0 firmware image

## 1.5 Minimum Firmware Baseline for Hardware

The table below shows the minimum released firmware that has been verified to directly upgrade to this firmware release.

Hardware Model	Firmware Image
WBM760	TS070550A_070412 (TS 7.5.50A)
TM702	TS070550A_070412 (TS 7.5.50A)
TM722	TS070550A_070412 (TS 7.5.50A)
TM802	TS070550A_070412 (TS 7.5.50A)
TM804	TS070550A_070412 (TS 7.5.50A)
TM822	TS070550A_070412 (TS 7.5.50A)
CM820	TS070532D_050712 (TS 7.5.32D)
TG852	TS070532D_050712 (TS 7.5.32D)
DG860	TS070532D_050712 (TS 7.5.32D)
TG862	TS070532D_050712 (TS 7.5.32D)
TM1602A	TS090126A_072114 (TS 9.1.26A)
TM1602G	TS090157_103014 (TS 9.1.57)
DG1660	TS0801102G_030714 (TS 8.1.102G)
TG1662	TS0801102G_030714 (TS 8.1.102G)
DG1670	TS080098_041014 (TS 8.0.98)
TG1672	TS080098_041014 (TS 8.0.98)
DG1680	TS090161F_122214 (TS 9.1.61F)
DG2460	TS0901617D_013115 (TS 9.1.67D)
DG2470	TS090161F_122214 (TS 9.1.61F)
TG2472	TS090161F_122214 (TS 9.1.61F)
TG2492	TS090175A_031215 (TS 9.1.75A)

DG3260	TS090165_121814 (TS 9.1.65)
DG3270	

## 1.6 Product Documentation

Other relevant information is included in the following documentation:

Product
<i>Touchstone® Firmware Guide (TS9.1)</i>



## 2 Release Notes

The Release Notes describe the New Product Features introduced in the Touchstone Firmware for the ARRIS Touchstone E-MTA and Gateway Modem(s). Included in the Resolved Product Deficiencies section is a list of resolved operational considerations noted in previous releases.

### 2.1 New Product Features

#### Added in TS 9.1.80A

##### Wi-Fi Airtime Management (TG862 Products)

This firmware release supports the Airtime Management feature on the TG862 product lines. Transmit opportunities are allocated based on configurable weight (percentage of airtime) to each BSSID. All clients in a BSSID share the airtime percentage allocated to the BSSID. Airtime Fairness evenly distributes available air time among client devices. This prevents clients with poor connections from consuming too much airtime.

##### 16 -> 24 -> 32 Downstream Channel Bonding Upgrade

A new MIB 'arrisCmDoc30SetupExpandedBondingKey' is implemented for this feature. This MIB is settable only via the CM configuration file. Setting with a key string will upgrade the modem's bonding capability. When walked, The MIB returns either 'valid' or 'invalid'. Another new MIB 'arrisCmDoc30BondingModeCapability' is implemented to configure and verify a modem's bonding capability.

##### IPv6 Speed Test (TM1602 and TG1682 Products)

This feature is enhanced to support IPv6 Speed Test hardware acceleration.

##### LGI Default Values (TG2492 UPC)

This firmware release supports UPC LGI-defined default values for configuration parameters based on the Customer ID (Brand).

### **Added in TS 9.1.76B**

#### **IPv6 Speed Test (TM1602 and TG1682 Products)**

This firmware release supports the ability to originate Speed Test activities on the TM1602 and TG1682 product lines, when the CM interface is configured with IPv6 format. This Speed Test feature is supported by the custom MIB group *arrisSpeedTestMib*, by the TR181 (TR143) Download and Upload profiles, and a SpeedTest GUI page under Advanced.

#### **Wifi Client List Enhancement**

This firmware release provides additional information for connected WiFi clients, extending the list of values available in the MIB Table *arrisRouterWiFiClientInfoTable*.

#### **TR69: Ignore Data Model Selection**

This firmware release provides a MIB, *arrisTR69DataModelSelectIgnoreNonPuma5*, to allow the device to ignore the directive of MIB *arrisTR69DataModelSelect*, if present in config file. The new MIB itself is ignored on 7XX and 8XX products.

#### **MTA DNS: Ignore RD Validation**

This firmware release provides a MIB, *arrisCmDoc30SetupIgnoreMtaDnsRDValidation*, to allow the device to ignore the RD flag in the DNS response received by the Mta layer. This feature may be needed in environments where the DNS server is incorrectly modifying the flag before returning response to modem.

#### **WiFi: Improved Performance in High Packet Error Environment**

This firmware release provides a MIB, *arrisRouterWifiLowInitRate*, to improve WiFi performance in cases of increasing packet error ratio. This feature lowers the data rate, to accommodate the increased error rate. This feature is useful in environments with significant barriers like thick walls.

### **Added in TS 9.1.75A**

#### **TG2492 Hardware Support**

This firmware release introduces support for the DOCSIS 3.0 Residential Gateway products with 802.11ac Dual-band Concurrent Wireless capabilities, internal 4 port 10/100/1000 Base-T Router interface, providing 2-lines of voice, and ultra-high speed

data throughput based on the DOCSIS 3.0 cable modem specifications with support for up to 24 bonded downstream channels, and up-to 8 bonded upstream channels.

## HomePlug AV Monitoring (16XX and 24XX GW Products)

This firmware release introduces support for the monitoring of HPAV (HomePlug AV) Adaptors, when the device is attached to a local adaptor with Ethernet. The key chips supported are the Qualcomm INT6300 and INT6400, and newer chipsets are also taken into account. This feature is managed via the custom MIB group *cmHomeplugAV.mib*.

## IPv4 SpeedTest *cmTest MIB* (16XX and 24XX GW Products)

This firmware release extends support for the Ipv4 SpeedTest feature to the custom MIB group *cmTest.mib*.

## Euro PC2.0 Support

This firmware release provides support for the European version of PacketCable 2.0 voice standard.

## Country Voice Templates

This firmware release introduces support for the country templates supporting tone and ring cadence definitions for the following nations:

- United Kingdom
- Ireland
- Romania
- Czech Republic
- Slovakia

## Horizontal over Temperature (HOT) for TG2492

This firmware release extends support of the Horizontal Over Temperature (HOT) feature to the TG2492 models.

## Enhanced Firmware Loading

This firmware release brings support of the advanced feature for downloading of modem firmware files, allowing the operator specify different load lineups for different models. This capability is managed by the custom MIBs *arrisCmDoc30SwTable* in the MIB file *arrisCmDoc30Mib*.

## Hotspot Transport Enhancements

This firmware release provides flexibility for hotspot transport requirements. Operators can now configure Hotspot GRE tunnels to locally originate/terminate at the CM interface (instead of default GW interface), and the operator can also choose to originate/terminate the RADIUS portion only at CM Interface.

## Hotspot Support for RADIUS

This firmware release provides enhancement for Hotspot applications to support RADIUS procedures to authenticate, authorize and perform accounting for client hotspot usage.

## DSLite TCP MSS Clamping

This firmware release provides configuration control to activate MSS Clamping for TCP traffic over DS Lite.

### **Added in TS 9.1.67D**

## IPv4 Speed Test (16XX and 24XX Products)

This firmware release supports the ability to originate Speed Test activities on the 16XX and 24XX product lines, when the CM interface is configured with IPv4 format. This Speed Test feature is supported by the custom MIB group *arrisSpeedTestMib*, by the TR181 (TR143) Download and Upload profiles, and a SpeedTest GUI page under Advanced.

## Model 7 and Model 8 Product Support

This firmware release introduces support Model 7 and Model 8 devices. Please refer to the table in section 1.5 Minimum Firmware Baseline for Hardware.

## DG2460 Hardware Support

This firmware release introduces support for the DOCSIS 3.0 Residential Gateway products with 802.11ac Dual-band Concurrent Wireless capabilities, internal 4 port 10/100/1000 Base-T Router interface, for ultra-high speed data throughput based on the DOCSIS 3.0 cable modem specifications with support for up to 24 bonded downstream channels, and up-to 8 bonded upstream channels.

## IPv6 GRE

The TS9.1.67D firmware release introduces acceleration of IPv6 GRE packets by the Intel Packet Processor.

### **Added in TS 9.1.61F**

## **DG2470 Hardware Support**

The TS 9.1.61F firmware release introduces support for the DOCSIS 3.0 Residential Gateway products with 802.11ac Dual-band Concurrent Wireless capabilities, internal 4 port 10/100/1000 Base-T Router and MoCA 2.0 interface, for ultra-high speed data throughput based on the DOCSIS 3.0 cable modem specifications with support for up to 24 bonded downstream channels, and up-to 8 bonded upstream channels.

## **TR69/181**

The TS9.1.61F firmware release supports specified TR69/TR181 parameters for configuring L2oGRE and standard TR181 GRE.

## **IPv6 GRE**

The TS9.1.61F firmware release introduces IPv6 GRE feature, it is an extension of existing IPv4 GRE. Both IPv4 packets and IPv6 packets can be relayed by IPv6 GRE tunnel. The IPv6 GRE tunnel in this release is not accelerated by the Intel Packet Processor and the GRE tunnel over 5G radio is not supported.

## **AP Scan WebGUI page (16XX and 24XX products only)**

The TS 9.1.61F firmware release introduces the AP Scan web GUI page. This page provides an approach to measure both 2.4GHz and 5GHz SSIDs currently active on the network. These can be from your router as well as other routers nearby. The view shows the channels being used and the power of signal. Data can be displayed in both graphical and tabular form. The AP Scan feature is only available for technician user and is supported on 16xx/24xx hardware platform. The service will be affected during the scan process.

## DS Spectrum Analysis WebGUI page (16XX and 24XX products only)

The TS 9.1.61F firmware release introduces DS spectrum analysis web GUI page. This page provides a localized approach to measure the downstream RF signal performance. The RF Spectrum View web GUI shows the RF input coming into the cable modem. Each measurement is a data that provides the power of the signal at a frequency within a specified range. The Downstream Spectrum Capture feature is only available for technician user and is supported on 16xx/24xx hardware platform.

## Increase UNII-1 Band 5G Transmit Power limit for recent FCC change (1682 and 2470 products use QCA WiFi chipset only)

Compliance to recent FCC changes in 5G band to increase maximum transmit power from 17dBm to 30 dBm on UNII band 1 (5GHz channels 36-48); it applies to US Country Code only.

### **Added in TS 9.1.60**

## TM1602G Hardware Support

The TS 9.1.60 firmware release introduces support for the TM1602G DOCSIS 3.0 E-MTA product, with battery backup support and Power Management functionality in addition to providing 2-lines of voice service and ultra-high speed data throughput based on the DOCSIS 3.0 cable modem specifications with 16x4 channel bonding (upgradeable to 24x8 functionality).

### **Added in TS 9.1.26A**

## TM1602 Memory Increase

The TS 9.1.26A FW release supports increased memory on the TM1602A variants. Please refer to ARRIS Technical Bulletin ATB14-066 for additional information.

### **Added in TS 9.1.26**

## TM1602 Hardware Support

The TS 9.1.26 firmware release introduces support for the TM1602A DOCSIS 3.0 E-MTA product which provides support for 2-lines of voice service and ultra-high speed data throughput based on the DOCSIS 3.0 cable modem specifications with 16x4 channel

bonding. The TM1602 is upgradable to 24x4 channel bonding functionality which will be introduced as a future FW licensing option. For additional description of product features, please refer to the TS 9.1 Firmware User Guide.

## 2.2 Resolved Field Bulletin(s)

The following field bulletin issues were resolved in this Touchstone firmware release or previous firmware releases.

Field Bulletin Number	Field Bulletin Title	Product Defect Number
-	Not applicable	-



## 2.3 Resolved Product Deficiencies

ARRIS continues to resolve any product deficiencies discovered. This Touchstone Firmware release contains closure for the detailed issues listed in the following section.

**The following issues were resolved in release 9.1.80A:**

2.3.1 Single snmpset Command with multiple OIDS	
<i>Tracking No.</i>	PD 2842
<i>Description</i>	Unable to set docsDevSwServerAddressType and docsDevSwServerAddress or similar MIBs in a single snmpset command.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.2 MTA: GUPI TFTP Override Provisioning	
<i>Tracking No.</i>	PD 3361
<i>Description</i>	Unable to complete MTA provisioning with GUPI TFTP override.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.3 MTA: Need to Update the UK Country Template.	
<i>Tracking No.</i>	PD 2746
<i>Description</i>	Update the stutter dial tone as below: Level at NTP 0dBm to -27dBm Frequency 400Hz $\pm$ 5% & 350Hz $\pm$ 5% Duty cycle Continuous 0.75s On / 0.75s Off
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.4 'arrisRouterFWMacBridgingWebPageEnabled' is not supported	
<i>Tracking No.</i>	PD 2057
<i>Description</i>	'arrisRouterFWMacBridgingWebPageEnabled' was not implemented.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.5 Online LED Stays ON when RF is Disconnected During Firmware Download	
<i>Tracking No.</i>	PD 2431
<i>Description</i>	Online LED stays ON when RF is disconnected during firmware download
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.6 MTA PC20: The OPTIONS Method is not Properly Handled	
<i>Tracking No.</i>	PD 2502
<i>Description</i>	The MTA is not properly handling the OPTIONS method while in 3-way conference.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.7 “GHOST” Security Vulnerability	
<i>Tracking No.</i>	PD 1911
<i>Description</i>	A potential issue to the “GHOST” vulnerability exists, in which attackers can exploit the modem via the gethostbyname function.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.8 Telemetry: Charger FW Load does not Upgrade on 8XX	
<i>Tracking No.</i>	PD 2574
<i>Description</i>	The battery charger Firmware loads are not able to upgrade on the 8XX product line.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.9 SpeedTest: Domain Name not working for Server Address	
<i>Tracking No.</i>	PD 2543
<i>Description</i>	The SpeedTest function is not able to successfully perform DNS resolution if the server address is provisioned as a domain name.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.10 PSM: Modem Unable to Recover if Reset	
<i>Tracking No.</i>	PD 2754
<i>Description</i>	When fully in PSM mode due to AC power disconnected, if the modem is then reset, then the modem does not recover.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.11 TG862: Bonding Mode Does Not Change to 1x1 After Call is Terminated	
<i>Tracking No.</i>	PD 2080
<i>Description</i>	On TG862 modems, if the system enters PSM (goes on battery), and call is in progress, the modem does not properly change to 1x1 bonding mode after the call is released (on-hook).
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.12 GW: Incorrect Index for MIB walk of <i>arrisRouterLanSrvTable</i> Causes GW Issues	
<i>Tracking No.</i>	PD 3281
<i>Description</i>	If performing a MIB walk of the <i>arrisRouterLanSrvTable</i> , and an incorrect index is used, then the modem's SNMP engine will be corrupted.
<i>Impact</i>	Service
<i>Occurrence</i>	High

**The following issues were resolved in release 9.1.76B:**

<b>2.3.13 GW: Setting Primary Subnet to Bridge Mode Disables SSIDs</b>	
<i>Tracking No.</i>	PD 1900
<i>Description</i>	When the routing mode for the primary subnet is set to “bridge” in the CM config file (via MIB <i>arrisRouterLanPassThru</i> ), the associated SSIDs are disabled.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<b>2.3.14 24XX Does not interop with ActionTEC WCB-3000N using WPS configuration</b>	
<i>Tracking No.</i>	PD 2516
<i>Description</i>	The eRouter does not share the WPA key over WPS to the extender.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<b>2.3.15 24XX WPS does not automatically re-authenticate after an RF disconnect</b>	
<i>Tracking No.</i>	PD 2513
<i>Description</i>	Devices that are connected to a 24XX using WPS will not be automatically authenticated after an RF signal loss. A re-initialization of the WPS process is required to re-authenticate the devices.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<b>2.3.16 Reserved DHCP IP Address not Assigned to Client CPE</b>	
<i>Tracking No.</i>	PD 2521
<i>Description</i>	Connected Devices are not assigned the Static IP Address that was reserved for the Client on the GW.
<i>Impact</i>	Service
<i>Occurrence</i>	Medium

2.3.17 MIB <i>pkcSigDefCallSigTos</i> does not set Signaling DSCP Correctly	
<i>Tracking No.</i>	PD 2521
<i>Description</i>	The DSCP value in the MIB <i>pkcSigDefCallSigTos</i> is not correctly used to setup the TOS/DSCP value in the associated CallP signaling messages.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.18 GUI: Unable to hide MoCA Page	
<i>Tracking No.</i>	PD 2356
<i>Description</i>	Operators are unable to hide GUI pages like MoCA page, as the MIB <i>arrisRouterWebAccessLevel</i> is not working properly.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.19 “POODLE” Potential Security Issue	
<i>Tracking No.</i>	PD 2149
<i>Description</i>	The device is a vulnerable to the man-in-the-middle attack known as the “POODLE” issue, which occurs due to an ability to drop back to SSL 3.0
<i>Impact</i>	Service
<i>Occurrence</i>	High

**The following issues were resolved in release 9.1.75A:**

2.3.20 Incorrect Default for arrisMtaDevPwrSupplyDataShutdownTime	
<i>Tracking No.</i>	PROD00221036
<i>Description</i>	The MIB <i>arrisMtaDevPwrSupplyDataShutdownTime</i> default value is reporting 900 where the correct default value is 300.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.21 Loop Diagnostics Not Supported	
<i>Tracking No.</i>	PD 2208
<i>Description</i>	Loop Diagnostics is not supported in this release.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.22 RIP: Low Throughput	
<i>Tracking No.</i>	PD 2180
<i>Description</i>	RIP throughput is limited to approximately 30Mbps in this release, as RIP traffic is not accelerated.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.23 SpeedTest does not work with Absolute File Path	
<i>Tracking No.</i>	PD 2099
<i>Description</i>	The SpeedTest feature will not function properly if the download URL is provisioned with an absolute file pathname.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.24 TM7X2: Ethernet Port does not Power Down After entering PSM	
<i>Tracking No.</i>	PD 2019
<i>Description</i>	When the TM702 and TM722 modems lose AC power and start running on battery, the Ethernet port does not power down.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.25 GW: Post Provisioning Ignored in Bridge Mode	
<i>Tracking No.</i>	PD 1903
<i>Description</i>	Post provisioning does not get applied if the modem is in bridge mode after the CM config file is processed.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.26 MoCA2.0: Devices Unable to Recover after Upgrade	
<i>Tracking No.</i>	PD 1935
<i>Description</i>	On upgrade of units that feature MoCA 2.0 support, some of the units are not able to properly boot, and cannot be recovered.
<i>Impact</i>	Service
<i>Occurrence</i>	Medium
2.3.27 DG2470: Incorrect sysDescr	
<i>Tracking No.</i>	PROD00222882
<i>Description</i>	The System Descriptor for the DG2470 incorrectly reports as DG2400 for the modem name.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.28 GUI: Web Access Blocked with Multiple Rules Configured	
<i>Tracking No.</i>	PD 2331
<i>Description</i>	When more than one IP range is configured via MIB <i>arrisRouterWebAccessWANACL</i> , all WAN side access to the GUI is blocked
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.29 GUI: Web Pages Access Control Not Configurable	
<i>Tracking No.</i>	PD 2236
<i>Description</i>	Most of the <i>arrisRouterWebAccessTable</i> MIB settings do not properly block web page content as required.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.30 GUI is Inoperative when the Modem uses XML for Configuration	
<i>Tracking No.</i>	PD 2004
<i>Description</i>	Systems using XML Config files can lead to issues with the internal SNMP Engine, causing all GUI access to be blocked.
<i>Impact</i>	Operational
<i>Occurrence</i>	Medium
2.3.31 <i>arrisRouterWebAccessLevel</i> MIB Values Incorrect	
<i>Tracking No.</i>	PD 2389
<i>Description</i>	Two of the possible values for this MIB are associated with the wrong numeric value: <ul style="list-style-type: none"> <li>• <i>accessUser</i> is 3, but should be 2</li> <li>• <i>accessAll</i> is 2, but should be 3</li> </ul>
<i>Impact</i>	Operational
<i>Occurrence</i>	High

**The following issues were resolved in release 9.1.67D:**

2.3.32 RIP Configuration may not Persist over Upgrade	
<i>Tracking No.</i>	PROD00219115/PROD00223997/PD 1063
<i>Description</i>	RIP configuration may not persist after upgrade to TS 9.1 FW.
<i>Impact</i>	Service
<i>Occurrence</i>	Low



2.3.33 ERouter MIBs over upgrades	
<i>Tracking No.</i>	PROD00222519
<i>Description</i>	<p>On a GW running TS 7.5 or TS 7.7 FW, static WAN configuration by subscriber WebGUI may not persist after upgrade to TS9.1 FW. Further, settings of the following MIBs previously configured by technician user in TS7.5 or TS7.7 FW may not persist following the upgrade:</p> <p> arrisRouterWanMTUSize.0  arrisRouterWanConnType.0  arrisRouterWanStaticIPAddr.1  arrisRouterWanStaticPrefix.1  arrisRouterWanStaticGateway.1  arrisRouterWanUserName.0  arrisRouterWanPassword.0  arrisRouterWanEnableIdleTimeout.0  arrisRouterWanIdleTimeout.0  arrisRouterWanTunnelHostName.0  arrisRouterWanEnableKeepAlive.0  arrisRouterWanKeepAliveTimeout.0  arrisRouterLanEnvironmentControl.200  arrisRouterFWDDNSEnable.0  arrisRouterFWEnableMulticast.0  arrisRouterSNTPServerAddr.1  arrisRouterSNTPServerAddr.2  arrisRouterLanEtherPortEnabled.1  arrisRouterLanEtherPortEnabled.2  arrisRouterLanEtherPortEnabled.3  arrisRouterLanEtherPortEnabled.4  arrisRouterLanEtherPortDuplex.1  arrisRouterLanEtherPortDuplex.2  arrisRouterLanEtherPortDuplex.3  arrisRouterLanEtherPortDuplex.4  arrisRouterLanEtherPortAuto.1  arrisRouterLanEtherPortAuto.2  arrisRouterLanEtherPortAuto.3  arrisRouterLanEtherPortAuto.4 </p>
<i>Impact</i>	Service
<i>Occurrence</i>	High

<b>2.3.34 ERouter DHCPv4 Option 43.2 is Incorrect</b>	
<i>Tracking No.</i>	PD 1150
<i>Description</i>	The eRouter's DHCPv4 option 43.2 "Device Type" gives "00", which should be "02".
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<b>2.3.35 WiFi: 5G Clients Unable to Connect via WPS</b>	
<i>Tracking No.</i>	PD 1719
<i>Description</i>	Clients are unable to connect on the 5G radio using the WPS security mechanisms.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<b>2.3.36 PSM: ERouter Unable to Recover after Running On Battery</b>	
<i>Tracking No.</i>	PD 1576, 1742
<i>Description</i>	After recovering from a short AC outage, the Gateway portion of the modem does not return to service.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<b>2.3.37 WiFi: Customized SSID String Includes "-"</b>	
<i>Tracking No.</i>	PROD00224271
<i>Description</i>	When constructing SSID Names based on MIB <i>arrisRouterWiFiCustomSSIDStr</i> , the character "-" is incorrectly added between the string and the 4 MAC digits.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<b>2.3.38 PSM: Modem Unable to Recover after RF Cut while Running on Battery</b>	
<i>Tracking No.</i>	PROD00224249
<i>Description</i>	The modem does not recover if running on battery, and then experiences a loss of WAN side RF.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.39 WiFi: Country Codes AN, GD, JM Unable to use Channels 12,13	
<i>Tracking No.</i>	PROD00221312
<i>Description</i>	If configured for country codes AN, GD, or JM, the radio is not able to use channels 12 or 13.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.40 Extended Upstream Value Should Not Be Stored Persistently	
<i>Tracking No.</i>	PROD00221987
<i>Description</i>	The MIB <i>arrisCmDoc30SetupExtendedUpstreamTransmitPowerValue</i> , when set in the CM config file, is being stored persistently, surviving resets and removal from CM config file. The Value should be reset to defaults after a reset.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.41 MoCA: Network Loop Causes Modem Resets	
<i>Tracking No.</i>	PROD00221290
<i>Description</i>	In cases where modems form a MoCA network loop (insufficient plant filters), multicast packets can flood the loop and cause modems to run out of memory and reboot.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.42 WiFi: Country Code EU Not Accepted	
<i>Tracking No.</i>	PROD00221728
<i>Description</i>	The CM Config file setting “ <i>arrisRouterWiFiCountry.0=EU</i> ” causes the CM Config file to be rejected.
<i>Impact</i>	Service
<i>Occurrence</i>	High

**The following issues were resolved in release 9.1.61F:**

<b>2.3.43 WAN Access of DMZ Server</b>	
<i>Tracking No.</i>	PROD00220396
<i>Description</i>	If configured in the DMZ, attempts to access a LAN side HTTP server from a WAN-side host may not be successful.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<b>2.3.44 One-Way Audio during Off-net Call</b>	
<i>Tracking No.</i>	PROD00221924
<i>Description</i>	For an EMTA line configured with HD Voice (G.722), the far-end of an off-net call may not hear the near-end EMTA caller if the far-end is not enabled for HD Voice.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<b>2.3.45 BPI Authorization Does Not Complete</b>	
<i>Tracking No.</i>	PROD00219826, PROD00220949
<i>Description</i>	On certain CMTSSs, the 16XX modems with sysUptime values longer than approximately 40 days will be unable complete the registration sequence due to BPI authorization errors.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<b>2.3.46 Subscriber Cannot Duplicate SSID Names Across 2.4GHz and 5GHz SSID</b>	
<i>Tracking No.</i>	PROD00213734
<i>Description</i>	It is not possible for the subscriber to duplicate the SSID name for both 2.4GHz and 5GHz radios.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<b>2.3.47 LAN side CPE can't get Stateful IPv6 address</b>	

<i>Tracking No.</i>	PROD00223853
<i>Description</i>	If enable stateful DHCPv6, DHCPv6 server sometimes would not start up correctly during initialization.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
<b>2.3.48 Upgrade from some old version FW would cause modem continuously reboot.</b>	
<i>Tracking No.</i>	PROD00223666
<i>Description</i>	Some old FW writes invalid information to /nvram/8/clientdb.txt file, it would cause modem continuously reboot after upgrade to TS9.1.60 FW.
<i>Impact</i>	Service
<i>Occurrence</i>	Low

**The following issues were resolved in release 9.1.60:**

<b>2.3.49 UI Security Issue</b>	
<i>Tracking No.</i>	PROD00219824, PROD220571, PROD00220646
<i>Description</i>	Security Issue Reported - Cross-site Request (CSRF), Cross-site Scripting
<i>Impact</i>	Service
<i>Occurrence</i>	Low
<b>2.3.50 UCC May Cause Loss of Layer 3</b>	
<i>Tracking No.</i>	PROD00222890
<i>Description</i>	While DS bonded and not US bonded, TM822 IP layer stops responding following move command or upstream channel change (UCC) from the CMTS.
<i>Impact</i>	Service
<i>Occurrence</i>	High

## 3 Letter of Operational Considerations

The Letter of Operational Considerations is to inform operators of any system considerations for the Touchstone Firmware that may affect service, operations, or maintenance for this product release.

### 3.1 Operational Considerations

Listed are known Operational Considerations that have been identified during ARRIS' standard quality testing that can affect normal operation. Any additional items discovered during field deployments would be noted in future *Release Notes and Letter of Operational Consideration* or *Field Bulletins*. Unless specifically noted, it is ARRIS' intention to have all considerations resolved in future product releases.

3.1.1 SpeedTest: Select Devices Not Supported	
<i>Tracking No.</i>	PD 2081
<i>Description</i>	The SpeedTest capability is not supported on the following devices due to memory constraints: <ul style="list-style-type: none"><li>- DG860</li><li>- TM8xx</li><li>- TM7xx</li><li>- CM820</li><li>- WBM760</li></ul>
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	None
3.1.2 WEP Password Change for one SSID Applies to all SSIDs	
<i>Tracking No.</i>	PD 1995
<i>Description</i>	For certain models (24XX), a change of a WEP password for any one SSID will modify the WEP password for all SSIDs
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	None

### 3.1.3 16XX: Modem Reboots When Entering PSM

<i>Tracking No.</i>	PD 1854
<i>Description</i>	When configured for WiFi Shutdown Only, the 16XX modems reboot when attempting to enter Power Save Mode.
<i>Impact</i>	Service
<i>Occurrence</i>	Medium
<i>Workaround</i>	Choose alternate PSM settings.

### 3.1.4 AP Scan Displays One Channel for 80MHz

<i>Tracking No.</i>	PD 1820
<i>Description</i>	When the surrounding AP works at 80MHz, the AP Scan result displays only one channel and the frequency bandwidth is equal to 20MHz on the GUI.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	None

### 3.1.5 Hotspot: Max Clients Setting does not extend to Multiple SSIDs

<i>Tracking No.</i>	PD 1807
<i>Description</i>	The MIB <i>arrisRouterSoftGreMaxSessions</i> does not limit the concurrent SoftGRE client sessions connecting to multiple hotspot SSIDs.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	Set <i>arrisRouterBssMaxWifiClients</i> for each SSID.

### 3.1.6 Syslog Messages Formatted Incorrectly

<i>Tracking No.</i>	PD 3233
<i>Description</i>	Syslog output includes characters that violate the Base-64 string formatting.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

### 3.1.7 GW: 2.4G Channel Bandwidth Default is Incorrect

<i>Tracking No.</i>	PD 3225
<i>Description</i>	The default for channel bandwidth for the 2.4G radio is incorrectly set to 20/40MHz, it should be 20MHz.
<i>Impact</i>	Service
<i>Occurrence</i>	High

### 3.1.8 IPv6 GW: DHCPv6 Issues on Second SSID

<i>Tracking No.</i>	PD 2925
<i>Description</i>	If DHCP is enabled in Gateway for IPv6 clients, and if an IPv6 client is associated with the first (primary) SSID, then an IPv6 client associating with the second (or later) SSID is unable to associate. This is due to modem incorrectly sending out Lifetime of 0.
<i>Impact</i>	Service
<i>Occurrence</i>	Medium

### 3.1.9 Hotspot: Missing Accounting Message after Client DHCP Renew/Rebind

<i>Tracking No.</i>	PD 2925
<i>Description</i>	If a hotspot client fails a DHCP renew or rebind, then the RADIUS accounting messages (request, stop) will not be sent.
<i>Impact</i>	Operational
<i>Occurrence</i>	High



<i>Workaround</i>	Correct DHCP issues
<b>3.1.10 MAC Bridging: IPv6 not supported</b>	
<i>Tracking No.</i>	PD 2447
<i>Description</i>	Clients that are configured against the MAC Bridging feature are unable to pull an appropriate IPv6 address.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	Use IPv4 address
<b>3.1.11 TR69: Special Characters not Supported</b>	
<i>Tracking No.</i>	PD 2215
<i>Description</i>	<p>TR69 is unable to properly encode special characters (eg. “&amp;”, “&lt;” and “&gt;”), and is not able to deliver parameter values containing these characters successfully to the ACS.</p> <p>One example of possible use of special characters is SSID Names.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	Do not utilize special characters in parameter values.
<b>3.1.12 IPv6 SoftGRE Traffic is not Accelerated</b>	
<i>Tracking No.</i>	PD 1218
<i>Description</i>	IPv6 softGRE data traffic is not accelerated via the modem’s packet processor.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	None

**3.1.13 SpeedTest: The Payload and Total Interface Traffic Counters are incorrect from SNMP**

<i>Tracking No.</i>	PD 3706
<i>Description</i>	MIB values 'arrisTR143DownloadTestBytesReceived' and 'arrisTR143DownloadTotalBytesReceived' are incorrect.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	None

**3.1.14 IPv6 SpeedTest Feature Requires Use of One CPE MAC Address**

<i>Tracking No.</i>	PD 3985
<i>Description</i>	One internal MAC address will be counted as a CPE, which will impact the max CPE number counting (docsDevMaxCpe).
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	Increase max CPE by one.

## **3.2 Unsupported Features**

The following features are not supported in the TS 9.1 release at this time.

- Voice / Media Security (Encryption of RTP stream capabilities)
- Voice Payload Header Suppression
- Silence Suppression and UGS/AD Service Flows
- USB
- HD Voice Loop Diagnostics
- 64ms Echo Canceller tail length for UK.

### 3.3 Upgrade Considerations

The following considerations are important to take into account when upgrading to this firmware release.

#### **Added in TS 9.1.80A**

#### TS 7.6 to TS 9.1 Upgrade Process only Applied Once

The user settings are only transferred on the first upgrade from TS 7.6 to TS 9.1. Subsequent changes will not be retained when migrating from one release to another.

Performing a factory reset on TS 7.6 will only affect provisioning for TS 7.6. Similarly, performing a factory reset on TS 9.1 will only affect provisioning for TS 9.1.

#### MIB OID Changes

- 1) *arrisRouterFWSrvTr69LastInstance*  
The OID of this MIB node has moved from 1.3.6.1.4.1.4115.1.20.1.1.4.34 to 1.3.6.1.4.1.4115.1.20.1.1.4.46
- 2) *arrisRouterRIPInterface*  
The OID of this MIB node has moved from 1.3.6.1.4.1.4115.1.20.1.1.2.5.19 to 1.3.6.1.4.1.4115.1.20.1.1.2.5.23
- 3) *arrisRouterCpuSpeed*  
The OID of this MIB node has moved from 1.3.6.1.4.1.4115.1.20.1.1.5.51 to 1.3.6.1.4.1.4115.1.20.1.1.5.64

#### MIB Name Changes

- 1) Change MIB 'arrisrouterWifiLowInitRate' to 'arrisRouterWifiLowInitRate'

#### **Added in TS 9.1.67D**

#### MIB OID Changes

In order to properly align with MIB OID definitions established in the TS7.X series of releases, the following MIB node OIDs have been modified:

- 1) *arrisRouterLanUSBPortTable*  
The OID of this MIB node has moved from 1.3.6.1.4.1.4115.1.20.1.1.2.12 to 1.3.6.1.4.1.4115.1.20.1.1.2.16.
- 2) *arrisRouterLanFileSharingObjs*

This MIB node's OID has changed from 1.3.6.1.4.1.4115.1.20.1.1.2.13 to 1.3.6.1.4.1.4115.1.20.1.1.2.17.

The MIB *arrisRouterLanMaxIPv6RAInterval* is now at OID 1.3.6.1.4.1.4115.1.20.1.1.2.13.

3) *arrisRouterWMM50Cfg*

The change in OID for this WiFi MIB Node is from

1.3.6.1.4.1.4115.1.20.1.1.3.52 to 1.3.6.1.4.1.4115.1.20.1.1.3.63.

The original OID is reserved for MIB *arrisRouterWiFiAllChannelsAllowed*.

4) *arrisRouterWPS50Cfg*

For this MIB Node, the OID has migrated from 1.3.6.1.4.1.4115.1.20.1.1.3.53 to 1.3.6.1.4.1.4115.1.20.1.1.3.65.

5) *arrisRouterWiFiExtensionChannel*

This WiFi MIB has altered its OID from 1.3.6.1.4.1.4115.1.20.1.1.3.54 to 1.3.6.1.4.1.4115.1.20.1.1.3.64. The WiFi MIB *arrisrouterWifiClientIdleTimeout* has reserved OID 1.3.6.1.4.1.4115.1.20.1.1.3.54.

## MIB *arrisRouterLanClientAdapterType* Value Changes

In order to provide finer granularity for client information (per SSID and per Ethernet Port data), there have been some minor modifications to the values returned by the read-only MIB *arrisRouterLanClientAdapterType*.

One value has changed:

- ***wireless(2)* is now *usb(2)***

The following values are newly introduced:

- *dsg(4)*,
- *wireless1(5)*,
- *wireless2(6)*,
- *wireless3(7)*,
- *wireless4(8)*,
- *wireless5(9)*,
- *wireless6(10)*,
- *wireless7(11)*,
- *wireless8(12)*,
- *wireless9(13)*,
- *wireless10(14)*,
- *wireless11(15)*,
- *wireless12(16)*,
- *wireless13(17)*,
- *wireless14(18)*,
- *wireless15(19)*,
- *wireless16(20)*,

- *ethernet2(21)*,
- *ethernet3(22)*,
- *ethernet4(23)*

### **Added in TS 9.1.61F**

## **ARRIS Interactive LLC Manufacturer CVC Expiration**

The current ARRIS DOCSIS and Euro-DOCSIS Manufacturer CVCs for “Arris Interactive L.L.C.” covering the following products have expired:

Models 7xx, 8xx, DG1660, TG1662, DG1670, and TG1672.

Per agreement with CableLabs, ARRIS is permitted to continue using the existing “Arris Interactive L.L.C.” CVCs for existing field deployed products, and will ensure that all future firmware loads are “signed” with a valid date code within the range for upgrade compatibility purposes. MSOs will continue to be able to both upgrade and downgrade their existing products without needing to modify their CM configuration files.

For customers that co-sign the images with their MSO CVC, there is no impact. No changes are required.

## **New ARRIS Group Inc. Manufacturer CVC**

Going forward, ARRIS will use a new DOCSIS and Euro-DOCSIS Manufacturer “ARRIS Group, Inc.” CVCs starting with the following products:

TM1602, DG2470, and TG2472.

In the sysDescr.0 MIB object (for these products) the vendor field will be “ARRIS Group, Inc.”.

For customers that co-sign the images with their MSO CVC, there is no impact. No changes are required.

Customers that utilize the existing ARRIS Interactive Manufacturer’s CVC in their CM configuration files are impacted if they plan to deploy the new hardware models above, as DOCSIS specifications only allow one Manufacturer’s CVC per configuration file. To address the issue, customers should plan to deploy separate CM configuration files for the different hardware models.

Please contact ARRIS Tech Support for assistance.

## Web Browser Cache after Downgrade from TS 9.1 to TS 7.X Releases

Following a downgrade of a GW device from TS 9.1 to TS 7.5 or TS 7.7, users accessing the Technician GUI will observe that some options are not displayed or are greyed-out. A refresh of the Web Browser's cache will resolve.

## Downgrades from TS 9.1.61F to Previous TS7.X Releases

Customer downgrades from TS9.1 to prior TS 7.5 or TS 7.7 release are fully supported as TS 7.x non-volatile settings are retained after upgrade. However, after a downgrade, any subsequent provisioning changes made on a TS 7.5 or TS 7.7 firmware release will NOT be preserved upon return to TS 9.1.45A.

## Upgrading from NCS to SIP

The following provides general information about upgrading from NCS to SIP.

### **PacketCable 1.5 NCS to PacketCable 2.0 Upgrade via Configuration File:**

#### **Existing customer:**

1. The modem is up and running PacketCable 1.5 NCS. Voice service is functional.
2. Reboot the unit with the new PacketCable 2.0 firmware image name in the CM configuration file.
3. The modem boots up, downloads the new image, and resets. The upgrade is successful.
4. The modem boots up again and comes back on line using the PacketCable 1.5 NCS MTA configuration file. Data service is functional. Voice service is not.
5. The back-office changes the MTA configuration file to PacketCable 2.0.
6. The modem is reset.
7. The modem boots up and comes back online in PacketCable 2.0 mode.

#### **New Customer (with unit loaded with PacketCable 1.5 NCS image):**

1. The new PacketCable 2.0 firmware image name is added to the CM configuration file.
2. The MTA configuration file is constructed for PacketCable 2.0 SIP.

3. Power up the modem.
4. The modem boots up, downloads the new image, and resets. The upgrade is successful. During the short period of time in which the modem is online during the upgrade voice service is not functional.
5. The modem boots up and comes back online in PacketCable 2.0 mode.

### **PacketCable 1.5 NCS to PacketCable 2.0 Upgrade via SNMP:**

#### **Existing customer:**

1. The modem is up and running PacketCable 1.5 NCS. Voice service is functional.
2. An upgrade via SNMP is triggered for the PacketCable 2.0 firmware image.
3. The modem downloads the new image and resets.
4. The modem boots up and comes back on line using the PacketCable 1.5 NCS MTA configuration file. Data service is functional. Voice service is not.
5. The back-office changes the MTA configuration file to PacketCable 2.0.
6. The modem is reset.
7. The modem boots up and comes back online in PacketCable 2.0 mode.

#### **New Customer (with unit loaded with PacketCable 1.5 NCS image):**

1. A standard CM configuration file is used. The PacketCable 2.0 firmware image name is not included.
2. The MTA configuration file is constructed for PacketCable 2.0 SIP.
3. Power up the modem.
4. The modem boots up and comes on line using the PacketCable 2.0 SIP MTA configuration file. Data service is functional. Voice service is not.
5. An upgrade via SNMP is triggered for the PacketCable 2.0 firmware image.
6. The modem downloads the new image and resets.
7. The modem boots up and comes back online in PacketCable 2.0 mode.

Note that the contents of the CM configuration file may affect these procedures particularly if they are different between PacketCable 1.5 NCS and PacketCable 2.0 SIP.

### **Added in TS 9.1.26A**

No Upgrade Path from TS 9.1.26 (TM1602A platform only)



The TS 9.1.26A release is the initial introduction of Firmware for the enhanced TM1602A platform with increase memory. Early TM1602 platforms running TS 9.1.26 cannot upgrade to TS 9.1.26A. In addition, enhanced devices running TS 9.1.26A cannot be downgraded to TS 9.1.26. Please refer to ARRIS Technical Bulletin ATB14-066 for additional information on distinguishing these platforms.

## CM Interface Table (ifTable)

The TS 9.1 release supports expanded US and DS capabilities. For current and future feature capabilities across multiple platforms, the indecies for

ifIndex	ifType	ifDescr	ifName	Purpose
48-78	docsCableDownstream (128)	RF Downstream Interface #	dsch(x) where x = one of available dschs	Secondary RF Downstream Channel(s)
80-86	docsCableUpstream (129)	RF Upstream Interface #	usch(x) where x = one of available uschs	Secondary RF Upstream Channel(s)

The full Cable Modem Interface Table is as follows:

## CM Interface MIB Table (ifTable)

ifIndex	ifType	ifDescr	ifName	Purpose	Changes from TS 7.5
1	other (1)	eRouter Embedded Interface	esafe0	Controls the Operator-Facing Interface. **	Replaces index 10 in TW loads.  Ethernet CPE Interface moved to index 6
2	docsCableMacLayer (127)	RF MAC Interface	cni0		
3	docsCableDownstream (128)	RF Downstream Interface	dsch(x) where x = one of the available dschs	Primary RF Downstream	
4	docsCableUpstream (129)	RF Upstream Interface	usch(x) where x = one of the available uschs	Primary RF Upstream	

ifIndex	ifType	ifDescr	ifName	Purpose	Changes from TS 7.5
6 – 9	ethernetCsmacd (6)	External Switch Port #  Where # = 1..4	ext1 – ext4	Enable /disables Ethernet Port #  Where # = 1..4	Controls Adds the ability of shutting/starting individual Ethernet port and also to get the statistics.
12	ieee80211 (71)	Wireless Interface	wifi	Used to enable/disable access to residential subscribers BSSs/SSID	Removed interface number  Control for SSID1 on 2.4GHz radio is now index 10100
16	other (1)	PacketCable Embedded Interface	esafe1	Used to enable/disable MTA/EDVA functionality.	
40	mocaVersion1 (236)	MoCA Interface	moca	Used to enable/disable access to the MoCA interface	New interface for future release.
48 - 79	docsCableDownstream (128)	RF Downstream Interface #  (# = 1..31)	dsch(x)  ( x = available dschs)	Secondary RF Downstream	
80 - 86	docsCableUpstream (129)	RF Upstream Interface #  (# = 1..7)	usch(x)  ( x = available uschs)	Secondary RF Upstream	
200 – 2xx  (xx = highest LAN index)	ipforward (142)	Logical Lan Interface #  (# = 1..16)	l2sd0.2 – l2sd0.xx	Logical Lan's/IP information defined in DHCP servers for SSID/ETH/USB ETC...	New interface
300	ipforward (142)	Wan Side Interface 1: For CM	wan0	WAN Side Interface for CM	
301	ipforward (142)	Wan Side Interface 2: For eRouter	erouter0	WAN Side Interface for eRouter	Called lbr0 in 7.5
302	ipforward (142)	Wan Side Interface 3: For MTA	mta0	WAN Side Interface for MTA	Was located at index 16 in 7.5
10000	ieee80211 (71)	Wi-Fi Radio interface	wifi24	2.4GHz Radio interface	New interface

ifIndex	ifType	ifDescr	ifName	Purpose	Changes from TS 7.5
10001 - 10016	ieee80211 (71)	Wi-Fi SSID sub-interface #  (# = 1..8, see Note 2)	wifi24_1 – wifi24_8	SSID 1-8 on 2.4GHz Radio interface	New interface  Indexes 10001 – 10004 replace indexes 12-15
10100	ieee80211 (71)	Wi-Fi Radio interface	wifi50	5.0GHz Radio interface	New interface
10101 - 10116	ieee80211 (71)	Wi-Fi SSID sub-interface #  (# = 1..8, see Note 2)	wifi50_1 – wifi50_8	SSID 1-8 on 5.0GHz Radio interface	New interface

**NOTE 1:** Operator-Facing Interface - The eRouter interface that is connected to the embedded cable modem. As defined in [RFC 6204], this is a Wide Area Network (WAN) interface. In CWMP this is called an upstream interface.

**NOTE 2:** TS 9.1 for the Time Warner release will only have support for eight (8) Wireless Interfaces (SSIDs) per radio.

## 4 Customer Service and Support

For Technical Support, please visit the ARRIS Technical Support web page at <http://ask.arrisi.com>.

Other methods for contacting the support organization are listed below.

### **North America**

Email [techsupport.na@arrisi.com](mailto:techsupport.na@arrisi.com)  
Telephone (888) 221 9797 (US toll free)  
+1 678 473 5656 (Worldwide)  
Office Hours 8:00 a.m. to 8:00 p.m. EST

### **South America – Chile**

Email [techsupport.cala@arrisi.com](mailto:techsupport.cala@arrisi.com)  
Telephone +56 2 678 4500  
Office Hours 9:00 a.m. to 6:00 p.m. (Chile local time).

### **Europe – Amsterdam, The Netherlands**

Email [techsupport.europe@arrisi.com](mailto:techsupport.europe@arrisi.com)  
Telephone +31 20 311 2525  
Office Hours 8:30 a.m. to 17:30 p.m. CET

### **Japan – Tokyo**

Email [techsupport.japan@arrisi.com](mailto:techsupport.japan@arrisi.com)  
Telephone +81 (0) 3 5371 4142  
Office Hours 9:30 a.m. to 6:00 p.m. (Tokyo local time)

### **Asia**

Email [techsupport.asia@arrisi.com](mailto:techsupport.asia@arrisi.com)  
Telephone +82 31 783 4893  
Office Hours 9:30 a.m. to 6:00 p.m. (local time)

### **Korea**

Email [techsupport.asia@arrisi.com](mailto:techsupport.asia@arrisi.com)  
Telephone +82 31 783 4893  
Office Hours 9:30 a.m. to 6:00 p.m. (local time)

### **Worldwide – North America**

Email [techsupport@arrisi.com](mailto:techsupport@arrisi.com)  
Telephone USA +1 678 473 5656

**Emergency support** is available after normal business hours for customers with a support contract ID via the listed contact information.

# **Touchstone<sup>®</sup> Gateway Firmware**

## **Release 9.1.80A**

### **Release Notes and Letter of Operational Consideration**

Copyright ©2015 ARRIS Group, Inc.  
All rights reserved

The information disclosed herein is proprietary to ARRIS Group, Inc and is not to be used by or disclosed to unauthorized persons without written consent of ARRIS Group, Inc. The recipient of this document shall respect the security status of the information.

Version:1.0  
Status: Approved