
Touchstone[®] Telephony Firmware



Release 6.1.95

Release Notes and
Letter of Operational
Considerations

Touchstone[®] Telephony Firmware

Release 6.1.95

Release Notes and Letter of Operational Considerations

Document release	Release 1.0
Document date	April 1, 2010

© 2010 ARRIS
All Rights Reserved

Printed in the USA

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. User must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to ARRIS.

ARRIS, ARRIS International, and Voice Port are trademarks of ARRIS Licensing Company. Cornerstone is a registered trademark of ARRIS Licensing Company.

The firmware described in this document is furnished under a license agreement and may only be used in accordance with the terms of that license.

Publication History

April 1, 2010

Initial Draft, v0.1

Table of Contents

1	OBJECTIVES OF THIS DOCUMENT	1
1.1	ARRIS COMMITMENT	1
1.2	PURPOSE AND SCOPE OF THIS DOCUMENT	1
1.3	PRODUCT IDENTIFICATION AND PURPOSE OF RELEASE	1
1.4	FIRMWARE FILENAME VARIANT INFORMATION	2
1.5	FILENAME INFORMATION FOR MIB OBJECTS	2
1.6	MINIMUM FIRMWARE BASELINE FOR HARDWARE	3
1.7	PRODUCT DOCUMENTATION	5
2	RELEASE NOTES	6
2.1	NEW PRODUCT FEATURES	6
2.2	RESOLVED FIELD BULLETIN	19
2.3	RESOLVED PRODUCT DEFICIENCIES	20
3	LETTER OF OPERATIONAL CONSIDERATIONS	93
3.1	OPERATIONAL CONSIDERATIONS	93
3.2	UPGRADE CONSIDERATIONS	105
4	CUSTOMER SERVICE AND SUPPORT	107
	APPENDIX A: COMPLIANCE MATRIX	108

1 Objectives of This Document

1.1 ARRIS Commitment

ARRIS is committed to developing high quality, value-added products and services to the Multiple System Operator (MSO). ARRIS continually strives toward meeting our customer's needs with solutions that will help achieve their business objectives.

1.2 Purpose and Scope of This Document

This document describes the value-added features and anomaly resolutions associated with this release. It also informs operators of known Operational Considerations associated with this product release that have been identified either through ARRIS' testing or field operations.

1.3 Product Identification and Purpose of Release

Described in this document is the Touchstone Telephony Firmware. This Touchstone Firmware release is intended for ARRIS manufactured E-MTAs. Information pertaining to support for this specific release is detailed in the table below. **Not all configurations and hardware variants are supported with each release.**

Product Description	Maintenance Supplemental Release 7 – TS6.1.95
Validation Sequence	<ul style="list-style-type: none">• Maintenance Supplemental Release (MSUP)
Supported DOCSIS Standard(s)	<ul style="list-style-type: none">• DOCSIS® 2.0• Euro-DOCSIS® 2.0
Supported Signaling Protocol(s)	<ul style="list-style-type: none">• Network-Based Call Signaling (NCS)• Session Initiation Protocol (SIP)
Supported PacketCable Standards	<ul style="list-style-type: none">• PacketCable® 1.0• Euro-PacketCable® 1.0
Firmware Filename	TS060195_032610
SysDescriptor	SW_REV: 6.1.95
PacketACE	Version 12.10 or later release

1.4 Firmware Filename Variant Information

The table below presents the filename extensions used on Touchstone products. **Not all variants of a load are created for a release.**

FILENAME EXTENSION	PURPOSE OF EXTENSION
_NA.img	North America signed firmware image
_EU.img	European signed firmware image
TELNET_ON	Loads with Telnet access permanently enabled
MODEL_4_5	Supports TM40X models (TM402), TM50X models (TM501, TM502 and TM504), and TP40X models (TP402 and TP404)
MODEL_6	Supports TM60X models (TM601, TM602, TM604, DTM602)
SIP	Session Initiation Protocol (SIP) firmware image
EURO	Supports Euro-PacketCable including Euro-Provisioning Changes
D11PLUS	Features to easily transition from DOCSIS 1.0+ to DOCSIS 1.1
MODEL_5_WR	Supports the WTM552 wireless router module
MODEL_6_WR	Supports the WTM652 wireless router module
MODEL_5_ML	Supports TM508 and TM512 Multi-line E-MTAs
MODEL_6_ML	Supports TM608
WDOCSIS	Supports WM550, WM502, WM602 wireless DOCSIS modules
F741	ONLY looks at a DS frequency of 741 MHz
CM550	Supports CM550 Cable Modems

1.5 Filename Information for MIB Objects

The table below presents the names for the files used to distribute the MIB objects for a Touchstone release. **Not all versions are created for a release.**

FILENAME	DOCSIS Standard	Signaling Protocol	PacketCable Standard
NCS MIBS	DOCSIS	NCS	PacketCable
EURO MIBS & NCS MIBS	DOCSIS	NCS	Euro-PacketCable

SIP MIBS	DOCSIS	SIP	PacketCable
SIP MIBS & EURO MIBS	DOCSIS	SIP	Euro-PacketCable
NCS MIBS	Euro-DOCSIS	NCS	PacketCable
NCS MIBS & EURO MIBS	Euro-DOCSIS	NCS	Euro-PacketCable
SIP MIBS	Euro-DOCSIS	SIP	PacketCable
SIP MIBS & EURO MIBS	Euro-DOCSIS	SIP	Euro-PacketCable

1.6 Minimum Firmware Baseline for Hardware

The table below shows the minimum released firmware needed to operate a specific model of hardware.

Hardware Model	Firmware Image
TM401X	TS040431_041805 (TS4.4.32)
TM402X	TS040122_071504 (TS4.1.22)
TP40X	TS040435_042805 (TS4.4.35)
TM501X	TS040552_121405 (TS4.5.52)
TM502A/B/G	TS040514_071305 (TS4.5.14)
TM502C	TS050060_021307 (TS5.0.60)
TM502H	TS050014_071306 (TS5.0.14)
TM504G	TS050111_030207 (TS5.1.11)
TM504H	TS050117_033007 (TS5.1.17)
TM508A	TS040628_042706 (TS4.6.28)
TM512A	TS040628_042706 (TS4.6.28)
WTM552A/B/G/H	TS050050B_111406 (TS5.0.50B)
WM602 / -2	TS060147_012909 (TS6.1.47)
WM550 / -2	TS050237_111207 (TS5.2.37)
TM602X – Rev 1	TS050222_081607 (TS5.2.22)
TM602G – Rev 2	TS060121_071108 (TS6.1.21)

TM601X	TS060121_071108 (TS6.1.21)
TM604G	TS060121_071108 (TS6.1.21)
TM608G	TS060121_071108 (TS6.1.21)
DTM602G	TS060121_071108 (TS6.1.21)
WTM652	TS060160_052109 (TS6.1.60)
TM602S	TS060188_012810 (TS6.1.88)

1.7 Product Documentation

Other relevant information is included in the following documentation:

Product
<i>Touchstone® Telephony Feature Guide (TS6.1)</i>
<i>Touchstone® Telephony Management Guide (TS6.1)</i>
<i>Touchstone® Telephony Provisioning Guide (TS6.1)</i>
<i>Touchstone® Telephony Troubleshooting Guide (TS6.1)</i>

2 Release Notes

The Release Notes describe the New Product Features introduced in the Touchstone Firmware for the ARRIS Touchstone Telephony Modem(s) and the Touchstone Telephony Port(s). Included in the Resolved Product Deficiencies section is a list of resolved operational considerations noted in previous releases.

2.1 New Product Features

Added in TS6.1.95

Remote RTCPxR MIB Setting Now Persistent

Included in this release of firmware is the ability via SNMP to set the `arrisMtaDevVqmEnableRemote` MIB and the information being stored in NVRAM. This makes the setting of this MIB persistent over resets of the E-MTA.

SIP: Geo Redundancy with SIP Penalty Box

In this release of firmware the SIP Penalty Box feature has been extended to also act on failure of non-REGISTER messages. Any failure of these messages will now also lead to assignment of the SIP proxy to the penalty box. This will cause the MTA to re-register to the secondary SIP proxy instead of starting the initial registration when the primary SIP proxy is down. Also, when the penalty box timer expires and the failed SIP Proxy is released from the penalty box, it will trigger the E-MTA to re-register.

SIP: Forking Enhancements

Enhancements have been added to the SIP Forking feature for this release so that when a call is placed and fork responses are received, the E-MTA will always use the SDP from the last 1xx response received. If the 200 OK message response contains a new SDP, then that SDP will be used. All previous fork responses will be discarded once the 200 OK message is received.

MTA Configuration File TFTP Override

Included in this release of firmware is a feature to change the location in which the MTA will TFTP its configuration file. The new MIB, `arrisCmDevTftpMtaIpOverride`, when added to the CM configuration file will go to a specified location to obtain the MTA configuration file regardless of information in the DHCP offer.

SIP: DNS Caching

This release of firmware will now store and re-use the DNS information if the DNS server is unavailable. This robustness already existed for NCS and is now added for SIP releases.

WRM Configuration File Name based on WRM MAC Address

Included in this release of firmware is the new MIB, `arrisCmDevWrmProvFileNameMacEnable`, which generates the value of the `arrisCmDevWrmProvFileName` based on WRM MAC address. When it is enabled in CM configuration file, this value specifies the name of WRM provisioning file.

ARRIS Advance Webpage Addition of Log Buffer

The Advance webpage now includes a print out of the log buffer command. This is to help facilitate troubleshooting in instances where telnet access is not available.

Added in TS6.1.88

TM602S/CE Support

Included in this release of firmware is support for an additional Touchstone hardware model variant. The TM602S is a model 6 version of the E-MTA which provides an on/off power switch. The hardware version on the webpage and via the CLI will note if the model is a TM602S.

Clear CPE list Feature

In this firmware release the CPE list will be cleared when the E-MTA loses link on all LAN interfaces. E-MTA will only remove dynamically detected CPEs and not eSAFE devices or pre-provisioned CPEs.

Added in TS6.1.77A

No new features were added to this release.

Added in TS6.1.77

IPv6 MDD Override Functionality

This release of firmware includes the ability to override the IP mode contained within the MDD message from the CMTS. This information is stored in NVRAM and is persistent over resets of the E-MTA. The new MIB Object, `MddIpModeOverride`, will control the IP mode used by the E-MTA. Extreme caution should be used when setting this MIB object. If an E-MTA is set to IPv6 mode it will only register in that mode.

Added in TS6.1.72

Unique Configuration Files for RIP

When using the RIP protocol, information containing the unique LAN gateway IP address is required in the CM configuration file. This makes the RIP feature impossible to enable on provisioning systems that cannot support a unique configuration file per modem. This release of firmware supports a feature to allow a unique text file on another

server to be accessed, that will provide the provisioning for the unique RIP MIB objects. This allows operators to use a common CM configuration file but still utilize the RIP feature.

Please see the Touchstone Firmware Features Issue 4.1 for additional information.

Added in TS6.1.67A

Transmit and Receive Gain Control Setting per Line

Included in this release of firmware is the ability via SNMP to set the transmit (TX) and receive (RX) gain per line. This information is stored in NVRAM and is persistent over resets of the E-MTA. The new MIB Objects for this functionality are `arrisMtaDevEndPntGainControlTxVoice` and `arrisMtaDevEndPntGainControlRxVoice`.

MTA Security Ticket Timeout

The E-MTA now has a provisionable capability to re-initialize the MTA security tickets if an MTA provisioning sequence expires and starts over. This is accomplished by setting the feature switch 'resetMtaTicketsOnProvisioningTimerExpiry' in the MIB `arrisCmDevModemFeatureSwitch2`.

UGS Flow Packet Discard

Some customers may choose to play audio calls over the E-MTA's Ethernet link but still use guaranteed UGS service flows to deliver the packet stream over the RF connection. In this case, it is appropriate to keep the UGS Service flow queue short so no delays are introduced in the upstream. This is configured with MIB `arrisCmDevUGSTxQueueSize`.

Allow Detection of Bell Modem Protocol Data Tones

Certain networks may choose to use the older data modem protocols known as Bell modem, for example Bell 103 modulation. In order to detect the unique tone defined for Answering, the MIB `arrisMtaDevDspHandleBellModemTone` must be enabled.

IPV4 Load Variant

This firmware release provides a new load variant to only support IPV4. To identify these loads, an '.IPV4' had been added to the firmware file name as well as to the `sysdescr` field. Some loads are not released in this variant.

Added in TS6.1.60

WTM652 Support

Included in this release of firmware is support for an additional Touchstone hardware model. The WTM652 is a model 6 version of the Wireless E-MTA which will support WPS.

New Wireless Features

This firmware release supports the following features for both the WTM552 and WTM652 (except where explicitly noted):

- **Configurable Power Level:** The MIB object, `arrisWrmDevWlanApPowerLevel`, has been added to this release to support the ability to configure the wireless radio power level.
- **Channel Auto Detect:** The MIB object, `arrisWrmDevWlanApConfigChannel`, along with the CLI and WebGUI allow the user to change the default channel of 11 to 'Auto'. When placed in the 'Auto' mode, the WTM will look for the first wireless channel available for use to reduce possible interference from other devices.
- **LAN/WLAN Bandwidth Limit:** Several new MIB objects have been added to this release to allow the user the ability to configure the amount of bandwidth used by both the WAN and LAN interfaces. The MIB tree to access these specific MIB objects is called `arrisWrmDevWlanQosConfig`.
- **LAN/WLAN Isolation:** In order to prevent CPE to CPE traffic between WTM users, the MIB tree `arrisWrmWlanApIsolation` has been added in this release. Several MIB objects under this tree can be used by the operator to control traffic from CPE devices attached to the WTM.
- **WiFi Protected Setup (WPS):** The feature is only available on the WTM652 product. WPS is enabled via a pushbutton, PIN, or manual configuration.
- **Multiple Service Set Identifier (SSID) Support:** This release of firmware will now support two SSIDs from WTM.

CallerID Suppression

This release supports the ability to disable parts of the callerID display. Three new MIB objects have been added to support this new functionality. The MIB objects are detailed below:

- `arrisMtaDevEndPntCIDEnable`: Determines whether the callerID will be presented to the phone.
- `arrisMtaDevEndPntCIDNameEnable`: Determines if the individual name will be made available in the callerID information sent to phone.
- `arrisMtaDevEndPntCIDDateTimeEnable`: Determine if the date/time fields will be made available in the callerID information sent to phone.

Loop Reversal Control

This release supports the ability to help manage loop reversal interactions for NCS Call Servers. This feature will revert phones back from loop reversal at the end of a call for

call servers that do not support that signaling. The MIB object, `arrisMtaDevEndPntLoopReversal` sets up this management.

Call Waiting Repeat Indefinitely

This firmware release supports the ability to have the call waiting tone continuously played while the phone is off-hook. This feature can be enabled by using the MIB object `arrisMtaDevEndPntCallWaitingRepeatSteady`.

SIP: Restrict Incoming CODEC Offer

This firmware release supports a feature which allows the operator to restrict the acceptance of CODECs in the incoming INVITE to the list provisioned in `sipCfgProvisionedCodecArray` MIB. This feature is enabled by the feature switch, `0x00000001 restrictIncomingOffer`, which is set in the `sipCfgSipFeatureSwitch`.

Added in TS6.1.57

SIP: BYE Delay for Called Party

This firmware release supports a new SIP feature that allows the MSO to set a bye delay time. This time is the amount of time a call will be maintained after the called party hangs up before the call is disconnected if the originator remains off-hook. If called party goes off-hook during this time interval, the timer will be cancelled and the call will remain connected. The MIB object to set the bye delay time is `sipCfgPortCallByeDelay`.

SIP: Disconnect Reorder Tone Delay

The ability to specify the time period for the E-MTA to delay the playing of the reorder tone is available in this release. This is the amount of time to wait after the BYE message has been received to tear down the call. The following MIB object is used to set that value: `sipCfgDisconnectReorderToneDelay`.

SIP: Support of INFO Method

In order for session information to be exchanged between the SIP Proxy Server and E-MTA, RFC2976 needs to be supported. This release of firmware supports that option which is the ability of the E-MTA to receive the INFO message and respond to that message.

Dual Mode Enhancement

In this release of firmware, the dual mode feature will now support a frequency change request and move to another annex. The feature is specifically triggered off of frequency change request from the RNG-RSP message, TLVs in the CM configuration file, and CLI command for tuning. This feature is only supported on the TM601/DM and TM602B/DM hardware.

Enhancement to ifPhysAddr.16

Per the e-DOCSIS specification, when running in a provisioning mode other than full PacketCable this MIB object should return a value of zero. In this release to support provisioning systems deployed in the field, this behavior has been changed so the MIB object will now report the MTA MAC Address.

Slovenia Country Template

A new line card template for Slovenia is supported in this release. This template defines unique tones, tone levels, hookflash times, and ring cadences for this region. This template can be set using the ppCfgMtaCountryTemplate MIB.

Added in TS6.1.51D

No new features added in this release.

Added in TS6.1.51

SIP: SIP INFO Support for Hook Flash Reporting

This firmware release provides new SIP INFO support for hook flash reporting. To enable this feature, the sipCfgSipFeatureSwitch bit 0x00000020 must be added to the configuration file. When this bit is enabled the hook flash events are reported via a SIP INFO message with the following characteristics:

Content-Type: application/hook-flash

signal=hf

RFC 2833 DTMF End Event Duration

The MIB object, arrisMtaDevDTMFEndEventForceAscending, has been added to this release to provide flexibility with the RFC 2833 DTMF events to help with CPE compatibility. This MIB allows the customer to enable/disable a feature to make the RFC 2833 DTMF end event duration to be at least as big as the last 'interim' event duration.

Persistent Line Status Feature

A new MIB Object, arrisMtaDevPersistentLineStatus, has been added to the release to support a persistent line status feature. This feature allows a customer to set a line permanently down (forceDisable(1)) and for that setting to remain over resets. This MIB can only be set after registration and by the use of SNMP. To restore a line to service, the MIB must be set to ignore (Ignore(0)) or the unit reset to factory default.

Added in TS6.1.47

Additional IPv6 CLI Commands

Three new CLI commands have been added to support the display of the ARP table and route when using IPv6. The commands are listed below:

- route6Show: Prints out the IPv6 default route, interface, flags, and how long until it expires.
- pfxList: Prints out prefix information including the prefix, interface, flags, reference count, lifetimes and when it will expire.
- rtdebug: Includes the state of the route, detailed interface data, and link local data.

SIP Feature: Insert Additional Character into Dial String

This feature introduces a new MIB Object, sipCfgDialProxyMethodDelimiter, to provide a provisionable value which can be inserted into the SIP dial string.

Added in TS6.1.38C

No new features were added.

Added in TS6.1.38B

No new features were added.

Added in TS6.1.38

SIP Stutter Dial Tone on Hook Flash

A sipCfgSipFeatureSwitch, 0x00000040, has been added to play stutter dial tone when a hook flash occurs for a second call.

WTM552 WPA Enterprise Support

WTM552 WPA Enterprise encryption is supported in this release.

Added in TS6.1.34A

No new features were added.

Added in TS6.1.34

MaxCPE Bypass Update

The MaxCPE Bypass MIB has been updated so that new models of E-MTAs are automatically taken into consideration when they use additional space in the CPE table. For example, the WTM552 will automatically take into consideration the extra CPE row needed for the WRM module.

SIP Penalty Box Timer

A new SNMP MIB Object, sipCfgPenaltyBoxTimeout, has been added to this release to enable timers to expire entries in the SIP Penalty Box. If this timeout value is set to zero, the current functionality will still exist of entries being blacklisted until all SRV records have experienced similar failures.

Argentina Country Template

A new line card template for Argentina is supported in this release. This template defines unique tones, tone levels, hookflash times, and ring cadences for this region. This template can be set using the ppCfgmtaCountryTemplate MIB.

CMIM Support

CMIM is a new field in the US classifier structure that can be used to classify traffic based on the CM interface. When this field is present in the US classifier, a packet is said to match the classifier only if the traditional fields match and the source interface of the packet is present in the CMIM of the classifier. For the DOCSIS 2.0+IPv6 release, the CMIM will have a maximum length of 32 bits or 4 -bytes.

Dialing Method Persistence MIB

The Dialing Method Persistence MIB, arrisMtaDevEndPntDialingMethod, has been modified to allow SNMP initiated changes to persist over reboots and restarts of the E-MTA.

Daylight Savings Time (DST) Feature

The Daylight Savings Time feature allows the user to configure a rule to define when DST time changes are applied. This policy defines the start/end dates/times of the DST for the given region. To enable this feature the MIB, arrisCmDevDSTPolicy, should be used.

WTM552 Enhancements

Several new enhancements have been added to the WTM552 to support new MIBs, disabling of the reset button, and provisioning file error detection. A brief explanation on these additions is provided below:

- **WTM552 MIBS:** This firmware release adds the capability to configure the WRM operational parameters using SNMP. This new MIB, ARRIS-WRM-DEVICE-MIB, supports this functionality.
- **WRM Provisioning File Error Detection:** This release adds support to help debug and report provisioning file errors. A new webpage, provf.html, has been added to illustrate important provisioning file characteristics as well as any detected parse error messages. SNMP and CLI commands have also been added to view this information.
- **Disable Factory Default Reset Button:** A new feature switch has been added to the MIB, arrisCmDevModemFeatureSwieth2, to allow the operator to disable the

WRM card factory reset. This reset occurs when the WRM reset button is pressed for more than 8 seconds. When bit 5 is enabled, the WRM reset button will not cause the WRM to reset to factory defaults.

Load Variant to Only Look at Downstream Frequency 741 MHz

A new load variant has been created with an extension of 'F741'. This load when applied to an E-MTA will only look at a downstream frequency of 741 MHz. This load should only be used in a network where the CMTS downstream is set to that frequency.

Added in TS6.1.21

New Hardware Support

Included in this release of firmware is support for addition Touchstone hardware models. Below is a list of new models supported.

- TM602G rev2
- TM601
- TM604
- TM608
- DTM602 – The DTM602 hardware combines the functionality of the TM602 hardware with the Vtech IP8301 Digital Enhanced Cordless Telecommunications (DECT) phone set.

IPv6 Support for the Cable Modem

This release supports the usage of IPv6 addressing for the Cable Modem over a DOCSIS 2.0 interface. This capability allows MSOs the opportunity to reclaim some of the IPv6 addresses currently used in deployment. All supporting servers and applications pertaining to the CM operation must support IPv6. The DOCSIS 3.0 MAC Domain Descriptor (MDD) message is used to determine where IPv6 should be used for the CM device. In the absence of an MDD message, the CM will only use IPv4 addressing.

Several additional MIBs have been updated so access to the address and address type can be obtained. The additional MIBs are to support this for the DHCP Server, TOD Server, TFTP Server, and SYSLOG Server. Additional changes have been made to support IPv6 in the CLI trace information and web page displays.

IPv6 addressing is not supported for SingleMAC provisioning, the MTA IP Address, or CPE devices. Unique CM configuration files will be required for devices operating in each mode. Additional details regarding this new feature can be found in the user documentation.

Updated Management Information Base (MIB) Trees

Support has been added for several new RFC defined MIB trees. The below list provides information on the RFC MIB trees now supported.

RFC 4639 – Cable Device MIB for DOCSIS Compliant CM and CMTS

RFC 3419 – Textual Conventions for Transport Addresses which contains enhancements for the SNMP Target Address Table

RFC 3584 – Coexistence between V1, V2, and V3 of the internet-standard Network Management Framework

RFC 3413 – Simple Network Management Protocol Applications

RFC 4293, Management Information Base for the Internet Protocol, is not supported for this release but the MIBs have been added. If read a 0 or empty string will be returned.

Reset to Factory Defaults

A new feature is supported in this release to set the E-MTA back to factory defaults and clear settings stored in NVRAM. Under the NVM menu in the CLI, the '!defaults' command will restore the E-MTA to factory defaults. The SNMP MIB Object, `arrisMtaDevRestoreNvmFactoryDefault`, will also restore factory defaults.

SuperG3 Fax Support

In this release, SuperG3 fax support for V.8 CM signaling is supported for the following hardware models: TM601, TM602, TM604, TM608, DTM602, TM508, and TM512. A new MIB, `arrisMtaDevSuperG3FaxRelay`, has been included in this release to allow the user to decide how to setup the fax transmission. The default operation will setup the connection over the G.711 CODEC instead of using T.38. In T.38 mode, SuperG3 is supported at T.38v0 which is a 14.4 bps connection.

Automatic DOCSIS Configuration Support

The TM601B/DM and TM602B/DM hardware platforms in this release can support either a North America or European CMTS plant. The E-MTA during the registration process will search Annex A and Annex B frequency bands. Once a frequency is identified, the information is stored to the Dual Mode Discovered Market (DMDM) that is stored in NVRAM. The SNMP MIB, `arrisCmDevDualModeDiscoveredMarket`, will display the currently stored DMDM. In this configuration, the European CVC needs to be used in the configuration file.

SIP Session Expire Control

This release introduces support of a new SNMP MIB, `sipCfgSessionExpires`, that allows a user to specify the preferred session expiry timeout that is sent in the SIP Invite message. Setting this MIB to 0 seconds will allow the proxy to control the session expiration timer settings.

Time Offset Adjustment

Time of Day (TOD) changes within a network cause operator issues with features such as CLIP information in SIP. The changes are handled through the DHCP timing offset but these changes only take affect when the devices goes through a renew. This release implements an SNMP MIB, `arrisCmDevTODTimeOffset`, which allows an operator to

adjust the TOD using the CM IP Address. The DHCP timing offset received at renewal will take precedence over this setting.

SIP Registration Timer

The sipCfgRegExpires MIB object was created to allow customers to customize the registration expiry value through the MTA configuration file. If this MIB is set to a non-zero value, the MTA will suggest a registration expiry value in the REGISTER request's contact header.

Last Call Voice Quality Metrics (VQM)

A new read-only MIB has been added to the existing MIB in the arrisMtaDevVqm MIB tree to allow easier access to the VQM information for the last call. The new SNMP MIB, arrisMtaDevVqmCallNumberIdentifierLastCall, will point the existing arrisMtaDevVqmCallNumberIdentifier MIB to the appropriate last call information. The user can now simply read the arrisMtaDevVqmMetricTable to obtain the VQM data.

Fax Only Line

This release supports a fax only line for NCS that has previously been supported for SIP releases only. This new SNMP MIB, arrisMtaDevEndPntFaxOnlyLineTimeout, can be used for either SIP or NCS to set a line for fax transmission only. The line will wait the amount of time specified in this MIB to detect a fax tone before disconnecting the call. The previously supported SNMP MIB for the configuration of a SIP line in fax only mode is still supported.

CallerID Enhancements

An additional SNMP MIB as well as another option for an existing SNMP MIB was added to this release to improve CallerID interoperability. An additional option for the arrisMtaDevDefaultReasonNoCIDName MIB was added to send the MDMF format but exclude any name parameters. A new SNMP MIB, arrisMtaDevOffHookFskDelay, was added to control the amount of time the MTA delays transmitting the FSK after receiving the ACK from the CPE.

Trivial File Transfer Protocol (TFTP) Block Size Configuration

This feature supports the ability to increase the block transfer size which directly decreases the transfer time of the configuration file. The block size can be modified using the SNMP MIB arrisCmDevTftpBlkSize.

PacketCable 1.5 Battery Backup MIBs

The PacketCable 1.5 Battery Backup MIBs are supported with this release on the TM502, TM504, and TM60X products. The following MIB support has been included:

- upsShutdownType – type of UPS shutdown to perform
- upsShutdownAfterDelay – turn off UPS after X amount of time

- upsStartupAfterDelay – start of the output after X amount of time
- upsRebootWithDuration – immediate shutdown of UPS

RIPv2 Support on non-WTM552 E-MTAs

Currently, the E-MTA operates in bridge mode to the CPE devices. Enabling RIPv2 via the CM configuration file (non-WTM552 devices) will allow the CM to be setup in routing mode. A RIP webpage is now available to view the settings for this feature. Information on the RFC MIBs available to support this configuration can be found in the user documentation.

RIPv2 Support on WTM552

Support for RIPv2 on the WTM552 can be configured using the WRM configuration file, HTTP, CLI, or SNMP. Setting for RIP can be viewed under the RIP Status heading on the Wireless Router Web Page. The proprietary MIBs used to configure RIP on the WTM552 can be reviewed in the user documentation.

PacketCable 1.5 Voice Quality Metrics

The PacketCable 1.5 Voice Quality Metric Support with a call agent is supported for NCS in this release of firmware. SNMP MIBs have been added to disable this feature as well as control thresholds for value to report on. Turning on this capability greatly increases the size of the report provided to the call agent.

WTM552 Router Web Page Access

In this release of firmware, the WTM552 router web page can be accessed from the 192.168.100.1 IP address. This one location can now be used to seamlessly move through all the web pages needed to support the WTM552.

MAC Address Aging

A new feature bit (0x20000000) in the arrisCmDevModemFeatureSwitch2 controls the ability to allow an MTA to recycle learned table entries in the CPE MAC address table. This is in violation to the DOCSIS specification but necessary in some applications where multiple users are continuously using an E-MTA device. This feature will cause older entries in the CPE MAC address table to be deleted when space is needed for a new user.

SIP 486 Ringback

A new SIP feature switch is added to play a local busy tone upon receipt of a 486 message. To activate this feature, set the sipCfgSipFeatureSwitch to 0x00000400.

Highest Temperature Recorded MIBs

This release supports the ability to display the highest temperature ever recorded along with the date and time in which that occurred. These new SNMP MIBs are supported for the TM502, TM504, WTM552, TM602 and TM604 E-MTAs.

PacketCable 1.5 Provisioning Methods

ARRIS currently supports all five provisioning flows defined in the PacketCable 1.5 specification. These flows are Basic.1, Basic.2, Hybrid.1, Hybrid.2 and secure. These provisioning methods are determined via the DHCP options and the SNMP MIB `arrisMtaDevPacketcableProvisioningFlow` will display the current provisioning method. The existing ARRIS provisioning methods with still work but will not be displayed in the above MIB.

2.2 Resolved Field Bulletin

The following Field Bulletin issues were resolved in this Touchstone Firmware release or previous Firmware release.

Field Bulletin Number	Field Bulletin Title	Product Defect Number
AFB-09-0311	ARRIS Modem May Lose Layer 3 Connectivity in the Event the CM REG-ACK is Not Received.	PROD00146799
AFB-09-0310	ARRIS Model 6 E-MTAs Running TS6.1 Firmware Will Not Forward Multicast Streams to CPE	PROD00147529
AFB-09-0309	ARRIS Model 6 E-MTAs May Not Complete A Successful Firmware Download from Release TS6.1 to Release TS6.1	PROD00147108, PROD00145391
AFB-09-0307	ARRIS Modem May Not Complete Ranging after a DCC Followed by a Ranging Abort Initiated from the CMTS	PROD00146241
AFB-09-0306	IPv6 DHCP Failure Results in Loss of Service	PROD00143180
AFB-09-0305	ARRIS E-MTA may not Complete its Ranging Adjustment During a DCC Operations	PROD00144302
AFB-09-0304	ARRIS E-MTA Resets Approximately Every 10 Days	PROD00139683
AFB-09-0303	WTM552 may get Stuck in a Reboot Loop if the Upgrade Process is Interrupted	PROD00139786
AFB-09-0302	MTA May Lose Layer3 Connectivity After a DHCP Renew-No Response	PROD00134378
AFB-09-0301/ AFB-09-0301R	ARRIS EMTAs may Lose Layer 3 Connectivity after Dynamic Channel Change Request (DCC-REQ) on the CMTS	PROD00138654
AFB-08-0315	E-MTAs Operating Using G.729 CODEC May Experience Static	PROD00129912
AFB-08-0314	DOCSIS 2.0 Auto Detection Feature on E-MTA may not Activate DOCSIS 2.0 Mode	PROD00131033
AFB-08-0313	MTA may Reset due to Broadcast Negative Acknowledgement (NAK) Destined for Other Devices	PROD00128484

2.3 Resolved Product Deficiencies

ARRIS continues to resolve any product deficiencies discovered. This Touchstone Firmware release contains closure for the detailed issues listed in the following section.

Considerations that apply to a specific feature implementation will be designated with one of the following prefixes included in the heading:

- X-JC: Japan NCS Package
- EU: Euro-PacketCable Provisioning Sequence
- SIP: SIP Signaling Protocol
- NCS: NCS Signaling Protocol
- T.38: T.38 Feature Specific Issue
- SSH: Secure Shell
- IPv6: Internet Protocol version 6

The following issues were resolved in release 6.1.95

2.3.1 RIP CLI Commands are not Accessible via PWOD	
<i>Tracking No.</i>	PROD00148405
<i>Description</i>	The RIP CLI commands are not accessible via the CLI for non-WRM models for troubleshooting. This is design intent and user documentation has been updated to reflect this operation.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.2 WTM552 Frequent IP Releases	
<i>Tracking No.</i>	PROD00148849
<i>Description</i>	The WTM552 was found to lose its WRM IP address resulting in the PC connected to the WTM552 not being to access the WAN side and packet loss is experienced.
<i>Impact</i>	Service

<i>Occurrence</i>	Low
2.3.3 Web GUI Displays Incorrect Status for Computers Detected	
<i>Tracking No.</i>	PROD00149168, PROD00141979
<i>Description</i>	E-MTAs Web interface displays incorrect status for Computers Detected. Computers detected may display '0' even through the LAN interface is UP and Ethernet access is available.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.4 TM402: FIFO Event Causes TEK Invalid and DSP Reset	
<i>Tracking No.</i>	PROD00152040
<i>Description</i>	An issue was identified with a specific CMTS vendor that resulted in the TM402 observing a FIFO event. This event previously resulted in a TEK invalid message on the CMTS and a DSP reset on the E-MTA. This release will store the TEK key and does not reset the DSP in this scenario.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.5 pktcDevEvProgrammableReporting MIB with Value 0xC0 Working Incorrectly	
<i>Tracking No.</i>	PROD00151278
<i>Description</i>	When the MIB pktcDevEvProgrammableReporting is set to 0xC0 (Local event log and Trap server) both syslog and trap events are received. .
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.6 Webpage Battery Serial Number	
<i>Tracking No.</i>	PROD00141856
<i>Description</i>	When the power save shutdown is in effect (10 minutes after AC removed), the webpage will now show the Battery Serial number instead of stating it is unavailable.

<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.7 Discrepancy with Battery Ordering Codes	
<i>Tracking No.</i>	PROD00146604
<i>Description</i>	Battery Ordering Code is being incorrectly read and displayed. This is due to a communication problem between the processor and the EPROM.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
2.3.8 Australia Line Card Country Template Change	
<i>Tracking No.</i>	PROD00145225
<i>Description</i>	For the line card country template Australia, a solid tone was being played instead of stutter dial tone.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.9 Lockup during Bulk Call Testing	
<i>Tracking No.</i>	PROD00152073, PROD00151312
<i>Description</i>	With an active telnet session present, turning on multiple traces during extremely high call volume such as bulk call testing could cause the EMTA to lock up. Traces of this nature should not be enabled in the field unless directed to do so by ARRIS technical support. These traces can cause issues if enabled during bulk call testing in a lab environment. To help avoid this issue, additional robustness has been added in this area to keep the telnet session alive.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.10 SIP: Restriction of Incoming Offer was Incorrectly Accepting G.711 CODEC when not in the CODEC Array	
<i>Tracking No.</i>	PROD00152548
<i>Description</i>	The sip feature switch contains a setting that allows the user to restrict the acceptance of certain CODECs. Regardless of the

	settings in the MIB, the G.711 CODEC was being accepted.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.11 Battery Depleted Alarm Missing	
<i>Tracking No.</i>	PROD00151717
<i>Description</i>	When AC power is removed and the battery level goes from Low to Depleted, no trap or syslog message is sent.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.12 Source MAC Address Incorrect if TOD Server is Offline	
<i>Tracking No.</i>	PROD00150554
<i>Description</i>	If the TOD Server is Offline when the modem registers, the source MAC address in the response is not correct.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.13 MuSecurity HTTP and Telnet Robustness	
<i>Tracking No.</i>	PROD00150826, PROD00143184, PROD00143321
<i>Description</i>	During recent security test runs using the Mu Security test application, several potential vulnerabilities were identified in the D2.0 HTTP and Telnet firmware. This update adds robustness to provide stricter validation of the incoming HTTP and Telnet requests.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.14 Incorrect Ring Frequency for Israeli Template	
<i>Tracking No.</i>	PROD00150582
<i>Description</i>	The ring signal frequency of 20 Hz was causing some CPEs not to detect the ring signal and not to answer the incoming call. The ringing signal frequency has been updated to 25 Hz.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.15 SysObjectID Incremented for Firmware Release

<i>Tracking No.</i>	PROD00151925
<i>Description</i>	The MIB Object, sysObjectID, previously incremented for each firmware release.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.16 Reset Reason of Other

<i>Tracking No.</i>	PROD00152102
<i>Description</i>	In the firmware, a few error paths were noted where OTHER was used as a valid Reset Reason. These have been changed to a more descriptive reset reason to decrease the usage of 'Other'.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.17 Battering Ordering Codes Updated

<i>Tracking No.</i>	PROD00151653
<i>Description</i>	The ordering codes for the two battery packs BPB088S and BPB026S were added in this release to be displayed on the web page. Previously these batteries were listed as a type of 'Contact ARRIS'.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.18 WTM552/WTM652: Downloads Hang at 99% When Downloading Files Greater than 75MB

<i>Tracking No.</i>	PROD00149447
<i>Description</i>	When a user attempts to download files greater than 75 MB in size, the download hangs at 99% and never completes.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.19 E-MTA does not Support Payload Type 96

<i>Tracking No.</i>	PROD00151504
---------------------	--------------

<i>Description</i>	When a CRCX with payload 96 is sent from the CMS to the MTA, the MTA returns with payload 101 in the SDP. The payload should return what was sent in the CRCX.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.20 E-MTA does not accept the maximum value allotted (4294957295) for SF max-tr-burst	
<i>Tracking No.</i>	PROD00127450
<i>Description</i>	The maximum value for Service Flow SF max-tr-burst is 4294967295. The E-MTA only accepts up to half that value. This issue currently has no fix planned.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.88

2.3.21 Incorrect Response to dot1dTpFdbAddress MIB Walk	
<i>Tracking No.</i>	PROD00146317
<i>Description</i>	MIB walk of dot1dTpFdbAddress returns USB IP and MAC addresses even if the CPE is disconnected from the USB port.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.22 Incorrect Response on UDP Port 67	
<i>Tracking No.</i>	PROD00150795
<i>Description</i>	E-MTA does not reply with “Port Unreachable” on closed UDP Port 67.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.23 RTCP-XR Local Metrics Reporting Incorrectly

<i>Tracking No.</i>	PROD00144624
<i>Description</i>	When extended local metrics is enabled, the E-MTA will respond with all '0's in the 250 ACK for all extended local metrics.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.24 TM402 High Data Traffic Causes Failures if Dynamic Interleave is Enabled

<i>Tracking No.</i>	PROD00149432, PROD00149197
<i>Description</i>	A timing issue has been discovered on the TM402 when interleaving is enabled on the CMTS. The E-MTA may reset or not provide dial tone. This issue has been observed in cases of large burst of data traffic which results in a processor delay handling upstream messages.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.25 Extraneous Log in TS 6.1.77 Release

<i>Tracking No.</i>	PROD00148956
<i>Description</i>	A debug message was left in the TS 6.1 stream that would appear in the log after a power cycle, reset button pressed, !reset, or docsDevResetNow. 12:59:26 RT 53 tMVX_D ***** in hwu_McBspl_reset()*
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.26 E-MTA Fails to Upgrade From Server in the DHCP Offer

<i>Tracking No.</i>	PROD00149125
<i>Description</i>	When docsDevSwServer mib is not set in the CM config file and there has been a corruption in the application portion of the firmware image in flash, the firmware upgrade using the siaddr from the DHCP Offer would fail with E-MTA reporting TFTP Timeout.

<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.27 Incorrect Response to arrisMtaDevPersistentLineStatus MIB Set	
<i>Tracking No.</i>	PROD00149478
<i>Description</i>	If an E-MTA line has not yet registered and arrisMtaDevPersistentLineStatus for that line is set, it returns success but the operation actually fails. This MIB can only be set after successful registration.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.28 Reject Call Message due to Blank SDP Session Parameter	
<i>Tracking No.</i>	PROD00149362
<i>Description</i>	E-MTA is returning a '510 Parsing Error' with calls where the SDP contains a blank session name parameter, "s=".
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.29 E-MTAs Fail to Recover After Loop Diagnostics	
<i>Tracking No.</i>	PROD00142337
<i>Description</i>	Some E-MTAs are stuck in an "Out of Service" state after running loop diagnostics due to test results falling outside self-test limits.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.30 Incorrect Name for arrisCmDevDhcpOfferedLeaseTime MIB	
<i>Tracking No.</i>	PROD00148803
<i>Description</i>	The MIB arrisCmDevDhcpOfferedLeaseTime appeared in the MIB files incorrectly as arrisMtaDevDhcpOfferedLeaseTime.
<i>Impact</i>	Operational

<i>Occurrence</i>	High
2.3.31 E-MTA Reset when Completing Fax Call	
<i>Tracking No.</i>	PROD00149159
<i>Description</i>	E-MTA could reset when completing a fax call if call agent deletes connection before fax call is completed.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.32 E-MTA is Not Correctly Setting IP ToS/DiffServ Bits in RTP Packets for MTA-originated Calls	
<i>Tracking No.</i>	PROD00150636
<i>Description</i>	When outgoing calls made by the E-MTA, with certain Call Agents, the RTP packets were found not to contain the correct TOS value as set in the configuration file or connection requested from the Call Agent.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
2.3.33 Caller ID Not Signaled According to Brazilian Standard	
<i>Tracking No.</i>	PROD00149723
<i>Description</i>	The Brazilian callerid signaling, which uses DTMF mode, should be sent before the first ring but it is being sent between the first and the second ring.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.34 DST Policy MIB Object Does Not Work for Year 2010	
<i>Tracking No.</i>	PROD00150934
<i>Description</i>	The arrisCmDevDSTPolicy MIB does not work for the year 2010. This is due to a time function not returning the correct value when year turns to 2010. This issue will be documented and released in a Field Bulletin.
<i>Impact</i>	Service

<i>Occurrence</i>	High
2.3.35 E-MTA Resets Due to EXCEPTION During Call Waiting Scenario	
<i>Tracking No.</i>	PROD00150445
<i>Description</i>	In a Call Waiting scenario, the E-MTA intermittently resets when the call waiting call is answered. The E-MTA will issue an exception and reboots. This only happens when remote VoIP metrics are enabled.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.36 DCC to Change Upstream Bandwidth Causes E-MTA to Re-range	
<i>Tracking No.</i>	PROD00143244
<i>Description</i>	When Pre-Equalization is enabled and there is a change in upstream bandwidth, a DCC with init-tech 2/3/4 may cause the E-MTA to go off-line and completely re-range before coming back online.
<i>Impact</i>	Service
<i>Occurrence</i>	Low

The following issues were resolved in release 6.1.77A

2.3.37 EURO: DiffServ-DSCP-TC MIB Objects Are Not Available	
<i>Tracking No.</i>	PROD00147422
<i>Description</i>	The DiffServ-DSCP-TC MIB objects are not available in TS 6.1.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.38 WRM Webpage Cannot be accessed from LAN IP Address	
<i>Tracking No.</i>	PROD00147213

<i>Description</i>	On the WTM552 and WTM652, the WRM webpage cannot be access from the LAN IP address.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.77

2.3.39 IPv6: Renew / Rebind MIB Values Incorrect	
<i>Tracking No.</i>	PROD00143605
<i>Description</i>	The value of the TimeUntilRenew and DhcpState MIB Objects do not display correct information for IPv6 mode E-MTAs.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.40 E-MTA Sends 200OK to CRCX with ptime:30	
<i>Tracking No.</i>	PROD00144800
<i>Description</i>	When the E-MTA receives a request for a ptime:30 request, the E-MTA will accept this request but provide one-way speech path. For NCS, this release will be able to accept the ptime:30 message and handle the conversation without causing a one-way speech path. For SIP deployments, the call setup will be accepted and the E-MTA outgoing packet rate will be 20ms..
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.41 IPv6: E-MTA Not Sending Option Code 17 in ORO	
<i>Tracking No.</i>	PROD00148061
<i>Description</i>	When running in IPv6 mode, the E-MTA was not including option 17 in theDHCPv6 Option Request Option (ORO) list.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.42 Extreme Robustness Testing Issues Resolved	
<i>Tracking No.</i>	See Below

<i>Description</i>	<ul style="list-style-type: none"> • PROD00130874: Final provisioning status failed after power cut • PROD00146386: SIP E-MTAs may experience a small memory leak if a cable cut occurs while a call is active. Over 100 instances of this must occur before the user will experience an issue.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.43 WTM: Additional MIBs Needed to Support WRM RIP Unique Configuration File	
<i>Tracking No.</i>	PROD00147677
<i>Description</i>	<p>Additional MIBs are needed to utilize the WRM RIP Unique configuration file feature. The following MIBs are now available:</p> <ul style="list-style-type: none"> • rip2IfConfSend • arrisWrmDevNATEnable
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.44 SDP Payload may cause Bandwidth Error	
<i>Tracking No.</i>	PROD00147587
<i>Description</i>	A call from an IMS subscriber to an ARRIS NCS subscriber may result in a 510 Protocol Error on the ARRIS E-MTA. The root cause is in the SDP payload when the bandwidth information "b=AS:X" and "b=TIAS:Y" are both present.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.45 RF Issue During Registration Results in Loss of Layer 3 Connectivity	
<i>Tracking No.</i>	PROD00146799
<i>Description</i>	<p>If interference occurs during registration and the REG-ACK is dropped, the E-MTA will register successfully but layer 3 connectivity will be lost.</p> <p>This issue is documented in AFB-09-0311.</p>

<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.46 TM6XX: Multicast Traffic Does Not Work	
<i>Tracking No.</i>	PROD00147529
<i>Description</i>	When running release TS6.1 on a TM6XX model, multicast traffic is not recognized by the E-MTA and discarded. This issue is documented in AFB-09-0310
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.47 Loop Voltage May Drop After E-MTA Reset	
<i>Tracking No.</i>	PROD00130884
<i>Description</i>	Due to some register initializations, loop voltage may be dropped on the following E-MTAs regardless of the Loop Voltage Management setting during an E-MTA reset. This will result in loop voltage being unavailable for 4 to 5 seconds. TM401, TM402, TM501, TM502, TM504, WTM552, TM608
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.48 PacketACE 12.6: CMTS MIC Issue	
<i>Tracking No.</i>	PROD00144847
<i>Description</i>	PacketACE 12.6 cannot generate the CMTS MIC correctly for CM configuration files. In some cases, the file is saved with incorrect CMTS MIC value.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.49 IPV6: Upgrade Fails If Upgrade Server Set to 0.0.0.0 in Configuration File	
<i>Tracking No.</i>	PROD00144853
<i>Description</i>	When running in IPV4 mode, the upgrade file server can be set to 0.0.0.0 in the CM configuration file and the E-MTA will look

	<p>for the upgrade file name on the server from which the CM Configuration file was obtained. This functionality does not work when operating in IPv6 mode.</p> <p>This was a test case failure due to the IP address not being in IPv6 format.</p>
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.50 Upgrade MIB Stuck in “In Progress” after a Power Failure during an Upgrade	
<i>Tracking No.</i>	PROD00144309
<i>Description</i>	<p>When E-MTA is power cycled while downloading a new load via SNMP, the DocsDevSwOperStatus MIB can get stuck in the “In Progress” State.</p> <p>This issue could not be reproduced.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	Medium
2.3.51 MIB docsDevNmAccessIpMask = 0.0.0.0 Does Not Enable Traps	
<i>Tracking No.</i>	PROD00142446, PROD00142553
<i>Description</i>	<p>Traps do not properly enable if the MIB docsDevNmAccessIpMask is set to 0.0.0.0.</p> <p>This was not an issue but a problem with the test scenario.</p>
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.52 Voice Line Total Failure with DSP Reset	
<i>Tracking No.</i>	PROD00137824, PROD00144458, PROD00143374
<i>Description</i>	<p>During bulk traffic testing, a problem was observed where the DSP autonomously reset. The MTA event log showed a Voice Line Total Failure. The E-MTA automatically recovers from this issue and data service is not affected.</p> <p>This issue could not be reproduced.</p>

<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.53 Extreme Robustness Testing Issues	
<i>Tracking No.</i>	PROD00131669
<i>Description</i>	<ul style="list-style-type: none"> • PROD00131669: Exception during a power cut • PROD00136844: Watchdog Timer Reset <p>The following issues cannot be reproduced.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.54 Incorrect T.38 DS QOS Bandwidth Calculation	
<i>Tracking No.</i>	PROD00107684
<i>Description</i>	<p>When calculating the DS bandwidth required for a T.38 call, the MTA should use only the t38MaxDatagram and not include the provisioned redundancy level for the US. This can cause fax failures to occur between NCS and SIP devices.</p> <p>This was not an issue but a problem with the test scenario.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	Low

The following issues were resolved in release 6.1.72

2.3.55 CM DHCP Lease Time on WebGUI Displays 0 days	
<i>Tracking No.</i>	PROD00143022
<i>Description</i>	On the WebGUI, the CM DHCP lease time value is displayed as 0.0 days regardless of the lease time value. The value shown in seconds is correct.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.56 Codeword Error Rate Calculation Incorrect

<i>Tracking No.</i>	PROD00140668
<i>Description</i>	In prior releases, the codeword (CW) error rate was incorrectly counting the corrected and uncorrected errors. This made the CW Error appear to be incorrect. The CW errors now only take into account the uncorrected errors.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.57 One-way Audio Path when Using Unsupported 30 ms Packetization Rate

<i>Tracking No.</i>	PROD00144800
<i>Description</i>	The E-MTA should reject a request to negotiate an unsupported packetization rate of 30ms to fall back to a lower packetization rate of 20ms or 10ms. Instead, the E-MTA accepts the request resulting in a one-way audio from the E-MTA to the far-end device.
<i>Impact</i>	Service
<i>Occurrence</i>	Low

2.3.58 Interoperability Issue With Load Balancing on CISCO CMTS

<i>Tracking No.</i>	PROD00146241
<i>Description</i>	<p>An issue has been observed where the load balancing feature on CISCO CMTS loads can cause the E-MTA to become stuck looking for a valid US. When this occurs, the CMTS places the E-MTA in an offline status. The only way to recover the E-MTA is with a power cycle.</p> <p>This issue is documented in AFB-09-0307.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	Low

2.3.59 RF Cut During Registration May Result in No Dial Tone

<i>Tracking No.</i>	PROD00146421
---------------------	--------------

<i>Description</i>	When multiple RF cuts occur during registration, the MTA may become stuck in a Tele-TFTP provisioning state. In this scenario, the MTA MAC address is no longer present in the CPE table. To get into this condition, a failure to ACK the SNMP final Inform must happen. A reset of the E-MTA will now automatically occur to clear this problem. This LOC item is still being tracked to identify the root cause of this issue.
<i>Impact</i>	Service
<i>Occurrence</i>	High (Full PC Provisioning)
2.3.60 Downstream Frequency Override (DFO) Caused E-MTA to Become Non-Responsive	
<i>Tracking No.</i>	PROD00146426
<i>Description</i>	An issue was identified where the ARRIS E-MTA would become stuck with the US LED flashing when a DFO was received with the US Frequency changing but the DS TLV remaining the same.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.61 SIP: Post Provisioning Configuration Download Does Not Delete Lines	
<i>Tracking No.</i>	PROD00130691
<i>Description</i>	The SIP firmware load has the ability to download a configuration file without affecting service. This allows operators to change the configuration file while an E-MTA is in-service. This mechanism does not allow the operator to delete lines already provisioned on the E-MTA by simply omitting the line provisioning from the special downloaded configuration file.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.62 Password of the Day Not Hidden on CLI	
<i>Tracking No.</i>	PROD00145575
<i>Description</i>	If another attempt is made to log into the CLI after issuing the quit command, the password of the day (PWOD) is seen in the clear instead of being hidden.

<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.63 Automatic OSI Does Not Function In An IPDT Environment	
<i>Tracking No.</i>	PROD00145814
<i>Description</i>	An issue has been discovered with the ARRIS feature automatic OSI. If this feature is enabled via the callpfeature switch, the OSI will not be generated in an IPDT solution due to a timing issue.
<i>Impact</i>	Service
<i>Occurrence</i>	Medium
2.3.64 TM402: Battery MIBs Prevent Registration	
<i>Tracking No.</i>	PROD00134874
<i>Description</i>	Setting the following MIB Objects in the CM configuration file will cause the TM402 to fail registration. <ul style="list-style-type: none"> • arrisMtaDevPwrSupplyConfigReplaceBatTime.0 • upsConfigLowBattTime.0
<i>Impact</i>	Service
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.67A

2.3.65 RF Cut During Registration May Result in No Dial Tone	
<i>Tracking No.</i>	PROD00145767
<i>Description</i>	When multiple RF cuts occur during registration, the MTA may become stuck in a Tele-TFTP provisioning state. In this scenario, the MTA MAC address is no longer present in the CPE table. To get into this condition, a failure to ACK the SNMP final Inform must happen. A reset of the E-MTA will now automatically occur to clear this problem. An LOC item is still being tracked to identify the root cause of this issue.
<i>Impact</i>	High (Full PC Provisioning)

<i>Occurrence</i>	High
2.3.66 Occasional T3 Event Observed After DCC Initiated	
<i>Tracking No.</i>	PROD00144452
<i>Description</i>	When the E-MTA gets a DCC request from the CMTS, the modem may change upstream channels. If this scenario occurs, the E-MTA may T3 causing it to re-range.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.67 Network Ringback Tone Volume Too Low	
<i>Tracking No.</i>	PROD00145069
<i>Description</i>	When the network ringback tone was played by the E-MTA to the far end, it was incorrectly padded by 6dB making the volume level low.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.68 Network Ringback Tone Distortion	
<i>Tracking No.</i>	PROD00145198, PROD00145295
<i>Description</i>	When network ringback tone was played, distortion of the ringback signal was possible prior to the initial off-hook of the E-MTA. This issue could occur at installation or after a reset of the E-MTA.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.69 Recovery Robustness for MTA Security Socket Failure	
<i>Tracking No.</i>	PROD00145306
<i>Description</i>	Recovery robustness has been added around the MTA security socket. During recovery, if this socket is found to be in an invalid state the E-MTA will automatically reset. When this occurs, the E-MTA is not providing service and the last reset reason will be updated to display a reason of 'OS'.
<i>Impact</i>	Service
<i>Occurrence</i>	Low

2.3.70 E-MTA Stuck in Ranged State on CMTS

<i>Tracking No.</i>	PROD00143975
<i>Description</i>	E-MTAs running TS 6.1 loads prior to this release, could become stuck in a ranged state if they saw an IPv6 Offer. Once the IPv6 Offer was seen, the E-MTA would no longer accept an IPv4 offer until the unit was power cycled. This issue is documented in AFB-09-0305.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.71 ARRIS E-MTA's Can Flap and Re-Range after DCC

<i>Tracking No.</i>	PROD00144302
<i>Description</i>	When doing DCC operations with init-tech 2 or init-tech 3, the E-MTA's can fail to successfully move to the new channel. In these instances, the E-MTA will appear to reset and remain on the old channel.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.72 SIP: G729 Data Calls Do Not Fall Back to G711

<i>Tracking No.</i>	PROD00137205
<i>Description</i>	An issue has been identified where G729 SIP calls do not fall back to the G711 CODEC because the data Bell Modem protocol CED tone is not detected. Please refer to the feature section for additional information.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.73 SIP: Inbound Fax DSx QoS Failure During Codec Negotiation

<i>Tracking No.</i>	PROD00142592
<i>Description</i>	When the callfeature switch is set to enable DSx QoS, the re-invite message falsely set the CODEC value to zero. This incorrect CODEC negotiation value causes QoS setup to fail, dropping the call.

<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.74 IPv6: DHCP Failure May Result in No Service	
<i>Tracking No.</i>	PROD00143180, PROD00143282
<i>Description</i>	<p>If running in IPv6 mode, a failure to renew the CM IP address during renew and rebind may result in an E-MTA not obtaining a CM IP address. The E-MTA if affected will require a power cycle to recover.</p> <p>This issue is documented in AFB-09-0306.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	Medium
2.3.75 CM DHCP Offer Error Results in CM DHCP Discover Error	
<i>Tracking No.</i>	PROD00142902
<i>Description</i>	If a CM Offer is received and it does not contain option 177/122, the subsequent DHCP discovers will only advertise support for option 177.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.76 SIP: SIP Message Tracing Information Missing on Webpage	
<i>Tracking No.</i>	PROD00142600
<i>Description</i>	Some details are missing from the SIP message output provided under the Advanced webpage. The output available from an SSH/Telnet session with tracing enabled displayed all of the messaging.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.77 Battery Ordering Code 'Contact ARRIS' String Incomplete	
<i>Tracking No.</i>	PROD00143031

<i>Description</i>	The ordering code displayed for HW models that do not support the reading of the EPROM on the battery and batteries that do not support EPROM is displayed as 'Contact ARRIS'. In some instances, the entire string may not be displayed such that only parts of 'Contact ARRIS' are shown.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
2.3.78 Dual Mode E-MTA on Annex B Displays Wrong Model Type	
<i>Tracking No.</i>	PROD00143922, PROD00143948, & PROD00143983
<i>Description</i>	If a Dual Mode E-MTA is registered on an Annex B downstream, the model type in system description is improperly displayed as a North American Model (A) instead of a European Model (B).
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.79 TFTP Failure with PkctEnNcsEndPntFaxDetection MIB Object in Configuration File	
<i>Tracking No.</i>	PROD00143568
<i>Description</i>	When the pkctEnNCSEndPntFaxDetection MIB Objects are placed in the MTA configuration file, the MTA will fail TFTP.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.80 E-MTA rejects SDP with 'a=rtcp-xr:'	
<i>Tracking No.</i>	PROD00136523
<i>Description</i>	With NCS messaging, connection messages that included the value 'a=rtcp-xr:' without a parameter was rejected. This resulted in the call setup failing.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.81 TM608: Argentina Template Tones Incorrect	
<i>Tracking No.</i>	PROD00143786

<i>Description</i>	Tones including rt, bz, cf, and ot are incorrect in the Argentina country template on the TM608 modem. The problem is not observed on the TM602.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.82 WRM Upgrade Issue if Power-cycled During Upgrade	
<i>Tracking No.</i>	PROD00142010
<i>Description</i>	When the WTM552G is being upgraded, if power is removed briefly after the CM has rebooted from the upgrade, the WRM model will not upgrade.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.83 E-MTA Re-provisions after DCC	
<i>Tracking No.</i>	PROD00144484
<i>Description</i>	Once a DCC operation completes successfully, the MTA call processing layer performs a full provisioning sequence instead of simply returning lines to service.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.84 MuSecurity Lab Test Failure	
<i>Tracking No.</i>	PROD00143383
<i>Description</i>	Denial of Service attack using Syn Flood with HTTP will result in an E-MTA failure after several thousand attempts (2500 PPS).
<i>Impact</i>	Operational
<i>Occurrence</i>	Rare
2.3.85 Extreme Robustness Testing Issue(s)	
<i>Tracking No.</i>	See Below
<i>Description</i>	<ul style="list-style-type: none"> • PROD00130818: Additional reset after docsDevResetNow • PROD00138025: RF Cut during off hook event may cause E-MTA to not be able to provide service

	<ul style="list-style-type: none"> • PROD00134846: Exception during a power cut • PROD00134847 & PROD00134848: Exception after docsDevResetNow • PROD00139004: During registration when an RF cut occurs, an extremely small amount of memory may be lost on the TM602.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.86 Israeli Template: Ringback Tone Timers Incorrect	
<i>Tracking No.</i>	PROD00143054
<i>Description</i>	<p>The ringback tone for the Israeli template should be 1 second on, 3 seconds off. This value is incorrectly set to 2 seconds on, 4 seconds off in the current release.</p> <p>Issue was the result of a configuration problem.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.87 RIP: CLI Commands Not Available via PWOD	
<i>Tracking No.</i>	PROD00143028
<i>Description</i>	<p>Prior to RIP being enabled on a non-WTM unit, the RIP commands should be accessible via the password of the day; however, they cannot be accessed.</p> <p>No fix planned.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.88 Enhanced Software Loading (ESL) Uses Wrong Table for Upgrade Loadname	
<i>Tracking No.</i>	PROD00137149
<i>Description</i>	<p>When using the arrisCmDevSwTable to upgrade the E-MTA, the E-MTA incorrectly uses the firmware load specified in another table, docsDevSoftware, for download purposes.</p> <p>Invalid test case resulted in this issue. No fix planned.</p>

<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.89 DCC May Result In LED Issue	
<i>Tracking No.</i>	PROD00145579
<i>Description</i>	After sending a DCC to an E-MTA with lines registered with the CMS, the LED for line 2 flashes continuously.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.90 IPv6: Modem Resets in Traffic on Certain DHCP Server	
<i>Tracking No.</i>	PROD00130279
<i>Description</i>	Failures of the E-MTA have been observed during traffic runs in cases where the E-MTA is supported by the ISC DHCP Server. This problem has not been reproduced on other provisioning servers. In this scenario, the MTA may not recover after a DHCP renewal during traffic testing.
<i>Impact</i>	Service
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.60

2.3.91 TM60X: Power Failure During Upgrade Causes DSP Corruption	
<i>Tracking No.</i>	PROD00147108
<i>Description</i>	ARRIS has identified a rare condition in which the ARRIS TM60X E-MTAs may fail to complete a successful firmware download as a result of the E-MTA previously experiencing a DSP image header corruption related to a power failure during a previous firmware download. A TM60X E-MTA in this state will not recover and will continuously reboot. This issue is documented in AFB-09-0309.
<i>Impact</i>	Service

<i>Occurrence</i>	Rare
2.3.92 PacketACE: EURO MIB Objects Use CableLabs OIDs	
<i>Tracking No.</i>	PROD00141089
<i>Description</i>	In PacketACE 12.4, some MIB objects incorrectly use the CableLabs OIDs in EURO mode. This issue is resolved in PacketACE 12.6.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.93 SIP: SIP INFO Feature Switch for Hook Flash Not Shown in MIB Object	
<i>Tracking No.</i>	PROD00138817
<i>Description</i>	A new feature was added to provide new SIP INFO support for hook flash reporting. To enable this feature, the sipCfgSipFeatureSwitch bit 0x00000020 must be added to the configuration file. This update was not included in the MIB Object so it is not displayed if an SNMP MIB walk is performed.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.94 Three-way Calling (3WC) May Not Operate Correctly Depending Upon Flash Hook Timing	
<i>Tracking No.</i>	PROD00141815 & PROD00142427
<i>Description</i>	When trying to setup a 3WC, the originator (caller A) calls a second user (caller B). Once that call is established, Caller A can then perform a flash hook to call caller C. During the ring back tone for Caller C, if Caller A flashes back to talk to Caller B, the 3WC can no longer be setup.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.95 System Description Discrepancy with Option 43	
<i>Tracking No.</i>	PROD00142611
<i>Description</i>	On the E-MTA, the Boot Rom value in Option 43 is not the

	same as in the sys description.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.96 TM60X Models Have the Same Value in SysObjectID	
<i>Tracking No.</i>	PROD00142947
<i>Description</i>	The MIB Object, sysObjectID, previously displayed the integer '9' for all TM60X models. The firmware has been updated so the model value will now be displayed. To uniquely identify model types, ARRIS recommends the use of the SysDescr MIB Object.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.97 *82 Feature May Fail if Automatic OSI Enable	
<i>Tracking No.</i>	PROD00143160
<i>Description</i>	An issue was observed with a call server sending a DLCX message after receiving the *82 command. When this occurred, it triggered the automatic OSI feature on the E-MTA so the call was disconnected.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.98 SIP: sipCfgCallWaitingStarCodeSurvivesReset May Not be Stored Correctly in NVM	
<i>Tracking No.</i>	PROD00138478, PROD00138512
<i>Description</i>	Setting this MIB allows persistent storage of a user requesting that Call Waiting be disabled in a SIP application. However, this MIB currently may become out of sync with the current storing of the MIB in NVM. This could result in Call Waiting not being disabled after setting of the MIB. This MIB is also not reset by the factory defaults MIB.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.99 Enrollment Inform Trap Incorrectly Sent	
<i>Tracking No.</i>	PROD00138913
<i>Description</i>	When using the ARRIS proprietary BASIC.1 provisioning method, the E-MTA sends an enrollment inform trap. This message should not be sent for this provisioning method.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.57

2.3.100 SIP Euro: Noise After Call Waiting Tone	
<i>Tracking No.</i>	PROD00137803
<i>Description</i>	Just after the Call Waiting tone is played, there is brief annoying noise on the line around the time callerid should be displayed. Not an issue.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.101 PacketACE: MIB Processing Errors	
<i>Tracking No.</i>	PROD00131305
<i>Description</i>	PacketACE is not able to process correctly double indexed MIBs in the pkcSigDevToneTable and pkcSigDevMultiFreqToneTable.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.102 Euro: Incorrect MIB Format in SNMP Traps	
<i>Tracking No.</i>	PROD00136894
<i>Description</i>	MIBs tcomPkcMtaDevCorrelationId and tcomPkcMtaDevMacAddress are not correctly formatted when output as part of an enrollment and status inform trap.

<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.103 SIP: Unexpected SUBSCRIBE for Event ua-profile	
<i>Tracking No.</i>	PROD00139989 & PROD00138459
<i>Description</i>	After a SIP line registers, it is succeeded by a SUBSCRIBE message for the UA-Profile event. This is unnecessary and is typically ignored or nack'd by the proxy. The SUBSCRIBE may be repeated a few times, depending on retransmit timers.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.104 IP Filters for Ethernet Port also Discards USB Packets	
<i>Tracking No.</i>	PROD00141246
<i>Description</i>	<p>If the MIB object docsDevFilterIpTable with the docsDevFilterIPIfIndex is set to discard Ethernet packets, the packets will also be discarded for the USB port even when that port is not specified.</p> <p>E-MTA is operating per the specification and this was a test case failure.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.105 Provisioning Stops if ACK Not Received	
<i>Tracking No.</i>	PROD00142177
<i>Description</i>	In MTA-25 if we do not receive the ACK, the PacketCable specification says that provisioning should stop and manual interaction is required. Since all the information is available for the E-MTA to function, the E-MTA will now come on-line even if the ACK is not received.
<i>Impact</i>	Operational
<i>Occurrence</i>	Rare

2.3.106 Some MTA Traps and Syslogs were Not Provided	
<i>Tracking No.</i>	PROD00141941
<i>Description</i>	The logs for the following events were not sent via snmp or syslog trap; however, these logs were still reported to the local log. This issue appeared on the following events: <ul style="list-style-type: none"> • MTA event 3 (Voice Line State Change) • MTA event 16 (MTA TFTP: Successful) • MTA event 26 (MTA PROV: Successful)
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.107 SIP: Repeat Dialing Deficiencies	
<i>Tracking No.</i>	PROD00140172
<i>Description</i>	When Repeat Dialing is activated during busy indication, there is no indication to the user that the feature is successfully activated (i.e. busy tone is not broken when dialing and there is no confirmation tone played). The same is true when Repeat Dialing is cancelled during initial dialing. There is no indication that the feature has been successfully cancelled.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.108 docsDevCpeTable Not Populated	
<i>Tracking No.</i>	PROD00141247
<i>Description</i>	When queried via SNMP, the docsDevCPETable is not populated with the attached CPE equipment.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.109 SNMP Entity of 0.0.0.0 Allowed for MTA	
<i>Tracking No.</i>	PROD00143173 & PROD00141908
<i>Description</i>	MTA should stop provisioning when receiving an option 122 Sub-Option 3 of 0.0.0.0. However, the MTA will continue with provisioning and accept a valid IP address if one is provided.
<i>Impact</i>	Service

<i>Occurrence</i>	High
2.3.110 IPv6: arrisCmDevDhcpSvrParameters MIB Object Incorrect	
<i>Tracking No.</i>	PROD00133400
<i>Description</i>	The arrisCmDevDhcpSvrParameters MIB tree is set incorrectly when the CM is in IPv6 mode.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.111 IPv6: Recovery Problems from RF Cut	
<i>Tracking No.</i>	PROD00140241, PROD00139882
<i>Description</i>	When running in IPv6 mode, the E-MTA may have trouble recovering. In this scenario, the E-MTA may perform an extra reset automatically or require a power cycle to come back on-line.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.112 SNMP Traps Incorrectly Sent to Trap Server	
<i>Tracking No.</i>	PROD00139562
<i>Description</i>	The SNMP MIB object, pktcDevEvFixedReporting, was being set to 01.00 to send traps to the local server only but they were still being sent to all servers.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.113 SIP: Advanced Calling Features Work Only on Line 1	
<i>Tracking No.</i>	PROD00139853, PROD00139876, PROD00140424, PROD00141900
<i>Description</i>	Through lab testing, ARRIS has identified some advanced SIP calling features that will only function correctly when used on line one of the E-MTA. The features are listed below: <ul style="list-style-type: none"> • Hot Line • Repeat Dialing (*62) • Advanced Flash RO (Euro Only)

	Advanced Flash Feature Call Transfer
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.114 CMTS UCC Takes Longer than Expected to Complete	
<i>Tracking No.</i>	PROD00139230
<i>Description</i>	When performing a UCC from the CMTS, the E-MTA takes several seconds to recover. Due to the expended recovery time, a T3 event may occur.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.115 WTM: 'R active' Command Does Not Validate Values	
<i>Tracking No.</i>	PROD00139461
<i>Description</i>	When using the 'r active' command to write values to the WTM, the prior firmware did not validate the information was correct which could result in the writing of an incorrect IP address.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.116 WTM552: Reboot Loop When Corrupt Application Image on E-MTA	
<i>Tracking No.</i>	PROD00139786
<i>Description</i>	<p>If during the firmware download process the application image becomes corrupt on a WTM552, the E-MTA will become stuck in a reboot loop. This only occurs when the CM configuration file contains MTA MIBs.</p> <p>This issue was presented in AFB-09-0303.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	Rare

2.3.117 LVM Key and Policy MIBS state a Read/Write Status but are only Writable via Configuration File	
<i>Tracking No.</i>	PROD00138138
<i>Description</i>	LVM Key and Policy MIB objects state a Read/Write status but are only writable via configuration file. The description has been modified to reflect the firmware code which states that the LVM Key will fail unless present in the configuration file.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.118 Information Mismatch in CLI Command http_all	
<i>Tracking No.</i>	See Below
<i>Description</i>	<ul style="list-style-type: none"> • PROD00132023: In the http_all CLI command, the System Information for individual lines will sometimes display provisioned, although the line is not. • PROD00138040: DHCP server address wrong under 'Server IP Information'
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.119 IPv6: TM6XX Registration Issue	
<i>Tracking No.</i>	PROD00135353
<i>Description</i>	TM6XX has problems in some TS 6.1 releases with registration when IPv6 was being used. Registration would fail with DHCP never appearing to start.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.120 Extreme Robustness Testing Issues Resolved	
<i>Tracking No.</i>	See Below
<i>Description</i>	<ul style="list-style-type: none"> • PROD00130818: Additional reset after docsDevResetNow due to exception during a firmware reset. • PROD00138096: Software Reset
<i>Impact</i>	Service

<i>Occurrence</i>	Rare
-------------------	------

The following issues were resolved in release 6.1.51D

2.3.121 E-MTA Reset Approximately Every 10 days	
<i>Tracking No.</i>	PROD00139683
<i>Description</i>	An issue exists whereby modems will reset after the system uptime reaches approximately 10 days. This issue could affect voice service if the subscriber is off-hook when the problem occurs. This issue was presented in AFB-09-0304.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.122 Persistent Line Status is not Preserved over a Modem Reset	
<i>Tracking No.</i>	PROD00140366
<i>Description</i>	When using the persistent line status feature, the status was not preserved over a modem reset. This issue was only seen on certain provisioning methods such as BASIC.1.
<i>Impact</i>	Service
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.51

2.3.123 Management Message Print Out to CLI Session	
<i>Tracking No.</i>	PROD00138266
<i>Description</i>	When logging into the CLI, unexpected management messages that the firmware does not recognize would be noted in the

	capture. This can greatly impact the ability to troubleshoot existing issues. In the TS 6.1 release, the management messages can be disabled from tracing. Below are some message examples: DIST: Unexpected management Message Type->33 - Discard message DIST: Unexpected management Message Type->34 - Discard message
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.124 SIP: 3-Way Calling Fails if DisableSessionTimers Enabled	
<i>Tracking No.</i>	PROD00137281, PROD00138911
<i>Description</i>	If the sipCfgSipFeatureSwitch, 'disableSessionTimers', is enabled a problem has been observed where a 3-way call drops the existing call.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.125 WTM552: Wired CPE Equipment Ages Out of CPE Table	
<i>Tracking No.</i>	PROD00133493
<i>Description</i>	The Least Frequently Used (LFU) algorithm will age out CPEs that are hardwired to the WTM552 in addition to wireless CPEs. No Fix Planned – Works per design and was a test plan failure.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.126 RIPv2: CLI Command Fails	
<i>Tracking No.</i>	PROD00125462
<i>Description</i>	If RIPv2 is enabled on non-WTM552 devices, the command to provide RIP message traces, ripdebuglevel in the rip directory, does not properly turn on the tracing capability.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.127 SIP: INFO Message for Hook Flash Not Standard	
<i>Tracking No.</i>	PROD00136596
<i>Description</i>	If the operating environment requires a hook flash to be reported via the INFO message, the E-MTA will send a non-standard value which is compatible with the Broadsoft solution.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.128 Problems with DTMF Tones	
<i>Tracking No.</i>	PROD00136676
<i>Description</i>	Certain devices can have trouble handling DTMF events from the E-MTA. This is a result of the interim packets for the DTMF Tone reporting total event duration (amount of time) greater than the final declared duration.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.129 ARRIS E-MTAs may Lose Layer 3 Connectivity after Dynamic Channel Change Request	
<i>Tracking No.</i>	PROD00138654
<i>Description</i>	An issue exists whereby modems running TS6.1.47 and all prior TS6.1 releases may lose layer 3 connectivity after any one of initialization technique options 2, 3, or 4 are commanded by the Cable Modem Termination System (CMTS) for Dynamic Channel Change Requests (DCC-REQ). This issue was presented in AFB-09-0301/AFB-09-0301R.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.130 SIP G729: Rapid Hook Transition May Cause Voice Line Failure	
<i>Tracking No.</i>	PROD00137853
<i>Description</i>	After rapid on-hook / off-hook transitions, the E-MTA goes into a state where the line on the SIP proxy server shows registration. When this occurs, an incoming call will receive

	treatment tones. This issue is cleared by waiting up to 10 minutes or resetting the unit. ARRIS has identified a DSP error when this occurs that is resolved in this release.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.131 IPv6: Unable to Recover E-MTA	
<i>Tracking No.</i>	PROD00137971
<i>Description</i>	Multiple configurations have been observed in which E-MTAs are unable to complete the recovery process when in IPv6 mode.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.132 DHCP Renewal Failure May Cause Temporary Loss of Connectivity	
<i>Tracking No.</i>	PROD00134378
<i>Description</i>	<p>A problem has been observed where the E-MTAs occasionally lose their Layer 3 IP connectivity after a CM DHCP Renewal Failure. This occurs due to a buffer exhaustion problem which is resolved in this release.</p> <p>This issue was presented in AFB-09-0302.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.133 Noise During Playout of RT Tone on Poland Templates	
<i>Tracking No.</i>	PROD00123368
<i>Description</i>	If using the Poland or Poland1010 country template, then the playout of the Ringback Tone (RT) maybe too loud and cause static on some phone sets.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.134 Information Mismatch in CLI Command http_all	
<i>Tracking No.</i>	PROD00132096
<i>Description</i>	In the http_all CLI command, the LC states expressed under “Line Card state machine” and “CallP state machine” don’t match the same values displayed under “Line LC State Callp State”, in a later section. The first listing is the correct value.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.135 TM602 Phase II Battery Hold-up Time Slightly Below Expectation	
<i>Tracking No.</i>	PROD00138309, PROD00138385
<i>Description</i>	A problem has been identified where the TM602 Phase II battery backup time is slightly below expectation (approximately 10 minutes). This issue is resolved with a new battery charger firmware release in this load.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.136 SIP: Unable to Handle Messages Larger than 2048	
<i>Tracking No.</i>	PROD00136679
<i>Description</i>	The E-MTA is not able to properly process received SIP messages of a length greater than 2048 bytes.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.137 TM608: 8 Cell Battery Holdup Time Insufficient	
<i>Tracking No.</i>	PROD00137572, PROD00138385
<i>Description</i>	A problem has been observed where the 8 cell battery pack in a TM608 does not support the specified holdup time when 5 or more lines are off-hook.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.138 LVM: Policy 2 Fails When Non-DOCSIS QAM Present	
<i>Tracking No.</i>	PROD00137981, PROD00138016
<i>Description</i>	Loop Voltage Management (LVM) Policy 2 does not maintain the line voltage in the presence of a non-DOCSIS QAM on the RF link.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.139 IPv6: MTA IP Address Not Accessible via Telnet, SSH or Web Page	
<i>Tracking No.</i>	PROD00133337, PROD00133338
<i>Description</i>	Telnet, SSH and HTML access to the MTA's IP address is not available if the CM is configured in IPv6 mode.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.140 RIPv2: Web Page Displays Subnet Mask Incorrectly	
<i>Tracking No.</i>	PROD00132932
<i>Description</i>	The RIP web page, when enabled, only displays classful subnet masks information.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.141 RIPv2: Incorrect Advertisement Sent to CMTS	
<i>Tracking No.</i>	PROD00137691
<i>Description</i>	For non-WTM devices, RIPv2 has been observed incorrectly advertising a subnet mask of 16 instead of the expected provisioned value. This causes the setup of RIPv2 to fail.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.142 LVM: Occasional Loss of Loop Voltage	
<i>Tracking No.</i>	PROD00122626
<i>Description</i>	The E-MTA, while recovering from a reset or loss of RF, may first attempt to lock onto a non-DOCSIS QAM before finally locking onto the correct carrier. In these scenarios, it is possible that the E-MTA may briefly experience a clocking failure. This failure causes loop voltage to be dropped from provisioned lines momentarily.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.143 Battery Serial Number Invalid During AC Failure	
<i>Tracking No.</i>	PROD00133492
<i>Description</i>	A problem was identified where the EPROM could be incorrectly populated after AC Failure. This could result in an invalid battery serial number being displayed.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
2.3.144 Access to WRM WebGUI via WAN IP cannot be Disabled if NAT Status is Disabled	
<i>Tracking No.</i>	PROD00139647
<i>Description</i>	If access to NAT is disabled, the WAN IP address cannot be used to disable the WRM WebGUI.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.145 WTM Not Flushing CPE Devices	
<i>Tracking No.</i>	PROD00139916
<i>Description</i>	On the WTM552, the 'DHCP Client List' in the webGUI shows entries (IP address, Host Name, MAC Address) for CPEs that have not been connected since the DHCP lease expired. The IP addresses are also not released.
<i>Impact</i>	Service
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.47

2.3.146 allowCpeOverFlowWrap Feature Caused MTA MAC Address Discarded	
<i>Tracking No.</i>	PROD00133488
<i>Description</i>	The MTA MAC address was discarded in the event the allowCpeOverflowWrap feature was enabled and MacCpeAllowed limit was met.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.147 Maximum Number of CPEs Bypass the MaxAllowedCPE TLV Limit	
<i>Tracking No.</i>	PROD00133494
<i>Description</i>	It was observed that in the event the allowCpeOverFlowWrap and maxCPEBypass features were enabled, the number of CPEs added to the CPE table surpassed the allowable limit set using the MaxAllowedCPE TLV.
<i>Impact</i>	Service
<i>Occurrence</i>	Medium
2.3.148 ifPhysAddress.5 provides incorrect MAC address of the USB interface	
<i>Tracking No.</i>	PROD00127787
<i>Description</i>	The MIB ifPhysAddress.5 provides incorrect MAC address of the USB interface.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.149 DCC Request on E-MTA Recovery May Cause Failure	
<i>Tracking No.</i>	PROD00130604

<i>Description</i>	If an E-MTA receives a DCC request early in its recovery cycle, the E-MTA may fail to recover and require a manual reset.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.150 IPv6: CLI Output Does Not Display the Prefix or Lease Time Correctly	
<i>Tracking No.</i>	PROD00132230
<i>Description</i>	The CLI output “System>dhcp” failed to display the prefix or lease time of the E-MTA when operating in IPv6 mode.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.151 IPv6: DHCP and TOD Server IPs incorrectly displayed in CLI	
<i>Tracking No.</i>	PROD00120362
<i>Description</i>	The DHCP and TOD server IP addresses were incorrectly displayed when executing the http_all or sysinfo command from CLI.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.152 IPv6: Walking the docsDevServerDhcpAddress and docsDevServerDhcpAddressType MIB Object Returns IPv4 Data	
<i>Tracking No.</i>	PROD00133392, PROD00133393
<i>Description</i>	While walking the docsDevServerDhcpAddress and docsDevServerDhcpAddressType MIB objects, the query returned data in IPv4 format instead of IPv6.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.153 ‘*’ Code Feature Failure	
<i>Tracking No.</i>	PROD00133663

<i>Description</i>	Certain failures have been noted with ‘*’ code features that require additional digit collection to be activated. This problem has been noticed against the Nortel call server solution.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.154 Extreme Robustness Testing Issues	
<i>Tracking No.</i>	See Below
<i>Description</i>	<ul style="list-style-type: none"> • PROD00132995 – E-MTA reset with a TLB Exception. • PROD00136139 – Watchdog Reset occurring due to issue with state machine become unavailable during RF cut when MTA is pulling the configuration file via TFTP. • PROD00133590 – RF cuts during registration resulted in a small memory leak.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.155 TM508/512: Telemetry State Displayed Incorrectly After External Power Disconnected	
<i>Tracking No.</i>	PROD00133565
<i>Description</i>	The telemetry states on ARRIS MultiLine E-MTAs failed to indicate that the external power cable had been disconnected. “Cable Disconnected” has been added as a new state for this event.
<i>Impact</i>	Service
<i>Occurrence</i>	Medium
2.3.156 Consecutive RF Cuts may Cause TLB Exception	
<i>Tracking No.</i>	PROD00130465
<i>Description</i>	Consecutive RF cuts within a short period of time caused the E-MTA to issue a TLB exception error and reboot.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.157 SIP: PacketACE 12.1 and 14.1 MIB Object Issues	
<i>Tracking No.</i>	PROD00135367
<i>Description</i>	PacketACE releases 12.1 and 14.1 had several issues when attempting to create an MTA SIP configuration file. The following problems have been resolved. <ul style="list-style-type: none"> - ARRIS MIB sipCfgT1 not recognized - Export of file shows values in HEX - IPv6 support for network address information
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.158 SingleMAC: All Calls Fail When an FQDN is Used	
<i>Tracking No.</i>	PROD00134654
<i>Description</i>	All calls fail to complete when a Fully Qualified Domain Name(FQDN) is used for the call agent in ARRIS singleMAC provisioning due to DNS query failure.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.159 WTM552: WRM MAC Address Discarded When allowCpeOverflowWrap Feature was Enabled	
<i>Tracking No.</i>	PROD00134027
<i>Description</i>	The WRM MAC address was discarded in the event the allowCpeOverflowWrap feature was enabled and MacCpeAllowed limit was met.
<i>Impact</i>	Service
<i>Occurrence</i>	Medium
2.3.160 E-MTA Autonomous Reset Observed During Traffic Run	
<i>Tracking No.</i>	PROD00128316
<i>Description</i>	Traffic has been observed to be impacted when an autonomous E-MTA reset occurs during a long traffic run. The traffic recovers automatically. The reason for the E-MTA reset is under investigation.

<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.161 Provisioning Method Indicator on Webpage Maybe Incorrect	
<i>Tracking No.</i>	PROD00134993
<i>Description</i>	The Provisioning Method displayed on DHCP tab of the webpage only reflected the arrisMtaDevProvMethodIndicator MIB and may have not matched the actual method. The fix now reflects ARRIS and PacketCable 1.5 methods.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.162 WM550 / WM602: Corrected Downstream Errors Reported	
<i>Tracking No.</i>	PROD00125134
<i>Description</i>	On the wireless products, WM550 and WM602, at low symbol rates corrected downstream errors were being reported when no issue was occurring.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.163 PacketCable 1.5 MTA Option 60 Subtype Error	
<i>Tracking No.</i>	PROD00135563
<i>Description</i>	When using PacketCable 1.5 provisioning, the MTA option 60 suboption 5.1 is sending a value of 0 instead of 1.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.164 Remote Tone Not Heard When Connection Mode is Set to Inactive	
<i>Tracking No.</i>	PROD00131684
<i>Description</i>	During a call setup, when the remote connection is set to inactive using a MDCX or CRCX, the remote tone request s:rt is not heard.

<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.165 WTM552: Fails PacketCable Security	
<i>Tracking No.</i>	PROD00136139
<i>Description</i>	The WTM552 MTA failed provisioning in PCSEC mode. The WTM552 stayed in "Telephony-DHCP" status.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.166 arrisMtaDevPacketcableProvisioningFlow MIB Object May Show Incorrect Value	
<i>Tracking No.</i>	PROD00135407
<i>Description</i>	The arrisMtaDevPacketcableProvisioningFlow MIB object does not show the correct value when the arrisMtaDevSpecialConfigurationOverrideEnable MIB is in the CM configuration file and option 122 sub-option 6 is set to BASIC.1 or 2.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.167 TM402: DHCP Task Issue on Upgrade	
<i>Tracking No.</i>	PROD00135400
<i>Description</i>	A problem was discovered on the TM402P where an upgrade from TS 5.2 to TS 6.1 would cause the DHCP task to become non-operational. This was a result of a timing problem that has now been corrected.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.168 Line Card Incorrectly in Protection State after RF Event	
<i>Tracking No.</i>	PROD00131588
<i>Description</i>	Lines on an E-MTA have been observed to enter the protection state after an RF event occurs. This is happening on provisioned and unprovisioned lines. The issue is resolved by

	resetting the E-MTA
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.169 DCC or UCC may Cause the Registration State and LED Sequence to be Displayed Incorrectly	
<i>Tracking No.</i>	PROD00123286
<i>Description</i>	A Dynamic Channel Change (DCC) or Upstream Channel Change (UCC) may cause the E-MTAs registration state and LED sequence to be displayed incorrectly. The Event tab on the webpage and CLI incorrectly display the CM provisioning state as “Complete”; however, the MTA portion is displayed as “Not Started.” The LED sequence also incorrectly displays the state to match the registration state where the Telephony 1 and Telephony 2 LEDs are turned off.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.170 TM512 Resets during Bulk Traffic Testing	
<i>Tracking No.</i>	PROD00137598
<i>Description</i>	When running bulk traffic testing for the TM512, the E-MTAs were resetting occasionally due to an exception. This was the result of an incorrect function being occasionally called.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.171 Traffic Results Below Baseline on TM508 and TM512	
<i>Tracking No.</i>	PROD00128411, PROD00120024
<i>Description</i>	Traffic results on the TM508 and TM512s running the TS 6.1 load have shown a 0.01 to 0.10% drop in call completion rate.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare

2.3.172 Downgrade/Upgrade Issue When arrisCmDevDSTPolicy MIB in Configuration File	
<i>Tracking No.</i>	PROD00134537
<i>Description</i>	Due to a problem corrected in TS 6.1.38B (PROD00133559), if the DST MIB is set in the configuration file a downgrade to a release older than TS 6.1.38B will result in future upgrade failures. This issue causes a problem that results in an invalid CVC.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.173 pktcSigDefMediaStreamTos Is Not Applied to RTP Packet	
<i>Tracking No.</i>	PROD00134150
<i>Description</i>	The RTP packets are being sent with the default value for TOS byte settings regardless of the pktcSigDefMediaStream MIB. Customer configuration problem.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.174 SIP: sipCfgSessionExpire MIB for terminating E-MTA does not work correctly	
<i>Tracking No.</i>	PROD00130430
<i>Description</i>	When the sipCfgSessionExpire MIB object is set for the terminating E-MTA, the terminating E-MTA does not respond back to the originating device with the correct session expiration value after receiving the INVITE.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.175 E-MTA may fail if the CPE connected to the USB port is powered down	
<i>Tracking No.</i>	PROD00128512
<i>Description</i>	Cases have been observed in which the E-MTA is impacted (data and voice) if the CPE connected to the USB port is

	powered down. Could not reproduce.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.176 E-MTA accessible by telnet but not SNMP	
<i>Tracking No.</i>	PROD00127078
<i>Description</i>	Certain cases have been observed in which if the E-MTA does not properly initialize after a reset or RF cut, the E-MTA is accessible by telnet but not accessible by SNMP.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
2.3.177 PacketACE Does Not Support SigDevToneTable MIB Objects	
<i>Tracking No.</i>	PROD00122374
<i>Description</i>	PacketACE does not provide support to display or create entries for the SNMP MIB Objects of the SigDevToneTable for North America PacketCable. If these MIBs are present in the configuration file, they will be viewed by PacketACE as unknown OIDs. Configuration issue identified.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.178 Recovery from KRB_ERROR takes too Long when Establishing Security Association with CMS	
<i>Tracking No.</i>	PROD0095336
<i>Description</i>	A clock skew error in the AP-REPLY from the CMS during establishment of the security association with the CMS causes the E-MTA to retransmit the AP-REQUEST until the clock skew is within an acceptable range. No fix planned.
<i>Impact</i>	Operational

<i>Occurrence</i>	High
2.3.179 ifLinkUpDownTrapEnable Does Not Disable E-MTA Traps	
<i>Tracking No.</i>	PROD0087199
<i>Description</i>	The ifLinkUpDownTrapEnable MIB can be set and read via SNMP, but is not working correctly as traps cannot be disabled. No fix planned.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.180 E-MTA Stops Responding to SNMPv1 Queries	
<i>Tracking No.</i>	PROD00084037
<i>Description</i>	SNMPv1 queries to the E-MTA IP address using the same source port repeatedly may not be answered. This could cause an NMS that continually polls the E-MTA, using SNMP v1, to inadvertently mark the unit as 'not providing service' even though the unit is providing service. This problem does not occur with SNMPv2 coexistence. No fix planned.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.181 No Voice Path during PCMA or PCMU 30ms Call Setup	
<i>Tracking No.</i>	PROD0082607
<i>Description</i>	When a call is setup to use 30ms packetization, there is no speech path on the eMTA. No fix planned at this time.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.182 E-MTA Records Only 50 Events in the pktcDevEventTable MIB Object	
<i>Tracking No.</i>	PROD00075338
<i>Description</i>	After the E-MTA records 50 events in the pktcDevEventTable MIB table, the E-MTA will no longer record a new event. No fix planned at this time.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.183 E-MTA Stops Responding to SNMP if Row Created with CreateAndGo or CreateAndWait	
<i>Tracking No.</i>	PROD00070616
<i>Description</i>	In SNMP coexistence mode, rows for the E-MTA must be created with a rowStatus of active. If either createAndGo or createAndWait is used, the E-MTA stops responding to SNMP. No fix planned at this time.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.184 E-MTA Acceptance of DHCP Sub-Option 3 as 0.0.0.0	
<i>Tracking No.</i>	PROD00067816
<i>Description</i>	The E-MTA incorrectly accepts an offer from the primary DHCP server with suboption 3 equal to 0.0.0.0. The E-MTA should continue to look for a valid offer from a back-up server instead of accepting the original offer. No fix planned at this time.
<i>Impact</i>	Service
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.38C

2.3.185 TM608: Unable to Complete 14 th Call Leg	
<i>Tracking No.</i>	PROD00134294
<i>Description</i>	Previously when using a CISCO BTS call server solution, a 14 th call leg could not be established on a TM608. This occurs when 3-way calling is enabled for multiple lines.
<i>Impact</i>	Service
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.38B

2.3.186 SIP: MuSecurity Malformed Packet Test Failure	
<i>Tracking No.</i>	PROD00125609, PROD00134109
<i>Description</i>	In the SIP release, the MuSecurity test for malformed packets is failing causing the E-MTA to have an exception error.
<i>Impact</i>	Service
<i>Occurrence</i>	High (In Given Scenario)
2.3.187 arrisCmDevDSTPolicy MIB Causes Upgrade Issue	
<i>Tracking No.</i>	PROD00133559, PROD00134539
<i>Description</i>	The arrisCmDevDSTPolicy MIB Object in the configuration file prevents an upgrade from an NCS load to a SIP load.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.188 arrisCmDevDSTPolicy Does Not Work if TOD Fails	
<i>Tracking No.</i>	PROD00134112
<i>Description</i>	During the provisioning phase of E-MTA recovery, if the Time of Day (TOD) server is not available or has a delayed response, the arrisCmDevDSTPolicy MIB will not be correctly processed.
<i>Impact</i>	Operational
<i>Occurrence</i>	Rare

The following issues were resolved in release 6.1.38

2.3.189 TM608: Unable to Support 9th Simultaneous Call	
<i>Tracking No.</i>	PROD00133156
<i>Description</i>	A limitation was observed on the TM608 where it could only support 8 simultaneous calls. When the 9 th connection was established, no audio stream was available.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.190 arrisCmDevTftpBlkSize fails with certain TFTP Servers	
<i>Tracking No.</i>	PROD00132411
<i>Description</i>	The ARRIS feature to allow the TFTP Server block size to be configured can cause TFTP failures if the server does not participate in blksize negotiation.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.191 WTM552: Loss of Filters if arrisCmDevRouterMode Included in Configuration File	
<i>Tracking No.</i>	PROD00131759
<i>Description</i>	All LLC and IP filters in the CM configuration file are lost on the WTM552 when the arrisCmDevRouterMode MIB Object is in the CM configuration file.
<i>Impact</i>	Operational
<i>Occurrence</i>	Medium
2.3.192 No Dial Tone After an E-MTA Reset (via the reset button) with Phone Off-Hook	
<i>Tracking No.</i>	PROD00124160
<i>Description</i>	If a phone is off-hook and the reset button on the E-MTA is pressed, the E-MTA will reset but the line will not return to service. Problem was resolved as no fault found.
<i>Impact</i>	Service

<i>Occurrence</i>	High
2.3.193 G729: E-MTA may Experience Static Using G729 CODEC	
<i>Tracking No.</i>	PROD00129912
<i>Description</i>	E-MTAs operating using the G729 compression CODEC may experience static during a telephone call. The static is heard only after the connection is established and both parties are silent. This issue was presented in AFB-08-0315.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.194 MTA sends duplicate DNS Request	
<i>Tracking No.</i>	PROD00130815
<i>Description</i>	The MTA is sending a second DNS query before the original DNS query has timed out.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.195 SIP: sipCfgCallWaitingStarCodeSurvivesReset does not Permit Persistent Storage of Call Waiting Enabled	
<i>Tracking No.</i>	PROD00130329
<i>Description</i>	Setting this MIB allows persistent storage of a user requesting that Call Waiting be disabled. However, this MIB currently will not store the MIB being enabled persistently.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.196 Operational errors with 3 arrisWrm MIBs	
<i>Tracking No.</i>	PROD00130116
<i>Description</i>	1) The MIBs arrisWrmDevVsEnableStatus and arrisWrmDevSapStatus display incorrectly when disabled (they show 0 =Not Defined)

	2) MIB arrisWrmDevMfEnable cannot be disabled in certain conditions
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.197 Call Forwarding (*72) Incompatibility Issue with Siemens HiQ	
<i>Tracking No.</i>	PROD00127402, PROD00131030
<i>Description</i>	When a CPE initiated a *72, the E-MTA may miss the '*' resulting in a failed Call Forwarding attempt. This issue was observed with the Siemens HiQ CMS.
<i>Impact</i>	Service
<i>Occurrence</i>	Medium
2.3.198 DOCSIS 2.0 Auto Detection Feature on E-MTA may not Activate DOCSIS 2.0 Mode	
<i>Tracking No.</i>	PROD00131033
<i>Description</i>	<p>A problem has been identified whereby an E-MTA may not automatically convert to DOCSIS 2.0 via the ARRIS DOCSIS 2.0 Auto Detection Feature. With this issue, approximately 10 percent of the units were observed to stay in DOCSIS 1.1 mode while attempting to complete the auto detection. This resulted in the units becoming stuck in a reboot loop until the DOCSIS 2.0 Upstream channel(s) was removed.</p> <p>This issue was presented in AFB-08-0314.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.199 Changes to Argentina Tone and Ring Template	
<i>Tracking No.</i>	PROD00130369
<i>Description</i>	The call waiting tones (WT1-4) and distinctive ringing cadences (r0-r7) do not match the latest requirements for Argentina.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.200 E-MTAd may cease to Provide Dial Tone if CMTS MAC Address is learned as CPE on E-MTA	
<i>Tracking No.</i>	PROD00131196, PROD00102012
<i>Description</i>	<p>With this problem, an E-MTA may learn the CMTS MAC address as a CPE. This problem is the result of a reflection on the Ethernet port from the CPE of the CMTS MAC address back to the E-MTA. This has been observed when the Ethernet device on the CPE changes speeds (specifically on an Apple Computer in Stand-by Mode). Once in this state, the E-MTA will not provide service and fails to respond to MTA and CM IP pings.</p> <p>This issue was presented in AFB-08-0316.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.201 IPv6: IPv4 Filters Cause IP Connectivity Loss	
<i>Tracking No.</i>	PROD00132551
<i>Description</i>	IPv4 filters in the CM configuration file cause the CM to discard IPv6 packets.
<i>Impact</i>	Service
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.34A

2.3.202 TM602, TM604, TM608, DTM602 Improvements in Battery Holdup Times	
<i>Tracking No.</i>	PROD00132471
<i>Description</i>	TM602, TM604, TM608, DTM602 modems have cases in which they do not meet their advertised maximum holdup times.
<i>Impact</i>	Service
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.34

2.3.203 arrisMtaDevDspHandleNonPhaseReversedTone MIB Setting Incorrectly Applied when Transmitting	
<i>Tracking No.</i>	PROD00130118
<i>Description</i>	The arrisMtaDevDspHandleNonPhaseReversedTone MIB is designed to help with devices that do not support nonphase reversed tone in the receive direction. This MIB is incorrectly being applied in the transmit direction. This results in some failures on devices that do not support nonphase reversed tones such as a fax machine.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.204 IPv6: TM402 and TM502 Failure on Boot when Using IPv6	
<i>Tracking No.</i>	PROD00129974
<i>Description</i>	The ARRIS E-MTA was attempting to process the RA event prior to the modem interfaces becoming operational. This was observed with the unsolicited RA interval (on the CMTS) set to 3 seconds.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.205 Illegal Quote in Caller Name Drops Call	
<i>Tracking No.</i>	PROD00130289
<i>Description</i>	If the Caller Name is received with an illegal quote character, the call is dropped. With this change, the call is accepted and the Caller Name is ignored.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.206 Updates to upsAlarmDescr MIB Object	
<i>Tracking No.</i>	PROD00113352
<i>Description</i>	Several items for the upsAlarmDescr MIB object have been updated in support of PacketCable 1.5. The type of MIB was

	changed to “Autonomous” and additional MIB states added.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.207	Duplicate Trap for Voice Line State Change
<i>Tracking No.</i>	PROD00125443
<i>Description</i>	A duplicate SNMP Trap message was being sent for a voice line state change.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.208	MIB Objects Updated
<i>Tracking No.</i>	PROD00129468, PROD00129876
<i>Description</i>	<p>The arrisMtaDevPwrSupplyFullChargeTime MIB object was updated to correct a spelling error and to add a more detailed model description.</p> <p>The arrisMtaDevPwrSupplyHighestTemperatureTime MIB Object was updated for models that do not support this MIB (aka no battery). This MIB will now display a default time of January 1, 1970 for units that do not support this feature.</p>
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.209	E-MTA No Dial Tone Due to Forward Disconnect State and Lease Expiration
<i>Tracking No.</i>	PROD00127036
<i>Description</i>	If the OSI delay value was set to 0, during a reset of the MTA or lease expiration a line could become stuck in a forward disconnect state.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.210	E-MTA Not Processing DHCP NAKs
<i>Tracking No.</i>	PROD00128027

<i>Description</i>	When the E-MTA was in the renewal or rebind state, DHCP NAKs were not being processed. The NAKs were also not stored under the DHCP logging history.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.211 MaxCPE Value Increases Over Time	
<i>Tracking No.</i>	PROD00117809
<i>Description</i>	The MaxCPE count could increase over time beyond the value specified in the configuration file.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.212 E-MTA May Reset due to Negative Acknowledgement (NAK) Destined for Other Devices	
<i>Tracking No.</i>	PROD00128484
<i>Description</i>	<p>The MTA will reset as a result of a broadcast DHCP NAK being processed by the MTA while the MTA is waiting on a response to a DHCP renewal request. Due to the short amount of time the E-MTA is in the renewal or rebind state expecting DHCP messages, this issue is believed to be a rare occurrence. However, a MTA reset will result in No Dial Tone for a very brief period of time and drop any existing calls.</p> <p>This issue was presented in AFB-08-0313</p>
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.213 Delete Connection Failure from CMS May Result in Stuck Connection	
<i>Tracking No.</i>	PROD00125487
<i>Description</i>	A rare double failure scenario has been observed when the CMS fails to delete a connection and send a DLCX. In this situation the DLCX is not provided after initial disconnect or after the audit detects the connection. When this occurs, the connection becomes stuck and requires an E-MTA reset to clear the issue.

<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.214 Debug Level REPL 18 with Other Actions May Cause E-MTA Reset	
<i>Tracking No.</i>	PROD00126434
<i>Description</i>	In cases when REPL 18 is enabled and other actions occur, the E-MTA has been observed to reset. This issue was directly noted when the tracing was enabled and the 'stand-by' button was pressed on the E-MTA.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.215 CM IP Address Not Pingable After CMTS Upgrade	
<i>Tracking No.</i>	PROD00126415
<i>Description</i>	A rare issue has been observed where the CM IP Address was not pingable after the CMTS was upgraded. The problem is related to a corruption of the DS Buffer in the E-MTA.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.216 SNMP MIB arrisMtaDevPwrSupplyBatteryTest cannot be changed for TM402	
<i>Tracking No.</i>	PROD00127308
<i>Description</i>	The arrisMtaDevPwrSupplyBatteryTest MIB should not have previously supported a write option for the TM402. This resulted in inaccurate reporting for the MIB. For this release, the MIB has been modified to not accept a write request from a TM402 and to accurately display the battery status when read.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
2.3.217 Exception Occurs When CLI Call Processing Command Executed	
<i>Tracking No.</i>	PROD00126206

<i>Description</i>	When running the CLI command 'CID 0' from the Call Processing Menu, the E-MTA will issue an exception and reboot. This command is only used by the direction of technical support when troubleshooting an issue.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.218 MTA Feature Switch for Basic.2 Provisioning Change Adds Additional Time to Provisioning Complete	
<i>Tracking No.</i>	PROD00126986
<i>Description</i>	The MTA feature switch, ppCfgMtaFeatureSwitch, can be used to disable the need for a NAK when using Basic.2 provisioning. In this configuration, the MTA took an additional minute to complete provisioning. The feature switch is snmpInformBypass.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.219 SIP: Warmline Feature Works Only on Line 1	
<i>Tracking No.</i>	PROD00126922
<i>Description</i>	The warmline feature, which dials a pre-provisioned number, only works properly on the first line of the E-MTA.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.220 Extreme Robustness Test Issue – Zero MOS Score	
<i>Tracking No.</i>	PROD00114671
<i>Description</i>	After recovery from a cable cut during registration, a few E-MTAs have reported a MOS score of 0.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.221 Accepted G729A Codec is Advertised in SDP as G729	
<i>Tracking No.</i>	PROD00111796

<i>Description</i>	When MTA receives a CRCX or MDCX requesting the codec G729A, it accepts the request, but responds with SDP listing G729 as offered codec. Third party MTAs may require G729A in the SDP response, in order to setup call.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.222 Endpoint Link Up Trap Not Sent at Proper Time During Registration	
<i>Tracking No.</i>	PROD00058432
<i>Description</i>	The E-MTA sends the SNMP Endpoint Link Up trap after acquiring the E-MTA configuration file instead of after registration with the call server.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

The following issues were resolved in release 6.1.21

2.3.223 CPE Device Not Pingable When Non-Zero Value Set for Certain MIB Objects	
<i>Tracking No.</i>	PROD00103213
<i>Description</i>	For an ICMP packet, docsDevFilterIpDestPort and docsDevFilterIpSourcePort MIB values should be ignored but previously were not. This resulted in a inability to ping the CPE devices when the MIB objects were set to a non-zero value.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.224 No Dial Tone After Using CLI 'tune' Command	
<i>Tracking No.</i>	PROD00104022, PROD00103893
<i>Description</i>	On rare occasion, an issue has been reported where using the 'tune' command manually via the CLI results in the MTA not having dial tone.
<i>Impact</i>	Service

<i>Occurrence</i>	Rare
2.3.225 DEA Causes Code Word Errors on QAM256	
<i>Tracking No.</i>	PROD00103968
<i>Description</i>	Approximately 10 seconds after locking onto a QAM256 downstream channel, a burst of codeword errors may be experienced due to the DEA feature.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.226 Jitter Buffer Not Working with 40 msec of Jitter	
<i>Tracking No.</i>	PROD00104821
<i>Description</i>	Injecting 40 ms of jitter into the packet flow for a voice call results in a significantly decreased MOS score when the packetization rate was 20 ms.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.227 SSH Logins Can Cause E-MTA Failure	
<i>Tracking No.</i>	PROD00106778
<i>Description</i>	On rare occasions at the end of an active Telnet/SSH debug session, the E-MTA may experience an issue that requires a hard reset of the modem to recover.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.228 WTM552 Upgrade Issue	
<i>Tracking No.</i>	PROD00106925, PROD00105431
<i>Description</i>	An issue has been identified where the Wireless Router Module (WRM) image may fail to work after an upgrade of the firmware image on the WTM552. This is a result of a corrupt image being applied to the WRM flash or failure for the flash to become active. This was presented in AFB-07-0322.
<i>Impact</i>	Service

<i>Occurrence</i>	High
2.3.229 Learned CPEs Not Returned From docsDevCpeTable MIB Object	
<i>Tracking No.</i>	PROD00112058
<i>Description</i>	A walk of the docsDevCpeTable MIB object does not provide a full list of learned CPE.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.230 E-MTA Autonomous Reset	
<i>Tracking No.</i>	PROD00112474
<i>Description</i>	An occasional E-MTA reset has been observed due to a SDRAM refresh problem.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
2.3.231 MTAs Provisioned in 'BASIC 1' Negotiating Security	
<i>Tracking No.</i>	PROD00113906
<i>Description</i>	A small number of E-MTAs provisioned with Basic 1 have been observed to continue to unnecessarily negotiate with the KDC server for security keys. This should not occur with a provisioning method of Basic 1.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
2.3.232 MTAs Reject Configuration File if DHCP Is Incorrect	
<i>Tracking No.</i>	PROD00114802
<i>Description</i>	If the MTA is using a simplified provisioning method, then the MTA will fail to configure if the DHCP option 122 sub-option 6 is set.
<i>Impact</i>	Service
<i>Occurrence</i>	High (in give configuration)

2.3.233 SingleMAC E-MTA Cannot Configure Distinctive Ringing	
<i>Tracking No.</i>	PROD00114678
<i>Description</i>	When using the 'singleMAC' provisioning method, the E-MTA does not accept ringing cadences provided in the configuration file.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.234 'Detect_tone' CLI Command Causes E-MTA Reset	
<i>Tracking No.</i>	PROD00123839
<i>Description</i>	The console command 'detect_tone 1 1' will cause the E-MTA to reset.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.235 Noise Issue on TM508/TM512 Line After Dialing	
<i>Tracking No.</i>	PROD00118015, PROD00120410
<i>Description</i>	The dialing party on the TM508/TM512 may hear a brief noise (20ms) after dialing the last digit before the other end is connected. This problem is only seen when one line is active and another call is initiated on an adjacent line.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.236 pktcNcsEndPntConfigStutterDialToneTO MIB Ignored	
<i>Tracking No.</i>	PROD00126585
<i>Description</i>	The pktcNcsEndPntConfigStutterDialToneTO MIB settings are ignored by the E-MTA and the default value of 16 seconds is used.
<i>Impact</i>	Service
<i>Occurrence</i>	High

2.3.237 E-MTA is Not Able to Register with Call Server	
<i>Tracking No.</i>	PROD00126820
<i>Description</i>	In cases where the operator's DHCP/Provisioning servers are overloaded, the E-MTA can fail to properly complete provisioning and secure communications with the call server. This is a result of the MTA sending a registration complete message prior to security provisioning completing.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.238 PHS CallFeature Switch Setting Does Not Work	
<i>Tracking No.</i>	PROD00126819
<i>Description</i>	When using the SNMP command to set the callfeature switch, it will not take affect when trying to disable PHS.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.239 SIP: E-MTA Responds to G729A CODEC	
<i>Tracking No.</i>	PROD00121333
<i>Description</i>	When E-MTA receives a request to negotiate for G729A CODEC, it accepts the request but responds with G729. This can potentially be rejected since the CODEC is not G729A.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.240 'System' MIBs Not Accessible from MTA IP Address	
<i>Tracking No.</i>	PROD00121818
<i>Description</i>	'System' MIB Group, OID 1.3.6.1.2.1.1, is only accessible from the CM IP Address.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.241 SIP: Reduced Number of Available Compressed CODECs	
<i>Tracking No.</i>	PROD00121886
<i>Description</i>	If the SIP E-MTA offers a compressed CODEC such as G729 when negotiating a call but does not use the compressed CODEC, the resources are not released. This could prevent other available compressed CODECs from working.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.242 CLI Tones Command May Not Show All Provisioned Elements of Tone	
<i>Tracking No.</i>	PROD00122310
<i>Description</i>	When using the tones command from the Callp CLI, the last elements provisioned using the IETF tone MIBs may not be shown. The tone and all its provisioned elements are played correctly when requested.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.243 Ring Cadence Limit is Four On/Off Cycles	
<i>Tracking No.</i>	PROD00122811
<i>Description</i>	When modifying the RxCadence MIBs any on/off cycles after the fourth one are dropped and not played. This can be a limitation for distinctive ringing.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.244 LAN Duplex Mode Not Displayed	
<i>Tracking No.</i>	PROD00120308
<i>Description</i>	On the status web page, the display of the interface LAN's speed is missing the duplex mode.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.245 Setting pktnCsEndPntConfigStatus Does Not Set ifAdminStatus	
<i>Tracking No.</i>	PROD00120052
<i>Description</i>	Setting the pktnCsEndPntConfigStatus to a non-active value does not set the ifAdminStatus MIB to similar non-active value.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.246 '*67' Occasionally Fails to Process Digits and Complete Call	
<i>Tracking No.</i>	PROD00121196
<i>Description</i>	If using the *67 feature against certain call agents, it is possible that the E-MTA will not be able to correctly gather the dialed digits and the call will fail. This occurs when the '7' digit is depressed for a long period of time.
<i>Impact</i>	Service
<i>Occurrence</i>	Medium
2.3.247 Display Values Incorrect After Extended Period of Time	
<i>Tracking No.</i>	PROD00116577
<i>Description</i>	The sysUptime is calculated incorrectly after 49 days and can display a large number on the webGUI. The CM DHCP and MTA DHCP time will have the same issue after 124 days. This problem is not service affecting and is only an internal display problem.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.248 Dynamic Channel Change Problems with SCDMA	
<i>Tracking No.</i>	PROD00110210
<i>Description</i>	E-MTAs, TM5XX and TM602, have issues with the Dynamic Channel Change feature when SCDMA modulation is used. When an ARRIS E-MTA, departs from an SCDMA US channel, it may fail to lock onto the new DS channel. The problem may also occur even when the destination US is not an

	SCDMA channel as long as the originating US is an SCDMA channel. In the docsDevEvText of the CM, the following text appears: "DCC aborted unable to acquire new downstream channel".
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.249 Reset Timeout Timer Not Re-started After resetMTA When Using LVM Policy 3	
<i>Tracking No.</i>	PROD00107458
<i>Description</i>	The LVM Policy 3 timer for monitoring when to remove Loop Voltage is not restarted after an MTA only reset (resetMTA), which causes the provisioned Reset Timeout value (arrisMtaDevLoopVoltageResetTimeout) to be ignored.
<i>Impact</i>	Operational
<i>Occurrence</i>	High , if using LVM Policy 3 and resetMTA
2.3.250 SIP: PRACK Authorization Not Supported	
<i>Tracking No.</i>	PROD00109506
<i>Description</i>	If a challenge is received in response to a PRACK message, the MTA will not re-send the PRACK message with the authentication header.
<i>Impact</i>	Service
<i>Occurrence</i>	Operational
2.3.251 SSH: 128 Byte Memory Leak	
<i>Tracking No.</i>	PROD00109068
<i>Description</i>	Approximately 128 bytes are lost with each successful login via SSH.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

2.3.252 SIP: Call Forwarding Setting Should Survive a Reset	
<i>Tracking No.</i>	PROD00105999
<i>Description</i>	Currently, Call Forwarding settings do not survive a reset of the E-MTA. This means that if a customer uses a star code to setup call forwarding and the E-MTA is reset, call forwarding will not occur with the next call. No fixed planned for this issue as Call Forwarding handled differently in PacketCable 2.0.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.253 Wireless Router Module DNS Client Incorrectly Running on LAN Side of Router on WTM552	
<i>Tracking No.</i>	PROD00111956
<i>Description</i>	The DNS client that downloads the WRM configuration file uses an IP address on the router's LAN subnet. When NAT is turned off, this can prevent the WRM configuration file from getting downloaded if the tftp-server-name is set as a FQDN instead of an IP address.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.254 Issuing !logout When Using NetTerm Causes E-MTA Reset	
<i>Tracking No.</i>	PROD00114377
<i>Description</i>	A load exception occurs if !logout is issued to the CLI when using the NetTerm telnet application.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.255 arrisMtaDevPwrSupplyConfigReplaceBatTime MIB Object Value May Be Incorrect After Battery Type Change	
<i>Tracking No.</i>	PROD00113726

<i>Description</i>	When using the MIB object <code>arrisMtaDevPwrSupplyConfigReplaceBatTime</code> to control the replacement time for the battery, the value can be recalculated incorrectly when the battery is replaced by a different type of battery (example: replace 4 cell with 8 cell battery), leading to incorrect replace times.
<i>Impact</i>	Operational
<i>Occurrence</i>	High, in the described scenario
2.3.256 WTM552 Wireless Router Module (WRM) Does DHCP Twice	
<i>Tracking No.</i>	PROD00115595
<i>Description</i>	The wireless router module on the WTM552 performs the DHCP sequence twice when going through provisioning.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.257 Model 5 E-MTAs Incorrectly Display “Battery Test Scheduled” Messages	
<i>Tracking No.</i>	PROD00116461
<i>Description</i>	“Battery Test Scheduled” messages should only be displayed by Model 4 E-MTAs, not Model 5 E-MTAs.
<i>Impact</i>	None
<i>Occurrence</i>	High
2.3.258 MTA Lease Time May Be Displayed Incorrectly after Renew/Rebind	
<i>Tracking No.</i>	PROD00116577
<i>Description</i>	E-MTAs have been observed in the field to have a lease time much larger than the value given during MTA DHCP renew/rebind. This is a display error and service is not impacted.
<i>Impact</i>	Service
<i>Occurrence</i>	Low

2.3.259 WTM552 WRM Web Page Access Blocked When in AP Mode	
<i>Tracking No.</i>	PROD00117317
<i>Description</i>	In AP mode, if WRM LAN IP is on a different subnet than the PC making the request for the WRM web page, then the WRM page will be unavailable.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.260 Telnet Console Active after ResetMTA Command Executed	
<i>Tracking No.</i>	PROD00117019
<i>Description</i>	Telnet sessions (using MTA IP address) that are active fail to be discontinued by the ResetMTA command.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
2.3.261 E-MTA sends MTA-25 SNMP Inform for ARRIS Basic.1 provisioning and requires acknowledgement	
<i>Tracking No.</i>	PROD00125160, PROD00125546
<i>Description</i>	The E-MTA incorrectly sends an SNMP Inform (step MTA-25) as part of the ARRIS Simplified PacketCable Provisioning Method (ARRIS Basic.1). The E-MTA requires acknowledgement of this Inform from the SNMP Entity in order for the provisioning sequence to complete. If the Inform is not acknowledged, the provisioning process stops.
<i>Impact</i>	Service
<i>Occurrence</i>	High
2.3.262 MTA Reset Causes Loop Voltage Drop	
<i>Tracking No.</i>	PROD00126318
<i>Description</i>	Regardless of the loop voltage management settings, if an MTA reset occurs from a T4, the CLI, or via firmware, the loop voltage is removed until the line interface is restored.
<i>Impact</i>	Service

<i>Occurrence</i>	Low
2.3.263 Extreme Robustness Testing Currently Under Investigation	
<i>Tracking No.</i>	See Below
<i>Description</i>	<ul style="list-style-type: none"> • PROD00102746: A single E-MTA reset with “Resetting with reason SYSLOG_DELAY.” <p>The above issue is currently under investigation as of the time of this release.</p>
<i>Impact</i>	Service
<i>Occurrence</i>	Low
2.3.264 Delay Detecting RF Cut on TM602B Using LVM Policy 4	
<i>Tracking No.</i>	PROD00109156
<i>Description</i>	On a TM602B unit using Loop Voltage Policy 4, the modem can take up to 35 seconds to detect an Upstream RF cut.
<i>Impact</i>	Operational
<i>Occurrence</i>	High, TM602B

3 Letter of Operational Considerations

The Letter of Operational Considerations is to inform operators of any system considerations for the Touchstone Firmware that may affect service, operations, or maintenance for this product release.

3.1 Operational Considerations

Listed are known Operational Considerations that have been identified during ARRIS' standard quality testing that can affect normal operation. Any additional items discovered during field deployments would be noted in future *Release Notes and Letter of Operational Consideration* or *Field Bulletins*. Unless specifically noted, it is ARRIS' intention to have all considerations resolved in future product releases.

Considerations that apply to a specific feature implementation will be designated with one of the following prefixes included in the heading:

- X-JC : Japan experimental NCS package
- EU : European Provisioning Sequence
- SIP : SIP Call Sequence
- T.38 : T.38 Feature Specific Issue
- SSH : Secure Shell
- IPv6: Internet Protocol version 6

3.1.1 WTM652/WTM552: Daylight Savings Time (DST) Setting Not Applied to WRM Portion of WTM652/WTM552	
<i>Tracking No.</i>	PROD00153267
<i>Description</i>	Currently the E-MTA gets the correct time offset of -14400 in the DHCP Option during DST changes. However, the WRM portion is one hour behind even if in "Systems Settings" under the "Wireless Router" tab, the time zone is correctly set to "Eastern US GMT-5" Time Zone AND the "Automatically Adjust Daylight Saving" box is checked. DST setting seems to be ignored by WRM.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
<i>Workaround</i>	None

3.1.2 TM508/TM512 Reports "unknown" as a State in the upsBatteryStatus MIB

<i>Tracking No.</i>	PROD00152821
<i>Description</i>	Currently, the TM508/TM512 reports a state of 'unknown' for the 'upsBatteryStatus' MIB.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	None

3.1.3 CODEC Negotiation Failure with G.729AB

<i>Tracking No.</i>	PROD00152157
<i>Description</i>	The E-MTA is reporting Codec Negotiation Failure when it receives a CRCX containing G.729AB.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	The use of G729 does not have any issues.

3.1.4 ifAdminStatus.16 Change from Down to Up Causes MTA Provisioning Issue

<i>Tracking No.</i>	PROD00151824
<i>Description</i>	When an MTA is originally set down using the ifAdminStatus.16 MIB, the MTA will not get provisioned if the MTA status is changed back to up.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	Reset the E-MTA after changing the ifAdminStatus.

3.1.5 E-MTAs Getting Into Sysbusy Due to DSP Failure

<i>Tracking No.</i>	PROD00148576
---------------------	--------------

<i>Description</i>	E-MTAs found to be in “Endpoint Not Ready” state when audited and in “Sysbusy” state at the switch, which appears to be related to DSP failures.
<i>Impact</i>	Service
<i>Occurrence</i>	Low
<i>Workaround</i>	Reset the E-MTA

3.1.6 E-MTAs Passing Ethernet Traffic with IfAdminStatus.1 DOWN

<i>Tracking No.</i>	PROD00150527
<i>Description</i>	Some E-MTAs are reported to be passing traffic via the Ethernet port even if the latter has been disabled via IfAdminStatus.1 in the CM config file. Issue seems to be happening only on certain CPEs.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
<i>Workaround</i>	None

3.1.7 Extreme Robustness Testing Currently Under Investigation

<i>Tracking No.</i>	See Below
<i>Description</i>	<ul style="list-style-type: none"> • PROD00150227 Tlb load exception found during registration when an RF cut occurs. • PROD00147571 Watchdog reset found during registration when an RF cut occurs.
<i>Impact</i>	Operational
<i>Occurrence</i>	Rare
<i>Workaround</i>	None

3.1.8 arrisMtaDevPwrSupplyOverTempAlarmControl MIB Walk Displays Invalid Value

<i>Tracking No.</i>	PROD00151287
<i>Description</i>	MIB walk of arrisMtaDevPwrSupplyOverTempAlarmControl should return either disable(0), enable(1), pendingenable(2), or pendingdisable(3) but for TM402, TM508 and TM512 returns a negative value which is invalid.

<i>Impact</i>	Operational
<i>Occurrence</i>	Low
<i>Workaround</i>	None
3.1.9 arrisMtaDevBatteryEprom MIB Walk Displays Invalid Value	
<i>Tracking No.</i>	PROD00151290
<i>Description</i>	MIB walk of arrisMtaDevBatteryEprom returns incorrect string.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
<i>Workaround</i>	None
3.1.10 SNMP MIB Object pktcSigDefCallSigDscp Issue	
<i>Tracking No.</i>	PROD00148979
<i>Description</i>	The SNMP MIB object, pktcSigDefCallSigDscp, does not work when set via SNMP. Using this MIB object in the configuration file works as expected.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	Use SNMP MIB in configuration file.
3.1.11 MDD Override Feature	
<i>Tracking No.</i>	PROD00148619, PROD00148552
<i>Description</i>	When using the MDD Override MIB, if this MIB is set to 'ignore' in the configuration file the E-MTA will record this setting in flash but fail to reset. This could result in the E-MTA maintaining the incorrect IP address.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	Reset the E-MTA

3.1.12 Remote VOIP Metrics Record Not Generated	
<i>Tracking No.</i>	PROD00147051
<i>Description</i>	When the arrisDevMtaVqmEnableRemote SNMP MIB Object is set to '0', no remote VOIP metrics data is generated in the delete connections.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	Set the arrisDevMtaVqmEnableRemote MIB to '2'.
3.1.13 TM402 Returns Invalid Value for Some Battery MIBs	
<i>Tracking No.</i>	PROD00147315
<i>Description</i>	<p>The TM402 may report invalid information for the following MIBs:</p> <ul style="list-style-type: none"> • upsEstimatedMinutesRemaining • upsEstimatedChargeRemaining <p>All of the TM402s reported either 310 or 409 minutes when fully charged.</p>
<i>Impact</i>	Operational
<i>Occurrence</i>	Low
<i>Workaround</i>	None
3.1.14 EXCLUDE Statements in MIB File Causes Compatibility Issues with Incognito	
<i>Tracking No.</i>	PROD00148243
<i>Description</i>	<p>The following MIB objects include EXCLUDE statements and cause an incompatibility issue when an attempt is made to load the files into Incognito.</p> <ul style="list-style-type: none"> • pkcSigDevToneTable • pkcSigDevMultiFreqToneTable • pkcSigDevToneFreqRepeatCount
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	Customer should remove the EXCLUDE statement from MIB objects prior to importing the MIBs into Incognito.

3.1.15 WTM652: Battery Ordering Code Incorrect Displayed on WebGUI	
<i>Tracking No.</i>	PROD00145275
<i>Description</i>	The WTM652G does not display the correct battery ordering code on the WebGUI. The order number is displayed as "Ordering Code Unavailable: 13".
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	The SNMP MIB object, arrisMtaDevBatteryOrderingCode, displays the correct information.
3.1.16 IPV6: E-MTA Does Not Work Properly with the IP Filters	
<i>Tracking No.</i>	PROD00145097
<i>Description</i>	When operating in IPV6 mode, the IP filters in the configuration file are not properly applied to the packets.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	None
3.1.17 IPV6: E-MTA Reboots When Configuring Incorrect DS Frequency	
<i>Tracking No.</i>	PROD00145096
<i>Description</i>	When an incorrect frequency is configured in the CM configuration file in IPV6 mode, the E-MTA will reboot instead of starting DS scanning again.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	Remove DS Frequency from configuration file.
3.1.18 WTM Client IP Filters Do Not Work	
<i>Tracking No.</i>	PROD00145088

<i>Description</i>	Client IP Filters when set via the GUI \ Wireless Router \ Firewall settings do not block traffic or work as specified when attempting to block based on the date and time.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	Setup filters to always be applied to the WTM.
3.1.19 IPV6: Bridging of Data Packets Does Not Work	
<i>Tracking No.</i>	PROD144881
<i>Description</i>	The ability to support the bridging of IPV6 packets from the CM to the CPE devices does not work.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	None
3.1.20 IPV6: Extended MTA Recovery Time	
<i>Tracking No.</i>	PROD00144766
<i>Description</i>	When several E-MTA resets occur in succession, the MTA takes longer to recover when the CM is using an IPV6 address. The MTA recovery time is extended by approximately 2 minutes.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	None
3.1.21 SIP: MWI Fails to Deactivate on G.729	
<i>Tracking No.</i>	PROD00144050
<i>Description</i>	When SIP Application uses G.729, the Message Waiting Indicator (MWI) will not deactivate even after SIP Notify message to cancel MWI is sent to the modem following message retrieval.
<i>Impact</i>	Operational
<i>Occurrence</i>	High

<i>Workaround</i>	None
3.1.22 Rare E-MTA Reset May Be Observed When Calling Specific PSTN	
<i>Tracking No.</i>	PROD00144426
<i>Description</i>	When calling between two PSTN networks through a SIP trunk, a rare condition has been observed where the E-MTA may reset and drop the call.
<i>Impact</i>	Service
<i>Occurrence</i>	Rare
<i>Workaround</i>	None
3.1.23 CM MIB Walk Omits WRM MIBS	
<i>Tracking No.</i>	PROD00143828
<i>Description</i>	When performing an SNMP MIB walk with the CM IP address, the walk will omit WRM MIBs if the SNMP MIB walk starts with a CM MIB.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	Walk the WRM MIB Objects separately from CM MIB Objects.
3.1.24 PacketACE Installation on Newer Windows Platforms May Fail	
<i>Tracking No.</i>	PROD00143292
<i>Description</i>	PacketACE installations on newer Window's Operating systems such as Windows Vista and Windows 7 (Beta) may experience a failure. This is the result of a security check in these new operating systems around User Account Control (UAC) that Window's has enabled. This will result in the PacketACE license key being needed each time the tool is utilized.
<i>Impact</i>	Operational
<i>Occurrence</i>	Low

<i>Workaround</i>	Disable UAC in newer Window's Platforms.
3.1.25 Some PacketCable 1.5 Battery MIBs Not Supported	
<i>Tracking No.</i>	PROD00140852
<i>Description</i>	The upsAlarmAwaitingPower, upsAlarmOutputOffAsrequired, and upsAlarmShutdownPending are required to be implemented in PacketCable 1.5. These MIBs are currently not supported by the firmware.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	None
3.1.26 IPv6: Duplicate Address Detection (DAD) is not functioning properly	
<i>Tracking No.</i>	PROD00139690
<i>Description</i>	When CM is using IPv6 mode, the Duplicate Address Detection capability does not correctly detect cases of duplicate addresses.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	Manually validate addresses are unique.
3.1.27 SIP: SRV Penalty Box Does Not Use Sixth Entry	
<i>Tracking No.</i>	PROD00138093
<i>Description</i>	With the SRV penalty box full (5 entries in the penalty box), the sixth SRV record is never tried.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	None
3.1.28 IPv6: arrisCmDevDhcpNoSvcImpact MIB Object Not Supported	
<i>Tracking No.</i>	PROD00114299

<i>Description</i>	The arrisCmDevDhcpNoSvcImpact MIB object currently supported for IPv4 currently does not work for IPv6. This feature enables functionality to not perform a DHCP renewal during an active call.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	None
3.1.29 PacketACE Issue with sipProvisionedCodecsArray MIB Object	
<i>Tracking No.</i>	PROD00132125
<i>Description</i>	PacketACE incorrectly places a space in the sipProvisionedCodecsArray MIB object. A space is incorrectly inserted after the semicolon delimiter.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	Use of another Configuration File Editor.
3.1.30 Web Page Provisioning Method Incomplete	
<i>Tracking No.</i>	PROD00134993
<i>Description</i>	If using one of the standard PC1.5 Provisioning Flows, then the value for the Provisioning Method on the DHCP web page will be incomplete.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	Walk the SNMP MIB object arrisMtaDevPacketcableProvisioningFlow.
3.1.31 IPv6: Unable to recover if CMTS Neighbor Solicit Interval is too long	
<i>Tracking No.</i>	PROD00133332
<i>Description</i>	The E-MTAs are unable to recover if the Neighbor Solicit (NS) interval on the associated CMTS is set too high (i.e., 30 seconds).

<i>Impact</i>	Service
<i>Occurrence</i>	Low
<i>Workaround</i>	Set the interval to less than 7 seconds. The default value is 1 second.
3.1.32 Voice Quality Metrics Inaccuracies on Short Duration Calls and with Gap and Burst Metrics	
<i>Tracking No.</i>	PROD00111959, PROD00111960, PROD00112034, PROD00112128, PROD00112310, PROD00112465
<i>Description</i>	The eMTA is reporting inaccurate gap and burst measurements results on short duration calls (i.e., under 10-seconds) . There are also inaccuracies in VQM on short duration (i.e., under 10-second) calls.
<i>Impact</i>	Operational
<i>Occurrence</i>	High
<i>Workaround</i>	None
3.1.33 SIP: Appending Too Many Authentication Headers Causes Load Exception Error	
<i>Tracking No.</i>	PROD00116409
<i>Description</i>	When a request (INVITE/SUBSCRIBE/REGISTER) message is sent to the proxy and responded to by a 401/407 message, a new authorization is added to that request transaction. If multiple 401/407 messages are received, the list of authorization headers grows. If too many authorization headers are added an exception may occur.
<i>Impact</i>	Service
<i>Occurrence</i>	High, in described scenario
<i>Workaround</i>	None
3.1.34 NVM Data Corruption Prevents E-MTAs from Upgrading	
<i>Tracking No.</i>	PROD00111555
<i>Description</i>	Mfg Code and Mfg CVC Access Start Times get corrupted with a time that is after the firmware image signing time. Affected E-MTAs are not able to upgrade.
<i>Impact</i>	Operational

<i>Occurrence</i>	Low
<i>Workaround</i>	None
3.1.35 Calls May Fail to Setup When a=X-pc-codec Parameter Received in SDP	
<i>Tracking No.</i>	PROD00110381
<i>Description</i>	When receiving a CRCX or MDCX NCS message containing SDP with parameter a= X-pc-codec, the message is rejected with reason 510 Protocol Error. This will cause a call to fail setup.
<i>Impact</i>	Service
<i>Occurrence</i>	High
<i>Workaround</i>	None
3.1.36 Duplicate Information in Local Connection Options (LCO) Allowed for RTCP-XR and T.38	
<i>Tracking No.</i>	PROD00107856
<i>Description</i>	The RTCP-XR and T.38 CallP features should return error code 534 (Inconsistent LCO) if duplicate information is found in the Local Connection Options (LCO) of a CRCX or MDCX message.
<i>Impact</i>	Compliance Only
<i>Occurrence</i>	Low
<i>Workaround</i>	None

3.2 Upgrade Considerations

The following considerations are important to take into account when upgrading to this firmware release.

Automatic OSI Feature Switch Update

Starting TS 6.1.60, if the feature is enabled by including the `arrisMtaCallpFeatureSwitch` MIB object with a bit value of `0x20000000`, OSI will now only be applied to the terminating lines. If the feature is active, and a line originates a call, OSI will not be applied to the originating line if call is completed and line remains offhook.

Default Changes to D11Plus Load Build Variant

A few changes have been made in this release to the default behaviour of the D11PLUS load build variant. The changes are detailed below:

- The NVM value of the hardware revision for TM602G Phase 2 products will be incremented by 50 for the `sysDescr` hardware field. This will allow the TM602G Phase 2 units to be differentiated from the Phase 1 models. For example, a TM602G Phase 2 with a hardware revision of 4 will display the below in the `sysDescr` field.

```
ARRIS DOCSIS 2.0 / PacketCable 1.0 Touchstone  
Telephony Modem <<HW_REV: 54;
```

- PROD00146689: The `arrisMtaDevLoopVoltageResetTimeout` will be multiplied by a value of 3. This is a result of the configuration download taking slightly longer in TS 6.1 resulting in a possible drop of loop voltage during a reset. This multiply will allow the same configuration file setting while increasing the timeout value to allow recovery of the E-MTA from a reset.
- PROD00146884: During the DHCP Renew/Rebind process, if the SNMP entity changes the E-MTA will not take action until all lines are on-hook. This allows an SNMP entity change to not be service affecting.
- PROD00146893: The SDP has been modified to remove static payload types (PCMU, PCMA, G728, G729, etc.) from the `rtpmap` attributes of the SDP.

CM550 Upgrade to TS 6.1

If a Cable Modem (CM) is running a TS 6.1 release prior to the RTM load (TS 6.1.47), the CM must first be downgraded to an earlier release such as CM 6.0.15 and then upgraded to the TS 6.1 RTM release. This problem is caused by the size of the CM firmware load prior to the RTM release.

DOCSIS 2.0 Advertisement

For this release, all E-MTAs will advertise as DOCSIS 2.0 after upgrading to TS6.1 release. This is not service affecting if the customers network supports DOCSIS 2.0 but customers who have networks that do not support DOCSIS 2.0 may see issues.

Deprecated Feature Switch

The enableIpv6Multicast feature switch in the arrisCmDevModemFeatureSwitch is no longer needed. This feature switch has been reclaimed for future use and should not be used in a configuration file.

Firmware Load Change for Hardware Variant

In releases prior to TS6.1, a firmware image for support of the Touchstone Telephony Models 4, 5, and 6 existed. For this release, the firmware image has been broken up to support the Model 4 and Model 5 release and a second image to support the Model 6 release. The Multi-line image for the TM508 and TM512 has also been renamed as well as the WTM images. Please refer to the load extension table in section 1 to understand which firmware load goes with each hardware variant.

4 Customer Service and Support

For Technical Support, please visit the ARRIS Technical Support web page at <http://ask.arris.com>.

Other methods for contacting the support organization are listed below.

North America

Email techsupport.na@arris.com
Telephone (888) 221 9797 (US toll free)
+1 678 473 5656 (Worldwide)
Office Hours 8:00 a.m. to 8:00 p.m. EST

South America – Chile

Email techsupport.cala@arris.com
Telephone +56 2 678 4500
Office Hours 9:00 a.m. to 6:00 p.m. (Chile local time).

Europe – Amsterdam, The Netherlands

Email techsupport.europe@arris.com
Telephone +31 20 311 2525
Office Hours 8:30 a.m. to 17:30 p.m. CET

Japan – Tokyo

Email techsupport.japan@arris.com
Telephone +81 (0) 3 5371 4142
Office Hours 9:30 a.m. to 6:00 p.m. (Tokyo local time)

Asia – Tokyo, Japan

Email techsupport.asia@arris.com
Telephone +81 (0) 3 5371 4142
Office Hours 9:30 a.m. to 6:00 p.m. (Tokyo local time)

Korea – Seoul

Email techsupport.asia@arris.com
Telephone +82 2 6007 2880
Office Hours 9:30 a.m. to 6:00 p.m. (local time)

Worldwide – North America

Email techsupport@arris.com
Telephone USA +1 678 473 5656

Emergency support is available after normal business hours for customers with a support contract ID via the listed contact information.

Appendix A: Compliance Matrix

DOCSIS 1.1/2.0	CW53 ECNs
SP-BPI+	I12
SP-CMCI	I10
SP-RFIv2.0	I11
SP-OSSIv2.0	I10
SP-eDOCSIS	I13
PacketCable 1.0	CW28 ECNs
PKT-SP-DQOS	I12
PKT-SP-CODEC	I06
PKT-SP-EC-MGCP	I11
PKT-SP-MIBS	I10
PKT-SP-MIB-SIG	I09
PKT-SP-PROV	I11
PKT-SP-SEC	I12

Touchstone[®] Telephony Firmware

Release 6.1.95

Release Notes and Letter of Operational Consideration

Copyright ©2010 ARRIS International, Inc.
All rights reserved

The information disclosed herein is proprietary to ARRIS, Inc and is not to be used by or disclosed to unauthorized persons without written consent of Arris, Inc. The recipient of this document shall respect the security status of the information.

Version: 1.0
Status: Released