

Network Manager

Release Notes v4.4.0.0 Fix 33

Introduction

This document defines the changes made to the Network Manager product for fix release v4.4.0.0 Fix 33 and is specifically targeted at end users.

After reading through this document, should you have any further training or consultancy requirements then please contact your **exor** account manager.

Fix Details

Baseline Release	4.4.0.0
Fix Description	use of snapping tools onto route shapes from locator give wrong unit translation
Prerequisites	
Implementation Instructions	<p>Unzip nm_4400_fix33.zip to a staging folder.</p> <p>Log onto SQL*PLUS as the Highways Owner with the staging folder as the working directory.</p> <p>At the prompt type "START nm_4400_fix33.sql" and press return.</p> <p>Exit SQL*PLUS.</p>
Limitations	None known
Configuration Information	None
How To Test	Recommend full regression test
Rollback Strategy	Initially implement on a test environment

List of Amended Files

Filename	Version
nm3sdo.pkw	2.56.1.13

Log No. Summary

This chapter summarises all software changes that have been made in this release.

These changes are derived from the following sources,

- Issues raised by Customers via Bentley Support
- Issues raised internally by Bentley

Issues

Internal Task ID	Issue	Support Log(s)
0112188	LRM tool on the MapViewer applet in locator uses server code which incorrcetly translates measures to the route units despite the snapping being made directly to a route shape. Unit translation has been removed from the server code but there remains a 2DP rounding from within the applet. This will not be appropriate for some customer data.	8001446309