

2015 Audi A4 Sedan (8K2) L4-2.0L Turbo (CAED)

Vehículo > Sensores e interruptores > Sensores e interruptores - Panel de instrumentos > Sensor de desgaste de pastillas de freno > Boletines de servicio técnico

FRENOS - INDICADOR DE DESGASTE DE PASTILLAS DE FRENO ENCENDIDO, PASTILLAS POR ENCIMA DEL LÍMITE DE DESGASTE

46 Advertencia de desgaste de pastillas de freno - pastillas no al mínimo

46 15 05

2038056/2

19 de febrero de 2015

Reemplaza el Boletín de servicio técnico Grupo 46 número 14-94 de fecha 11 de agosto de 2014 por las razones que se enumeran a continuación. Información del vehículo Estado Antecedentes técnicos La entrada de agua en la carcasa del conector del indicador de desgaste de las pastillas de freno puede provocar la oxidación de las clavijas. Esta oxidación puede aumentar la resistencia de contacto en el conector, lo que puede generar la advertencia Solución de producción No aplicable. Servicio 1. Desconecte el conector eléctrico del indicador de desgaste de las pastillas de freno (en el arnés). Use VAS 1978 B para quitar ambas clavijas del conector lateral del arnés. 2. Si hay corrosión presente en las clavijas (depósitos negros) (Figura 1), reemplace el indicador de desgaste de las pastillas de freno afectado y el arnés de cableado para el sensor de velocidad y el indicador de desgaste de las pastillas de freno (consulte ETKA). Garantía Información adicional Todas las piezas y referencias de servicio proporcionadas en este TSB (2038056) están sujetas a cambios y/o eliminación. Consulte siempre el departamento de repuestos y los manuales de servicio para obtener la información más reciente.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5, A5 Cabriolet	2010 - 2016	All	Not Applicable
Q5	2010 - 2016	All	Not Applicable
A8	2011 - 2016	All	Not Applicable
A6, A7	2012 - 2016	All	Not Applicable

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header data (Added model year) Revised <i>Warranty</i> (Changed Service Number; Added Labor Operations for rear indicators and harness replacement)
1	08/11/2014	Initial publication

The brake pad wear indicator comes on, but brake pad thickness is above the wear limit.




Figure 1. Corrosion (black deposits) on connector pins.

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4639		
Damage Code:	0040		
Labor Operations:	1 Front brake pad wear indicator replace	4639 1999	30 TU
	2 Front brake pad wear indicators replace (Only applicable to A8 models if both front brake pad wear indicators are damaged).	4639 2099	50 TU
	1 Rear brake pad wear indicator replace	4639 2999	30 TU
	2 Rear brake pad wear indicators replace (Only applicable to A8 models if both rear brake pad wear indicators are damaged).	4639 3099	50 TU
	Harness replacement - See Elsa	See Elsa	See Elsa
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2038056/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.