

MSP430G2x53, MSP430G2x33, MSP430G2x13, MSP430G2x03 Device Erratasheet

1 Current Version

See [Appendix A](#) for prior silicon revisions.

✓ The checkmark indicates that the issue is present in the specified revision

Device	Rev:	BCL12	CPU4	EEM20	SYS15	TA12	TA16	TA22	USCI20	USCI22	USCI23	USCI24	USCI25	USCI26	USCI29	USCI30	XOSC5
MSP430G2113	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2153	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2203	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2213	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2233	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2253	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2303	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2313	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2333	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2353	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2403	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2413	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2433	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2453	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2513	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2533	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430G2553	A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

2 Package Markings

N20


PDIP (N), 20 Pin



YM = Year and Month Date Code
 LLLL = LOT Trace Code
 S = Assembly Site Code
 # = DIE Revision

PW20


TSSOP (PW), 20 Pin



YM = Year and Month Date Code
 LLLL = LOT Trace Code
 S = Assembly Site Code
 # = DIE Revision
 o = PIN 1

PW28


TSSOP (PW), 28 Pin



YM = Year and Month Date Code
 LLLL = LOT Trace Code
 S = Assembly Site Code
 # = DIE Revision
 o = PIN 1

RHB32

QFN (RHB), 32 Pin



YM = Year and Month Date Code
 LLLL = LOT Trace Code
 S = Assembly Site Code
 # = DIE Revision
 o = PIN 1

3 Detailed Bug Description

BCL12 *Basic Clock Module*

Function Switching RSEL can cause DCO dead time

Description After switching RSELx bits (located in register BCSCCTL1) from a value of >13 to a value of <12 OR from a value of <12 to a value of >13, the resulting clock delivered by the DCO can stop before the new clock frequency is applied. This dead time is approximately 20 μ s. In some instances, the DCO may completely stop, requiring a power cycle.

Workaround

- When switching RSEL from >13 to <12, use an intermediate frequency step. The intermediate RSEL value should be 13.

CURRENT RSEL	TARGET RSEL	RECOMMENDED TRANSITION SEQUENCE
15	14	Switch directly to target RSEL
14 or 15	13	Switch directly to target RSEL
14 or 15	0 to 12	Switch to 13 first, and then to target RSEL (two step sequence)
0 to 13	0 to 12	Switch directly to target RSEL

- When switching RSEL from <12 to >13, ensure that the maximum system frequency is not exceeded during the transition. This can be achieved by clearing the DCO bits first (DCOCTL control register, bits 7–5), then increasing the RSEL value, and finally applying the target frequency DCO bit values. For more details, see the examples in the "TLV Structure" chapter in the *MSP430F2xx Family User's Guide* ([SLAU144](#)).

CPU4 *CPU Module*

Function PUSH #4, PUSH #8

Description The single operand instruction PUSH cannot use the internal constants (CG) 4 and 8. The other internal constants (0, 1, 2, –1) can be used. The number of clock cycles is different:

PUSH #CG uses address mode 00, requiring 3 cycles, 1-word instruction
PUSH #4/#8 uses address mode 11, requiring 5 cycles, 2-word instruction

Workaround Workaround implemented in assembler. No fix planned.

EEM20 *Enhanced Emulation Module*

Function Debugger might clear interrupt flags

Description During debugging, read-sensitive interrupt flags might be cleared as soon as the debugger stops. This is valid in both single-stepping and free-run modes.

Workaround None

SYS15	System Module
Function	LPM3 and LPM4 currents exceed specified limits
Description	LPM3 and LPM4 currents may exceed specified limits if the SMCLK source is switched from DCO to VLO or LFXT1 just before the instruction to enter LPM3 or LPM4 mode.
Workaround	After clock switching, a delay of at least four new clock cycles (VLO or LFXT1) must be implemented to complete the clock synchronization before going into LPM3 or LPM4.
TA12	Timer_A Module
Function	Interrupt is lost (slow ACLK)
Description	<p>Timer_A counter is running with slow clock (external TACLK or ACLK) compared to MCLK. The compare mode is selected for the capture/compare channel and the CCRx register is incremented by one with the occurring compare interrupt (if TAR = CCRx).</p> <p>Due to the fast MCLK, the CCRx register increment (CCRx = CCRx + 1) happens before the Timer_A counter has incremented again. Therefore, the next compare interrupt should happen at once with the next Timer_A counter increment (if TAR = CCRx + 1). This interrupt is lost.</p>
Workaround	Switch capture/compare mode to capture mode before the CCRx register increment. Switch back to compare mode afterward.
TA16	Timer_A Module
Function	First increment of TAR erroneous when IDx > 00
Description	The first increment of TAR after any timer clear event (POR/TACLR) happens immediately following the first positive edge of the selected clock source (INCLK, SMCLK, ACLK, or TACLK). This is independent of the clock input divider settings (ID0, ID1). All following TAR increments are performed correctly with the selected IDx settings.
Workaround	None
TA22	Timer_A Module
Function	Timer_A register modification after watchdog timer PUC
Description	Unwanted modification of the Timer_A registers TACTL and TAIV can occur when a PUC is generated by the watchdog timer (WDT) in watchdog mode and any Timer_A counter register TACCRx is incremented/decremented (Timer_A does not need to be running).
Workaround	Initialize TACTL register after the reset occurs using a MOV instruction (BIS or BIC may not fully initialize the register). TAIV is automatically cleared following this initialization.
Example	<pre>MOV.W #VAL, &TACTL</pre> <p>Where VAL = 0, if Timer is not used in application; otherwise, user defined per desired function.</p>

USCI20	<i>USCI Module</i>
Function	I ² C mode multi-master transmitter issue
Description	<p>When configured for I²C master-transmitter mode and used in a multi-master environment, the USCI module can cause unpredictable bus behavior if all of the following conditions are true:</p> <ol style="list-style-type: none"> 1. Two masters are generating SCL. and 2. The slave is stretching the SCL low phase of an ACK period while outputting NACK on SDA. and 3. The slave drives ACK on SDA after the USCI has already released SCL, and then the SCL bus line is released. and 4. The transmit buffer has not been loaded before the other master continues communication by driving SCL low. <p>The USCI remains in the SCL high phase until the transmit buffer is written. After the transmit buffer has been written, the USCI interferes with the current bus activity and may cause unpredictable bus behavior.</p>
Workaround	<ul style="list-style-type: none"> • Ensure that slave does not stretch the SCL low phase of an ACK period. or • Ensure that the transmit buffer is loaded in time. or • Do not use the multi-master transmitter mode.
USCI22	<i>USCI Module</i>
Function	I ² C master receiver with 10-bit slave addressing
Description	<p>Unexpected behavior of the USCI_B can occur when configured in I²C master receive mode with 10-bit slave addressing under the following conditions:</p> <ol style="list-style-type: none"> 1. The USCI sends first byte of slave address, the slave sends an ACK and when second address byte is sent, the slave sends a NACK. 2. Master sends a repeat start condition (if UCTXSTT = 1). 3. The first address byte following the repeated start is acknowledged. <p>However, the second address byte is not sent; instead, the master incorrectly starts to receive data and sets UCBxRXIFG = 1.</p>
Workaround	Do not use a repeated start condition; instead, set the stop condition UCTXSTP = 1 in the NACK ISR prior to the following start condition (USTXSTT = 1).

USCI23	<i>USCI Module</i>
Function	UART transmit mode with automatic baud rate detection
Description	Erroneous behavior of the USCI_A can occur when configured in UART transmit mode with automatic baud rate detection. During transmission if a "Transmit break" is initiated (UCTXBRK = 1), the USCI_A does not deliver a stop bit of logic high; instead, it sends a logic low during the subsequent synch period.
Workaround	<ul style="list-style-type: none"> Follow user's guide instructions for transmitting a break/synch field following UCSWRST = 1. or Set UCTXBRK = 1 before an active transmission; that is, check for bit UCBUSY = 0 and then set UCTXBRK = 1.
USCI24	<i>USCI Module</i>
Function	Incorrect baud rate information during UART automatic baud rate detection mode
Description	Erroneous behavior of the USCI_A can occur when configured in UART mode with automatic baud rate detection. After automatic baud rate measurement is complete, the UART updates UCAxBR0 and UCAxBR1. Under oversampling mode (UCOS16 = 1), for baud rates that should result in UCAxBRx = 0x0002, the UART incorrectly reports it as UCAxBRx = 0x5555.
Workaround	When break/synch is detected following the automatic baud rate detection, the flag UCBRK flag is set to 1. Check if UCAxBRx = 0x5555 and correct it to 0x0002.
USCI25	<i>USCI Module</i>
Function	TXIFG is not reset when NACK is received in I ² C mode
Description	When the USCI_B module is configured as an I ² C master transmitter, the TXIFG is not reset after a NACK is received if the master is configured to send a restart (UCTXSTT = 1 and UCTXSTP = 0).
Workaround	Reset TXIFG in software within the NACKIFG interrupt service routine.
USCI26	<i>USCI Module</i>
Function	t _{buf} parameter violation in I ² C multi-master mode
Description	In multi-master I ² C systems, the timing parameter t _{buf} (bus free time between a stop condition and the following start) is not ensured to match the I ² C specification of 4.7 μs in standard mode and 1.3 μs in fast mode. If the UCTXSTT bit is set during a running I ² C transaction, the USCI module waits and issues the start condition on bus release, causing the violation to occur.
	<hr/> <p>NOTE: It is recommended to check if UCBBUSY bit is cleared before setting UCTXSTT = 1.</p> <hr/>
Workaround	None

USCI29

USCI Module

Function

Timing of USCI I2C interrupts may result in call to a reserved ISR location

Description

When certain USCI I2C interrupt flags (IFG) are set and an automatic flag-clearing event on the I2C bus occurs, the device makes a call to the TRAPINT interrupt vector. This happens only if the IFG is cleared within a critical time window (~6 CPU clock cycles) after a USCI interrupt request occurs and before the interrupt servicing is initiated. The affected interrupts are UCBxTXIFG, UCSTPIFG, UCSTTIFG, and UCNACKIFG.

The automatic flag-clearing scenarios are described in the following situations:

- A pending UCBxTXIFG interrupt request is cleared on the falling SCL clock edge following a NACK.
- A pending UCSTPIFG, UCSTTIFG, or UCNACKIFG interrupt request is cleared by a following Start condition.

Workaround

1. Define an ISR for the reserved interrupt vector at location 0xFFE0 containing an RETI instruction. If the failure condition occurs; a call to the reserved ISR is made following which the device returns to the application code and continues execution.

Sample code for ISR definition:

```
; Dummy ISR
;-----

IntSR07 ; ISR call at 0xFFE0h
      reti ; return to application
;-----
```

2. Poll the affected flags instead of enabling the interrupts.

USCI30
USCI Module
Function

I2C mode master receiver / slave receiver

Description

The USCI I2C module, when configured as a receiver (master or slave), performs a double-buffered receive operation. For example, in a transaction of two bytes, after the first byte is moved from the receive shift register to the receive buffer, the byte is acknowledged and the state machine allows the reception of the next byte.

If the receive buffer has not been cleared of its contents by reading the UCBxRXBUF register by the time the seventh bit of the following data byte is received, an error condition may occur on the I2C bus. Depending on the USCI configuration, the following may occur:

- If the USCI is configured as an I2C master receiver, an unintentional repeated start condition can be triggered or the master can switch into an idle state (I2C communication aborted). The reception of the current data byte is not successful in this case.
- If the USCI is configured as I2C slave receiver, the slave can switch to an idle state, stalling I2C communication. The reception of the current data byte is not successful in this case. The USCI I2C state machine notifies the master of the aborted reception with a NACK.

Note that the error condition described above occurs only within a limited window of the seventh bit of the current byte being received. If the receive buffer is read outside of this window (before or after), then the error condition does not occur.

Workaround

The error condition can be avoided by servicing the UCBxRXIFG in a timely manner. This can be done by (a) servicing the interrupt and ensuring UCBxRXBUF is read promptly or (b) using the DMA to automatically read bytes from receive buffer upon UCBxRXIFG being set.

OR

If the receive buffer cannot be read out in time, test the I2C clock line before the UCBxRXBUF is read out to ensure that the critical window has elapsed. This is done by checking if the clock line low status indicator bit UCSCLOW is set for at least three USCI bit clock cycles; that is, $3 \times t_{\text{BitClock}}$.

NOTE: The last byte of the transaction must be read directly from UCBxRXBUF. For all other bytes, follow the workaround.

Code flow for workaround:

1. Enter RX ISR for reading receiving bytes
2. Check if UCSCLOW.UCBxSTAT == 1
3. If no, repeat step 2 until set.
4. If yes, repeat step 2 for a time period $> 3 \times t_{\text{BitClock}}$, where $t_{\text{BitClock}} = 1/f_{\text{BitClock}}$
5. If window of $3 \times t_{\text{BitClock}}$ cycles has elapsed, it is safe to read UCBxRXBUF.

XOSC5***LFXT1 Module***

Function

LF crystal failures may not be properly detected by the oscillator fault circuitry

Description

The oscillator fault error detection of the LFXT1 oscillator in low-frequency mode (XTS = 0) may not work reliably, causing a failing crystal to go undetected by the CPU; that is, OFIFG is not set.

Workaround

None

Appendix A Prior Revisions

None

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of TI information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation. Information of third parties may be subject to additional restrictions.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

TI products are not authorized for use in safety-critical applications (such as life support) where a failure of the TI product would reasonably be expected to cause severe personal injury or death, unless officers of the parties have executed an agreement specifically governing such use. Buyers represent that they have all necessary expertise in the safety and regulatory ramifications of their applications, and acknowledge and agree that they are solely responsible for all legal, regulatory and safety-related requirements concerning their products and any use of TI products in such safety-critical applications, notwithstanding any applications-related information or support that may be provided by TI. Further, Buyers must fully indemnify TI and its representatives against any damages arising out of the use of TI products in such safety-critical applications.

TI products are neither designed nor intended for use in military/aerospace applications or environments unless the TI products are specifically designated by TI as military-grade or "enhanced plastic." Only products designated by TI as military-grade meet military specifications. Buyers acknowledge and agree that any such use of TI products which TI has not designated as military-grade is solely at the Buyer's risk, and that they are solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI products are neither designed nor intended for use in automotive applications or environments unless the specific TI products are designated by TI as compliant with ISO/TS 16949 requirements. Buyers acknowledge and agree that, if they use any non-designated products in automotive applications, TI will not be responsible for any failure to meet such requirements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products

Audio	www.ti.com/audio
Amplifiers	amplifier.ti.com
Data Converters	dataconverter.ti.com
DLP® Products	www.dlp.com
DSP	dsp.ti.com
Clocks and Timers	www.ti.com/clocks
Interface	interface.ti.com
Logic	logic.ti.com
Power Mgmt	power.ti.com
Microcontrollers	microcontroller.ti.com
RFID	www.ti-rfid.com
RF/IF and ZigBee® Solutions	www.ti.com/lprf

Applications

Communications and Telecom	www.ti.com/communications
Computers and Peripherals	www.ti.com/computers
Consumer Electronics	www.ti.com/consumer-apps
Energy and Lighting	www.ti.com/energy
Industrial	www.ti.com/industrial
Medical	www.ti.com/medical
Security	www.ti.com/security
Space, Avionics and Defense	www.ti.com/space-avionics-defense
Transportation and Automotive	www.ti.com/automotive
Video and Imaging	www.ti.com/video
Wireless	www.ti.com/wireless-apps

TI E2E Community Home Page

e2e.ti.com

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265
Copyright © 2011, Texas Instruments Incorporated