


# ACC Power Source Circuit

## CIRCUIT DESCRIPTION


This is the power source for A/C amplifier and servomotors, etc.

## WIRING DIAGRAM



## INSPECTION PROCEDURE

## 1 Check voltage between terminals ACC and GND of A/C amplifier connector.

**PREPARATION:**

Remove A/C amplifier with connectors still connected.

**CHECK:**

- (a) Turn ignition switch ON.
- (b) Measure voltage between terminals ACC and GND of A/C amplifier.

**OK:**


Voltage : Battery positive voltage

OK

Proceed to next circuit inspection shown on problem symptoms table (See page DI-859).

NG

## 2 Check continuity between terminal GND of A/C amplifier and body ground.

**CHECK:**

Measure resistance between terminal GND of A/C amplifier and body ground.

**OK:**

Resistance : 0 Ω (continuity)


NG

Repair or replace harness or connector.

OK

**3 Check IGN fuse.**

Cowl Side J/B

**PREPARATION:**

Remove IGN fuse from cowl side J/B.

**CHECK:**

Check continuity of IGN fuse.

**OK:**

**Continuity**

**NG**

**Check for short in all the harness and components connected to the IGN fuse (See attached wiring diagram).**

**OK**

**Check and repair harness and connector between A/C amplifier.**