

TROUBLE SHOOTING

- 1 - When Form Tool Diameter Changes Size, Varies or Chatters.
 - a. Check for maximum rigidity in tool set-up and head locking.
 - 1a. Check for sloppy tool or work spindle bearings.
 - 2a. Check for proper hook in tool and on center.
 - 3a. Proper work support if necessary.
 - b. Check for loose slide or tool arm bushing.
 - c. See if all bolts are tight.
 - d. Check stop screw pressure (.005 pressure would be .010 on diameter of piece, this should be enough.)
 - e. Dull tool.
- 2 - When the hole gets big.
 - a. Head locking properly.
 - b. Sloppy spindles.
 - c. Center drill, chipped or off center.
 - d. Check if drill is dull or loaded.
 - e. Check drill alignment and spindle alignment.
- 3 - When threads come out stripped.
 - a. See if proper cam is used.
 - b. Check block location for proper rises.
 - c. Check proper clutch shifting.
 - d. Check for excess wobble in tap or die.
 - e. Check threading clutch torque.
 - f. Check if hole or body size is correct.
 - g. Spindle is out of line.
 - h. Dull, loaded up, tap or die.
- 4 - Variation in length.
 - a. Check head thrust and thrust bearings end play.
 - b. Worm or sloppy bearings in spindle.
 - c. Dull end working tools pushing work back into collets, such as drills, broaches, and etc.
 - d. Loose, worn, or dirty collets.
 - e. Check for equal feed finger pressure.
 - f. Check for clean cutoff on bar end.
 - g. Stock stop should be tight, highly polished, and proper length of stop plate.
 - h. Check for worn rolls and pins on end working cam lever.
- 5 - When parts have burr on cutoff.
 - a. Check for proper pressure on stop collar (1263-101-14-1) on the burring spindle.
 - b. Check timing of closing dogs so burring chuck is closing at proper time.
 - c. Check rolls and pins on cam levers.
 - d. Cutoff above or below center.
- 6 - When box tool dimension is rough or varies in size.
 - a. Check for proper grind on box tool.
 - b. Check for proper feed.
 - c. Check rollers for proper tension.