



# **SERVO MOTORS AND MOTION CONTROL SYSTEMS**

(Servo Motors, Drives, and Control Methods: Part I-  
Lecture 5)

---




# Interface to Servo



# DC PM Servo Motor Construction

CAT # MTE3300




**Baldor**

# State of the Art: AC Servos



**High Speed Spindle  
(Siemens)**




**DSD Servo  
(Baumüller)**

**High Torque Motor  
(Baumüller)**




**Spindle Motor  
(Franz Kessler)**




# Brushless Servo Motor

## Exploded View



**Baldor**



---

---

# Controls are Available in Various Packages

## UMH Servo Control



Controls (amplifiers) originally were designed for a particular application, to handle a specific load. About the late 70's a designer figured that a product could be made available to handle a wide variety of applications if potentiometers were provided for adjustments. Today, digital adjustments via keypad, and with PC setup, are also available.

## TSD Servo Controls



## H-Series Controls



## H2 Controls



## Flex+Drive<sup>II</sup>



---

---

**Baldor**



---

---

# Baldor Brushless Servo Motors



- Standard, custom and Stainless Steel motors
- Standard and low inertia models
- Potted stator – superior protection for high voltage and current spikes
- Premium 200°C moisture resistant, multi-coated wire
- Superior bearing grease provides 4 times greater life
- Worldwide acceptable mounting – IEC, NEMA & customs – UL/CSA/CE/BISSC
- Variety of feedback – resolver, encoder, Halls, SSI, EnDat, etc.

---

---

**Baldor**

---

# Stainless Steel Brushless Servos



- Stainless steel housing
- Non-corrosive
- FDA, BISSC, UL, CSA, CE
- Watertight 1500 psi & IP67
- Potted stator
- Exxon Polyrex<sup>®</sup>EX Polyurea grease
- Laser etched nameplate

---

**Baldor**

---

---

---

## Precision Gearheads for BSM Servos



- Mount directly onto BSM
- Planetary - high efficiency
- Low backlash
- Inertia matching
- Torque multiplication
- GBSM Models
  - Standard 8-15 arc min
  - Higher torque / Lower backlash
  - Right angle

---

---

**Baldor**

---

---

# AC Brushless Servo Control



- Rotary or linear brushless servos
- Analog or pulse/direction input
- Intuitive Windows™ front end provides full auto-tuning
- ActiveX libraries supplied free

## MicroFlex

- Cont 3, 6, 9 amp (pk = 2X)
- Anti-resonance filters


## FlexDrive<sup>II</sup>

- Cont 2 - 7.5 amp 1 $\phi$ ; 2 - 27.5 3 $\phi$ ; (pk=2X)
- 8/3 I/O; 1-14 bit analog input
- Master encoder input for gearing
- DeviceNet, ProfiBus, CANOpen

---

---

# Motion Controllers



- Coordinated motion control
- Programmable in MintMT Multi-Tasking, or 'C'
- CANOpen for distributed control

## **NextMovePCI**

- 1 – 8 axis servo/stepper
- USB & RS232 communications

## **NextMoveBX<sup>II</sup>**

- 2 - 4 axis servo
- RS232/485 communications

## **NextMoveESB**

- 3 axis servo / 4 axis stepper
- USB & RS232 communications

---

---

**Baldor**

---

---

# Accessories to Complete the Package



- Cable assemblies



- HMI operator panels



- Auxiliary breakout boards

---

---

**Baldor**

---

---

# Programmable Positioners Come in Wide Selection of Configurations...

MintDrive<sup>II</sup>



Programmable motion controls are available in many different configurations. Some include the motor control (amplifier) with an internal power supply, and typically control one motor. Others are multi-axis. These are commercially available in enclosures or printed circuit boards, which fit inside a PC.


NextMoveBX<sup>II</sup>  
Motion Controller  
2, 3, 4 Axes



NextMovePCI  
Motion Controller  
1-12 Axes PCI Bus



## Construction of position control system of one-axis mechatronic servo system





# General Concepts in Motor Control

---

Servomotors are specialized motors used for precise control of angular or linear position, velocity, and acceleration. These motors are essential in applications where precise positioning is crucial. In general, servomotors are controlled through position, velocity, and torque (current) controllers.

## Position, Speed, and Torque Control

**Position Control:** The most fundamental aspect of a servomotor. It involves moving the motor to a desired angle or position. Position controllers typically use feedback mechanisms, like encoders, to determine the motor's current position and adjust the control input accordingly.

**Speed Control:** This involves controlling the rate at which the motor shaft rotates. Speed control is vital in applications where the motor needs to maintain a constant speed, despite varying loads.

**Torque Control:** Torque, or rotational force, control is essential in scenarios where the motor must apply a specific amount of force. It is typically achieved by controlling the motor's current.

## Types of Servomotors

**Servomotors are broadly categorized into two types based on their construction and operation principles:**

**Brushed DC Motors:** These motors use brushes and a commutator to deliver current to the motor windings. The main advantage of brushed DC motors is their simplicity of control. However, they suffer from wear and tear due to brush friction and are typically less efficient.



---

**Brushless Motors:** These include Brushless DC Motors (BLDCM) and Permanent Magnet Synchronous Motors (PMSM).

**BLDCM:** These motors do not have brushes, reducing wear and tear and increasing efficiency. They use a permanent magnet rotor and require an electronic controller for phase shifting.



**PMSM:** Similar to BLDC motors but with a different rotor structure. They are known for high efficiency, better heat dissipation, and quieter operation.



# Brushed DC Motor




$$T_m = K \phi_s \phi_r \sin \theta$$

$$= K \phi_q \phi_d$$







# DC Motor: rotor body and windings




# Brushed DC motor equivalent representation

# Elements of a brushed DC Motor used in practice









# Permanent magnet DC Motor

---





**PMDC MOTOR**




**PMDC MOTOR**


# DC Brushed Servo Motors

---




- Sizes from 5 cm to 10 cm
- Continuous Torques from 0.3 to 6 Nm
- Not used often for new applications
- Stock and custom designs





Torque production mechanism in a PM synchronous machine


$$T_e = \frac{3}{2} \psi i$$





Torque production mechanism in a DC machine

$$T_e = \frac{3}{2} (\vec{\psi} \times \vec{i})$$

## Servo System Control Scheme



### Switched mode inverters for DC and AA motors



# DC Motor Control System

## 1. Mathematical Models for Different Mechanisms:

1. Each mechanical component in a servo system, like gears, shafts, and linkages, has its unique dynamics.
2. Mathematical models of these components typically involve equations representing their inertia, friction, stiffness, and other mechanical properties.

## 2. Servo Motor Mathematical Model:

1. Focusing first on DC motors, the mathematical model captures the relationship between input voltage, generated torque, motor speed, and electrical characteristics.
2. The model includes equations for electromotive force, resistance, inductance, and torque constants.

## 3. Servo Motor Driver Modeling:

1. Considering a controlled rectifier for a DC motor, which can operate in two quadrants, the model addresses the conversion of AC to DC power and how it controls the motor's speed and torque.
2. This involves understanding the power electronics, switching mechanisms, and control strategies used in the driver.

## Integration into a Closed-Loop Servo System

With the individual components modeled, we now look at integrating these into a closed-loop servo system. In a closed-loop system, feedback is used to adjust the control action, enhancing accuracy and stability.

## The Cascaded (Sequential) Control System

The most commonly used control architecture in high-performance servo systems is the cascaded control system. This system layers different control loops, each with its own function:

### 1. Inner Loop - Current (Torque) Control:

1. This loop responds to changes in load and commands from the speed control loop.
2. It ensures that the motor produces the required torque to maintain the desired speed.


### 2. Middle Loop - Speed Control:

1. This loop controls the motor's speed, responding to commands from the position control loop.
2. It adjusts the current setpoint to meet the speed requirements.

### 3. Outer Loop - Position Control:

1. The top layer in the cascade, this loop is responsible for the motor's position.
2. It sends speed commands to the speed control loop to bring the motor to the desired position.

## Modeling of Permanent Magnet Brushed DC Motor



$$V_q = R_q i_q + L_q \frac{di_q}{dt} + k_b \omega_m$$

$$k_t i_q = J \frac{d\omega_m}{dt} + B \omega_m + T_L$$

$$\frac{d\theta_m}{dt} = \omega_m$$



$$\frac{di_q}{dt} = -\frac{R_q}{L_q}i_q - \frac{k_b}{L_q}\omega_m + \frac{1}{L_q}V_q$$

$$\frac{d\omega_m}{dt} = -\frac{B}{J}\omega_m - \frac{1}{J}T_L$$

$$\frac{d\theta_m}{dt} = \omega_m$$


$$T_L = 0 \Rightarrow \text{Input}$$

$$V_q(s) = (R_q + sL_q)I_q(s) + k_b\omega_m(s)$$

$$k_t I_q(s) = (Js + B)\omega_m(s)$$

$$s\theta_m(s) = \omega_m(s)$$

Output



$$\frac{\theta_m(s)}{V_q(s)} = \frac{k_t}{\left[ s^2 J L_q + s(J R_q + B L_q) + B R_q + k_t k_b \right] s}$$

$$v_q = R_q i_q + k_b \omega$$

$$k_t i_q = \underbrace{B \omega_m + \text{Tload}}_{T_y} = T_m$$

$$i_q = \frac{T_y}{k_t} = \frac{T_m}{k_t}$$

$$v_q = \frac{R_q}{k_t} T_m + k_b \omega$$

$$\omega = \frac{v_q}{k_b} - \frac{R_q}{k_t k_b} T_m$$

**At Equilibrium (Steady regime)**

$$\frac{di_q}{dt} = -\frac{R_q}{L_q} i_q - \frac{k_b}{L_q} \omega_m + \frac{1}{L_q} V_q \Rightarrow = 0$$

$$\frac{d\omega_m}{dt} = -\frac{B}{J} \omega_m - \frac{1}{J} T_L \Rightarrow = 0$$

$$\frac{d\theta_m}{dt} = \omega_m$$


Idle

$$\omega = \omega_0$$

$$\omega_0 = \frac{v_g}{k_b}$$

$$\omega = \omega_0 - a \cdot T_m$$

$$= \frac{v_g}{k_b} - a T_m$$



**Problem 1:**

$$V_{qn} = 40V$$

$$n_n = 2000rpm$$

$$R_q = 2.86\Omega$$

$$L_q = 10mH$$

$$k_t = 0.15Nm / A$$

$$k_b = 0.15Ns / rad$$

$$J_m = 5 * 10^{-4} kgm^2$$

$$B_m = 2 * 10^{-4} Nms / rad$$

a) *Find the nominal current*

$$V_{qn} = R_q I_{qn} + k_b \omega_n$$

$$I_{qn} = \frac{V_{qn} - k_b \omega_n}{R_q} \simeq 3A$$

b) Find the nominal speed in idle mode


$$T_m = k_t i_q = T_g = 0$$

$$\underline{\underline{\dot{i}_q = 0}}$$

$$V_{qn} = R_q \cdot 0 + K_b \omega_{on}$$

$$\frac{V_{qn}}{K_b} = \omega_{on} = 266,67 \text{ rad/s} \rightarrow n_{on} = \frac{60 \times 266,67}{2\pi} = 2546 \text{ rpm}$$

**Speed – Torque Characteristic**



**c) Find the nominal torque**

$$T_{mn} = k_t \cdot i_{qn} = 0.15 \times 3 = \underline{\underline{0.45 \text{ Nm}}}$$

**d) Speed – Torque Relation**

$$V_{qn} = R_q i_q + k_b \omega$$

$$T_m = k_t i_q = T_y$$

$$i_q = \frac{T_m}{k_t} \rightarrow$$

$$V_{qn} = R_q \frac{T_m}{k_t} + k_b \omega$$

$$\omega = \frac{V_{qn}}{k_b} - \frac{R_q}{k_t k_b} T_m \Rightarrow \omega = \omega_n - \frac{2.86}{0.225} T_m$$

*(Note: In the original image, the term  $\frac{V_{qn}}{k_b}$  is circled and labeled  $\omega_n$  with an arrow.)*

$$\omega = 266.67 - 127.11 T_m$$

$$T_{mn} = 0.45 \text{ ium}$$

$$\omega_n = 266.67 - 127.11 \cdot 0.45 = \hat{=} 209.6$$


$V_q = \frac{V_{qn}}{2}$  yapılırsa aynı tork için hız değeri hesaplanır.  $V_q = 20V$

$$\omega = \frac{20}{0.15} - 177.11 \cdot 0.45 = 133.33 - 79.7 = 53.63 \text{ rad/s}$$

### e) Nominal Efficiency

$$\eta_n = \frac{P_n}{U_{qn} \cdot I_{qn}} \approx \underline{\underline{0.785}}$$





$$J_m = 5 \times 10^{-4} \text{ kgm}^2$$

$$B_m = 2 \times 10^{-4} \text{ Nm s/rad}$$

Yük tarafına alınacak nominal motor hızı

$$\boxed{\eta_n = 1} \text{ ideal diñli}$$

$$k_f = k_b = 0.15$$

$$R_q = 2.86 \Omega$$

$$V_{qn} = 40 \text{ V}, I_{qn} = 3 \text{ A}$$

$$n_n = 2000 \text{ rpm}$$

$$T_{mn} = 0.45 \text{ Nm}$$

$$\ddot{\theta} = 100 \text{ sec}^{-2}$$

$$r = 0.3 \text{ m}, M = 15 \text{ kg}$$


$$0.45 \times 100 = \underline{\underline{45 \text{ Nm}}}$$

$$\text{hızı} = \frac{209.44}{100} \approx 2.09 \text{ rad/s}$$

$$a = 0.1 \text{ m/s}^2$$

$$\begin{aligned} T_m &= J_m \frac{d\omega_m}{dt} + B_m \omega_m + \frac{Mr^2}{\ddot{h}^2} \frac{d\omega_m}{dt} + \frac{Mgr}{\ddot{h}} \\ &= \left( J_m + \frac{Mr^2}{\ddot{h}^2} \right) \frac{d\omega_m}{dt} + B_m \omega_m + \frac{Mgr}{\ddot{h}} \end{aligned}$$

$$= \left( \cancel{5 \times 10^4} + \frac{10 \times 0.3^2}{100^2} \right) \frac{d\omega_m}{dt} + \frac{10 \times 9.81 \times 0.3}{100}$$



$$T_m = f(i)$$

$$u - e = Ri + L \frac{di}{dt}$$

$$\frac{(U(s) - E(s))/R}{s\tau_{el} + 1} = I(s)$$

$$U(s) = \frac{U}{s}$$

$$E(s) = \frac{E}{s}$$

$$\tau_{el} \ll \tau_{mech}$$

$$i(t) = \frac{U-E}{R} (1 - e^{-t/\tau_{el}})$$

$$T_m = f(i)$$

$$T_m - T_L = J \frac{d\omega}{dt} + B\omega$$

$$0 \leq t < 1 \quad \omega_m = 200t \quad i_q = 3 + 0.27t$$

$$t=1 \quad \omega_m = 200 \text{ rad/s} \quad i_q = 3.27 \text{ A}$$

$$1 \leq t \leq 3 \quad \omega_m = 200 \quad i_q = 3.2 \text{ A}$$

$$3 < t < 4 \quad \omega_m = 200(4-t) \quad i_q = 2.97 + 0.27(4-t)$$

$$t=3 \quad \omega_m = 200 \quad i_q = 3.2$$

$$t=4 \quad \omega_m = 0 \quad i_q = 2.97$$

$$T_m - T_L = J \frac{d\omega}{dt} + B\omega$$

$$\frac{(T_m(s) - T_L(s))/B}{s\tau_{mech} + 1} \quad T_L(s) = \frac{T_L}{s}$$

$$\omega(s) = \frac{(T_m - T_L)/B}{s\tau_{mech} + 1} \cdot \frac{T_m(s)}{s} \quad T_m(s) \approx \frac{T_m}{s} \quad \tau_{mech} \gg \tau_{el}$$

$$\omega(t) = \frac{(T_m - T_L)/B}{s} (1 - e^{-t/\tau_{mech}})$$

$$0 \leq t < 1$$

$$V_q = 2.86 \cdot [3 + 0.27t] + 10^{-2} \cdot 0.27 \cdot 2.86 + 0.15 \cdot 200t$$


$$t=0 \quad V_q = 8.58 \text{ V}$$

$$t=1 \quad V_q = 39.36 \text{ V}$$

$$1 \leq t \leq 3 \quad V_q = \underline{\underline{39.36 \text{ V}}}$$

$$3 < t \leq 4 \quad V_q = 2.86 [2.97 + 0.27(4-t)] + 10^{-2} \cdot 0.27 \cdot 2.86 + 0.15 \cdot 200(4-t)$$

$$t=4 \text{ s} \quad V_q = 8.49 \text{ V}$$



Since the excitation is constant, the speed of the motor is changed by the voltage applied to the motor.

$$\omega = \frac{V_g - \frac{R_g}{k_t} T_m}{k_b} = \frac{V_g}{k_b} - \frac{R_g}{k_t k_b} T_m$$


$\omega_{on}$  = initial nominal speed

$$\omega_{on} = \frac{V_{gn}}{k_b}$$

$$\omega_n = \omega_{on} - \frac{R_g}{k_t k_b} T_{mn}$$

$$\tau_{elek} = \frac{L}{R} \approx 0$$

$$\tau_{mek} = \frac{J}{B} > 0$$



The speed of the DC motor is changed by the direct voltage applied to the machine.


$$v_q = R_q i_q + L_q \frac{di_q}{dt} + K_b \omega_m$$
$$K_t i_q = J \frac{d\omega_m}{dt} + \underbrace{B \omega_m + T_{fr} + T_{gr} + T_y}_{T_{load}}$$

In steady state: (in case the electrical time constants are small compared to the mechanical time constants and there is no fluctuation in the current)

$$v_q = R_q i_q + K_b \omega_m$$

$$K_t i_q = T_{yük} = T_m \rightarrow i_q = \frac{T_m}{K_t}$$

$$\omega_m = \frac{1}{K_b} v_q - \frac{R_q}{K_t K_b} T_m$$



If we switch to  $V_{q1} \rightarrow V_{q2}$  while working at point A,  $T_y = T_{y1} = \text{constant}$  in this case; The aim is to reduce the speed of the motor to a speed value smaller than  $\omega_1$ . When the voltage changes to  $V_{q1} \rightarrow V_{q2}$  while operating at point A, the speed of the motor cannot change quickly, but the torque goes to point B in a stepwise manner. The generator slowly moves to the operating region from point B to point C on the curve  $V_{q2}$ .



A

$$V_g = V_{gA} =$$

$$R_g i_{gA} + k_b \omega_{mA}$$

$$\omega_{mA} = \frac{V_{gA}}{k_b} - \frac{R_g}{k_t k_t} T_{mA}$$

B

$$V_g = V_{gC}$$

$$V_{gC} < V_{g1}$$

$$i_g = \frac{V_g - k_b \omega_{mA}}{R_g}$$

$$V_{gC} < k_b \omega_{mA}$$

$$i_q < 0 \quad T_m = k_t \cdot i_q < 0$$

$$T_m < 0 \quad \omega_m > 0$$

$$-\frac{T_m - T_y}{J} = \frac{d\omega_m}{dt} + \omega_m$$

$$\int_{\omega_{mA}}^{\omega_m} d\omega_m = -\frac{1}{J} \int_0^t (T_m + T_y) dt$$

$$\omega_m = \omega_{mA} - \frac{1}{J} \int_0^t (T_m + T_y) dt$$

$$V_{q2} = k_b \omega_{mE} \quad T_{mE} = 0$$


$$i_q > 0 \rightarrow T_m > 0$$

$$\omega_m > 0$$

$$V_{q2} > k_m \omega_m \quad | \quad 0 < \omega_m < \omega_{mE}$$

$$\omega_m = \omega_{mC} \text{ de.}$$

$$T_{mC} = T_{yC} = T_{y1}$$





# Controlled rectifier in driving DC Motor

With a 3-phase full-wave controlled rectifier, the average value of the voltage applied to the motor will be changed. Here  $L_s$  is used to reduce the ripple in the current. The average value of the voltage applied to the motor as a function of the trigger angle applied to the thyristors:

Here  $p$  is the number of peaks in a period,  $V_{LL}$  is the effective value of the inter-phase voltage,  $\alpha$  is the trigger angle.


$$V_{dc} = V_{d\alpha} = \frac{p}{\pi} \sqrt{2} V_{LL} \sin \frac{\pi}{p} \cos \alpha = 1.35 V_{LL} \cos \alpha = V_{d0} \cos \alpha$$





$$\omega_m = \frac{V_{dax}}{k_b} - \frac{R_g I_d}{k_b}$$



$$= \frac{V_{dax}}{k_b} - \frac{R_g T_m}{k_1 k_b}$$




$$\omega_m = \frac{V_{dax} \cos \alpha}{k_b} - \frac{R_g T_m}{k_1 k_b}$$

$\underbrace{k_b}_{k_1}$        $\underbrace{k_1 k_b}_{k_2}$



$$= k_1 \cos \alpha - k_2 T_m$$



**Motor 1 and generator operation in zone 4, or operation in rectifying and inverting mode when viewed from the full-wave bridge side**




# Rectifier average voltage-average current characteristics showing detailed discontinuous and continuous regions in the current





# Cascade Control Structure



DC servo systems are vital in applications requiring precise control of motion, such as robotics, CNC machines, and automated manufacturing systems. A key feature of these systems is their ability to accurately control position, speed, and torque.

## Cascaded Control Structure

The cascaded control structure is universally acknowledged as the most effective approach for high-performance servo systems. This structure comprises three layers of regulation:

### 1. Innermost Layer - Current (or Torque) Regulator

1. This layer directly controls the motor's torque, which is essential for immediate responses to command changes.
2. Torque is proportional to the current in DC motors, hence the term current regulator is often used.

### 2. Middle Layer - Speed Regulator

1. This wraps around the current regulator.
2. Controls the motor's speed and acts as an intermediary between the torque and position control layers.

### 3. Outermost Layer - Position Regulator

1. This layer ensures the motor reaches and maintains the desired position.
2. The position is the integral of speed, making this the highest layer in the control hierarchy.

## The Principle of Operation


- **Four Quadrant Power Supply:** A critical component in DC servo systems. It allows the motor to operate under all combinations of torque (current) and speed (voltage), enabling both forward and reverse motion, as well as motoring and braking in both directions.
- **Bandwidth Considerations:**
  - Bandwidth in control systems refers to the range of frequencies over which the system can accurately track command signals.
  - In the cascaded structure, bandwidth hierarchy is crucial:

---

    - The current regulator must have the highest bandwidth for rapid response.
    - The speed regulator follows with a lower bandwidth.
    - The position regulator has the lowest bandwidth, focusing on overall system stability and accuracy.

## System Tuning and Benefits

- **Tuning Process:**
  - Tuning starts from the innermost current regulator, progressing outward.
  - This ensures that each layer responds correctly to the commands from the outer layers.
- **Variable Limiting:**
  - Each variable (current, speed, position) can be individually limited, providing fine control over the system's behavior.
- **Benefits of Cascade Control:**
  - Improved precision in controlling torque, speed, and position.
  - Enhanced system stability.
  - Ability to handle disturbances and changes in load conditions effectively.



The current controller and speed controller are arranged in a cascade structure, as seen.

The output of the current controller is the average value of the voltage that will be applied to the DC motor.

This value indicates the change in the average voltage that needs to be applied to the motor, both in transient and steady-state conditions.

The voltage applied to the motor is expected to be the same as  $V_{dc}$ , with a scale difference.

$$V_c = V_q^{ref}$$

$$V_{dc} = V_{d0} \cos \alpha$$

$$V_q^{ref} = V_c = V_{c \max} \cos \alpha$$

$$\cos \alpha = \frac{V_{dc}}{V_{d0}} = \frac{V_c}{V_{c \max}} \quad \alpha = \cos^{-1} \left( \frac{V_c}{V_{c \max}} \right)$$



$$v_c = v_{cmax} \cdot \cos d$$


$$v_q = v_{do} \cos d$$


$$\frac{v_q}{v_c} = \frac{v_{do}}{v_{cmax}} = k_d$$

$$v_q = v_c \cdot k_d$$


$$v_{do} = k_d v_{cmax}$$








Load Torque,  $T_{load}=0$



The current loop is the inner loop in cascade control design.

Controller design will begin with this cycle, which has much smaller time constants than the speed cycle.


For this purpose, first the transfer function between current and voltage will be obtained:



$$\frac{I_q(s)}{V_q(s)} = \frac{(sJ + B)}{(sJ + B)(sL_q + R_q) + K_t K_b}$$

Rectifier's T.F.

$$G_{DC}(s) = \frac{V_q(s)}{V_c(s)} = \frac{K_d}{1 + sT_d}$$






$$\frac{I_q(s)}{V_q(s)} = \frac{(sJ + B)}{(sJ + B)(sL_q + R_q) + K_t K_b} = \frac{K_1 (sT_m + 1)}{(sT_1 + 1)(sT_2 + 1)}$$

$$K_t = K_b$$

$$G_{DC}(s) = \frac{V_q(s)}{V_c(s)} = \frac{K_d}{1 + sT_d}$$



$$T_m = \frac{J}{B}$$


**PID Controller Structure:**  $G_c(s) = \frac{K_c (sT_{c1} + 1)(sT_{c2} + 1)}{s}$

$$-\frac{1}{T_1}, -\frac{1}{T_2} = -\frac{1}{2} \left[ \frac{B}{J} + \frac{R_q}{L_q} \right] \pm \sqrt{\frac{1}{4} \left( \frac{B}{J} + \frac{R_q}{L_q} \right)^2 - \left( \frac{K_b^2 + R_q B}{J L_q} \right)}$$


$$K_1 = \frac{B}{K_b^2 + R_q B}$$

### Pole-Zero Cancellation

$$T_{c1} = T_1; T_{c2} = T_2$$



## Speed Controller Loop:




System Transfer Function


$$G(s) = \frac{\omega_m(s)}{V_{\omega_m}^r} = \frac{\frac{K_s(1+sT_s)}{sT_s} \frac{K_i}{(1+sT_i)} \frac{K_b/B}{(1+sT_m)}}{1 + \frac{K_s(1+sT_s)}{sT_s} \frac{K_{\omega}}{(1+sT_{\omega})} \frac{K_i}{(1+sT_i)} \frac{K_b/B}{(1+sT_m)}}$$

$$K_{\alpha} = K_s K_i \frac{K_b}{B}$$

$$T_s = T_m \quad G(s) = \frac{\omega_m(s)}{V_{\omega_m}^r} = \frac{\frac{K_{\alpha}}{T_i} \left( \frac{1}{T_{\omega}} + s \right)}{s^3 + s^2 \left( \frac{1}{T_{\omega}} + \frac{1}{T_i} \right) + s \frac{1}{T_{\omega} T_i} + \frac{K_{\alpha} K_{\omega}}{T_{\omega} T_i}}$$

Outside of the 2 control poles, the 3rd pole is 5-6 times larger than the real parts of the 2 control poles.  
The additional zero should also be at least 5-6 times further away.





A separately-excited dc motor with the following parameters:  $R_a = 0.5 \Omega$ ,  $L_a = 0.003\text{H}$ , and  $K_b = 0.8 \text{ V/rad/sec}$ , is driving a load of  $J = 0.0167 \text{ kg}\cdot\text{m}^2$ ,  $B_l = 0.01 \text{ N}\cdot\text{m/rad/sec}$  with a load torque of  $100 \text{ N}\cdot\text{m}$ . Its armature is connected to a dc supply voltage of  $220 \text{ V}$  and is given the rated field current. Find the speed of the motor.

**Solution** The electromagnetic torque balance is given by

$$T_e = T_l + B_l \omega_m + J \frac{d\omega_m}{dt}$$

In steady state,  $\frac{d\omega_m}{dt} = 0$

$$T_e = T_l + B_l \omega_m = 100 + 0.01 \omega_m$$

$$T_e = K_b i_a = 100 + 0.01 \omega_m$$

$$i_a = \frac{(100 + 0.01 \omega_m)}{K_b} = (125 + 0.0125 \omega_m)$$

$$e = V - R_a i_a = 220 - 0.5 \times (125 + 0.0125 \omega_m) = 157.5 - 0.00625 \omega_m = K_b \omega_m$$

Rearranging in terms of  $\omega_m$ ,

$$\omega_m(0.8 + 0.00625) = 157.5$$

$$\text{Hence } \omega_m = \frac{157.5}{0.80625} = 195.35 \text{ rad/sec}$$

## Example

Design a speed-controlled dc motor drive maintaining the field flux constant. The motor parameters and ratings are as follows:

220 V, 8.3 A, 1470 rpm,  $R_a = 4 \Omega$ ,  $J = 0.0607 \text{ kg} \cdot \text{m}^2$ ,  $L_a = 0.072 \text{ H}$ ,  $B_f = 0.0869 \text{ N} \cdot \text{m} / \text{rad}/\text{sec}$ ,  $K_b = 1.26 \text{ V}/\text{rad}/\text{sec}$ .

The converter is supplied from 230V, 3-phase ac at 60 Hz. The converter is linear, and its maximum control input voltage is  $\pm 10 \text{ V}$ . The tachogenerator has the transfer function

$G_w(s) = \frac{0.065}{(1 + 0.002s)}$ . The speed reference voltage has a maximum of 10V. The maximum

current permitted in the motor is 20 A.

$f=60 \text{ Hz}$   $T=1/60=16.67 \text{ ms}$

There are 6 peaks in a period  $16.67/6= 2.778 \text{ ms} = T$  is the time it takes for the applied control signal to change  $0 < T_d < 2.778 \text{ ms}$ .

From here  $T_d=1.38 \text{ ms}$  is selected.

---

**Solution (i) Converter transfer function:**

$$K_r = \frac{1.35 \text{ V}}{V_{cm}} = \frac{1.35 \times 230}{10} = 31.05 \text{ V/V}$$
$$V_{dc}(\text{max}) = 310.5 \text{ V}$$

The rated dc voltage required is 220 V, which corresponds to a control voltage of 7.09 V. The transfer function of the converter is

$$G_r(s) = \frac{31.05}{(1 + 0.00138s)} \text{ V/V}$$

**(ii) Current transducer gain:** The maximum safe control voltage is 7.09 V, and this has to correspond to the maximum current error:

$$i_{\text{max}} = 20 \text{ A}$$
$$H_c = \frac{7.09}{I_{\text{max}}} = \frac{7.09}{20} = 0.355 \text{ V/A}$$



**(iii) Motor transfer function:**

$$K_1 = \frac{B_1}{K_h^2 + R_a B_1} = \frac{0.0869}{1.26^2 + 4 \times 0.0869} = 0.0449$$

$$-\frac{1}{T_1} - \frac{1}{T_2} = -\frac{1}{2} \left[ \frac{B_1}{J} + \frac{R_a}{L_a} \right] \pm \sqrt{\frac{1}{4} \left( \frac{B_1}{J} + \frac{R_a}{L_a} \right)^2 - \left( \frac{K_h^2 + R_a B_1}{J L_a} \right)}$$

$$T_1 = 0.1077 \text{ sec}$$

$$T_2 = 0.0208 \text{ sec}$$

$$T_m = \frac{J}{B_1} = 0.7 \text{ sec}$$

The subsystem transfer functions are

$$\frac{I_a(s)}{V_a(s)} = K_1 \frac{(1 + sT_m)}{(1 + sT_1)(1 + sT_2)} = \frac{0.0449(1 + 0.7s)}{(1 + 0.0208s)(1 + 0.1077s)}$$

$$\frac{\omega_m(s)}{I_a(s)} = \frac{K_b/B_t}{(1 + sT_m)} = \frac{14.5}{(1 + 0.7s)}$$

(iv) Design of current controller:

$$T_c = T_2 = 0.0208 \text{ sec} \quad T_{c1} = T_1 = 0.1077 \text{ sec}$$

$$K_i = \frac{K_1 K_d K_c T_m}{1 + K_1 K_d K_c T_m H_c} = \frac{0.0449 \times 31.05 \times 2 \times 0.7}{1 + 0.0449 \times 31.05 \times 2 \times 0.7 \times 0.355} = 1.153;$$

$$T_i = \frac{T_d}{1 + K_1 K_d K_c T_m H_c} = 0.0000815 \text{ sec}$$

$$K_{\alpha} = K_s K_i \frac{K_b}{B} = K_s \times 1.153 \times 14.5 = 16.72 K_s$$

$$T_s = T_m$$

$$G(s) = \frac{\omega_m(s)}{V_{\omega_m}^r} = \frac{\frac{K_{\alpha}}{T_i} \left( \frac{1}{T_{\omega}} + s \right)}{s^3 + s^2 \left( \frac{1}{T_{\omega}} + \frac{1}{T_i} \right) + s \frac{1}{T_{\omega} T_i} + \frac{K_{\alpha}}{T_{\omega} T_i}}$$


$$G_{\omega}(s) = \frac{0.065}{(s \cdot 0.002 + 1)}$$

$$\frac{1}{T_{\omega}} \ll \frac{1}{T_i}$$

$$G(s) = \frac{16.72 K_s \left( \frac{1}{T_{\omega}} + s \right)}{T_i s^3 + s^2 + s \frac{1}{T_{\omega}} + \frac{1.087 K_s}{T_{\omega}}}$$

$$T_{\omega} = 0.002 \text{ san}$$


$$G(s) = \frac{16.72 K_s (s + 500)}{s^2 + 500s + 543.4 K_s}$$




If  $K_s = 115.016$  is selected, the system will have a multiple root at  $-250$ . Since zero at  $-500$  is closer than 5 times, the critical damped response expected from the system cannot be obtained.



# Permanent Magnet DC Motor with DC-DC Drive

DC-DC chopper is preferred in DC motor control systems in order not to give too much harmonics to the network and to reduce motor torque oscillations.




In order for current to flow in one direction from the motor, T1 and T2 or T3 and T4 must be in conduction at the same time.






transient



# First Quadrant





(i) Continuous Conduction



(ii) Discontinuous Conduction







## Second Quadrant









# Third Quadrant




(ii) Discontinuous Conduction

# Fourth Quadrant







I




II



III



IV




$$V_{q,avg} = \frac{T_{on}}{T} \cdot V_{DC}$$

$$V_{q,avg} = 0$$

$$T_{on} = 0$$

$$V_{q,avg} = V_{DC}$$



$$T_{on} = T$$



$$\frac{T_{on}}{T} = d \quad \text{duty cycle}$$

$$0 \leq d \leq 1$$

$$V_{q, \text{avg}} = d \cdot V_{DC}$$




$$I_{q, \text{avg}} = \frac{V_{q, \text{avg}} - E_b}{R_q}$$

duty cycle  $d = \frac{T_{on}}{T} \rightarrow (dT = T_{on})$

Average Armature Current

$$I_a = \frac{V_a - E_b}{R_a} = \frac{dV_{dc} - E_b}{R_a}$$

$$T_m = k_t I_a = \frac{k_t (dV_{dc} - E_b)}{R_a}$$



$$\tau_q = \frac{L_q}{R_q}$$

$T_{on}$

$$V_{DC} = R_q i_q + L_q \frac{di_q}{dt} + e_b$$

Mechanical time constant is bigger than T

$T_{on}$  and  $T_{off}$  steadily changes.

$T_{off}$

$$0 = R_q i_q + L_q \frac{di_q}{dt} + e_b$$

$$0 = R_q i_q + L_q \frac{di_q}{dt} + k_b \omega$$

$$T_{on} < t \leq T$$

$$\frac{V_{DA}}{s} = (sL_q + R_q) I_q(s) - L_q I_q(0) + \frac{E_b}{s}$$

$$L_q I_q(0) + \frac{V_{DA} - E_b}{s} = (sL_q + R_q) I_q(s)$$

$$I_q(s) = \frac{V_{DA} - E_b}{s(sL_q + R_q)} + \frac{L_q I_q(0)}{sL_q + R_q}$$



$$I_q(s) = \frac{\left( \frac{V_{DA} - E_b}{R_g} \right) k}{s \left( s + \frac{R_g}{L_g} \right)} + \frac{s I_q(0)}{s + \frac{R_g}{L_g}}$$

$$= \frac{k_1}{s(s+a)} + \frac{k_2}{s+a}$$

$$= \frac{k_1/a}{s} + \frac{-k_1/a}{s+a} + \frac{k_2}{s+a}$$

$$= \frac{V_{DA} - E_b}{\frac{L_g}{R_g}} \left( 1 - e^{-t/\tau_0} \right) + I_{q_{min}} e^{-t/\tau_0}$$

$$i_q(t) = \frac{V_{dc} - E_b}{R_q} (1 - e^{-t/\tau_q}) + I_{min} e^{-t/\tau_q} \quad 0 \leq t < dT$$

$$i_q(t) = -\frac{E_b}{R_q} (1 - e^{-(t-dT)/\tau_q}) + I_{max} e^{-(t-dT)/\tau_q} \quad dT \leq t < T$$

$$i_q(t) = i_q(t+T)$$

$$i_q(t) = \frac{V_{DA} - E_b}{R_q} (1 - e^{-t/\tau_e}) + I_{qmin} e^{-t/\tau_e}$$

$$t=0 \quad i_q(0) = I_{qmin}$$

$$t = T_{on} \quad I_{qmax} = i_q(T_{on}) = \frac{V_{DA} - E_b}{R_q} (1 - e^{-T_{on}/\tau_e}) + I_{qmin} e^{-T_{on}/\tau_e}$$


$$I_{\min} = \frac{V_{dc} (e^{dT/\tau_a} - 1)}{R_a (e^{T/\tau_a} - 1)} - \frac{E_b}{R_a}$$

$$I_{\max} = \frac{V_{dc} (1 - e^{-dT/\tau_a})}{R_a (1 - e^{-T/\tau_a})} - \frac{E_b}{R_a}$$

$$i_a(0) = 0$$

$$V_{dc} = E + R_a i_a + L_a \frac{di_a}{dt} \quad 0 < t < dT$$

## Discontinuity in Current



$$V_s = E + R_a i_a + L_a \frac{di_a}{dt}, \quad 0 < t < dT$$

$$0 = E + R_a i_a + L_a \frac{di_a}{dt}, \quad dT < t < (t_x + dT)$$

$$i_a(t_x + dT) = 0$$

$$i_a(0) = 0$$

$$I_{al} = \frac{V_s - E}{R_a} (1 - e^{-dT/T_a})$$


$$i_a(t_x + dT) = -\frac{E}{R_a} (1 - e^{-\frac{t_x}{T_a}}) + I_{al} e^{-\frac{t_x}{T_a}}$$

$$t_x = T_a \log_e \left[ 1 + \frac{I_{al} R_a}{E} \right]$$

$$i_a(t) = \frac{V_s - E}{R_a} (1 - e^{-t/T_a}), \quad 0 < t < dT$$

$$i_a(t) = I_{al} e^{-\frac{(t-dT)}{T_a}} - \frac{E}{R_a} (1 - e^{-\frac{(t-dT)}{T_a}}), \quad dT < t < t_x + dT$$

$$i_a(t) = 0, \quad (t_x + dT) < t < T$$



$$\theta(s) = \theta^{ref}(s) \frac{G_\theta(s) k_t G_m(s)}{1 + G_\theta(s) k_t G_m(s)} - \frac{T_y(s) G_m(s)}{1 + G_\theta(s) k_t G_m(s)}$$

$$\theta^{ref}(s) = \frac{\theta^r}{s} \quad T_y(s) = \frac{T_y}{s}$$

$$\theta_\infty = \lim_{s \rightarrow 0} \frac{G_\theta(s) k_t G_m(s) \cdot \theta^r}{1 + G_\theta(s) k_t G_m(s)} - \frac{G_m(s) \cdot T_y}{1 + G_\theta(s) k_t G_m(s)}$$

$$\lim_{s \rightarrow 0} G_m(s) \rightarrow \infty$$

$$\theta_\infty = \theta^r - \lim_{s \rightarrow 0} \frac{T_y}{G_\theta(s) k_t}$$

$$G_\theta(s) = \frac{Q(s)}{s P_\theta(s)}$$

$$\lim_{s \rightarrow 0} G_\theta(s) \rightarrow \infty$$

$$\theta_\infty \rightarrow \theta^r$$

$$G_w(s) = \frac{K_w(s+\alpha)}{s} \quad T_y = 0$$

$$T(s) = \frac{k_t K_w(s+\alpha)}{s(s+\beta)} \cdot \frac{1}{1 + \frac{k_t K_w k_g(s+\alpha)}{s(s+\beta)(sT_g+1)}} = T(s)$$

$$T(s) = \frac{-k_t K_w (sT_g+1)}{s(sT_g+1) + k_t K_w k_g} = \frac{k_1(s+\beta)}{(s+\delta)(s+\gamma)}$$

$$\beta = \frac{1}{T_g}$$

**Problem:** In a DC machine with permanent magnet brushes given as  $R_q=1$  Ohm,  $L_q=10$  mH,  $K_t=K_b=0.8$ ,  $J=0.01$  kgm<sup>2</sup>,  $B=0.04$  Nm/s, position control will be made via the DC-DC chopper.

---

A controller with hysteresis structure was used as the current controller.

In the system that moves a fixed load of  $T_y = 10$  Nm

Design a controller that will make the steady-state error zero and provide a critically damped response.


**SOLUTION:** Since it is a hysteresis current controller, the reference current can be considered as the approximate motor current. In this case, the system block diagram can be simplified as follows.

$$k_f = 0.8$$

$$J = 0.01 \text{ kgm}^2$$

$$B = 0.04 \text{ Nm/s}$$


$$G_m(s) = \frac{100}{s(s+4)}$$



$$G_\theta(s) = \frac{(s+a)(s+b)}{s} k$$

$$b = 0,001$$

$$a = -10$$



If it is assumed that zero at  $b = 0.001$  and one of the poles at  $s = 0$  are approximated,  
 $K = 0.005$  is found when  $s = 2$ -fold poles.

$$1 + \frac{80K(s+10)}{s(s+4)} = 0$$


$$\frac{G_o(s) K_t G_m(s)}{1 + G_o(s) K_t G_m(s)} = \frac{s^2(s+4) + 80K(s+10)(1+0.001s)}{s^3 + s^2(80K+4) + s(800K+8K) + 8K} = 0$$

$$(s^4 + 4s + 4)(s+p) = s^3 + (p+4)s^2 + (4p+4)s + 4p$$

$$p+4 = 80K+4 \quad 4p+4 = 800K \quad 480K=4 \quad K = \frac{4}{48}$$


$$320K+4 = 800K \rightarrow$$







$$V_{d\alpha} = V_{d0} \cdot \cos \alpha$$

$$T_d \approx 1,67 \text{ ms}$$



Torque is proportional with the current

Torque Reference




$$v_c = v_{cmax} \cdot \cos d$$



$$v_q = v_{do} \cos d$$



$$\frac{v_q}{v_c} = \frac{v_{do}}{v_{cmax}} = k_d$$

$$v_q = v_c \cdot k_d$$

$$v_{do} = k_d v_{cmax}$$







$$\alpha = \cos^{-1} \left( \frac{V_c}{V_{cm}} \right) \rightarrow V_c = \overset{V_{do}}{V_{cm}} \cdot \cos \alpha$$

$$V_{d\alpha} = \underbrace{\frac{3}{\pi} V_m}_{V_{do}} \cos \alpha = \cancel{1.35 V} \cos \alpha$$
$$= \cancel{1.35 V}_{V_{do}} \cdot \frac{V_c}{V_{cm}}$$


$$K_d = \frac{\cancel{1.35 \cdot V}_{V_{do}}}{V_{cm}} \quad \text{olarak tanımlanırsa}$$

$$V_{d\alpha} = K_d \cdot V_c = G_d(s) \cdot V_c$$


$$G_d(s) = K_d e^{-sT_d} \approx \frac{K_d}{1+sT_d}$$

### PID Controller

$$G_I(s) = \frac{K_I (s+a)(s+b)}{s}$$







$$c = \frac{B}{J} = \frac{1}{\tau_{mek}}$$

$$G_I(s) = \frac{K_I (s+a)(s+b)}{s}$$

$$\frac{\frac{K_1(s+c)}{s(s+\alpha)}}{1 + \frac{K_1(s+c)}{s(s+\alpha)}} = \frac{K_1(s+c)}{s^2 + s(\alpha + K_1) + K_1 c} \approx \frac{K_1(s+c)}{(s+c)(s+\beta)}$$


$$\frac{I_q(s)}{V_q(s)} = \frac{J \left( s + \frac{B}{J} \right)^{\frac{1}{\tau_{mek}}}}{s^2 J L_q + s (R_q J + B L_q) + (R_q B + K_t K_b)}$$

$$\frac{I_q(s)}{V_q(s)} = \frac{K (s\tau_m + 1)}{(s\tau_1 + 1)(s\tau_2 + 1)}$$

$$G_I(s) = \frac{K_A (s\tau_A + 1)}{s} = \frac{K_I (s + \alpha)}{s}$$

$$s^2 + s \left( \frac{R_q}{L_q} + \frac{B}{J} \right) + \frac{R_q B + K_t K_b}{L_q J}$$

$$\frac{1}{\tau_{el}} + \frac{1}{\tau_{mek}} \quad \tau_{mek} \gg \tau_{el}$$



$$\frac{1}{\tau_{el}} \gg \frac{1}{\tau_{mech}}$$

$$s^2 + s \frac{1}{\tau_{el}} + \frac{1}{\tau_{el} \tau_{mech}} + \frac{k_t k_b}{L_q J}$$

$$-\frac{1}{2\tau_{el}} \mp \sqrt{\frac{1}{4\tau_{el}^2} - \frac{1}{\tau_{el} \tau_{mech}} - \frac{k_t k_b}{L_q J}}$$

$$\tau_1 > \tau_2 > T_d$$


$$G_I(s) = \frac{K_A (1+s\tau_2)(1+s\tau_d)}{s}$$

$$GH(s) = \frac{K_A (1+s\tau_2)(1+s\tau_d)}{s} \cdot \frac{K (s\tau_m+1)}{\cancel{(s\tau_1+1)} \cancel{(s\tau_2+1)}} \cdot \frac{K_{dc}}{\cancel{(1+s\tau_b)}}$$


$$s\tau_m+1 \approx s\tau_m$$

$$GH(s) = \frac{K_A K K_d \tau_m}{(1+s\tau_d)}$$

$$\frac{I_q(s)}{I_q^{ref}(s)} = \frac{GH}{1+GH} = \frac{K_{AI}}{1+s\tau_i}$$



$$6 + 8 + 12 = 26$$



$$(s+2)(s+3)(s+4)$$

$$(s^2 + 5s + 6)(s+4)$$

$$s^3 + 9s^2 + 26s + 24$$




$$s^3 + (a_1 + a_2 + a_3)s^2 + (a_1a_2 + a_1a_3 + a_2a_3)s + a_1a_2a_3$$




$$\frac{s(s+4)}{s^2+4s}$$

$$G_w(s) = \frac{(s+\delta) k_w (s+\gamma)}{s}$$

$$T(s) = \frac{\frac{k_2 k_w k_1 k_t (s+\delta) (s+\gamma)}{(s+p) s (s+\frac{B}{J})}}{1 + \frac{\frac{k_w k_1 k_t (s+\delta) (s+\gamma)}{J} (k_g/T_g)}{(s+\beta) s (s+\frac{B}{J}) (s+\frac{1}{T_g})}} = \frac{\frac{k_2}{s}}{1 + \frac{k_3}{s(s+\eta)}}$$

$$T(s) = \frac{k_2 (s+\eta)}{s^2 + \eta s + k_3}$$









duty cycle  $d = \frac{T_{on}}{T} \rightarrow (dT = T_{on})$


$$I_q = \frac{V_q - E_b}{R_q} = \frac{dV_{dc} - E_b}{R_q}$$

$$T_m = k_t I_q = \frac{k_t (dV_{dc} - E_b)}{R_q}$$



$$\frac{V_{dc}}{V_{cm}} = k_{DC}$$





$$G_w(s) = \frac{k_w (s+\delta)(s+\delta^*)}{s}$$

PRD

## Brushed Permanent Magnet DC Servo Motors

### 1. Construction and Principle:

- **Permanent Magnets:** These motors use permanent magnets to create the magnetic field. This design simplifies the motor and eliminates the need for external field excitation.
- **Brushes and Commutator:** The brushes provide current to the commutator, which in turn energizes different armature coils as the motor rotates, ensuring continuous rotation.

### 2. Operation:

- When voltage is applied, the current flowing through the armature interacts with the magnetic field from the permanent magnets, creating a force that rotates the armature.

## Drive and Control Methods

### 1. DC-DC Choppers:

- **For Small Power:** Power MOSFETs are typically used. MOSFETs are efficient and suitable for lower power applications due to their fast switching speed and lower losses.
- **For Higher Power:** IGBTs (Insulated Gate Bipolar Transistors) are employed. IGBTs combine the high-current handling capability of a bipolar transistor with the ease of control of a MOSFET.

### 2. Voltage Control:

- **Adjustable Output Voltage:** The output voltage of the DC-DC choppers, usually fed from a constant voltage source, needs to be adjusted within the range of  $-V_{da} < V_q < V_{da}$ . This adjustment is crucial for controlling the motor speed.
- **Operating Regions:** The motor operates mainly in the I and III regions, as per your provided information. This implies that the motor works effectively across a range of voltages and speeds.

### 3. Speed Control:

- PWM (Pulse Width Modulation):** A common method to control the speed of these motors is through PWM, where the average voltage and thus the speed of the motor is controlled by adjusting the duty cycle of the voltage applied to the motor.

### 4. Feedback Mechanisms:

- To achieve precise control, feedback mechanisms like encoders or tachometers are often used. These provide real-time feedback on the motor's position or speed, enabling more accurate control.

### Application and Advantages


- Precision and Simplicity:** These motors are popular in applications requiring precise control of speed and position, such as in robotics and automation.

- Reliability:** The simplicity of their design makes them reliable and easy to maintain, albeit with the need to periodically replace brushes.

### Challenges

- Brush Maintenance:** The brushes in these motors wear out over time and need regular replacement.



- Electrical Noise:** Brushed motors generate more electrical noise due to the commutation process.



$$V_{qort} = \frac{T_{on}}{T} \cdot V_{DC}$$

$$V_{qort} = 0 \quad T_{on} = 0$$



$$V_{qort} = V_{DC} \quad T_{on} = T$$



$$\frac{T_{on}}{T} = d \quad \text{duty cycle}$$



$$0 \leq d \leq 1$$

$$V_{qort} = d \cdot V_{DC}$$



$$I_{qort} = \frac{V_{qort} - E_b}{R_q}$$

4 DC-DC



voltage → speed  
 current → torque

Transmission


$$\omega = \frac{V_g}{k_b} - \frac{T_m R_g}{k_t k_b} = \frac{V_g}{k_b} - \frac{i_g R_g}{k_b}$$

$\omega_0$




Yük

$$\omega = \omega_0 - b T_m$$


$$\omega = a V_q - b i_q$$



$V_q > 0$  ( $\omega > 0$ )  
 $i_q > 0$  ( $T_m > 0$ )









$$i_q(t) = \frac{V_{dc} - E_b}{R_g} (1 - e^{-t/\tau_g}) \quad 0 < t < dT$$

$$i_q(t) = I_{max} e^{-(t-dT)/\tau_g} - \frac{E_b}{R_g} (1 - e^{-(t-dT)/\tau_g})$$

$$i_q(t) = 0 \quad \begin{array}{l} dT \leq t < t_x + dT \\ t_x + dT \leq t < T \end{array}$$



$$G_{DA} = \frac{K_{DA}}{sT_{DA} + 1} = \frac{K_{DA}}{s\frac{T}{2} + 1}$$



**PWM Generator  
+ Power**

**Example:**

A brushed DC motor lifts a load via a DC-DC converter.

Given parameters:

$$V_{q,n} = 100V$$

$$n_n = 1000rpm$$

$$R_q = 1\Omega$$

$$L_q = 10mH$$

$$k_b = k_t = 0.9$$

$$V_{DC} = 120V$$

$$T_L = 5Nm(\text{constant})$$

$$B = 0$$

$$J = 1kgm^2$$

- Find the duty cycle for  $n=0$  and  $n=n_{\text{nominal}}$ .
- At  $n_{\text{nominal}}$  speed, evaluate  $I_{\text{min}}$  and  $I_{\text{max}}$   
 $T=1ms$  (switching frequency)

$$n=0 \quad \text{lim} \quad V_q = dV_{DC} = R_q i_q + k_b \omega$$
$$d: 120 = 1 \cdot I_q$$

$$T_L = T_m = k_t i_q = 5$$
$$i_q = \frac{5}{0.9} = 5.55 A$$

$$d = \frac{5.55}{120} = 0.046 = d_{\min}$$

$$n = 1000 \text{ rpm} \quad \omega = 104.72 \text{ rad/sec}$$

$$T_L = T_m \rightarrow I_q = 5.55 \text{ A}$$

$$dV_{DC} = 0.9 \cdot 104.72 + 5.55$$

$$d = \frac{0.9 \cdot 104.72 + 5.55}{120} = 0.8317 = d_{\max}$$

$$\frac{E_b}{R_q} = \frac{V_{DC}}{R_q} \frac{(e^{dT/\tau_q} - 1)}{(e^{T/\tau_q} - 1)}$$

$$\frac{E_b}{V_{DC}} = \frac{e^{dT/\tau_q} - 1}{e^{T/\tau_q} - 1}$$

$$E_b (e^{T/\tau_q} - 1) = V_{DC} e^{dT/\tau_q} - V_{DC}$$

$$\frac{E_b (e^{T/\tau_q} - 1) + V_{DC}}{V_{DC}} = e^{dT/\tau_q}$$

$$\frac{E_b}{V_{bc}} (e^{T/\tau_q} - 1) + 1 = e^{dT/\tau_q}$$

$$\ln \left( \frac{E_b}{V_{bc}} (e^{T/\tau_q} - 1) + 1 \right) = \frac{dT}{\tau_q}$$

$$d_c = \frac{\tau_q}{T} \ln \left[ \frac{E_b}{V_{bc}} (e^{T/\tau_q} - 1) + 1 \right]$$

$$I_{q_{av}} = 5.547 \text{ A}$$

$$d = 0.8317$$

$$I_{q_{min}} = \frac{120 (e^{0.8317 \times 10^{-3} / 10^{-3}} - 1)}{(e^{0.4} - 1)} - \frac{0.9 \times 104.7}{1}$$

$$\tau_q = \frac{L_q}{R_q} = 10 \text{ ms}$$

$$I_{q_{min}} = 4.707 \text{ A}$$

$$I_{q_{max}} = \frac{120 (1 - e^{-0.817/10})}{(1 - e^{-0.1})} - 0.9 \times 104.72$$

$$= 6.387 \text{ A}$$

$$f = 1 \text{ kHz}$$


$$T = 10^{-3} \text{ s}$$

$$0.9 \times 104.7$$

$$V_q(s) - k_b \omega_m(s) = (R_q + sL_q) I_a(s)$$

$$T_y(s) = 0 \quad (sJ + B) \omega_m(s) = k_t I_a(s)$$

$$\omega_m(s) = \frac{k_t}{sJ + B} I_a(s)$$




$$V_q(s) = \frac{(sL_q + R_q)(sJ + B) + k_t k_b}{sJ + B} I_q(s)$$

$$\frac{I_q(s)}{V_q(s)} = \frac{sJ + B}{s^2 J L_q + s(JR_q + B L_q) + (R_q B + k_t k_b)}$$

$$\frac{K(s+c)}{(s+a)(s+b)}$$

$$K = \frac{1}{L_q} \quad C = \frac{B}{J}$$

Current Control Cycle




$$\frac{1}{2} \left( \frac{R_q}{L_q} + \frac{B}{J} \right) \pm \sqrt{\left( \frac{R_q}{L_q} + \frac{B}{J} \right)^2 - \frac{4(R_q B + k_t k_b)}{L_q J}}$$

DC-DC Converter

$$\frac{K_{DC}}{1 + \frac{sT}{2}}$$

$$\frac{i_q}{i_{ref}} = \frac{K(s+c)}{(s+a)(s+b)} \rightarrow$$




$$G_c(s) = \frac{K_c (s+a)(s+b)}{s}$$

PID



$$\begin{aligned}
 \frac{i_q}{i_q^{\text{ref}}} &= \frac{K_c K_{DC} K (s+c)}{(1+s\frac{T}{2})s} = \frac{K_c K_{DC} K (s+c)}{s(1+s\frac{T}{2}) + K_c K_{DC} K (s+c)} \\
 &= \frac{K_c K_{DC} K (s+c)}{1 + \frac{K_c K_{DC} K (s+c)}{(1+s\frac{T}{2})s}} = G_I(s) \approx \frac{K_1}{(s+\beta)}
 \end{aligned}$$

### Speed Control Loop




$$T_y(s) = 0$$

$$\frac{G_\omega(s) K_{AD} \cdot k_t}{(sJ+B)(s\tau_i+1)}$$

$$G_w(s) = \frac{K_w (1 + s\tau_w)}{s}$$

$$\frac{K_w K_{AI} K_t (1 + s\tau_w)}{s (sJ + B) (s\tau_i + 1)} = \frac{K_w K_{AI} \frac{K_t}{B} (1 + s\tau_w)}{s (s\tau_{mech} + 1) (s\tau_i + 1)}$$

$$\tau_w = \tau_m$$



## Pulse Width Modulation (PWM) Basics

- **Definition:** PWM is a technique used in electronic circuits to control the amount of power delivered to a load. It achieves this by rapidly switching the power source on and off.

- **Application in Motor Control:** In electric motors, PWM is used to regulate the speed and torque by varying the average voltage sent to the motor.

### DC-DC Converters

- **Role:** These converters are essential for transforming a source of direct current (DC) from one voltage level to another.

- **Importance in Motor Applications:** They are crucial in electric vehicles and various motor control applications, providing the required voltage levels for efficient operation.

## Hysteresis Current Control

Now, let's focus on the core topic: Hysteresis Current Control.

### Concept of Hysteresis in Current Control

- **Hysteresis Loop:** A hysteresis loop in the context of current control represents the allowable deviation of current from its desired value. When the actual current deviates from the setpoint by a certain threshold, the control system reacts.

- **Rapid Response:** This form of control is known for its fast response, making it ideal for applications where immediate current adjustment is necessary.


### Integration with PWM and DC-DC Converters


- **Duty Cycle Control:** In a PWM system, the duty cycle—the proportion of 'on' time to the regular interval or 'period' of time—directly affects the average power delivered to the load.

- **Average Current Control:** In a DC-DC converter, managing the average current is crucial. This is where hysteresis control plays a significant role. It ensures that the current stays within the desired range, adjusting the duty cycle of the PWM as needed.

## Applications and Advantages

- **Precision in Motor Control:** Hysteresis current control is particularly beneficial in scenarios where precise motor control is required. Electric vehicles, robotic arms, and precision machining tools are prime examples.
- **Efficiency:** By minimizing the deviation from the desired current, efficiency in energy usage is maximized, which is crucial in battery-operated systems like electric vehicles.
- **Reduced Noise and EMI:** The controlled approach to managing current can also lead to reduced electromagnetic interference (EMI) and noise, which is vital in sensitive electronic applications.





$$i_q^{ref} - \Delta i \geq i_q \quad V_q = V_{dc}$$



$$i_q^{ref} + \Delta i \leq i_q \quad V_q = 0$$



$\Delta i$

$$v_q = k \cdot e_i$$


$$|e_i| \leq \Delta i$$


$$k \gg$$














**A four-quadrant chopper circuit**




First-quadrant operation with positive voltage and current in the load



First-quadrant operation with zero voltage across the load




(i) Continuous Conduction




(ii) Discontinuous Conduction


Voltage and current waveforms in first-quadrant operation




Second-quadrant operation, with negative load voltage and positive current



Second-quadrant operation of the chopper




(i) Increasing load current




(ii) Decreasing load current

Modes of operation in the third quadrant




(i) Continuous Conduction




(ii) Discontinuous Conduction

Third-quadrant operation






Fourth-quadrant operation of the chopper





Rectifier average voltage-average current characteristics, where discontinuous and continuous regions in the current are shown in detail.






- As can be seen, the current controller and speed controller have a cascade structure.
- The output of the current controller is the average value of the voltage to be applied to the DC motor.
- This value shows the change in the average voltage that should be applied to the motor in both transient and continuous regimes.
- They are expected to be the same as the voltage  $V_{dc}$  applied to the motor, with a scale difference.  $V_c = V_q^{ref}$


$$V_{dc} = V_{d0} \cos \alpha \quad V_q^{ref} = V_c = V_{cmax} \cos \alpha$$

$$\cos \alpha = \frac{V_{dc}}{V_{d0}} = \frac{V_c}{V_{cmax}} \quad \alpha = \cos^{-1} \left( \frac{V_c}{V_{cmax}} \right)$$

The current loop is the inner loop in cascade control design. Controller design will begin with this cycle, which has much smaller time constants than the speed cycle. For this purpose, first the transfer function between current and voltage will be obtained:



Transfer function between  $i_q$  and  $v_q$ , taking  $T_y = 0$ :



$$\frac{I_q(s)}{V_q(s)} = \frac{(sJ + B)}{(sJ + B)(sL_q + R_q) + K_t K_b}$$


Transfer function of rectifier:  $G_{DC}(s) = \frac{V_q(s)}{V_c(s)} = \frac{K_d}{1 + sT_d}$

$$\frac{I_q(s)}{V_q(s)} = \frac{(sJ+B)}{(sJ+B)(sL_q+R_q)+K_t K_b} = \frac{K_1(sT_m+1)}{(sT_1+1)(sT_2+1)}$$

$$-\frac{1}{T_1}, -\frac{1}{T_2} = -\frac{1}{2} \left( \frac{B}{J} + \frac{R_q}{L_q} \right) \pm \sqrt{\frac{1}{4} \left( \frac{B}{J} + \frac{R_q}{L_q} \right)^2 - \left( \frac{K_t K_b + R_q B}{J L_q} \right)}$$

$$K_1 = \frac{B}{K_t K_b + R_q B} \quad T_m = \frac{J}{B}$$


The model of the rectifier:  $G_{DC}(s) = \frac{V_q(s)}{V_c(s)} = \frac{K_d}{1+sT_d}$



If PID controller is selected as the controller:



$$G_c(s) = \frac{K_c (sT_{c1} + 1)(sT_{c2} + 1)}{s}$$

- If zero-pole cancellation is carried out:  $T_{c1} = T_1; T_{c2} = T_2$




$$K_i = \frac{K_1 K_d K_c T_m}{1 + K_1 K_d K_c T_m H_c}; \quad T_i = \frac{T_d}{1 + K_1 K_d K_c T_m H_c}$$

$$H_c = 1$$



### Speed Control Loop



Transfer Function of the System:


$$G(s) = \frac{\omega_m(s)}{V_{\omega_m}^r} = \frac{\frac{K_s(1+sT_s)}{sT_s} \frac{K_i}{1+sT_i} \frac{K_b/B}{1+sT_m}}{1 + \frac{K_s(1+sT_s)}{sT_s} \frac{K_\omega}{(1+sT_\omega)} \frac{K_i}{1+sT_i} \frac{K_b/B}{1+sT_m}}$$

$$K_\alpha = K_s K_i \frac{K_b}{B}$$

$$T_s = T_m$$

$$G(s) = \frac{\omega_m(s)}{V_{\omega_m}^r} = \frac{\frac{K_\alpha}{T_i} \left( \frac{1}{T_\omega} + s \right)}{s^3 + s^2 \left( \frac{1}{T_\omega} + \frac{1}{T_i} \right) + s \frac{1}{T_\omega T_i} + \frac{K_\alpha K_\omega}{T_\omega T_i}}$$


Apart from the 2 control poles, the 3rd pole should be 5-6 times further away from the real parts of the 2 control poles, and the additional zero should be at least 5-6 times further away.





For operation in 4 zones, the direction of the motor torque and therefore the motor current must change.

In a controlled rectifier that can only flow current in one direction, a second controlled rectifier that flows current in the other direction is required.



A separately-excited dc motor with the following parameters:  $R_a = 0.5 \Omega$ ,  $L_a = 0.003\text{H}$ , and  $K_b = 0.8 \text{ V/rad/sec}$ , is driving a load of  $J = 0.0167 \text{ kg}\cdot\text{m}^2$ ,  $B_l = 0.01 \text{ N}\cdot\text{m/rad/sec}$  with a load torque of  $100 \text{ N}\cdot\text{m}$ . Its armature is connected to a dc supply voltage of  $220 \text{ V}$  and is given the rated field current. Find the speed of the motor.

**Solution** The electromagnetic torque balance is given by

$$T_e = T_l + B_l \omega_m + J \frac{d\omega_m}{dt}$$

In steady state,  $\frac{d\omega_m}{dt} = 0$

$$T_e = T_l + B_l \omega_m = 100 + 0.01 \omega_m$$

$$T_e = K_b i_a = 100 + 0.01 \omega_m$$

$$i_a = \frac{(100 + 0.01 \omega_m)}{K_b} = (125 + 0.0125 \omega_m)$$

$$e = V - R_a i_a = 220 - 0.5 \times (125 + 0.0125 \omega_m) = 157.5 - 0.00625 \omega_m = K_b \omega_m$$

Rearranging in terms of  $\omega_m$ ,

$$\omega_m(0.8 + 0.00625) = 157.5$$

$$\text{Hence } \omega_m = \frac{157.5}{0.80625} = 195.35 \text{ rad/sec}$$

---

A 3-phase full-wave controlled rectifier is fed from a 230 V, 60 Hz network.

The control input of the rectifier is +/- 10V.

The maximum value of the speed reference voltage is 10 V.

The maximum motor current is 20 A.

Speed feedback is received with the help of a tacho generator.

The transfer function of the tacho generator and filter is given below.

$$G_u(s) = \frac{0.065}{(1 + 0.002s)^*}$$

f=60 Hz T=1/60=16.67 ms There are 6 peaks in a period 16.67/6= 2.778 ms = T The time taken for the applied control signal to change is 0<Td<2.778 ms. Here Td=1.38 ms is selected.

**Solution (i)** Converter transfer function:

$$K_r = \frac{1.35 \text{ V}}{V_{cm}} = \frac{1.35 \times 230}{10} = 31.05 \text{ V/V}$$

$$V_{dc}(\text{max}) = 310.5 \text{ V}$$

The rated dc voltage required is 220 V, which corresponds to a control voltage of 7.09 V. The transfer function of the converter is

$$G_r(s) = \frac{31.05}{(1 + 0.00138s)} \text{ V/V}$$

**(ii)** Current transducer gain: The maximum safe control voltage is 7.09 V, and this has to correspond to the maximum current error:

$$i_{\text{max}} = 20 \text{ A}$$

$$H_c = \frac{7.09}{I_{\text{max}}} = \frac{7.09}{20} = 0.355 \text{ V/A}$$

**(iii)** Motor transfer function:

$$K_1 = \frac{B_1}{K_b^2 + R_a B_1} = \frac{0.0869}{1.26^2 + 4 \times 0.0869} = 0.0449$$

$$-\frac{1}{T_1} - \frac{1}{T_2} = -\frac{1}{2} \left[ \frac{B_1}{J} + \frac{R_a}{L_a} \right] \pm \sqrt{\frac{1}{4} \left( \frac{B_1}{J} + \frac{R_a}{L_a} \right)^2 - \left( \frac{K_b^2 + R_a B_1}{J L_a} \right)}$$

$$T_1 = 0.1077 \text{ sec}$$

$$T_2 = 0.0208 \text{ sec}$$

$$T_m = \frac{J}{B_1} = 0.7 \text{ sec}$$

The subsystem transfer functions are

$$\frac{I_a(s)}{V_a(s)} = K_1 \frac{(1 + sT_m)}{(1 + sT_1)(1 + sT_2)} = \frac{0.0449(1 + 0.7s)}{(1 + 0.0208s)(1 + 0.1077s)}$$
$$\frac{\omega_m(s)}{I_a(s)} = \frac{K_b/B_t}{(1 + sT_m)} = \frac{14.5}{(1 + 0.7s)}$$

(iv) Design of current controller:

$$T_c = T_2 = 0.0208 \text{ sec}$$

$$K = \frac{T_1}{2T_r} = \frac{0.1077}{2 \times 0.001388} = 38.8$$

$$K_c = \frac{KT_c}{K_1 H_c K_r T_m} = \frac{38.8 \times 0.0208}{0.0449 \times 0.355 \times 31.05 \times 0.7} = 2.33$$

$$K_\alpha = K_s K_i \frac{K_b}{B} = K_s \times 1.153 \times 14.5 = 16.72 K_s$$

$$G(s) = \frac{\omega_m(s)}{V_{\omega_m}^r} = \frac{\frac{K_\alpha}{T_i} \left( \frac{1}{T_\omega} + s \right)}{s^3 + s^2 \left( \frac{1}{T_\omega} + \frac{1}{T_i} \right) + s \frac{1}{T_\omega T_i} + \frac{K_\alpha}{T_\omega T_i}}$$

$$T_s = T_m$$

$$G_\omega(s) = \frac{0.065}{(s \cdot 0.002 + 1)}$$

$$\frac{1}{T_\omega} \ll \frac{1}{T_i}$$

$$G(s) = \frac{16.72 K_s \left( \frac{1}{T_\omega} + s \right)}{T_i s^3 + s^2 + s \frac{1}{T_\omega} + \frac{1.087 K_s}{T_\omega}}$$

$$T_\omega = 0.002 \text{ sec}$$

$$G(s) = \frac{16.72 K_s (s + 500)}{s^2 + 500s + 543.4 K_s}$$

If  $K_s = 115.016$  is selected, the system will have a multiple root at  $-250$ . Since zero at  $-500$  is closer than 5 times, the critical damped response expected from the system cannot be obtained.

