

FUJITSU SUPPORT INFORMATION - File description: FileDesc_1203957 - LIFEBOOK S762



SUPPORT INFORMATION

File description

Flash - BIOS

Date: 05/27/2024

LIFEBOOK S762

BIOS Admin Pack S762

File

FTS_BIOS Admin Pack S762_2.13FJJ_1203957.zip

Version (Date)

2.13FJJ (27/03/2018)

Size:

7.5 MB

Language

Supports all languages

Status

✓ Released for LIFEBOOK S762

Manufacturer

Fujitsu

MD5

CEAC539165405D7D23B2781A5B11E9C1

SHA256

AF3D2EE244C5BE21265AD56747A3080FD013651907CFFA2032C0D585B70783FC

Important information

Please read the following instructions before flashing the System BIOS:

- This system BIOS can only be flashed to a system which has installed BIOS 2.xx.
A cross flash from BIOS version 1.xx to 2.xx is not possible.
- If DeskFlash is already installed to your system please assure that it is the latest version.
Please check the details at <http://ts.fujitsu.com/manageability>.
- If Secure BIOS is enabled there is no possibility to flash the BIOS in DOS environment.
Please use the Windows based flash procedures instead of.
- Please connect a working AC adapter before starting BIOS flash.
- Please suspend BitLocker encryption before starting BIOS flash in case BitLocker encryption is enabled.

- Please do not switch off your system until BIOS flash process is completed.
- Please reboot your system after BIOS flash has been completed.

Installation description

BIOS Update - Admin Pack supporting FUJITSU Notebook PCs and Tablet PCs

- Inventory -

1. Introduction
 2. Preparation
 3. BIOS Update Procedure
 4. BIOS Version History
-

1. Introduction

This package contains BIOS update files supporting BIOS Update in DOS & Windows environment.

- BIOS Update - DOS
 - BIOS Update – Windows (bup file)
-

2. Preparation

2a) BIOS Update - DOS

After downloading the *.zip file containing the BIOS Update - Admin Pack you need to extract all files of the DOS folder (\DOS) to a e.g. FreeDOS bootable media (e.g. USB Memory Stick). You can create a FreeDOS bootable USB Memory Stick using the following link:

Win7:

<http://support.ts.fujitsu.com/indexdownload.asp?Softwareguid=4C7EAC35-E4B9-4EB2-B51D-C7AB265A9690>

Win8, 8.1, 10:

<http://support.ts.fujitsu.com/indexdownload.asp?Softwareguid=3FC6ED6D-19A5-4424-95D0-AFFF4A1C2869>

WARNING

!!! ALL DATA STORED ON THE USB MEMORY STICK WILL BE ERASED PERMANENTLY!!!
!!! PLEASE ENSURE THAT A DATA BACKUP HAS BEEN DONE BEFORE!!!

2b) BIOS Update – Windows (bup file)

After downloading the *.zip file containing the BIOS Update - Admin Pack you need to extract all files/folders/subfolders in the WINDOWS folder (\WINDOWS) of the zip file to the desired directory of your hard drive.

3. BIOS Update Procedure

3a) BIOS Update - DOS

Run \DOS\DOSflash.bat to update your System BIOS in DOS environment.

3b) BIOS Update - Windows:

Open a command prompt (cmd.exe) with administrator privileges.

Run \WINDOWS\WINflash.bat to update your System BIOS in Windows environment.

For automated BIOS Updates we recommend you use the DeskView / DeskFlash solution (<http://www.fujitsu.com/de/solutions/business-technology/manageability>) using the BIOS files in BUP file format.

Please refer to the corresponding BUP file provided in the \WINDOWS\ folder.

4. BIOS Version History

This information will be provided at the FUJITSU Support pages.

URL: <http://ts.fujitsu.com/support/downloads.html>

Copyright (c) Fujitsu Technology Solutions 2018

Comment

BIOS Update - AdminPack for LIFEBOOK S762

Current BIOS V. 2.13

Solved problems:

- CPU Microcode Update [Spectre Meltdown (INTEL-TA-201710-003)]
- Neither SETUP nor Boot Menu can be entered when a UEFI Boot Option with description containing 61 or more characters is registered

Known errors, problems and restrictions:

- None

Additional information:

- BIOS versions 2.12 has been skipped
- Changed BIOS Version Display (Version 2.13)

- Update Microcode for Ivy Bridge E-1 Stepping (Rev.1Fh)
 - Update Microcode for Sandy Bridge D-2/J-1 Stepping (Rev.2Dh)
-

BIOS Version History

BIOS V. 2.11

Solved problems:

- The battery numbers are shown in reverse order on Windows 10
- Upgrading OS from Windows 7 GPT to Windows 10 may fail
- S3/ Resume vulnerability (VU#976132)
- Pointers and SMI Handlers vulnerability (INTEL-TA DOC #548744)
- Use of Non-Locked BARs in SMI Handlers vulnerability (INTEL-TA DOC #553902)

Known errors, problems and restrictions:

- None

Additional information:

- Changed BIOS Version Display (Version 2.11)
-

BIOS V. 2.10 (only available as BIOS Update - Windows package v2.10 FJJ):

Solved problems:

- Fix capsule update error
- Improved usage of UEFI variables
- After repeating the lid to be opened and closed the display power is turned off even if the lid is opened

Known errors, problems and restrictions:

- None

Additional information:

- Changed BIOS Version Display (Version 2.10)
 - Improved SystemLock3 feature
-

BIOS V. 2.09:

Solved problems:

- The system shuts down intermittently before 60 seconds time out when BitLocker screen for entering PIN is displayed
- System stop occurs intermittently when the boot priority of NETWORK is set to a top priority and USB devices are disabled in BIOS menu
- System goes through BIOS menu when BIOS menu is launched by BIOS password under enabling finger print authentication and "Load Setup Defaults" is executed by F9 key
- "Recovery and Utility" is not displayed in "Application menu" when HDD password is set
- DHCPv6 error occurs during PXE IPv6 boot
- POST stop occurs when USB devices connected to USB3.0 port is unplugged during POST

- After inserting an ExpressCard the CPU Performance goes up to 30-50% and keeps also up after removing the ExpressCard
- UMTS module unsupported by FJ appears after booting for hybrid boot on Windows 8
- USB legacy emulation is not functional when over ten USB devices are connected
- PXE/TFTP boot issue

Known errors, problems and restrictions:

- None

Additional information:

- Changed BIOS Version Display (Version 2.09)
 - Improved POST process when EFI variable is full
 - Update Microcode for Ivy Bridge E-1/L-1 Stepping (Rev.17h)
-

BIOS V. 2.08FJJ:**Solved problems:**

- A PIN pop-up to enter PIN number during POST is not displayed when Fast Boot item in BIOS menu is enabled
- BIOS fingerprint authentication prompt cannot be displayed correctly on full HD panel when “CSM“ is disabled in BIOS menu
- POST stop occurs after certifying with fingerprint when “Select Authentication Method“ screen is displayed
 - and “Fingerprint“ is selected
- BIOS fingerprint authentication prompt cannot display correctly when “Select Authentication Method“ screen is displayed
 - and “Fingerprint“ is selected
- Keyboard is not functional infrequently when diagnostic screen is displayed by pressing ESC key
- BIOS password prompt displays rarely instead of BIOS fingerprint authentication prompt
- BIOS menu and Boot menu cannot be infrequently launched by F2/F12 key after updating OS from Windows 7 (GPT) to Windows 8(GPT)
- BIOS update by DOSFLASH.exe (v1.3.23.3) and WINFLASH32/64.exe (v1.3.27.7) is not blocked when Flash Write item
 - in BIOS menu is disabled
- BSoD occurs during resuming from S3 with HDD password enabled in case of Hynix encrypted SSD (HFS128G3AMNM, HFS064G3AMNM)
- GABI Get Item cannot get PXE Boot Protocol item after Secure Boot item is enabled by GABI Set Setup item
- Language changes to previous value when “Exit Discarding Changed“ in Exit menu is canceled
- GABI Get Item can get Display item after CSM item is enabled by GABI Set Setup item
- The current setting of Boot Time Diagnostic Screen item cannot be changed by GABI Set Item when BIOS password is set

Known errors, problems and restrictions:

- None

Additional Information:

- Changed BIOS Version Display (Version 2.08)
-

Relevant for the following products**LIFEBOOK S762****CONTACT**

Fujitsu Technology Solutions GmbH
Mies-van-der-Rohe-Strasse 8
80807 Muenchen
Germany
Website: www.fujitsu.com/fts/

All rights reserved, including intellectual property rights. Changes to technical data reserved. Delivery subject to availability.

Any liability that the data and illustrations are complete, actual or correct is excluded.

Designations may be trademarks and/or copyrights of the respective manufacturer, the use of which by third parties for their own purposes may infringe the rights of such owner.

For further information see www.fujitsu.com/fts/resources/navigation/terms-of-use.html

Copyright © Fujitsu Technology Solutions 2024