

# RENESAS TECHNICAL UPDATE

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan  
RenesasTechnology Corp.

Product Category	User Development Environment		Document No.	TN-CSX-080A/EA	Rev.	1.0
Title	SuperH RISC engine C/C++ Compiler ver.7 Known Bug Report(13)		Information Category	Usage Limitation		
Applicable Product	P0700CAS7-MWR P0700CAS7-SLR P0700CAS7-H7R	Lot No.	Reference Document	SuperH RISC engine C/C++ Compiler Assembler Optimizing Linkage Editor User's Manual REJ10B0047-0100H Rev.1.00		
		Ver.7.x				

Attached is the description of the known bug in Ver. 7 series of the SuperH RISC engine C/C++ compiler.

The bug will affect the package version in the table below.

	Package Version	Compiler Version
P0700CAS7-MWR	7.0B	7.0B
	7.0.01	7.0.03
	7.0.02	7.0.04
	7.0.03	7.0.06
	7.1.00	7.1.00
	7.1.01	7.1.01
	7.1.02	7.1.01
	7.1.03	7.1.02
	7.1.04	7.1.03
P0700CAS7-SLR	7.0B	7.0B
	7.0.02	7.0.03
	7.0.03	7.0.04
	7.0.04	7.0.06
	7.1.00	7.1.00
	7.1.01	7.1.01
	7.1.02	7.1.01
	7.1.03	7.1.02
	7.1.04	7.1.03
P0700CAS7-H7R	7.0B	7.0B
	7.0.02	7.0.03
	7.0.03	7.0.04
	7.0.04	7.0.06
	7.1.00	7.1.00
	7.1.01	7.1.01
	7.1.02	7.1.01
	7.1.03	7.1.02
	7.1.04	7.1.03

The check tool can be downloaded from the following URL.

<http://www.renesas.com/eng/products/mpumcu/tool/index.html>

Attached: P0700CAS7-040722E

SuperH RISC engine C/C++ Compiler Ver. 7 Known Bug Report (13)

## SuperH RISC engine C/C++ Compiler ver.7

### Known Bug Report(13)

The bug detected in the ver.7 of the SuperH RISC engine C/C++ Compiler is shown below.  
 The check tool can be downloaded from the following URL:  
<http://www.renesas.com/eng/products/mpumcu/tool/index.html>

#### 1. Incorrect replacement of loop induction variable (SHC-0003)

##### [Description]

When loop induction variables existed and their type differs others in a loop, they might be commonized incorrectly.

##### [Example]

```
extern void g();
void func(unsigned int x) {
    unsigned long i=3;
    signed long k=3;

    while (i<x) {
        if (k<-3) { /* variable k was replaced illegally by variable i. */
            break;
        }
        g();
        --i;
        --k;
    }
}
```

##### [Conditions]

This problem might occur when all of the following conditions were fulfilled.

- (1) The optimize=1 option was specified.
- (2) A loop existed.
- (3) The loop of (2) had a signed int type or signed long type loop induction variable and an unsigned int type or unsigned long type one.
- (4) Initial values of the loop induction variables of (3) were constant value.
- (5) Updating values of the loop induction variables of (3) were the same value.

##### [Solution]

If a relevant failure exists, prevent the problem by one of the following methods.

- (1) Specify optimize=0.
- (2) Declare either of the loop induction variables of (3) as volatile.
- (3) Declare either of the loop induction variables of (3) as char/unsigned char/short/ unsigned short type variable.
- (4) Declare the loop induction variables of (3) as the same type variables.