

G-04505
May 2004

SUBJECT: NONCOMPLIANCE RECALL (U.S., EXPORT)
Park Brake Relay Valve on 7400, 7500, and 7600
Models with Air Brakes built 2/8/2004 through
2/25/2004

DEFECT DESCRIPTION

A standard fitting was installed in place of a single check valve on the park brake relay valve. A single point failure of either the primary or secondary air circuits will cause the entire air system to bleed down. If this happens, there will not be enough air in the system to disengage the park brakes.

MODELS INVOLVED

This Noncompliance Recall involves 7400, 7500, and 7600 models with air brakes built 2/8/2004 through 2/25/2004.

OWNER NOTIFICATION

International Truck and Engine Corporation will notify owners of these vehicles about this campaign. A copy of the owner letter is attached. During the recall process, a listing of owner names and addresses will be furnished to the involved dealers to enable dealers to follow up with owners and have the vehicles corrected. You must limit the use of this listing to this campaign because the list may contain information obtained from state motor vehicle registration records and the use of such motor vehicle registration data for purposes other than this campaign is a violation of law in several states.

PARTS INFORMATION

The part required for this recall is:

Part Number	Part Description	Quantity
3588343C1	Valve, Check, 90 deg Elbow	1

SERVICE PROCEDURE



WARNING:

TO PREVENT SERIOUS EYE INJURY, ALWAYS WEAR SAFE EYE PROTECTION WHEN YOU PERFORM VEHICLE MAINTENANCE OR SERVICE.



WARNING:

TO PREVENT UNEXPECTED MOVEMENT OF THE VEHICLE AND POSSIBLE SERIOUS PERSONAL INJURY OR DEATH, BLOCK THE WHEELS TO PREVENT THE VEHICLE FROM MOVING IN BOTH DIRECTIONS.

1. Completely bleed air systems to **0 psi (0 KPa)**.

2. Locate the park brake relay valve (see figure 1) and disconnect the 1/2" orange tube from park brake relay valve that contains the standard fitting.




Figure 1 – Approximate Frame Location of Park Brake Relay Valve

3. Remove the standard fitting from the *LOWER, INBOARD* (see figure 2) port of the park brake relay valve.




Figure 2

4. Install check valve in place of standard fittings. Orient check valve towards the front of the vehicle.




Figure 3

5. Re-connect the ½" orange tube.
6. Start vehicle and fill up air system to full capacity.
7. Ensure there are no air leaks, repair as necessary.

END OF SERVICE PROCEDURE


LABOR INFORMATION

<u>Operation No.</u>	<u>Description</u>	<u>Time</u>
A40-04505-1	<i>Replace Standard Fitting with Check Valve</i>	0.6 Hr

CAMPAIGN IDENTIFICATION LABEL

*Each vehicle corrected in accordance with this campaign **must be** marked with a CTS-1075 Campaign Identification Label.*

Complete the label and attach on a clean surface next to the vehicle identification number (VIN) plate.

A black and white image of a rectangular label. The label has a black border. At the top, it says "DO NOT REMOVE" in white capital letters. Below that, in a white rounded rectangle, it says "INTERNATIONAL" in bold. Underneath, there are fields for "Campaign No.", "VIN", and "Eng.#". Below these fields, it says "COMPLETED" in bold. Underneath that, there is a field for "Service Location Code #". At the bottom of the label, it says "DO NOT REMOVE" in white capital letters.

DO NOT REMOVE

INTERNATIONAL

Campaign No.

VIN
Eng.#

COMPLETED

Service Location Code #

DO NOT REMOVE

ADMINISTRATIVE/DEALER RESPONSIBILITIES (U.S. & POSSESSIONS)

Proceed immediately to make necessary correction to units in inventory. **All inventory vehicles subject to this recall campaign must be corrected prior to sale, transfer or delivery.** If vehicles have been sold or transferred and you are in receipt of Customer Notification Letters and Authorization for Recall Service cards for those vehicles, the transfer location or customer must be notified **IMMEDIATELY** from your dealer location.

Dealers must correct all vehicles subject to this campaign at no charge to the owner, regardless of mileage, age of vehicle, or ownership, from this time forward.

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle that is subject to a vehicle recall campaign must be adequately **repaired** within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within **60 days** after a tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within 60 days, the owner may be entitled to **replacement** with an identical or reasonable equivalent vehicle at no charge, or to a **refund** of the purchase price less a reasonable allowance for depreciation.

However, consistent with the customer notification, dealers are expected to complete the repairs on the mutually agreed upon service date.

To avoid having to replace an owner vehicle or refund the purchase price, every effort must be made to promptly schedule an appointment with each owner to repair his or her vehicle as soon as possible.

WARRANTY CLAIMS

Refer to Dealer Warranty Manual for procedures to conduct Recall Campaigns.

It is important that the Recall Coding be completed properly to assist in processing the warranty claim. Complete instructions will be found in the Warranty Manual, Section 7-1. Special attention should be given to Items 39 through 44:

GROUP	NOUN	C	WARR.	TP	PAD
GROUP: Enter Recall Number	NOUN: Leave Blank.	C: (CAUSE) Enter either 1, 2, or 3.	WARRANTY: (Warranty Code) Enter 40.	TYPE PART: Enter P for type part causing failure.	PAD: Enter 100.
		1. Inspected – no corrections necessary 2. Inspected and repaired. 3. Defective part from parts stock.			

ADMINISTRATIVE/DISTRIBUTOR RESPONSIBILITY (EXPORT)

Proceed immediately to make necessary correction to units in inventory. All inventory vehicles subject to this recall campaign must be corrected prior to sale, transfer or delivery. If vehicles have been sold or transferred and you are in receipt of Customer Notification Letters and Authorization for Recall Service cards for those vehicles, the transfer location or customer must be notified from your distributor location.

Export locations are to submit warranty claims in the usual manner making reference to this recall number.

We ask for your full cooperation and follow-up to this important subject matter. If you have any questions or need further assistance, please contact the Regional Service Manager at your regional office.

INTERNATIONAL TRUCK AND ENGINE CORPORATION